

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
N. M. LAND COMMISSION
P.O. BOX 1000

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELL NO. 88240

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Conoco Inc.	8. FARM OR LEASE NAME Janes B-1
3. ADDRESS OF OPERATOR P.O. Box 460 - Hobbs, New Mexico 88240	9. WELL NO. No 9
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 330' FSL & 1980' FWL - Unit letter F	10. FIELD AND POOL, OR WILDCAT Hobbs Sandrough Yates
14. PERMIT NO. 30-025-20650	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 31-26S-37E 7 R12S
15. ELEVATIONS (Show whether DP, RT, GR, etc.)	12. COUNTY OR PARISH Lea
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. MIRU
2. Run scraper
3. Set CIBP at 2975'. Load & circulate hole full w/ 68 bbl 9.5 ppq mud (9.0 ppq brine plus 25 sxg gel/ 100 bbl brine) Pressure test casing to 300 psi.
4. Spot a 30 sx cement plug on top of CIBP. Displace w/ 15.4 bbls 9.5 ppq mud. Top of plug at 2686'.
5. POOH to 1445' & spot 20 sx cement plug. Displace w/ 7.1 bbls 9.5 ppq mud. Top of plug at 1252'.
6. POOH to 150' & circulate a 20 sx surface cement plug.
7. Install P & A marker.

18. I hereby certify that the foregoing is true and correct

SIGNED W. F. FINNEY

TITLE Administrative Supervisor

DATE October 12, 1987

This space for a term or State office use)

APPROVED W. F. FINNEY

TITLE Administrative Supervisor

DATE 11-5-87

CONDITIONS OF APPROVAL, IF ANY:

*See instructions on Reverse Side

Title of 18 U.S.C. section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM - Carlsbad (6) ARCO (2) Amoco (2) Chevron (1) F&L