NO. OF COPIES RECEIVED					Form C-103		
DISTRIBUTION				Supersedes Old C-102 and C-103			
SANTA FE	N	EW MEXICO OIL CONSE	RVATION COMMISSION	4	Effective 1-1-		
FILE							
U.S.G.S.					,		
LAND OFFICE					L	Fee	
OPERATOR						s Lease No.	
					mmm	mmm	
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)					2 Unit American Name		
OIL GAS WELL WELL	OTHER-						
2. Name of Operator BTA OIL. PRODUCERS					1	•	
3. Address of Operator						06 04-2	
104 S. Pecos, N	Sa. Indicate Type of Lease State						
4. Location of Well	<u> </u>				10. Field and Po	ol, or Wildcat	
E	1650	north	330		Comanche-S	tateline (Ya	
						THITTINI T	
THE West LINE	. SECTION28	township26-S	36-E	нмрм.			
						444444	
UNIT LETTER E 1650 FEET FROM THE NORTH LINE AND 330 FEET FROM THE West Line, Section 28 Township 26-S RANGE 36-E NAMED					Lea		
16.	<u> </u>					<u> </u>	
	•••	e Box To Indicate Na	•	•			
NOTICE	OF INTENTION	то:	501	BSEQUENI	REPORT OF:		
PERFORM REMEDIAL WORK		PLUG AND ABANDON	REMEDIAL WORK	\Box	ALTER	ING CASING	
PERFORM REMEDIAL WORK		PLUG AND ABANDON	REMEDIAL WORK			ING CASING	
=		PLUG AND ABANDON		—		<u> </u>	
TEMPORARILY ABANDON		,	COMMENCE DRILLING OPNS	—		<u> </u>	
TEMPORARILY ABANDON		,	COMMENCE DRILLING OPNS	—		<u> </u>	
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER	leted Operations (Cle	CHANGE PLANS	COMMENCE DRILLING OPHS CASING TEST AND CEMENT OTHER	103	PLUG A	AND ABANDONMENT X	
TEMPORARILY ABANDON PULL OR ALTER CASING	leted Operations (Cle	CHANGE PLANS	COMMENCE DRILLING OPHS CASING TEST AND CEMENT OTHER	103	PLUG A	AND ABANDONMENT X	
OTHER 17. Describe Proposed or Comp. work) SEE RULE 1103.	3	CHANGE PLANS	COMMENCE DRILLING OPNS CASING TEST AND CEMENT OTHER ils, and give pertinent dat	103	PLUG A	AND ABANDONMENT X	
other 17. Describe Proposed or Comp. work) SEE RULE 1103. 9-10-84 - Set	CIBP @ 3,100	arly state all pertinent deta	COMMENCE DRILLING OPNS CASING TEST AND CEMENT OTHER ils, and give pertinent dat D.	es, including	PLUG A	AND ABANDONMENT X	
other 17. Describe Proposed or Comp. work) SEE RULE 1103. 9-10-84 - Set	CIBP @ 3,100	CHANGE PLANS	COMMENCE DRILLING OPNS CASING TEST AND CEMENT OTHER ils, and give pertinent dat D.	es, including	PLUG A	AND ABANDONMENT X	
other 17. Describe Proposed or Comp. work) SEE RULE 1103. 9-10-84 - Set	CIBP @ 3,100	arly state all pertinent deta	COMMENCE DRILLING OPNS CASING TEST AND CEMENT OTHER ils, and give pertinent dat D.	es, including	PLUG A	AND ABANDONMENT X	
other 17. Describe Proposed or Compwork) SEE RULE 1103. 9-10-84 - Set Cut	CIBP @ 3,100 & pulled 5½"	arly state all pertinent deta W/20' cmt. on to csg. @ 2,191: Rec	COMMENCE DRILLING OPNS CASING TEST AND CEMENT OTHER ils, and give pertinent dat D.	es, including	PLUG A	AND ABANDONMENT X	
17. Describe Proposed or Comp. work) SEE RULE 1103. 9-10-84 - Set Cut	CIBP @ 3,100 & pulled 5½" 40 sx. cmt. p	arly state all pertinent deta w/20' cmt. on to csg. @ 2,191: Rec	COMMENCE DRILLING OPNS CASING TEST AND CEMENT OTHER ils, and give pertinent dat D.	es, including	PLUG A	AND ABANDONMENT X	
other 17. Describe Proposed or Comp. work) SEE RULE 1103. 9-10-84 - Set Cut 9-11-84 - Set Set	CIBP @ 3,100 & pulled 5½" 40 sx. cmt. p 50 sx. cmt. p	w/20' cmt. on to csg. @ 2,232' olug @ 1,459'	COMMENCE DRILLING OPNS CASING TEST AND CEMENT OTHER ils, and give pertinent dat D.	es, including	PLUG A	AND ABANDONMENT X	
other 17. Describe Proposed or Compwork) SEE RULE 1103. 9-10-84 - Set Cut 9-11-84 - Set Set Set	CIBP @ 3,100 & pulled 5½" 40 sx. cmt. p 50 sx. cmt. p	arly state all pertinent deta w/20' cmt. on to csg. @ 2,191: Rec lug @ 2,232' lug @ 1,459' lug @ Surface.	COMMENCE DRILLING OPNS CASING TEST AND CEMENT OTHER ils, and give pertinent dat D.	es, including	PLUG A	AND ABANDONMENT X	
other 17. Describe Proposed or Compwork) SEE RULE 1103. 9-10-84 - Set Cut 9-11-84 - Set Set Set Inst	CIBP @ 3,100 & pulled 5½" 40 sx. cmt. p 50 sx. cmt. p 10 sx. Cmt. p	arly state all pertinent deta w/20' cmt. on to csg. @ 2,191: Rec lug @ 2,232' lug @ 1,459' lug @ Surface.	COMMENCE DRILLING OPNS CASING TEST AND CEMENT OTHER ils, and give pertinent dat D.	es, including	PLUG A	AND ABANDONMENT X	
other 17. Describe Proposed or Compwork) SEE RULE 1103. 9-10-84 - Set Cut 9-11-84 - Set Set Set Inst	CIBP @ 3,100 & pulled 5½" 40 sx. cmt. p 50 sx. cmt. p 10 sx. Cmt. p alled dry hol	arly state all pertinent deta w/20' cmt. on to csg. @ 2,191: Rec lug @ 2,232' lug @ 1,459' lug @ Surface.	COMMENCE DRILLING OPNS CASING TEST AND CEMENT OTHER ils, and give pertinent dat D.	es, including	PLUG A	AND ABANDONMENT X	
other 17. Describe Proposed or Compwork) SEE RULE 1103. 9-10-84 - Set Cut 9-11-84 - Set Set Set Inst	CIBP @ 3,100 & pulled 5½" 40 sx. cmt. p 50 sx. cmt. p 10 sx. Cmt. p alled dry hol	arly state all pertinent deta w/20' cmt. on to csg. @ 2,191: Rec lug @ 2,232' lug @ 1,459' lug @ Surface.	COMMENCE DRILLING OPNS CASING TEST AND CEMENT OTHER ils, and give pertinent dat D.	es, including	PLUG A	AND ABANDONMENT X	
other 17. Describe Proposed or Compwork) SEE RULE 1103. 9-10-84 - Set Cut 9-11-84 - Set Set Set Inst	CIBP @ 3,100 & pulled 5½" 40 sx. cmt. p 50 sx. cmt. p 10 sx. Cmt. p alled dry hol	arly state all pertinent deta w/20' cmt. on to csg. @ 2,191: Rec lug @ 2,232' lug @ 1,459' lug @ Surface.	COMMENCE DRILLING OPNS CASING TEST AND CEMENT OTHER ils, and give pertinent dat D.	es, including	PLUG A	AND ABANDONMENT X	
other 17. Describe Proposed or Compwork) SEE RULE 1103. 9-10-84 - Set Cut 9-11-84 - Set Set Set Inst	CIBP @ 3,100 & pulled 5½" 40 sx. cmt. p 50 sx. cmt. p 10 sx. Cmt. p alled dry hol	arly state all pertinent deta w/20' cmt. on to csg. @ 2,191: Rec lug @ 2,232' lug @ 1,459' lug @ Surface.	COMMENCE DRILLING OPNS CASING TEST AND CEMENT OTHER ils, and give pertinent dat D.	es, including	PLUG A	AND ABANDONMENT X	
other 17. Describe Proposed or Compwork) SEE RULE 1103. 9-10-84 - Set Cut 9-11-84 - Set Set Set Inst	CIBP @ 3,100 & pulled 5½" 40 sx. cmt. p 50 sx. cmt. p 10 sx. Cmt. p alled dry hol	arly state all pertinent deta w/20' cmt. on to csg. @ 2,191: Rec lug @ 2,232' lug @ 1,459' lug @ Surface.	COMMENCE DRILLING OPNS CASING TEST AND CEMENT OTHER ils, and give pertinent dat D.	es, including	PLUG A	AND ABANDONMENT X	
other 17. Describe Proposed or Compwork) SEE RULE 1103. 9-10-84 - Set Cut 9-11-84 - Set Set Set Inst	CIBP @ 3,100 & pulled 5½" 40 sx. cmt. p 50 sx. cmt. p 10 sx. Cmt. p alled dry hol	arly state all pertinent deta w/20' cmt. on to csg. @ 2,191: Rec lug @ 2,232' lug @ 1,459' lug @ Surface.	COMMENCE DRILLING OPNS CASING TEST AND CEMENT OTHER ils, and give pertinent dat D.	es, including	PLUG A	AND ABANDONMENT X	
other 17. Describe Proposed or Compwork) SEE RULE 1103. 9-10-84 - Set Cut 9-11-84 - Set Set Set Inst	CIBP @ 3,100 & pulled 5½" 40 sx. cmt. p 50 sx. cmt. p 10 sx. Cmt. p alled dry hol	arly state all pertinent deta w/20' cmt. on to csg. @ 2,191: Rec lug @ 2,232' lug @ 1,459' lug @ Surface.	COMMENCE DRILLING OPNS CASING TEST AND CEMENT OTHER ils, and give pertinent dat D.	es, including	PLUG A	AND ABANDONMENT X	

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Regulatory Supervisor

OTT 8 CONDITIONS OF APPROVAL, IF ANY:

OTT 8 CONDITIONS OF APPROVAL, IF ANY: