

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other Instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.
LEASE DESIGNATION AND SERIAL NO.

NM 12280

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED
 P. O. DRAWER 992
 HOBBES, NEW MEXICO 88240

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
2. NAME OF OPERATOR American Trading & Production Corporation	7. UNIT AGREEMENT NAME Talco Unit
3. ADDRESS OF OPERATOR P. O. Drawer 992	8. FARM OR LEASE NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface Unit Letter H, 1980' FNL & 660' FEL of Section 11, T-26-S, R-35-E, 9 miles Southwest of Jal, New Mexico	9. WELL NO. 1
14. PERMIT NO.	10. FIELD AND POOL, OR WILDCAT Talco (Strawn)
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3074.4 GR	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 11 T-26-S R-35-E
	12. COUNTY OR PARISH 13. STATE Lea NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OFF <input type="checkbox"/> FRACTURE TREAT <input type="checkbox"/> SHOOT OR ACIDIZE <input type="checkbox"/> REPAIR WELL <input type="checkbox"/> (Other) Open additional pay & stimulate <input checked="" type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/> FRACTURE TREATMENT <input type="checkbox"/> SHOOTING OR ACIDIZING <input type="checkbox"/> (Other) _____ (NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETE <input type="checkbox"/> ABANDON* <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> ABANDONMENT* <input type="checkbox"/>

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Set WL plug in profile at 13,913'.
2. Load tubing with water.
3. Strip off tree and install 10,000 psi BOP.
4. Trip out of hole with tubing.
5. Set production packer with tail pipe at approximately 13,500'.
6. Trip in hole with tubing and seal assembly. Remove BOP and install tree.
7. Perforate 7 3/4" liner with one hole per foot @ 13591', 592,593; 13674', 676, 678; 13726', 727,728; 13751', 752; 13806', 808, 810; 13873', 874 (total 16 holes).
8. Flow well natural, then treat with 15% NEFE acid & ball sealers as necessary.
9. After clean up and testing new intervals, retrieve plug from profile @ 13,913'.

RECEIVED
 JAN -4 1982

18. I hereby certify that the foregoing is true and correct

SIGNED *James Atchley* TITLE Production Clerk DATE 12-30-81

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

APPROVED

DATE _____

JAN 5 1982
J.A.G.
 JAMES A. GILLHAM
 DISTRICT SUPERVISOR

*See Instructions on Reverse Side