

State of New Mexico
Energy Minerals and Natural Resources
Department
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Recycling Facility and/or Recycling Containment

Type of Facility: ☒ Recycling Facility ☒ Recycling Containment*
Type of action: ☐ Permit ☐ Registration
☐ Modification ☒ Extension
☐ Closure ☐ Other (explain) _____

* At the time C-147 is submitted to the division for a Recycling Containment, a copy shall be provided to the surface owner.

Be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances.

1.

Operator: Enduring Resources, LLC (For multiple operators attach page with information) OGRID #: 372286
 Address: 200 Energy Court, Farmington, NM 87401
 Facility or well name (include API# if associated with a well): WLU 2309 24N Water Recycle Facility
 OCD Permit Number: 3RF-29 (For new facilities the permit number will be assigned by the district office)
 U/L or Qtr/Qtr SW/4 SW/4 Section 24 Township 23N Range 9W County: San Juan
 Surface Owner: ☒ Federal ☐ State ☐ Private ☐ Tribal Trust or Indian Allotment

2.

☒ **Recycling Facility:**
 Location of recycling facility (if applicable): Latitude 36.205958 Longitude -107.740891 NAD83
 Proposed Use: ☒ Drilling* ☒ Completion* ☒ Production* ☒ Plugging*
**The re-use of produced water may NOT be used until fresh water zones are cased and cemented*
☐ Other, requires permit for other uses. Describe use, process, testing, volume of produced water and ensure there will be no adverse impact on groundwater or surface water.
☒ Fluid Storage
☒ Above ground tanks ☒ Recycling containment ☐ Activity permitted under 19.15.17 NMAC explain type _____
☐ Activity permitted under 19.15.36 NMAC explain type: _____ ☐ Other explain _____
☐ For multiple or additional recycling containments, attach design and location information of each containment
☐ **Closure Report (required within 60 days of closure completion):** ☐ Recycling Facility Closure Completion Date: _____

3.

☒ **Recycling Containment:**
☐ Annual Extension after initial 5 years (attach summary of monthly leak detection inspections for previous year)
 Center of Recycling Containment (if applicable): Latitude 36.205958 Longitude -107.740891 NAD83
☐ For multiple or additional recycling containments, attach design and location information of each containment
☐ Lined ☒ Liner type: Thickness 45 mil ☒ LLDPE ☐ HDPE ☐ PVC ☐ Other _____
☒ String-Reinforced
 Liner Seams: ☒ Welded ☒ Factory ☐ Other _____ Volume: 265,385 bbl Dimensions: L 350' x W 400' x D 25'
☐ Recycling Containment Closure Completion Date: _____

4.

Bonding:

- ☒ Covered under bonding pursuant to 19.15.8 NMAC per 19.15.34.15(A)(2) NMAC (These containments are limited to only the wells owned or operated by the owners of the containment.)
- ☐ Bonding in accordance with 19.15.34.15(A)(1). Amount of bond \$ _____ (work on these facilities cannot commence until bonding amounts are approved)
- ☐ Attach closure cost estimate and documentation on how the closure cost was calculated.

5.

Fencing:

- ☐ Four foot height, four strands of barbed wire evenly spaced between one and four feet
- ☒ Alternate. Please specify 8' Tall Chain Link Fencing

6.

Signs:

- ☐ 12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers
- ☒ Signed in compliance with 19.15.16.8 NMAC

7.

Variances:

Justifications and/or demonstrations that the proposed variance will afford reasonable protection against contamination of fresh water, human health, and the environment.

Check the below box only if a variance is requested:

- ☐ Variance(s): Requests must be submitted to the appropriate division district for consideration of approval. If a Variance is requested, include the variance information on a separate page and attach it to the C-147 as part of the application.

If a Variance is requested, it must be approved prior to implementation.

8.

Siting Criteria for Recycling Containment

Instructions: The applicant must provide attachments that demonstrate compliance for each siting criteria below as part of the application. Potential examples of the siting attachment source material are provided below under each criteria.

General siting**Ground water is less than 50 feet below the bottom of the Recycling Containment.**

NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells

☐ Yes ☒ No
☐ NA

Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended.

☐ Yes ☒ No
☐ NA

- Written confirmation or verification from the municipality; written approval obtained from the municipality

Within the area overlying a subsurface mine.

☐ Yes ☒ No

- Written confirmation or verification or map from the NM EMNRD-Mining and Minerals Division

Within an unstable area.

☐ Yes ☒ No

- Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; topographic map

Within a 100-year floodplain. FEMA map

☐ Yes ☒ No

Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark).

☐ Yes ☒ No

- Topographic map; visual inspection (certification) of the proposed site

Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application.

☐ Yes ☒ No

- Visual inspection (certification) of the proposed site; aerial photo; satellite image

Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application.

☐ Yes ☒ No

- NM Office of the State Engineer - iWATERS database search; visual inspection (certification) of the proposed site

Within 500 feet of a wetland.

☐ Yes ☒ No

- US Fish and Wildlife Wetland Identification map; topographic map; visual inspection (certification) of the proposed site

9.

Recycling Facility and/or Containment Checklist:

Instructions: Each of the following items must be attached to the application. Indicate, by a check mark in the box, that the documents are attached.

- ☐ Design Plan - based upon the appropriate requirements.
- ☐ Operating and Maintenance Plan - based upon the appropriate requirements.
- ☐ Closure Plan - based upon the appropriate requirements.
- ☐ Site Specific Groundwater Data -
- ☐ Siting Criteria Compliance Demonstrations -
- ☒ Certify that notice of the C-147 (only) has been sent to the surface owner(s)

10.

Operator Application Certification:

I hereby certify that the information and attachments submitted with this application are true, accurate and complete to the best of my knowledge and belief.

Name (Print): Heather Huntington Title: Permitting Technician

Signature:  Date: 8/25/2021

e-mail address: hhuntington@enduringresources.com Telephone: 505-636-9751

11.

OCD Representative Signature: Victoria Venegas Approval Date: 08/26/2021

Title: Environmental Specialist OCD Permit Number: 3RF-29

☒ OCD Conditions FACILITY ID fCS1828842180

☒ Additional OCD Conditions on Attachment



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLU 2309-24N Permit Number SJ-4301 Pad 3
 Section 24 Township 23N Range 4W County San Juan State NM
 Time Inspection Began 9:23 Time Inspection Ended 4:50
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 19 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of ULD (ft) 99.2
 Depth to Water in ULD (ft) 98.9
 Height of Water in ULD 3.5 in
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of LLD (ft) 95.8
 Depth to Water in LLD (ft) 95.8
 Height of Water in LLD 0
 Gallons of Water Removed 0

If leak detection contained liquid, was it removed? YES ☐ NO ☒ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☒

COMMENTS

No enough to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 1-6-20Name (Signature) Tina HarrisCompany ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLU 2309-24N Permit Number 4301-Pod 3
 Section 24 Township 23N Range 9W County San Juan State NM
 Time Inspection Began 9:23 Time Inspection Ended 10:10
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 20 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of ULD (ft)	<u>99.8</u>			
Depth to Water in ULD (ft)	<u>98.8</u>			
Height of Water in ULD	<u>3"</u>			
Gallons of Water Removed	<u>0</u>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of LLD (ft)	<u>95.8</u>			
Depth to Water in LLD (ft)	<u>95.8</u>			
Height of Water in LLD	<u>0</u>			
Gallons of Water Removed	<u>0</u>			

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

No enough water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 1-15-21

Name (Signature) Tina Harris

Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLU 2309-24N Permit Number 4301 Pod 3
 Section 4 Township 24N Range 9W County San Juan State NM
 Time Inspection Began 10:52 Time Inspection Ended 11:45
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 20 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 99.2
 Depth to Water in ULD (ft) 96.65
 Height of Water in ULD 4.5"
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of LLD (ft) 95.8
 Depth to Water in LLD (ft) 95.8
 Height of Water in LLD 0
 Gallons of Water Removed 0

If leak detection contained liquid, was it removed? YES ☐ NO ☒ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

Not enough water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Replaced 3 birds eye balls

Name (Print) Tina Harris

Date 1-21-21

Name (Signature) [Signature]

Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLU 2309-24N Permit Number 4301-Pod 3
 Section 24 Township 23N Range 9W County San Juan State NM
 Time Inspection Began 9:26 Time Inspection Ended 9:51
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 21 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of ULD (ft)		<u>99.1</u>		
Depth to Water in ULD (ft)		<u>98.0</u>		
Height of Water in ULD		<u>2"</u>		
Gallons of Water Removed		<u>0</u>		

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of LLD (ft)		<u>95.8</u>		
Depth to Water in LLD (ft)		<u>95.8</u>		
Height of Water in LLD		<u>0</u>		
Gallons of Water Removed		<u>0</u>		

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Not enough water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 1-27-21

Name (Signature) Tina Harris

Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLU 2309 24N Permit Number _____
 Section 24 Township 23N Range 9W County San Juan State CO
 Time Inspection Began 10:05 Time Inspection Ended 10:30
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 21/23

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYLING CONTAINMENT.

Containment has a minimum of three feet of freeboard	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of ULD (ft)		<u>99.1</u>		
Depth to Water in ULD (ft)		<u>98.6</u>		
Height of Water in ULD		<u>5"</u>		
Gallons of Water Removed		<u>0</u>		

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of LLD (ft)		<u>95.8</u>		
Depth to Water in LLD (ft)		<u>95.8</u>		
Height of Water in LLD		<u>0</u>		
Gallons of Water Removed		<u>0</u>		

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Not enough water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 2-3-21

Name (Signature) [Signature]

Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLU 2309-24N Permit Number 4301 Pod-3
 Section 24 Township 23N Range 9W County San Juan State NM
 Time Inspection Began 9:05 Time Inspection Ended 9:31
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 21.5 / 23

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS water well is running
water level is high due to 24hr test for frac.

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)			Lower Leak Detection (LLD)		
Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	<input checked="" type="checkbox"/>
Total Depth of ULD (ft)		<u>99.1</u>	Total Depth of LLD (ft)		<u>95.8</u>
Depth to Water in ULD (ft)		<u>98.8</u>	Depth to Water in LLD (ft)		<u>95.8</u>
Height of Water in ULD		<u>3 in</u>	Height of Water in LLD		<u>0</u>
Gallons of Water Removed		<u>0</u>	Gallons of Water Removed		<u>0</u>

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS No enough water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 2-11-21

Name (Signature) Tina Harris

Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLU 2309 24N Permit Number 4301-Pod-3
 Section 24 Township 23N Range 9W County Saa Juan State NM
 Time Inspection Began 9:28 Time Inspection Ended 10:00
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22/23

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

Crew on location, getting water well ready for Fracking

COMMENTS

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of ULD (ft)		<u>99.1</u>		
Depth to Water in ULD (ft)		<u>98.8</u>		
Height of Water in ULD		<u>3m</u>		
Gallons of Water Removed		<u>0</u>		

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of LLD (ft)		<u>95.8</u>		
Depth to Water in LLD (ft)		<u>95.8</u>		
Height of Water in LLD		<u>0</u>		
Gallons of Water Removed		<u>0</u>		

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Pond is full due to Fracking.

COMMENTS

Not enough water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 2-17-21

Name (Signature) Tina Harris

Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLU 2309 24N Permit Number 4301 Pod-3
 Section 24 Township 23N Range 9W County San Juan State NM
 Time Inspection Began 10:00 Time Inspection Ended 10:40
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 21F/23

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew on location

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 99.1
 Depth to Water in ULD (ft) 98.8
 Height of Water in ULD 3in
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of LLD (ft) 95.8
 Depth to Water in LLD (ft) 95.8
 Height of Water in LLD 0
 Gallons of Water Removed 0

If leak detection contained liquid, was it removed? YES ☐ NO ☒ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

Not enough water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Replaced 2 birds' eye

Name (Print) Tina Herro'sDate 2-24-21Name (Signature) D. H. iCompany ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLU 2309-24N Permit Number 4301-Pd.3
 Section 24 Township 23N Range 9W County San Juan State NM
 Time Inspection Began 11:24 Time Inspection Ended 11:45
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 11ft / 23

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 99.1
 Depth to Water in ULD (ft) 98.7
 Height of Water in ULD 4"
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of LLD (ft) 95.8
 Depth to Water in LLD (ft) 95.8
 Height of Water in LLD 0
 Gallons of Water Removed 0

If leak detection contained liquid, was it removed? YES ☐ NO ☒ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

No enough water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 8-3-21Name (Signature) [Signature]Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLU 2309 - 24N Permit Number 4301 Pod-3
 Section 24 Township 23N Range 9W County San Juan State NM
 Time Inspection Began 11:30 Time Inspection Ended 12:10
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 12 ft / 23

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of ULD (ft)		<u>99.1</u>		
Depth to Water in ULD (ft)		<u>98.75</u>		
Height of Water in ULD		<u>3 1/2"</u>		
Gallons of Water Removed		<u>0</u>		

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of LLD (ft)		<u>95.8</u>		
Depth to Water in LLD (ft)		<u>95.8</u>		
Height of Water in LLD		<u>0</u>		
Gallons of Water Removed		<u>0</u>		

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

No enough water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Replaced 2 bird eyes

Name (Print) Tina Harris

Date 3-10-21

Name (Signature) [Signature]

Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLU 2309-24N Permit Number 4301-Pod 3
 Section 16 Township 22N Range 9W County San Juan State NM
 Time Inspection Began 11:00 Time Inspection Ended 11:30
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 13 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of ULD (ft)	<u>95.8</u>			
Depth to Water in ULD (ft)	<u>95.8</u>			
Height of Water in ULD	<u>0</u>			
Gallons of Water Removed	<u>0</u>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)	<u>99.1</u>			
Depth to Water in LLD (ft)	<u>98.5</u>			
Height of Water in LLD	<u>6"</u>			
Gallons of Water Removed	<u>0</u>			

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Not enough water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 3-17-21

Name (Signature) [Signature]

Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLU 2309 24N Permit Number 3RF-29
 Section 24 Township 23N Range 9W County San Juan State NM
 Time Inspection Began 12:30 pm Time Inspection Ended 12:50 pm
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 14'

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of ULD (ft)	<input type="text"/>			
Depth to Water in ULD (ft)	<input type="text"/>			
Height of Water in ULD	<input type="text"/>			
Gallons of Water Removed	<input type="text"/>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)	<input type="text"/>			
Depth to Water in LLD (ft)	<input type="text"/>			
Height of Water in LLD	<input type="text"/>			
Gallons of Water Removed	<input type="text"/>			

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Did not have ULD, kick on pump No water

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Chad Snell

Date 3-26-21

Name (Signature) [Signature]

Company Enduring Resources



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLU 2309-24N Permit Number 4301 Pbd-3
 Section 24 Township 23N Range 9W County San Juan State NM
 Time Inspection Began 9:00 Time Inspection Ended 9:30
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 15 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of ULD (ft)	<u>99.1</u>			
Depth to Water in ULD (ft)	<u>98.8</u>			
Height of Water in ULD	<u>3m</u>			
Gallons of Water Removed	<u>0</u>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of LLD (ft)	<u>95.8</u>			
Depth to Water in LLD (ft)	<u>95.8</u>			
Height of Water in LLD	<u>0</u>			
Gallons of Water Removed	<u>0</u>			

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

No enough water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tim Harris

Date 3-31-21

Name (Signature) [Signature]

Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLU 2309-24N Permit Number 4301-Pod-3
 Section 4 Township 24N Range 9W County San Juan State NM
 Time Inspection Began 11:01 Time Inspection Ended 11:40
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 15 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew on location

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of ULD (ft)		<u>99.1</u>			Total Depth of LLD (ft)		<u>95.8</u>		
Depth to Water in ULD (ft)		<u>98.6</u>			Depth to Water in LLD (ft)		<u>95.8</u>		
Height of Water in ULD		<u>5.5 in</u>			Height of Water in LLD		<u>0</u>		
Gallons of Water Removed		<u>0</u>			Gallons of Water Removed		<u>0</u>		

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

No enough water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Crew skimming oil off water

Name (Print) Tina Harris

Date 4-7-21

Name (Signature) [Signature]

Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLU 2309-24N Permit Number 4301-Pod 3
 Section 24 Township 23N Range 9W County San Juan State NM
 Time Inspection Began 9:42 Time Inspection Ended 10:15
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 15 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew on location

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of ULD (ft)		<u>99.1</u>		
Depth to Water in ULD (ft)		<u>98.6</u>		
Height of Water in ULD		<u>5 in</u>		
Gallons of Water Removed		<u>0</u>		

Water Present in LLD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of LLD (ft)		<u>95.8</u>		
Depth to Water in LLD (ft)		<u>95.8</u>		
Height of Water in LLD		<u>0</u>		
Gallons of Water Removed		<u>0</u>		

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Not enough water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Replace one bird's eye ball

Name (Print) Tina Harris

Date 4-14-21

Name (Signature) [Signature]

Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLU 2309 24N Permit Number 4301-Pd 3
 Section 24 Township 23N Range 9W County San Juan State NM
 Time Inspection Began 11:07 Time Inspection Ended 11:45
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 184

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of ULD (ft)	<u>99.1</u>			
Depth to Water in ULD (ft)	<u>98.6</u>			
Height of Water in ULD	<u>5"</u>			
Gallons of Water Removed	<u>0</u>			

Water Present in LLD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of LLD (ft)	<u>95.8</u>			
Depth to Water in LLD (ft)	<u>95.8</u>			
Height of Water in LLD	<u>0</u>			
Gallons of Water Removed	<u>0</u>			

If leak detection contained liquid, was it removed?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Not enough water to remove, oil needs to be skimmed

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Sent pic of oil to Doug

Name (Print)

Tina Harris

Date

4-21-21

Name (Signature)

T. Harris

Company

ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLU 2309-24N Permit Number 4301-Pod3
 Section 24 Township 23N Range 9W County San Juan State NM
 Time Inspection Began 9:30 Time Inspection Ended 10:05
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 18 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS Oil on south side of pond, sent pictures to Chad and Doug Sprague

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Lower Leak Detection (LLD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 99.1
 Depth to Water in ULD (ft) 98.6
 Height of Water in ULD 5 in
 Gallons of Water Removed 0

Water Present in ULD? YES ☐ NO ☒
 Total Depth of LLD (ft) 95.8
 Depth to Water in LLD (ft) 95.8
 Height of Water in LLD A
 Gallons of Water Removed 0

If leak detection contained liquid, was it removed? YES ☐ NO ☒ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS No enough water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS Replaced 3 bird's eye balls

Name (Print) Tina Hurry

Date 4-28-21

Name (Signature) [Signature]

Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLU 2309-24N Permit Number 4301 Pod 3
 Section 24 Township 23N Range 9W County San Juan State NM
 Time Inspection Began 9:57 Time Inspection Ended 10:25
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 19 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew on location

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Lower Leak Detection (LLD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 99.1
 Depth to Water in ULD (ft) 98.7
 Height of Water in ULD 4.1
 Gallons of Water Removed 0

Water Present in ULD? YES ☐ NO ☒
 Total Depth of LLD (ft) 95.8
 Depth to Water in LLD (ft) 95.8
 Height of Water in LLD 0
 Gallons of Water Removed 0

If leak detection contained liquid, was it removed? YES ☐ NO ☒ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 5-5-21

Name (Signature) [Signature]

Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLU 2309-24N Permit Number 4301 Pod 3
 Section 24 Township 23N Range 9W County SAN JUAN State NM
 Time Inspection Began 11:00 Time Inspection Ended 11:30
 Recycling Facility ☐ Recycling Containment ☐ Water Level (Feet) 19.5

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 99.1
 Depth to Water in ULD (ft) 98.85
 Height of Water in ULD 2 in
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of LLD (ft) 95.8
 Depth to Water in LLD (ft) 95.8
 Height of Water in LLD 0
 Gallons of Water Removed 0

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

COMMENTS

Not enough water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 5-12-21

Name (Signature) [Signature]

Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLU 2309-24N Permit Number 4801 Pod-3
 Section 24 Township 23N Range 9 County San Juan State NM
 Time Inspection Began 7:45 Time Inspection Ended 8:15
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 20 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew going in and out of location

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 99.1
 Depth to Water in ULD (ft) 98.7
 Height of Water in ULD 4"
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of LLD (ft) 95.8
 Depth to Water in LLD (ft) 95.8
 Height of Water in LLD 0
 Gallons of Water Removed 0

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

COMMENTS

Oil needs to be skimmed, sent pictures to Doug Sprague
Not enough water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Name (Print) Tim Harris

Date 5-19-21

Name (Signature) TH

Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLU 2309 24N Permit Number 4301-10d 3
 Section 24 Township 23 Range 9 County San Juan State NM
 Time Inspection Began 9:45 Time Inspection Ended 10:15
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 21 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew on location

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 99.1
 Depth to Water in ULD (ft) 98.7
 Height of Water in ULD 4 in
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of LLD (ft) 95.8
 Depth to Water in LLD (ft) 95.8
 Height of Water in LLD 0
 Gallons of Water Removed 0

If leak detection contained liquid, was it removed? YES ☐ NO ☒ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

No enough water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 5-26-21

Name (Signature) [Signature]

Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLU 2309-24N Permit Number 4301 Pod-3
 Section 24 Township 23 Range 9W County San Juan State NM
 Time Inspection Began 8:40 Time Inspection Ended 9:00
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 21 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew on location

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 99.1
 Depth to Water in ULD (ft) 98.7
 Height of Water in ULD 4 in
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of LLD (ft) 95.8
 Depth to Water in LLD (ft) 95.8
 Height of Water in LLD 0
 Gallons of Water Removed 0

If leak detection contained liquid, was it removed? YES ☐ NO ☒ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

No enough water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 8-6-3-21Name (Signature) [Signature]Company ER

Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLU 2309 - 24N Permit Number 4301-Pool 3
 Section 24 Township 23 Range 9 County San Juan State NM
 Time Inspection Began 9:50 Time Inspection Ended 10:15
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 21ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew on location.

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 99.1
 Depth to Water in ULD (ft) 98.5
 Height of Water in ULD 8 in
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of LLD (ft) 95-8
 Depth to Water in LLD (ft) 95-8
 Height of Water in LLD 0
 Gallons of Water Removed 0

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

Not enough water to remove.

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 6-9-21Name (Signature) [Signature]Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLU 2309-24N Permit Number 4301 Pod 3
 Section 24 Township 23 Range 9 County San Juan State NM
 Time Inspection Began 7:57 Time Inspection Ended 8:30
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS Crew on location

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of ULD (ft)		<u>99.1</u>		
Depth to Water in ULD (ft)		<u>98.3</u>		
Height of Water in ULD		<u>8 in</u>		
Gallons of Water Removed		<u>0</u>		

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of LLD (ft)		<u>95.8</u>		
Depth to Water in LLD (ft)		<u>95.8</u>		
Height of Water in LLD		<u>0</u>		
Gallons of Water Removed		<u>0</u>		

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS Not enough water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 6-17-21

Name (Signature) [Signature]

Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLU 2309-24N Permit Number 4301 Pod-3
 Section 24 Township 23 Range 9 County San Juan State NM
 Time Inspection Began 9:30 Time Inspection Ended 9:50
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 99.1
 Depth to Water in ULD (ft) 98.4
 Height of Water in ULD 5'
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of LLD (ft) 95.8
 Depth to Water in LLD (ft) 45.8
 Height of Water in LLD 95.8
 Gallons of Water Removed 0

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☐

COMMENTS

Not enough water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 10-23-21Name (Signature) [Signature]Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLU 2309-24N Permit Number 4301-Pod 3
 Section 24 Township 23 Range 9W County San Juan State NM
 Time Inspection Began 8:37 Time Inspection Ended 9:00
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 99.1
 Depth to Water in ULD (ft) 98.6
 Height of Water in ULD 5 in
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of LLD (ft) 95.8
 Depth to Water in LLD (ft) 95.8
 Height of Water in LLD 0
 Gallons of Water Removed 0

If leak detection contained liquid, was it removed? YES ☐ NO ☒ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

No enough waste to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 10-30-21

Name (Signature) TH

Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLU 2309-24N Permit Number 4301 Pod-3
 Section 24 Township 23 Range 9 County San Juan State NM
 Time Inspection Began 10:10 Time Inspection Ended 10:40
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 99.1
 Depth to Water in ULD (ft) 98.5
 Height of Water in ULD 6 in
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of LLD (ft) 95.8
 Depth to Water in LLD (ft) 95.4
 Height of Water in LLD 4 in
 Gallons of Water Removed 0

If leak detection contained liquid, was it removed? YES ☐ NO ☒ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

Oil has been skimmed, but still some oil remains.

COMMENTS *Not enough water to remove*

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 7-7-21

Name (Signature) [Signature]

Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WL4 2309-24N Permit Number 4301 Pcd3
 Section 24 Township 23 Range 9 County San Juan State NM
 Time Inspection Began 11:05 Time Inspection Ended 11:30
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 21ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew on location

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of ULD (ft)	<u>99.1</u>			
Depth to Water in ULD (ft)	<u>98.1</u>			
Height of Water in ULD	<u>1ft.</u>			
Gallons of Water Removed	<u>0</u>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of LLD (ft)	<u>95.8</u>			
Depth to Water in LLD (ft)	<u>95.8</u>			
Height of Water in LLD	<u>0</u>			
Gallons of Water Removed	<u>0</u>			

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Need to rent pump to remove water

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print)

Tina Harris

Date

7-13-21

Name (Signature)

[Signature]

Company

ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLU 2309 24N Permit Number 4301-Pod 3
 Section 24 Township 23 Range 9 County San Juan State NM
 Time Inspection Began 9:50 Time Inspection Ended 10:15
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

TRI on location

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 99.1
 Depth to Water in ULD (ft) 98.2
 Height of Water in ULD 9m
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of LLD (ft) 95.8
 Depth to Water in LLD (ft) 95.8
 Height of Water in LLD 0
 Gallons of Water Removed 0

If leak detection contained liquid, was it removed? YES ☐ NO ☒ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

No enough water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 7-21-21

Name (Signature) [Signature]

Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLU 2309-24N Permit Number 43016013
 Section 24 Township 23 Range 9 County San Juan State NM
 Time Inspection Began 11:30 Time Inspection Ended 11:50
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of ULD (ft)	<u>99.1</u>			
Depth to Water in ULD (ft)	<u>98.45</u>			
Height of Water in ULD	<u>6.5 in</u>			
Gallons of Water Removed	<u>0</u>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of LLD (ft)	<u>95.8</u>			
Depth to Water in LLD (ft)	<u>95.8</u>			
Height of Water in LLD	<u>0</u>			
Gallons of Water Removed	<u>0</u>			

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

No enough water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 7-28-21Name (Signature) [Signature]Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLU 2309-24N Permit Number 4301-Pod 3
 Section 24 Township 23 Range 9 County San Juan State NM
 Time Inspection Began 10:38 Time Inspection Ended 11:00
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22P

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 99.1
 Depth to Water in ULD (ft) 98.3
 Height of Water in ULD 8M
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of LLD (ft) 95.8
 Depth to Water in LLD (ft) 95.8
 Height of Water in LLD 0
 Gallons of Water Removed 0

If leak detection contained liquid, was it removed? YES ☐ NO ☒ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

No enough water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 8-4-21

Name (Signature) TH

Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLU 2369 24N Permit Number 3RF-29
 Section 24 Township 23N Range 9W County San Juan State NM
 Time Inspection Began 12:30 Time Inspection Ended 12:50
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of ULD (ft)		<u>99.7</u>		
Depth to Water in ULD (ft)		<u>98.1</u>		
Height of Water in ULD		<u>1.1</u>		
Gallons of Water Removed		<u>0</u>		

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)		<u>95.8</u>		
Depth to Water in LLD (ft)		<u>95.7.5</u>		
Height of Water in LLD		<u>.5</u>		
Gallons of Water Removed		<u>0</u>		

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

NOT ENOUGH WATER TO REMOVE

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) JOE SARRASA

Date 8-13-21

Name (Signature) [Signature]

Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name WLU 2309-24N Permit Number 4301-Pod-3
 Section 24 Township 23 Range 9 County San Juan State NM
 Time Inspection Began 12:37 Time Inspection Ended 1:01
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 99.1
 Depth to Water in ULD (ft) 97.9
 Height of Water in ULD 1 ft 2"
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of LLD (ft) 95.8
 Depth to Water in LLD (ft) 95.4
 Height of Water in LLD 4 in
 Gallons of Water Removed 0

If leak detection contained liquid, was it removed? YES ☐ NO ☒ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

Need to rent pump next week

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 8-18-21Name (Signature) [Signature]Company ER

REQUEST FOR EXTENSION

August 20, 2021

Victoria Venegas
New Mexico Oil Conservation Division
Artesia Office
811 South 1st Street
Artesia, NM 88210

Re: WLU 2309 24N Recycling Facility 3RF-29

Ms. Venegas:

Enduring Resources (OGRID 372286) respectfully requests a variance from the cessation of operation closure requirements in 19.15.31.13 NMAC for the WLU 2309 24N Recycling Facility 3RF-29 due to delays in approvals for upcoming work. Enduring will continue to maintain the recycling facility in a manner that ensures protection of fresh water, public health, and the environment.

Enduring Resources last recycled water out of the WLU 2309 Recycling Facility 3RF-29 pond on February 27, 2021. Enduring's current frac schedule does not allow for recycling operations at the WLU recycling facility until late September or early October 2021, therefore Enduring would like to request an extension on the cessation of operation. Enduring appreciates your flexibility and understanding in this matter.

Sincerely,



Deidre Duffy
Authorized Agent on behalf of Enduring Resources
WSP USA Inc.

ATTACHMENTS:

Form C-147
Weekly Inspection Records

Venegas, Victoria, EMNRD

From: Venegas, Victoria, EMNRD
Sent: Thursday, August 26, 2021 10:49 AM
To: Heather Huntington; David Rogers; Enviro, OCD, EMNRD
Cc: McQueen, Costin; Jones, Christopher; Suthiwan, Khem; Duffy, Deidre
Subject: 3RF-29 - WLU 2309 24N Recycling Facility – FACILITY ID fCS1828842180
Attachments: C-147 Extension approved. 3RF-29 - WLU 2309 24N – FACILITY ID fCS1828842180.pdf

3RF-29 - WLU 2309 24N Recycling Facility – FACILITY ID [fCS1828842180](#). Extension of the cessation of operations Approved.

Good morning Ms. Huntington,
 NMOC has reviewed the determination of cessation of operations extension request for **3RF-29 - WLU 2309 24N Recycling Facility – FACILITY ID [fCS1828842180](#)**, received from [\[372286\]](#) ENDURING RESOURCES, LLC on August 20, 2021. The cessation for operations extension request is approved with the following conditions of approval:

- 3RF-29 - WLU 2309 24N Recycling Facility – FACILITY ID [fCS1828842180](#) permit expiration date is October 14, 2023.
- The 3RF-29 - WLU 2309 24N Recycling Facility – FACILITY ID [fCS1828842180](#) extension of cessation of operations is approved from August 1, 2021 through January 31, 2022.
- [\[372286\]](#) ENDURING RESOURCES, LLC must recycle at least 53,077 bbl of produced water no later than January 31, 2022, to be considered in operations.
- [\[372286\]](#) ENDURING RESOURCES, LLC will maintain a liquid level in the containment that is at least equal to the weight of the liner plus 20%. [\[372286\]](#) ENDURING RESOURCES, LLC may maintain a higher liquid level if they choose.
- Any withdrawal of fluid from the containment will negate this determination of the cessation of operations extension. Once the extension is negated and no longer in effect, an incremental fluid level test will be required.
- [\[372286\]](#) ENDURING RESOURCES, LLC will provide written notice to the OCD via [OCD Online](#) at least 72 hours, but no more than one week, prior to the incremental fill test and the recommencement of operations. Recommencement of recycling operations means that the operator plans to resume moving fluids through the containment and discharging fluids from the containment. The incremental fill test and notice of the test must be completed before fluids can move through the containment.
 - At the resumption of recycling operations, Enduring Resources is required to perform an incremental fluid level test for containment liquid levels above the minimum liquid level.
 - Enduring Resources will fill the containment. Enduring Resources will pause filling operations at every 10% of total fluid capacity above the minimum level.
 - Enduring Resources will maintain the liquid level for each 10% volume increase for 24 hours and inspect and operation the leak detection system at the end of the 24-hour period.
 - If there are no liquids present in the leak detection system, Enduring Resources may proceed to fill the next 10% volume and repeat the process until the containment full design capacity minus the 3-feet of freeboard is reached.
 - If liquids are present, Enduring Resources should immediately cease the incremental fill test and perform a liner inspection. Enduring Resources should provide written notice of the fluid detection and liner inspection findings to [OCD Online](#) using a C-147 (long form) with the “Other” box checked and “Notice of fluid detection” written as the explanation of “Other.”
- Upon notification of fluid detection in the leak detection system, the OCD will verify the source of water (condensation versus produced water).

- If the detected fluid is confirmed to be condensation, the OCD will issue a written approval to proceed with the incremental fluid level test.
- If the detected fluid is confirmed to be produced water, Enduring Resources must comply with 19.15.34.13 NMAC. Enduring Resources must provide written notification via [OCD Online](#) on the actions taken to comply with 19.15.34.13 NMAC.
- After fluid is detected in the leak detection system, the incremental fill test cannot continue until after a written approval to proceed is issued by the OCD.
- Enduring Resources must submit copies of the detailed containment inspection records for the prior three (3) months and a report detailing the incremental fluid level test process and results to [OCD Online](#) using a C-147 (long form) with the "Other" box checked. "Recommendation of Operations - Incremental Fluid Level Test" should be written as the explanation of "Other." Form C-147 must be completed and include information in sections 1 General Information, 2 Recycling Facility, 3 Recycling Containment, 4 Bonding, and 10 Operator Application Certification. Section 9 Recycling Facility and/or Containment Checklist may also need to be partially completed. Operators should verify that the resumption of operations notification does not result in any changes to the recycling containment operating and maintenance plan or the closure plan. If the recommencement of operations will affect the operating and maintenance plan or closure plan, operators should check those boxes in section 9 and provide updated plans or plan addendums as attachments to the C-147.
- [\[372286\]](#) ENDURING RESOURCES, LLC will continue to operate, maintain, and close the 3RF-29 - WLU 2309 24N Recycling Facility – FACILITY ID [fCS1828842180](#) in compliance with 19.15.34 NMAC, to include but not limited to: detailed inspection records, removal of trash/oil from containment, and monthly C-148 reporting (even if there is zero activity).
- Water reuse and recycling from 3RF-29 - WLU 2309 24N Recycling Facility – FACILITY ID [fCS1828842180](#) is limited to wells owned or operated by Enduring Resources OGRID 372286.
- A minimum of 3-feet freeboard must always be maintained in the recycling containment during operations.
- [\[372286\]](#) ENDURING RESOURCES, LLC should notify the surface owner of the cessation of operations extension request by October 30, 2020.
- [\[372286\]](#) ENDURING RESOURCES, LLC may request a variance for an additional extension to the determination of cessation of operations, which will be reviewed on a case-by-case basis and evaluated on their merit. Extensions are considered for a maximum length of six months. Additional requests must be submitted to OCD via [OCD Online](#) on a Form C-147 (long form) as an Extension request and should include a variance request and summary per 19.15.34.16 NMAC and the detailed inspection records for the prior three (3) months. The extension request should be submitted no later than January 1, 2022.

Please let me know if you have any questions or concerns.

Regards,

Victoria Venegas • Environmental Specialist

Environmental Bureau

EMNRD - Oil Conservation Division

811S. First St. | Artesia, NM 88210

(575) 909-0269 | Victoria.Venegas@state.nm.us

<http://www.emnrd.state.nm.us/OCD/>



District I

1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 43542

CONDITIONS

Operator: ENDURING RESOURCES, LLC 6300 S Syracuse Way, Suite 525 Centennial, CO 80111	OGRID: 372286
	Action Number: 43542
	Action Type: [C-147] Water Recycle Long (C-147L)

CONDITIONS

Created By	Condition	Condition Date
vvenegas	NMOCD has reviewed and approved the determination of cessation of operations extension request for 3RF-29 - WLU 2309 24N Recycling Facility – FACILITY ID fCS1828842180, received from [372286] ENDURING RESOURCES, LLC on August 20, 2021. The cessation for operations extension request is approved with conditions.	8/26/2021