

**RF-11  
Salado Draw Section  
23 Recycling Facility  
and Containment-  
Facility ID  
[fTO1706148730]  
Annual Extension  
Approved**

**[4323] CHEVRON USA INC  
November 30, 2022**

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Department  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-147  
Revised March 31, 2015

## Recycling Facility and/or Recycling Containment

Type of Facility: ☒ Recycling Facility ☒ Recycling Containment\*  
Type of action: ☐ Permit ☐ Registration  
☐ Modification ☒ Extension  
☐ Closure ☒ Other (explain) Annual Extension request from

12/16/2022 to 12/16/2023 for 1RF-11

**\* At the time C-147 is submitted to the division for a Recycling Containment, a copy shall be provided to the surface owner.**

Be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances.

1.

Operator: Chevron U.S.A. Inc. (For multiple operators attach page with information) OGRID #: 4323  
Address: 1400 Smith Street, Houston TX 77002  
Facility or well name (include API# if associated with a well): Salado Draw T26S R32E Sections 13 and 23 Recycling Facility & Containment  
OCD Permit Number: 1RF-11 (For new facilities the permit number will be assigned by the district office)  
U/L or Qtr/Qtr A Section 23 Township 26 South Range 32 East County: Lea  
Surface Owner: ☒ Federal ☐ State ☐ Private ☐ Tribal Trust or Indian Allotment

2.

☒ **Recycling Facility:** (Location: U/L M, Section 13, T26S, R32E)  
Location of recycling facility (if applicable): Latitude 32.036234 Longitude -103.636212 NAD: ☐ 1927 ☒ 1983  
Proposed Use: ☐ Drilling\* ☒ Completion\* ☐ Production\* ☐ Plugging\*  
**\*The re-use of produced water may NOT be used until fresh water zones are cased and cemented**  
☐ Other, **requires permit for other uses. Describe use, process, testing, volume of produced water and ensure there will be no adverse impact on groundwater or surface water.**  
☒ Fluid Storage  
☒ Above ground tanks ☒ Recycling containment ☐ Activity permitted under 19.15.17 NMAC explain type \_\_\_\_\_  
☐ Activity permitted under 19.15.36 NMAC explain type: \_\_\_\_\_ ☐ Other explain \_\_\_\_\_  
☐ For multiple or additional recycling containments, attach design and location information of each containment  
☐ **Closure Report (required within 60 days of closure completion):** ☐ Recycling Facility Closure Completion Date: \_\_\_\_\_

3.

☒ **Recycling Containment:** (Location: U/L A, Section 23, T26S, R32E)  
☐ Annual Extension after initial 5 years (attach summary of monthly leak detection inspections for previous year)  
Center of Recycling Containment (if applicable): Latitude 32.033156 Longitude -103.639194 NAD: ☐ 1927 ☒ 1983  
☒ For multiple or additional recycling containments, attach design and location information of each containment  
☒ Lined ☒ Liner type: Thickness 60 mil ☐ LLDPE ☒ HDPE ☐ PVC ☐ Other \_\_\_\_\_  
☐ String-Reinforced  
Liner Seams: ☒ Welded ☐ Factory ☒ Other Field Volume: 698,060 bbl Dimensions: L 925' x W 700' x D 23'  
☐ Recycling Containment Closure Completion Date: \_\_\_\_\_

4.

**Bonding:**

- ☒ Covered under bonding pursuant to 19.15.8 NMAC per 19.15.34.15(A)(2) NMAC (These containments are limited to only the wells owned or operated by the owners of the containment.)
- ☐ Bonding in accordance with 19.15.34.15(A)(1). Amount of bond \$ \_\_\_\_\_ (work on these facilities cannot commence until bonding amounts are approved)
- ☐ Attach closure cost estimate and documentation on how the closure cost was calculated.

5.

**Fencing:**

- ☐ Four foot height, four strands of barbed wire evenly spaced between one and four feet
- ☒ Alternate. Please specify Eight foot chain link fence with three strands of barbed wire on top

6.

**Signs:**

- ☒ 12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers
- ☐ Signed in compliance with 19.15.16.8 NMAC

7.

**Variances:**

Justifications and/or demonstrations that the proposed variance will afford reasonable protection against contamination of fresh water, human health, and the environment.

**Check the below box only if a variance is requested:**

- ☒ Variance(s): Requests must be submitted to the appropriate division district for consideration of approval. If a Variance is requested, include the variance information on a separate page and attach it to the C-147 as part of the application.

**If a Variance is requested, it must be approved prior to implementation.**

8.

**Siting Criteria for Recycling Containment**

**Instructions:** The applicant must provide attachments that demonstrate compliance for each siting criteria below as part of the application. Potential examples of the siting attachment source material are provided below under each criteria.

**General siting****Ground water is less than 50 feet below the bottom of the Recycling Containment.**

NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells

☐ Yes ☒ No  
☐ NA

Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended.

☐ Yes ☒ No  
☐ NA

- Written confirmation or verification from the municipality; written approval obtained from the municipality

Within the area overlying a subsurface mine.

☐ Yes ☒ No

- Written confirmation or verification or map from the NM EMNRD-Mining and Minerals Division

Within an unstable area.

☐ Yes ☒ No

- Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; topographic map

Within a 100-year floodplain. FEMA map

☐ Yes ☒ No

Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark).

☐ Yes ☒ No

- Topographic map; visual inspection (certification) of the proposed site

Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application.

☐ Yes ☒ No

- Visual inspection (certification) of the proposed site; aerial photo; satellite image

Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application.

☐ Yes ☒ No

- NM Office of the State Engineer - iWATERS database search; visual inspection (certification) of the proposed site

Within 500 feet of a wetland.

☐ Yes ☒ No

- US Fish and Wildlife Wetland Identification map; topographic map; visual inspection (certification) of the proposed site

9.

**Recycling Facility and/or Containment Checklist:****Instructions:** Each of the following items must be attached to the application. Indicate, by a check mark in the box, that the documents are attached.

- ☒ Design Plan - based upon the appropriate requirements.  
☒ Operating and Maintenance Plan - based upon the appropriate requirements.  
☒ Closure Plan - based upon the appropriate requirements.  
☒ Site Specific Groundwater Data -  
☒ Siting Criteria Compliance Demonstrations –  
☒ Certify that notice of the C-147 (only) has been sent to the surface owner(s)

10.

**Operator Application Certification:**

I hereby certify that the information and attachments submitted with this application are true, accurate and complete to the best of my knowledge and belief.

Name (Print): Tony Vallejo Title: Sr. Workforce Safety & Environmental Specialist - Factory  
 Signature: Tony Vallejo Date: 11/17/2022  
 e-mail address: jvallejo@chevron.com Telephone: O: 432-687-7524 or C: 325-450-1413

11.

OCD Representative Signature: Victoria Venegas Approval Date: 11/30/2022  
 Title: Environmental Specialist OCD Permit Number: 1RF-11  
☒ OCD Conditions \_\_\_\_\_  
☒ Additional OCD Conditions on Attachment

Salado Draw (1RF-11) Section 23 North Weekly Inspections					
DATE (Week of)	BIRD DETERRENT ISSUES	FLUID IN LEAK DETECTION ISSUES	FENCE ISSUES	BERM OR LINER ISSUES	NOTES
11/1/2021					
11/8/2021					
11/15/2021					aeration being repaired
11/22/2021					aeration being repaired
11/29/2021					aeration being repaired
12/6/2021					
12/13/2021					
12/20/2021					
12/27/2021					
1/3/2022					
1/10/2022					
1/17/2022					
1/24/2022					
1/31/2022				liner being repaired above fluid level	
2/7/2022					
2/14/2022					
2/21/2022					
2/28/2022					
3/7/2022					
3/14/2022					
3/21/2022					
3/28/2022					
4/4/2022					
4/11/2022					
4/18/2022					
4/25/2022					
5/2/2022					
5/9/2022	bird deterrent being repaired				
5/16/2022	bird deterrent being repaired				
5/23/2022	bird deterrent being repaired				
5/30/2022	bird deterrent being repaired				
6/6/2022					skimming oil off surface
6/13/2022					
6/20/2022					
6/27/2022					
7/4/2022					
7/11/2022					
7/18/2022					
7/25/2022					
8/1/2022					
8/8/2022					
8/15/2022					
8/22/2022					
8/29/2022					
9/5/2022					
9/12/2022					
9/19/2022					
9/26/2022					
10/3/2022					
10/10/2022					
10/17/2022					
10/24/2022					
10/31/2022					
11/7/2022					

Salado Draw (1RF-11) Section 23 South Weekly Inspections					
DATE (Week of)	BIRD DETERRENT ISSUES	FLUID IN LEAK DETECTION ISSUES	FENCE ISSUES	BERM OR LINER ISSUES	NOTES
11/1/2021				see notes	pond empty, being re-lined
11/8/2021				see notes	pond empty, being re-lined
11/15/2021				see notes	pond empty, being re-lined
11/22/2021				see notes	pond empty, being re-lined
11/29/2021				see notes	pond empty, being re-lined
12/6/2021				see notes	pond empty, being re-lined
12/13/2021				see notes	pond empty, being re-lined
12/20/2021				see notes	pond empty, being re-lined
12/27/2021				see notes	pond empty, being re-lined
1/3/2022					liner repaired, aeration being repaired
1/10/2022					
1/17/2022					
1/24/2022					
1/31/2022					
2/7/2022					
2/14/2022					
2/21/2022					
2/28/2022			needs new lock		
3/7/2022					
3/14/2022					
3/21/2022					
3/28/2022					
4/4/2022					
4/11/2022					
4/18/2022					
4/25/2022	bird deterrent being repaired				
5/2/2022	bird deterrent being repaired				
5/9/2022	bird deterrent being repaired				
5/16/2022					
5/23/2022					
5/30/2022					
6/6/2022					
6/13/2022					
6/20/2022					
6/27/2022					
7/4/2022					
7/11/2022					
7/18/2022					
7/25/2022					
8/1/2022					
8/8/2022					
8/15/2022					
8/22/2022					
8/29/2022					
9/5/2022					
9/12/2022					
9/19/2022					
9/26/2022					
10/3/2022				see notes	tear found in liner above fluid level, draining pond to repair
10/10/2022				see notes	pond drained and being repaired
10/17/2022				see notes	pond drained and being repaired
10/24/2022				see notes	pond drained and being repaired
10/31/2022				see notes	pond drained and being repaired
11/7/2022				see notes	pond drained and being repaired

**Venegas, Victoria, EMNRD**

---

**From:** Vallejo, Tony <JVallejo@chevron.com>  
**Sent:** Wednesday, November 30, 2022 10:08 AM  
**To:** Venegas, Victoria, EMNRD  
**Cc:** Patrick, Tonny; Barnes, Calvin C  
**Subject:** RE: [EXTERNAL] RE: 1RF-11 Salado Draw Section 23 Recycling Facility and Containment Facility ID [fTO1706148730]  
**Attachments:** original liner repair.jpg; 2 small leak liner repair.jpg

Victoria,

The liner was repaired on 10/25/22. However, the sump area had accumulated water, so they drained the water and found 2 small leaks. Water team drained sump and repaired both liner leaks on 11/14/22 and added 3-4 ft of water to verify. No issues of liner leaks resulted after this repair. We have attached the pictures that verify all 3 liner repairs.

Apologies for missing the notification and extension request for this October 3<sup>rd</sup> liner repair issue. The reason for missing the notification and extension request was due to the transition of the Water team supervisor role, which is now Tonny Patrick. However, going forward, Calvin Barnes will be the Chevron rep that will be submitting the email notification and extension requests to OCD for future liner repairs.

Please advise what additional information you need from the Water team to satisfy or comply with the notification and extension request for the Oct. 3<sup>rd</sup> liner repair or is the date of the repair sufficient?

Thank you,  
**Tony Vallejo**

**Sr. Workforce Safety & Environmental Specialist - Factory**  
**Chevron USA Inc. (MCBU)**

6301 Deauville Blvd/N3210

Midland, Tx 79706

C: [325-450-1413](tel:325-450-1413)

[jvallejo@chevron.com](mailto:jvallejo@chevron.com)



**Safety is as simple as ABC - Always Be Careful**

---

**From:** Venegas, Victoria, EMNRD <Victoria.Venegas@emnrn.nm.gov>  
**Sent:** Tuesday, November 29, 2022 2:16 PM  
**To:** Vallejo, Tony <JVallejo@chevron.com>  
**Subject:** [\*\*EXTERNAL\*\*] RE: [EXTERNAL] RE: 1RF-11 Salado Draw Section 23 Recycling Facility and Containment Facility ID [fTO1706148730]

**Be aware this external email contains an attachment and/or link.**

Ensure the email and contents are expected. If there are concerns, please submit suspicious messages to the Cyber Intelligence Center using the Report Phishing button.

Sounds great, thank you!

**Victoria Venegas** • Environmental Specialist  
Environmental Bureau  
EMNRD - Oil Conservation Division

(575) 909-0269 | [Victoria.Venegas@emnrd.nm.gov](mailto:Victoria.Venegas@emnrd.nm.gov)

<https://www.emnrd.nm.gov/ocd/>



---

**From:** Vallejo, Tony <[JVallejo@chevron.com](mailto:JVallejo@chevron.com)>

**Sent:** Tuesday, November 29, 2022 1:13 PM

**To:** Venegas, Victoria, EMNRD <[Victoria.Venegas@emnrd.nm.gov](mailto:Victoria.Venegas@emnrd.nm.gov)>

**Subject:** RE: [EXTERNAL] RE: 1RF-11 Salado Draw Section 23 Recycling Facility and Containment Facility ID [fTO1706148730]

Victoria,

Thanks for the clarification, ma'am. Let me do some research with the water team and get back to you probably tomorrow.

Thank you,

**Tony Vallejo**

**Sr. Workforce Safety & Environmental Specialist - Factory**

**Chevron USA Inc. (MCBU)**

6301 Deauville Blvd/N3210

Midland, Tx 79706

C: [325-450-1413](tel:325-450-1413)

[jvallejo@chevron.com](mailto:jvallejo@chevron.com)



***Safety is as simple as ABC - Always Be Careful***

---

**From:** Venegas, Victoria, EMNRD <[Victoria.Venegas@emnrd.nm.gov](mailto:Victoria.Venegas@emnrd.nm.gov)>

**Sent:** Tuesday, November 29, 2022 2:08 PM

**To:** Vallejo, Tony <[JVallejo@chevron.com](mailto:JVallejo@chevron.com)>

**Subject:** [\*\*EXTERNAL\*\*] RE: [EXTERNAL] RE: 1RF-11 Salado Draw Section 23 Recycling Facility and Containment Facility ID [fTO1706148730]

**Be aware this external email contains an attachment and/or link.**

Ensure the email and contents are expected. If there are concerns, please submit suspicious messages to the Cyber Intelligence Center using the Report Phishing button.

**Application ID: 159557**

This is the part of the weekly inspection records that says "tear found in liner above fluid level".



9/19/2022					
9/26/2022					
10/3/2022				see notes	tear
10/10/2022				see notes	
10/17/2022				see notes	
10/24/2022				see notes	
10/31/2022				see notes	
11/7/2022				see notes	

**Victoria Venegas** • Environmental Specialist  
 Environmental Bureau  
 EMNRD - Oil Conservation Division  
 (575) 909-0269 | [Victoria.Venegas@emnrd.nm.gov](mailto:Victoria.Venegas@emnrd.nm.gov)  
<https://www.emnrd.nm.gov/ocd/>



**From:** Vallejo, Tony <[JVallejo@chevron.com](mailto:JVallejo@chevron.com)>  
**Sent:** Tuesday, November 29, 2022 12:29 PM  
**To:** Venegas, Victoria, EMNRD <[Victoria.Venegas@emnrd.nm.gov](mailto:Victoria.Venegas@emnrd.nm.gov)>  
**Subject:** [EXTERNAL] RE: 1RF-11 Salado Draw Section 23 Recycling Facility and Containment Facility ID [fTO1706148730]

CAUTION: This email originated outside of our organization. Exercise caution prior to clicking on links or opening attachments.

Victoria,  
 Is there a specific one you are referring to?

Thank you,  
**Tony Vallejo**

**Sr. Workforce Safety & Environmental Specialist - Factory**  
**Chevron USA Inc. (MCBU)**  
 6301 Deauville Blvd/N3210  
 Midland, Tx 79706  
 C: 325-450-1413  
[jvallejo@chevron.com](mailto:jvallejo@chevron.com)



**Safety is as simple as ABC - Always Be Careful**

**From:** Venegas, Victoria, EMNRD <[Victoria.Venegas@emnrd.nm.gov](mailto:Victoria.Venegas@emnrd.nm.gov)>  
**Sent:** Tuesday, November 29, 2022 12:52 PM

To: Vallejo, Tony <[JVallejo@chevron.com](mailto:JVallejo@chevron.com)>

Subject: [**\*\*EXTERNAL\*\***] 1RF-11 Salado Draw Section 23 Recycling Facility and Containment Facility ID [fTO1706148730]

**Be aware this external email contains an attachment and/or link.**

Ensure the email and contents are expected. If there are concerns, please submit suspicious messages to the Cyber Intelligence Center using the Report Phishing button.

**1RF-11 Salado Draw Section 23 Recycling Facility and Containment Facility ID [fTO1706148730]**

Good morning Mr. Vallejo,

The annual extension request includes weekly inspection records showing that the pond was drained to repair the liner. We don't have any notification of that, nor did we receive an extension request to repair the liner

Per 19.15.34.13.B(4) and (5):

(4) If the containment's primary liner is compromised above the fluid's surface, the operator shall repair the damage or initiate replacement of the primary liner within 48 hours of discovery or seek an extension of time from the division district office.

(5) If the primary liner is compromised below the fluid's surface, the operator shall remove all fluid above the damage or leak within 48 hours of discovery, notify the division district office and repair the damage or replace the primary liner

Could you please clarify the status of the liner?

Thank you for your cooperation.

Regards,

**Victoria Venegas** • Environmental Specialist

Environmental Bureau


EMNRD - Oil Conservation Division

(575) 909-0269 | [Victoria.Venegas@emnrd.nm.gov](mailto:Victoria.Venegas@emnrd.nm.gov)

<https://www.emnrd.nm.gov/oed/>



1RF-11: The liner was repaired on 10/25/22. However, the sump area had accumulated water, so they drained the water and found 2 small leaks. Water team drained sump and repaired both liner leaks on 11/14/22 and added 3-4 ft of water to verify. No issues of liner leaks resulted after this repair. We have attached the pictures that verify all 3 liner repairs.



**C-147 Extension request (Salado Draw NM 1RF-11)**

To Whom It May Concern:

Chevron MCBU respectfully submits the enclosed C-147 form, summary of monthly inspections, and leak detection for the Salado Draw T26S R32E Sections 13 and 23 Recycling Facility & Containment. For original site plans and submittals, please refer to the facility's original registration application, 1RF-11, received on 12/16/2016. In accordance with NMAC 19.15.34.10 RECYCLING CONTAINMENTS, Chevron MCBU is requesting a one-year extension.

- 19.15.34.10 (C) NMAC states: *"Registered recycling containments may be operated for five years from the date on which the registration is filed with the division. The operator may extend the allowed time on an annual basis thereafter with division approval if, 30 days prior to the registration expiration, the operator files a form C-147 with an attached summary showing all monthly inspections at the containment, including the monitoring of the leak detection system, showing the containment's integrity has not been compromised."*

Should you have any questions or require additional information, please contact me at your convenience.

**Thank you,  
Tony Vallejo**

**Sr. Workforce Safety & Environmental Specialist - Factory  
Chevron USA Inc. (MCBU)**

6301 Deauville Blvd/N3210

Midland, Tx 79706

O: [432-687-7524](tel:432-687-7524)

C: [325-450-1413](tel:325-450-1413)

[jvallejo@chevron.com](mailto:jvallejo@chevron.com)



***Safety is as simple as ABC - Always Be Careful***

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Department  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-147  
Revised March 31, 2015

## Recycling Facility and/or Recycling Containment

**Type of Facility:** ☒ Recycling Facility ☒ Recycling Containment\*  
**Type of action:** ☐ Permit ☐ Registration  
☐ Modification ☒ Extension  
☐ Closure ☒ Other (explain) Annual Extension request from

12/16/2022 to 12/16/2023 for 1RF-11

**\* At the time C-147 is submitted to the division for a Recycling Containment, a copy shall be provided to the surface owner.**

Be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances.

1.

Operator: Chevron U.S.A. Inc. (For multiple operators attach page with information) OGRID #: 4323  
Address: 1400 Smith Street, Houston TX 77002  
Facility or well name (include API# if associated with a well): Salado Draw T26S R32E Sections 13 and 23 Recycling Facility & Containment  
OCD Permit Number: 1RF-11 (For new facilities the permit number will be assigned by the district office)  
U/L or Qtr/Qtr A Section 23 Township 26 South Range 32 East County: Lea  
Surface Owner: ☒ Federal ☐ State ☐ Private ☐ Tribal Trust or Indian Allotment

2.

☒ **Recycling Facility:** (Location: U/L M, Section 13, T26S, R32E)  
Location of recycling facility (if applicable): Latitude 32.036234 Longitude -103.636212 NAD: ☐ 1927 ☒ 1983  
Proposed Use: ☐ Drilling\* ☒ Completion\* ☐ Production\* ☐ Plugging\*  
**\*The re-use of produced water may NOT be used until fresh water zones are cased and cemented**  
☐ Other, **requires permit for other uses. Describe use, process, testing, volume of produced water and ensure there will be no adverse impact on groundwater or surface water.**  
☒ Fluid Storage  
☒ Above ground tanks ☒ Recycling containment ☐ Activity permitted under 19.15.17 NMAC explain type \_\_\_\_\_  
☐ Activity permitted under 19.15.36 NMAC explain type: \_\_\_\_\_ ☐ Other explain \_\_\_\_\_  
☐ For multiple or additional recycling containments, attach design and location information of each containment  
☐ **Closure Report (required within 60 days of closure completion):** ☐ Recycling Facility Closure Completion Date: \_\_\_\_\_

3.

☒ **Recycling Containment:** (Location: U/L A, Section 23, T26S, R32E)  
☐ Annual Extension after initial 5 years (attach summary of monthly leak detection inspections for previous year)  
Center of Recycling Containment (if applicable): Latitude 32.033156 Longitude -103.639194 NAD: ☐ 1927 ☒ 1983  
☒ For multiple or additional recycling containments, attach design and location information of each containment  
☒ Lined ☒ Liner type: Thickness 60 mil ☐ LLDPE ☒ HDPE ☐ PVC ☐ Other \_\_\_\_\_  
☐ String-Reinforced  
Liner Seams: ☒ Welded ☐ Factory ☒ Other Field Volume: 698,060 bbl Dimensions: L 925' x W 700' x D 23'  
☐ Recycling Containment Closure Completion Date: \_\_\_\_\_



4.

**Bonding:**

- ☒ Covered under bonding pursuant to 19.15.8 NMAC per 19.15.34.15(A)(2) NMAC (These containments are limited to only the wells owned or operated by the owners of the containment.)
- ☐ Bonding in accordance with 19.15.34.15(A)(1). Amount of bond \$ \_\_\_\_\_ (work on these facilities cannot commence until bonding amounts are approved)
- ☐ Attach closure cost estimate and documentation on how the closure cost was calculated.

5.

**Fencing:**

- ☐ Four foot height, four strands of barbed wire evenly spaced between one and four feet
- ☒ Alternate. Please specify Eight foot chain link fence with three strands of barbed wire on top

6.

**Signs:**

- ☒ 12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers
- ☐ Signed in compliance with 19.15.16.8 NMAC

7.

**Variances:**

Justifications and/or demonstrations that the proposed variance will afford reasonable protection against contamination of fresh water, human health, and the environment.

***Check the below box only if a variance is requested:***

- ☒ Variance(s): Requests must be submitted to the appropriate division district for consideration of approval. If a Variance is requested, include the variance information on a separate page and attach it to the C-147 as part of the application.

**If a Variance is requested, it must be approved prior to implementation.**

8.

**Siting Criteria for Recycling Containment**

**Instructions:** The applicant must provide attachments that demonstrate compliance for each siting criteria below as part of the application. Potential examples of the siting attachment source material are provided below under each criteria.

**General siting****Ground water is less than 50 feet below the bottom of the Recycling Containment.**

NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells

☐ Yes ☒ No  
☐ NA

Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended.

☐ Yes ☒ No  
☐ NA

- Written confirmation or verification from the municipality; written approval obtained from the municipality

Within the area overlying a subsurface mine.

☐ Yes ☒ No

- Written confirmation or verification or map from the NM EMNRD-Mining and Minerals Division

Within an unstable area.

☐ Yes ☒ No

- Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; topographic map

Within a 100-year floodplain. FEMA map

☐ Yes ☒ No

Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark).

☐ Yes ☒ No

- Topographic map; visual inspection (certification) of the proposed site

Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application.

☐ Yes ☒ No

- Visual inspection (certification) of the proposed site; aerial photo; satellite image

Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application.

☐ Yes ☒ No

- NM Office of the State Engineer - iWATERS database search; visual inspection (certification) of the proposed site

Within 500 feet of a wetland.

☐ Yes ☒ No

- US Fish and Wildlife Wetland Identification map; topographic map; visual inspection (certification) of the proposed site

9.

**Recycling Facility and/or Containment Checklist:**

**Instructions:** Each of the following items must be attached to the application. Indicate, by a check mark in the box, that the documents are attached.

- ☒ Design Plan - based upon the appropriate requirements.
- ☒ Operating and Maintenance Plan - based upon the appropriate requirements.
- ☒ Closure Plan - based upon the appropriate requirements.
- ☒ Site Specific Groundwater Data -
- ☒ Siting Criteria Compliance Demonstrations –
- ☒ Certify that notice of the C-147 (only) has been sent to the surface owner(s)

10.

**Operator Application Certification:**

I hereby certify that the information and attachments submitted with this application are true, accurate and complete to the best of my knowledge and belief.

Name (Print): Tony Vallejo Title: Sr. Workforce Safety & Environmental Specialist - Factory  
Signature: Tony Vallejo Date: 11/17/2022  
e-mail address: jvallejo@chevron.com Telephone: O: 432-687-7524 or C: 325-450-1413

11.

**OCD Representative Signature:** \_\_\_\_\_ **Approval Date:** \_\_\_\_\_

**Title:** \_\_\_\_\_ **OCD Permit Number:** \_\_\_\_\_

- ☐ OCD Conditions \_\_\_\_\_
- ☐ Additional OCD Conditions on Attachment

Salado Draw (1RF-11) Section 23 North Weekly Inspections					
DATE (Week of)	BIRD DETERRENT ISSUES	FLUID IN LEAK DETECTION ISSUES	FENCE ISSUES	BERM OR LINER ISSUES	NOTES
11/1/2021					
11/8/2021					
11/15/2021					aeration being repaired
11/22/2021					aeration being repaired
11/29/2021					aeration being repaired
12/6/2021					
12/13/2021					
12/20/2021					
12/27/2021					
1/3/2022					
1/10/2022					
1/17/2022					
1/24/2022					
1/31/2022				liner being repaired above fluid level	
2/7/2022					
2/14/2022					
2/21/2022					
2/28/2022					
3/7/2022					
3/14/2022					
3/21/2022					
3/28/2022					
4/4/2022					
4/11/2022					
4/18/2022					
4/25/2022					
5/2/2022					
5/9/2022	bird deterrent being repaired				
5/16/2022	bird deterrent being repaired				
5/23/2022	bird deterrent being repaired				
5/30/2022	bird deterrent being repaired				
6/6/2022					skimming oil off surface
6/13/2022					
6/20/2022					
6/27/2022					
7/4/2022					
7/11/2022					
7/18/2022					
7/25/2022					
8/1/2022					
8/8/2022					
8/15/2022					
8/22/2022					
8/29/2022					
9/5/2022					
9/12/2022					
9/19/2022					
9/26/2022					
10/3/2022					
10/10/2022					
10/17/2022					
10/24/2022					
10/31/2022					
11/7/2022					



Salado Draw (1RF-11) Section 23 South Weekly Inspections					
DATE (Week of)	BIRD DETERRENT ISSUES	FLUID IN LEAK DETECTION ISSUES	FENCE ISSUES	BERM OR LINER ISSUES	NOTES
11/1/2021				see notes	pond empty, being re-lined
11/8/2021				see notes	pond empty, being re-lined
11/15/2021				see notes	pond empty, being re-lined
11/22/2021				see notes	pond empty, being re-lined
11/29/2021				see notes	pond empty, being re-lined
12/6/2021				see notes	pond empty, being re-lined
12/13/2021				see notes	pond empty, being re-lined
12/20/2021				see notes	pond empty, being re-lined
12/27/2021				see notes	pond empty, being re-lined
1/3/2022					liner repaired, aeration being repaired
1/10/2022					
1/17/2022					
1/24/2022					
1/31/2022					
2/7/2022					
2/14/2022					
2/21/2022					
2/28/2022			needs new lock		
3/7/2022					
3/14/2022					
3/21/2022					
3/28/2022					
4/4/2022					
4/11/2022					
4/18/2022					
4/25/2022	bird deterrent being repaired				
5/2/2022	bird deterrent being repaired				
5/9/2022	bird deterrent being repaired				
5/16/2022					
5/23/2022					
5/30/2022					
6/6/2022					
6/13/2022					
6/20/2022					
6/27/2022					
7/4/2022					
7/11/2022					
7/18/2022					
7/25/2022					
8/1/2022					
8/8/2022					
8/15/2022					
8/22/2022					
8/29/2022					
9/5/2022					
9/12/2022					
9/19/2022					
9/26/2022					
10/3/2022				see notes	tear found in liner above fluid level, draining pond to repair
10/10/2022				see notes	pond drained and being repaired
10/17/2022				see notes	pond drained and being repaired
10/24/2022				see notes	pond drained and being repaired
10/31/2022				see notes	pond drained and being repaired
11/7/2022				see notes	pond drained and being repaired

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS  
  
Action 159557

CONDITIONS

Operator:  CHEVRON U S A INC 6301 Deauville Blvd Midland, TX 79706	OGRID:  4323
	Action Number:  159557
	Action Type:  [C-147] Water Recycle Long (C-147L)

CONDITIONS

Created By	Condition	Condition Date
vvenegas	NMOCD has reviewed and approved the permit annual extension request for RF-11 Salado Draw Section 23 Recycling Facility and Containment-Facility ID [FTO1706148730], received from [4323] CHEVRON USA INC on November 17, 2022.	11/30/2022