

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Department
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-147
Revised April 3, 2017

Recycling Facility and/or Recycling Containment

Type of Facility: ☒ Recycling Facility ☒ Recycling Containment*
Type of action: ☐ Permit ☐ Registration
☐ Modification ☒ Extension
☐ Closure ☐ Other (explain)

* At the time C-147 is submitted to the division for a Recycling Containment, a copy shall be provided to the surface owner.

Be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances.

1.
Operator: Enduring Resources IV, LLC (For multiple operators attach page with information) OGRID #: 372286
Address: 200 Energy Court, Farmington, New Mexico 87401
Facility or well name (include API# if associated with a well): SEU 2206-20M Water Recycle Facility / Containment
OCD Permit Number: #3RF-30 (For new facilities the permit number will be assigned by the district office)
U/L or Qtr/Qtr SE/4 SE/4 Section 20 Township 22N Range 6W County: Sandoval
Surface Owner: ☒ Federal ☐ State ☐ Private ☐ Tribal Trust or Indian Allotment

2.
☒ **Recycling Facility:**
Location of recycling facility (if applicable): Latitude 36.117776 Longitude -107.488825 NAD83
Proposed Use: ☒ Drilling* ☒ Completion* ☒ Production* ☒ Plugging *
**The re-use of produced water may NOT be used until fresh water zones are cased and cemented*
☐ Other, requires permit for other uses. Describe use, process, testing, volume of produced water and ensure there will be no adverse impact on groundwater or surface water.
☒ Fluid Storage
☒ Above ground tanks ☒ Recycling containment ☐ Activity permitted under 19.15.17 NMAC explain type _____
☐ Activity permitted under 19.15.36 NMAC explain type: _____ ☐ Other explain _____
☐ For multiple or additional recycling containments, attach design and location information of each containment
☐ Closure Report (required within 60 days of closure completion): ☐ Recycling Facility Closure Completion Date: _____

3.
☒ **Recycling Containment:**
☒ Annual Extension after initial 5 years (attach summary of monthly leak detection inspections for previous year)
Center of Recycling Containment (if applicable): Latitude 36.117776 Longitude -107.488825 NAD83
☒ For multiple or additional recycling containments, attach design and location information of each containment
☒ Lined ☐ Liner type: Thickness 45 mil ☒ LLDPE ☐ HDPE ☐ PVC ☐ Other _____
☒ String-Reinforced
Liner Seams: ☒ Welded ☒ Factory ☐ Other _____ Volume: 212,746 bbl Dimensions: L 362' x W 350' x D 25'
☐ Recycling Containment Closure Completion Date: _____

4.

Bonding:

- ☒ Covered under bonding pursuant to 19.15.8 NMAC per 19.15.34.15(A)(2) NMAC (These containments are limited to only the wells owned or operated by the owners of the containment.)
- ☐ Bonding in accordance with 19.15.34.15(A)(1). Amount of bond \$ _____ (work on these facilities cannot commence until bonding amounts are approved)
- ☐ Attach closure cost estimate and documentation on how the closure cost was calculated.

5.

Fencing:

- ☐ Four foot height, four strands of barbed wire evenly spaced between one and four feet
- ☒ Alternate. Please specify 8 foot chain link fence

6.

Signs:

- ☒ 12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers
- ☐ Signed in compliance with 19.15.16.8 NMAC

7.

Variances:

Justifications and/or demonstrations that the proposed variance will afford reasonable protection against contamination of fresh water, human health, and the environment.

Check the below box only if a variance is requested:

- ☐ Variance(s): Requests must be submitted to the appropriate division district for consideration of approval. If a Variance is requested, include the variance information on a separate page and attach it to the C-147 as part of the application.
- If a Variance is requested, it must be approved prior to implementation.**

8.

Siting Criteria for Recycling Containment

Instructions: The applicant must provide attachments that demonstrate compliance for each siting criteria below as part of the application. Potential examples of the siting attachment source material are provided below under each criteria.

General siting**Ground water is less than 50 feet below the bottom of the Recycling Containment.**

NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells

☐ Yes ☒ No
☐ NA

Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended.

☐ Yes ☒ No
☐ NA

- Written confirmation or verification from the municipality; written approval obtained from the municipality

Within the area overlying a subsurface mine.

☐ Yes ☒ No

- Written confirmation or verification or map from the NM EMNRD-Mining and Minerals Division

Within an unstable area.

☐ Yes ☒ No

- Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; topographic map

Within a 100-year floodplain. FEMA map

☐ Yes ☒ No

Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark).

☐ Yes ☒ No

- Topographic map; visual inspection (certification) of the proposed site

Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application.

☐ Yes ☒ No

- Visual inspection (certification) of the proposed site; aerial photo; satellite image

Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application.

☐ Yes ☒ No

- NM Office of the State Engineer - iWATERS database search; visual inspection (certification) of the proposed site

Within 500 feet of a wetland.

☐ Yes ☒ No

- US Fish and Wildlife Wetland Identification map; topographic map; visual inspection (certification) of the proposed site

9.

Recycling Facility and/or Containment Checklist:

Instructions: Each of the following items must be attached to the application. Indicate, by a check mark in the box, that the documents are attached.

- ☐ Design Plan - based upon the appropriate requirements.
- ☐ Operating and Maintenance Plan - based upon the appropriate requirements.
- ☐ Closure Plan - based upon the appropriate requirements.
- ☐ Site Specific Groundwater Data -
- ☐ Siting Criteria Compliance Demonstrations -
- ☒ Certify that notice of the C-147 (only) has been sent to the surface owner(s)

10.

Operator Application Certification:

I hereby certify that the information and attachments submitted with this application are true, accurate and complete to the best of my knowledge and belief.

Name (Print): Heather Huntington Title: Permitting Technician

Signature:  Date: 8/9/2023

e-mail address: hhuntington@enduringresources.com Telephone: (970) 749-0124

11.

OCD Representative Signature: Victoria Venegas Approval Date: 08/24/2023

Title: Environmental Specialist OCD Permit Number: 1RF-30

- ☒ OCD Conditions
- ☒ Additional OCD Conditions on Attachment



Enduring Resources IV, LLC

200 Energy Court Farmington, NM 87401
Field Office: 505.636.9720 | Main Office: 303.573.1222

Enduring Resources, LLC
SEU 2206 20M – 3RF-30
Recycling Facility/Containment
Permit Extension Request for 19.15.34
NMAC

New Mexico Oil Conservation Division
Attn: Victoria Venegas

Enduring Resources is requesting a permit extension for the SEU 2206 20M (RF-30) Water Recycling Facility. In accordance with 19.15.34.10.C NMAC, *"Registered recycling containments may be operated for five years from the date on which the registration is filed with the division. The operator may extend the allowed time on an annual basis thereafter with division approval if, 30 days prior to the registration expiration, the operator files a form C-147 with an attached summary showing all monthly inspections at the containment, including the monitoring of the leak detection system, showing the containment's integrity has not been compromised."*

The original facility permit was approved on October 18, 2018. The five year approval period ends on October 18, 2023. Enduring is requesting an extension through October 18, 2024. At that time Enduring will determine if additional annual extensions will be filed. Enduring has included records for the last 5 years of inspections at this facility. There have been no indications that the leak detection system's integrity is compromised. Enduring will continue to operate the facility per regulations in 19.15.34 NMAC.

Thank you,

Heather Huntington
Permitting Technician
Enduring Resources, LLC.
hhuntington@enduringresources.com

Venegas, Victoria, EMNRD

From: Venegas, Victoria, EMNRD
Sent: Thursday, August 24, 2023 11:12 AM
To: Heather Huntington; Kayla White
Subject: 3RF-30 - SEU 2206 - 20M FACILITY ID [FVF1828850052]
Attachments: C-147 3RF-30 - SEU 2206 - 20M FACILITY ID [FVF1828850052] 08.24.2023.pdf

3RF-30 - SEU 2206 - 20M FACILITY ID [FVF1828850052]

Ms. Huntington,

NMOCD has reviewed the determination of registration/permit extension request for 3RF-30 - SEU 2206 - 20M FACILITY ID [FVF1828850052] received from [372286] ENDURING RESOURCES, LLC on 08/09/ 2023, Application ID 250354. The registration/permit extension request is approved with the following conditions of approval:

- 3RF-30 - SEU 2206 - 20M FACILITY ID [FVF1828850052] is approved for one (1) year of operation from the date of the previous registration/permit expiration date of October 18, 2023. The new registration/permit expiration date is October 18, 2024.
- [372286] ENDURING RESOURCES, LLC will continue to operate, maintain, and close the 3RF-30 - SEU 2206 - 20M FACILITY ID [FVF1828850052] in compliance with 19.15.34 NMAC, to include but not limited to the performance of weekly inspections regardless of fluid levels in the containment; recording of detailed inspection reports; removal of debris, foreign objects and oil from the containment; and monthly reporting of recycling and reuse of produced water, drilling fluids, and liquid oil field waste via from C-148.
- If less than 20% of the total fluid capacity is utilized every consecutive six months, operations of the facility are considered ceased and the notification of cessation of operations should be sent electronically to [OCD Online](#). An extension to extend the cessation of operations, not to exceed six months, may be submitted using a C-147 form through the [OCD Online](#) system.
- However, if after this 6-month period, the containment was not utilized at a minimum of 20% fluid capacity, no additional extensions would be granted, and the operator would be directed to remove all fluids and proceed with the closure requirements.
- The recycling containment is bonded pursuant to 19.15.8 NMAC per 19.15.34.15(A)(2) NMAC. Water reuse and recycling from 3RF-30 - SEU 2206 - 20M FACILITY ID [FVF1828850052] is limited to wells owned or operated by [372286] ENDURING RESOURCES, LLC.
- A minimum of 3-feet freeboard must be maintained in the recycling containment at all times.
- [372286] ENDURING RESOURCES, LLC will comply with 19.15.29 NMAC Releases in the event of any release of produced water or other oil field wastes 3RF-30 - SEU 2206 - 20M FACILITY ID [FVF1828850052]. [372286] ENDURING RESOURCES, LLC will comply with all other OCD rules.
- [372286] ENDURING RESOURCES, LLC must perform weekly inspections of the containment and leak detection system.
- If [372286] ENDURING RESOURCES, LLC wishes to extend the registration/permit past October 18, 2024, a registration/permit extension request must be submitted to OCD. Extension requests are reviewed on a case-by-case basis and evaluated on their merit. Extensions are considered for a maximum length of one year. Additional requests must be submitted to OCD through the [OCD Online](#) on a Form C-147 (long form) as an Extension request and should include a formal extension request letter, a summary of the prior registration/permit period inspection reports, and the copies of the detailed inspection records for the prior permit period (2023-2024). The extension request should be submitted no later than September 18, 2024.
- **PLEASE NOTE:** 3RF-30 - SEU 2206 - 20M FACILITY ID [FVF1828850052] has an extension of cessation of operations approved from September 1/2023 to March 1/2024. However, if after this 6-month period, the containment was not utilized at a minimum of 20% fluid capacity, no additional extensions would be granted,

this annual extension will be revoked, and the operator would be directed to remove all fluids and proceed with the closure requirements.

Please let me know if you have any further questions or concerns.
Regards,

Victoria Venegas • Environmental Specialist
Environmental Bureau
EMNRD - Oil Conservation Division
506 W. Texas Ave. Artesia, NM 88210
(575) 909-0269 | Victoria.Venegas@emnrd.nm.gov
<https://www.emnrd.nm.gov/oed/>



From: [Kayla White](#)
To: [Tafoya, Jeff](#); [Smith, Gary](#)
Cc: [Heather Huntington](#); [Theresa Ancell](#)
Subject: Enduring Resources SEU 2206-20M Notice of Permit Extension
Date: Wednesday, August 9, 2023 5:34:00 PM

Good afternoon Mr. Tafoya,

Enduring Resources is requesting an extension of the operating permit from NMOCD for the SEU 2206 20M Water Recycling Facility. In accordance with 19.15.34.10.a NMAC, Enduring Resources is required to notify the surface owner of the request, which in this case is BLM. Please consider this email as surface owner notification of this extension request. The requested extension is in accordance with 19.15.34.10.C NMAC, *"Registered recycling containments may be operated for five years from the date on which the registration is filed with the division. The operator may extend the allowed time on an annual basis thereafter with division approval if, 30 days prior to the registration expiration, the operator files a form C-147 with an attached summary showing all monthly inspections at the containment, including the monitoring of the leak detection system, showing the containment's integrity has not been compromised."*

The original facility permit was approved on October 18, 2018. The five year approval periods ends on October 18, 2023. Enduring is requesting an extension through October 18, 2024. At that time Enduring will determine if additional annual extensions will be filed. There have been no indications that the leak detection system integrity is compromised. Enduring will continue to operate the facility per regulations in 19.15.34 NMAC.

This email is the surface owner notification of this permit extension request.

Please let us know if you have any questions.

Thank you,

Kayla White, P.E.
CDH Consulting, LLC
720-768-3575
kwhite@CDHConsult.com


www.CDHConsult.com



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Recycling Containment: SEU 2206 20M Permit Number: 3RF-30
 Qtr./Qtr. Or Lot: _____ Section: _____ Township: _____ Range: _____
 Date of Inspection: 5-21-19 Inspector: James Martinez
 Time arrived on location: 9:30 Time left location: 9:44
 General Comments: _____

General Site Condition	Yes	No ¹	N/A	Comments
Containment currently contains fluids		X		
Fencing is in good condition and functional	X			
Gates are closed and locked ²	X			
Signage visible & compliant	X			
No signs of surface water run on		X		
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
² only applicable if site is unattended by authorized personnel.				
Corrective Action	Personnel		Date	

Containment Compliance	Yes	No ¹	N/A	Comments
Containment is free of any visible layer of oil sheen			X	
Containment has at least three feet of freeboard			X	
Injection or withdrawal of fluids to/from containment is accomplished through a header, diverter or other hardware			X	
Oil absorbent booms or other device onsite, in good condition, and available for use for unanticipated release			X	
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action	Personnel		Date	

Page ___ of ___

Date Checked: _____

Checked by: _____



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Leak Detection System	Yes	No ¹	N/A	Comments
Site is free from evidence of leaks, spills or releases	X			
Liner above waterline shows no evidence of damage	X			
Leak detection system was checked and shows no sign of leak via fluid present	X			
If fluid is present in leak detection system, it was removed and volume recorded			X	UPPER: Pond vertical depth (ft): _____ Leak detection diagonal depth (ft): _____ Pump run time (hours): _____ Volume removed (gallons): _____ LOWER: Pond vertical depth (ft): _____ Leak detection diagonal depth (ft): _____ Pump run time (hours): _____ Volume removed (gallons): _____
Fluid was not present within leak detection two consecutive days in a row	X			
If fluid is present two consecutive days in a row, it has to be reported to HSE & Regulatory	X			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action	Personnel			Date

Page ___ of ___

Date Checked: _____

Checked by: _____



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Wildlife/Bird Deterrent System	Yes	No ¹	N/A	Comments
Audio deterrent system in working order and operating		X		Not hooked up yet
All visual deterrents in good working order and operating	X			
Any repairs or replacements of deterrents from previous inspections have been completed ²			X	
Entire location (perimeter and interior) was walked and inspected for evidence of bird/wildlife mortality or injury	X			
If evidence of bird/wildlife mortality or injury is identified it was immediately reported to HSE & Regulatory	X			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below. ² Note personnel that completed work and date completed in the Corrective Action section below.				
Corrective Action				Personnel
				Date

Page ___ of ___

Date Checked: _____

Checked by: _____



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Recycling Containment: SEU 2206 20 m Permit Number: 32F-30

Qtr./Qtr. Or Lot: _____ Section: _____ Township: _____ Range: _____

Date of Inspection: 5-24-19 Inspector: James Martinez

Time arrived on location: 11:19 Time left location: 11:33

General Comments:

General Site Condition	Yes	No ¹	N/A	Comments
Containment currently contains fluids		X		
Fencing is in good condition and functional	X			
Gates are closed and locked ²	X			
Signage visible & compliant	X			
No signs of surface water run on	X			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
² only applicable if site is unattended by authorized personnel.				
Corrective Action	Personnel		Date	

Containment Compliance	Yes	No ¹	N/A	Comments
Containment is free of any visible layer of oil sheen	X		X	
Containment has at least three feet of freeboard			X	
Injection or withdrawal of fluids to/from containment is accomplished through a header, diverter or other hardware			X	
Oil absorbent booms or other device onsite, in good condition, and available for use for unanticipated release	X			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action	Personnel		Date	

Page ____ of ____

Date Checked: _____

Checked by: _____



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Leak Detection System	Yes	No ¹	N/A	Comments
Site is free from evidence of leaks, spills or releases	X			
Liner above waterline shows no evidence of damage			X	
Leak detection system was checked and shows no sign of leak via fluid present			X	
If fluid is present in leak detection system, it was removed and volume recorded				UPPER: Pond vertical depth (ft): _____ Leak detection diagonal depth (ft): _____ Pump run time (hours): _____ Volume removed (gallons): _____ LOWER: Pond vertical depth (ft): _____ Leak detection diagonal depth (ft): _____ Pump run time (hours): _____ Volume removed (gallons): _____
Fluid was not present within leak detection two consecutive days in a row	X			
If fluid is present two consecutive days in a row, it has to be reported to HSE & Regulatory	X			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action	Personnel		Date	



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Wildlife/Bird Deterrent System	Yes	No ¹	N/A	Comments
Audio deterrent system in working order and operating		X		not hooked up.
All visual deterrents in good working order and operating	X			
Any repairs or replacements of deterrents from previous inspections have been completed ²			X	
Entire location (perimeter and interior) was walked and inspected for evidence of bird/wildlife mortality or injury	X			
If evidence of bird/wildlife mortality or injury is identified it was immediately reported to HSE & Regulatory	X			
¹ For any category above checked "No", a corresponding Corrective Action must be filled out below.				
² Note personnel that completed work and date completed in the Corrective Action section below.				
Corrective Action				Personnel
				Date

Page ___ of ___

Date Checked: _____

Checked by: _____



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Recycling Containment: SEU 2206 20M Permit Number: 3RF-30

Qtr./Qtr. Or Lot: _____ Section: _____ Township: _____ Range: _____

Date of Inspection: 8-26-19 Inspector: James Martinez

Time arrived on location: 9:01 Time left location: 9:27

General Comments:

General Site Condition	Yes	No ¹	N/A	Comments
Containment currently contains fluids		X		
Fencing is in good condition and functional	X			
Gates are closed and locked ²		X		
Signage visible & compliant	X			
No signs of surface water run on	X			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
² only applicable if site is unattended by authorized personnel.				
Corrective Action	Personnel		Date	

Containment Compliance	Yes	No ¹	N/A	Comments
Containment is free of any visible layer of oil sheen			X	
Containment has at least three feet of freeboard			X	
Injection or withdrawal of fluids to/from containment is accomplished through a header, diverter or other hardware			X	
Oil absorbent booms or other device onsite, in good condition, and available for use for unanticipated release	X			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action	Personnel		Date	

Page ___ of ___

Date Checked: _____

Checked by: _____



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Leak Detection System	Yes	No ¹	N/A	Comments
Site is free from evidence of leaks, spills or releases	X			
Liner above waterline shows no evidence of damage	X			
Leak detection system was checked and shows no sign of leak via fluid present	X			
If fluid is present in leak detection system, it was removed and volume recorded				UPPER: Pond vertical depth (ft): _____ Leak detection diagonal depth (ft): _____ Pump run time (hours): _____ Volume removed (gallons): _____ LOWER: Pond vertical depth (ft): _____ Leak detection diagonal depth (ft): _____ Pump run time (hours): _____ Volume removed (gallons): _____
Fluid was not present within leak detection two consecutive days in a row	X			
If fluid is present two consecutive days in a row, it has to be reported to HSE & Regulatory	X			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below				
Corrective Action	Personnel		Date	

Page ____ of ____

Date Checked: _____

Checked by: _____



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Wildlife/Bird Deterrent System	Yes	No ¹	N/A	Comments
Audio deterrent system in working order and operating	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>		
All visual deterrents in good working order and operating	<input checked="" type="checkbox"/>			
Any repairs or replacements of deterrents from previous inspections have been completed ²			<input checked="" type="checkbox"/>	
Entire location (perimeter and interior) was walked and inspected for evidence of bird/wildlife mortality or injury	<input checked="" type="checkbox"/>			
If evidence of bird/wildlife mortality or injury is identified it was immediately reported to HSE & Regulatory	<input checked="" type="checkbox"/>			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
² Note personnel that completed work and date completed in the Corrective Action section below.				
Corrective Action				Personnel
				Date

Page ___ of ___

Date Checked: _____

Checked by: _____



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Recycling Containment: SEU 2206 - 20M. Permit Number: _____
 Qtr./Qtr. Or Lot: _____ Section: 20 Township: 22W Range: 9W
 Date of Inspection: 7-16-19 Inspector: James Martinez
 Time arrived on location: 9:00 Time left location: 9:21
 General Comments:

General Site Condition	Yes	No ¹	N/A	Comments
Containment currently contains fluids		<input checked="" type="checkbox"/>		
Fencing is in good condition and functional	<input checked="" type="checkbox"/>			
Gates are closed and locked ²	<input checked="" type="checkbox"/>			
Signage visible & compliant	<input checked="" type="checkbox"/>			
No signs of surface water run on	<input checked="" type="checkbox"/>			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
² only applicable if site is unattended by authorized personnel				
Corrective Action	Personnel		Date	

Containment Compliance	Yes	No ¹	N/A	Comments
Containment is free of any visible layer of oil sheen			<input checked="" type="checkbox"/>	
Containment has at least three feet of freeboard			<input checked="" type="checkbox"/>	
Injection or withdrawal of fluids to/from containment is accomplished through a header, diverter or other hardware			<input checked="" type="checkbox"/>	
Oil absorbent booms or other device onsite, in good condition, and available for use for unanticipated release			<input checked="" type="checkbox"/>	
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action	Personnel		Date	

Page ___ of ___

Date Checked: _____

Checked by: _____



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Leak Detection System	Yes	No ¹	N/A	Comments
Site is free from evidence of leaks, spills or releases	X			
Liner above waterline shows no evidence of damage			X	
Leak detection system was checked and shows no sign of leak via fluid present			X	
If fluid is present in leak detection system, it was removed and volume recorded			X	UPPER: Pond vertical depth (ft): _____ Leak detection diagonal depth (ft): _____ Pump run time (hours): _____ Volume removed (gallons): _____ LOWER: Pond vertical depth (ft): _____ Leak detection diagonal depth (ft): _____ Pump run time (hours): _____ Volume removed (gallons): _____
Fluid was not present within leak detection two consecutive days in a row	X		X	
If fluid is present two consecutive days in a row, it has to be reported to HSE & Regulatory			X	
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action	Personnel		Date	

Page ___ of ___

Date Checked: _____

Checked by: _____



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Wildlife/Bird Deterrent System	Yes	No ¹	N/A	Comments
Audio deterrent system in working order and operating			✓	
All visual deterrents in good working order and operating	✓			
Any repairs or replacements of deterrents from previous inspections have been completed ²			✓	
Entire location (perimeter and interior) was walked and inspected for evidence of bird/wildlife mortality or injury	✓	✓		
If evidence of bird/wildlife mortality or injury is identified it was immediately reported to HSE & Regulatory	✓			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
² Note personnel that completed work and date completed in the Corrective Action section below.				
Corrective Action				Personnel
				Date

Page ____ of ____

Date Checked: _____

Checked by: _____



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Recycling Containment: SEU 2206-20m Permit Number: _____

Qtr./Qtr. Or Lot: _____ Section: 20 Township: 22N Range: 6W

Date of Inspection: 7-19-19 Inspector: James Martinez

Time arrived on location: 8:00 Time left location: 8:19

General Comments:

No water in Pond.

General Site Condition	Yes	No ¹	N/A	Comments
Containment currently contains fluids		X		
Fencing is in good condition and functional	X			
Gates are closed and locked ²	X			
Signage visible & compliant	X			
No signs of surface water run on	X			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
² only applicable if site is unattended by authorized personnel.				
Corrective Action	Personnel		Date	

Containment Compliance	Yes	No ¹	N/A	Comments
Containment is free of any visible layer of oil sheen			X	
Containment has at least three feet of freeboard			X	
Injection or withdrawal of fluids to/from containment is accomplished through a header, diverter or other hardware			X	
Oil absorbent booms or other device onsite, in good condition, and available for use for unanticipated release			X	
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action	Personnel		Date	

Page ____ of ____

Date Checked: _____

Checked by: _____



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Leak Detection System	Yes	No ¹	N/A	Comments
Site is free from evidence of leaks, spills or releases	X			
Liner above waterline shows no evidence of damage			X	
Leak detection system was checked and shows no sign of leak via fluid present			X	
If fluid is present in leak detection system, it was removed and volume recorded			X	UPPER: Pond vertical depth (ft): _____ Leak detection diagonal depth (ft): _____ Pump run time (hours): _____ Volume removed (gallons): _____ LOWER: Pond vertical depth (ft): _____ Leak detection diagonal depth (ft): _____ Pump run time (hours): _____ Volume removed (gallons): _____
Fluid was not present within leak detection two consecutive days in a row			X	
If fluid is present two consecutive days in a row, it has to be reported to HSE & Regulatory			X	
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below				
Corrective Action				Personnel
				Date

Page ____ of ____

Date Checked: _____

Checked by: _____



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Wildlife/Bird Deterrent System	Yes	No ¹	N/A	Comments
Audio deterrent system in working order and operating			X	
All visual deterrents in good working order and operating	X			
Any repairs or replacements of deterrents from previous inspections have been completed ²			X	
Entire location (perimeter and interior) was walked and inspected for evidence of bird/wildlife mortality or injury	X			
If evidence of bird/wildlife mortality or injury is identified it was immediately reported to HSE & Regulatory	X			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below. ² Note personnel that completed work and date completed in the Corrective Action section below.				
Corrective Action				Personnel
				Date

Page ____ of ____

Date Checked: _____

Checked by: _____



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Recycling Containment: SEU 2206 20M Permit Number: 3RF-30
 Qtr./Qtr. Or Lot: _____ Section: _____ Township: _____ Range: _____
 Date of Inspection: 6-7-19 Inspector: James Martinez
 Time arrived on location: 10:20 Time left location: 11:50
 General Comments: _____

General Site Condition	Yes	No ¹	N/A	Comments
Containment currently contains fluids		X		
Fencing is in good condition and functional	X			
Gates are closed and locked ²	X			
Signage visible & compliant	X			
No signs of surface water run on	X			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
² only applicable if site is unattended by authorized personnel.				
Corrective Action				
				Personnel
				Date

Containment Compliance	Yes	No ¹	N/A	Comments
Containment is free of any visible layer of oil sheen	X			
Containment has at least three feet of freeboard	X			
Injection or withdrawal of fluids to/from containment is accomplished through a header, diverter or other hardware	X			
Oil absorbent booms or other device onsite, in good condition, and available for use for unanticipated release		X		Need to Get Boom and Containment
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action				
				Personnel
				Date

Page ___ of ___

Date Checked: _____

Checked by: _____



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Leak Detection System	Yes	No ¹	N/A	Comments
Site is free from evidence of leaks, spills or releases	X			
Liner above waterline shows no evidence of damage	X			
Leak detection system was checked and shows no sign of leak via fluid present	X			
If fluid is present in leak detection system, it was removed and volume recorded				UPPER: Pond vertical depth (ft): <u>0</u> Leak detection diagonal depth (ft): <u>97.9</u> Pump run time (hours): <u>—</u> Volume removed (gallons): <u>—</u> LOWER: Pond vertical depth (ft): <u>—</u> Leak detection diagonal depth (ft): <u>—</u> Pump run time (hours): <u>—</u> Volume removed (gallons): <u>—</u>
Fluid was not present within leak detection two consecutive days in a row	X			
If fluid is present two consecutive days in a row, it has to be reported to HSE & Regulatory	X			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action				Personnel
				Date



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Wildlife/Bird Deterrent System	Yes	No ¹	N/A	Comments
Audio deterrent system in working order and operating		X		No Hooked up.
All visual deterrents in good working order and operating	X			
Any repairs or replacements of deterrents from previous inspections have been completed ²			X	
Entire location (perimeter and interior) was walked and inspected for evidence of bird/wildlife mortality or injury	X			
If evidence of bird/wildlife mortality or injury is identified it was immediately reported to HSE & Regulatory	X			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
² Note personnel that completed work and date completed in the Corrective Action section below.				
Corrective Action				Personnel
				Date

Page ____ of ____

Date Checked: _____

Checked by: _____



**ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET**

Recycling Containment: SEU 2206 20M Permit Number: 3RF-30
 Qtr./Qtr. Or Lot: _____ Section: _____ Township: _____ Range: _____
 Date of Inspection: 6-10-19 Inspector: James Martinez
 Time arrived on location: 11:25 Time left location: 12:00
 General Comments: _____

General Site Condition	Yes	No ¹	N/A	Comments	
Containment currently contains fluids		X			
Fencing is in good condition and functional	X				
Gates are closed and locked ²	X				
Signage visible & compliant	X				
No signs of surface water run on	X				
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.					
² only applicable if site is unattended by authorized personnel.					
Corrective Action				Personnel	Date

Containment Compliance	Yes	No ¹	N/A	Comments	
Containment is free of any visible layer of oil sheen			X		
Containment has at least three feet of freeboard			X		
Injection or withdrawal of fluids to/from containment is accomplished through a header, diverter or other hardware			X		
Oil absorbent booms or other device onsite, in good condition, and available for use for unanticipated release			X		
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.					
Corrective Action				Personnel	Date

Page ___ of ___

Date Checked: _____

Checked by: _____



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Leak Detection System	Yes	No ¹	N/A	Comments
Site is free from evidence of leaks, spills or releases	X			
Liner above waterline shows no evidence of damage			X	
Leak detection system was checked and shows no sign of leak via fluid present	X			
If fluid is present in leak detection system, it was removed and volume recorded			X	UPPER: Pond vertical depth (ft): _____ Leak detection diagonal depth (ft): _____ Pump run time (hours): _____ Volume removed (gallons): _____ LOWER: Pond-vertical depth (ft): _____ Leak detection diagonal depth (ft): _____ Pump run time (hours): _____ Volume removed (gallons): _____
Fluid was not present within leak detection two consecutive days in a row	X			
If fluid is present two consecutive days in a row, it has to be reported to HSE & Regulatory	X			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action				Personnel Date

Page ____ of ____

Date Checked: _____

Checked by: _____



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Wildlife/Bird Deterrent System	Yes	No ¹	N/A	Comments						
Audio deterrent system in working order and operating	X									
All visual deterrents in good working order and operating	X									
Any repairs or replacements of deterrents from previous inspections have been completed ²			X							
Entire location (perimeter and interior) was walked and inspected for evidence of bird/wildlife mortality or injury	X									
If evidence of bird/wildlife mortality or injury is identified it was immediately reported to HSE & Regulatory	X									
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below. ² Note personnel that completed work and date completed in the Corrective Action section below.										
Corrective Action				<table border="1"> <thead> <tr> <th>Personnel</th> <th>Date</th> </tr> </thead> <tbody> <tr> <td></td> <td></td> </tr> <tr> <td></td> <td></td> </tr> </tbody> </table>	Personnel	Date				
Personnel	Date									

Page ___ of ___

Date Checked: _____

Checked by: _____



**ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET**

Recycling Containment: SEU 220620m Permit Number: 3RF-30
 Qtr./Qtr. Or Lot: _____ Section: _____ Township: _____ Range: _____
 Date of Inspection: 6-14-19 Inspector: James Martinez
 Time arrived on location: 1:30 Time left location: 2:00
 General Comments: _____

General Site Condition	Yes	No ¹	N/A	Comments	
Containment currently contains fluids		X			
Fencing is in good condition and functional	X				
Gates are closed and locked ²	X				
Signage visible & compliant	X				
No signs of surface water run on	X				
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.					
² only applicable if site is unattended by authorized personnel.					
Corrective Action				Personnel	Date

Containment Compliance	Yes	No ¹	N/A	Comments	
Containment is free of any visible layer of oil sheen	X				
Containment has at least three feet of freeboard	X				
Injection or withdrawal of fluids to/from containment is accomplished through a header, diverter or other hardware	X				
Oil absorbent booms or other device onsite, in good condition, and available for use for unanticipated release		X			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.					
Corrective Action				Personnel	Date

Page ___ of ___

Date Checked: _____

Checked by: _____



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Leak Detection System	Yes	No ¹	N/A	Comments
Site is free from evidence of leaks, spills or releases	X			
Liner above waterline shows no evidence of damage	X			
Leak detection system was checked and shows no sign of leak via fluid present	X			
If fluid is present in leak detection system, it was removed and volume recorded			X	UPPER: Pond vertical depth (ft): _____ Leak detection diagonal depth (ft): _____ Pump run time (hours): _____ Volume removed (gallons): _____ LOWER: Pond vertical depth (ft): _____ Leak detection diagonal depth (ft): _____ Pump run time (hours): _____ Volume removed (gallons): _____
Fluid was not present within leak detection two consecutive days in a row	X			
If fluid is present two consecutive days in a row, it has to be reported to HSE & Regulatory	X			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action			Personnel	Date

Page ___ of ___

Date Checked: _____

Checked by: _____



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Wildlife/Bird Deterrent System	Yes	No ¹	N/A	Comments	
Audio deterrent system in working order and operating		X		Not hooked up.	
All visual deterrents in good working order and operating	X				
Any repairs or replacements of deterrents from previous inspections have been completed ²		X			
Entire location (perimeter and interior) was walked and inspected for evidence of bird/wildlife mortality or injury	X				
If evidence of bird/wildlife mortality or injury is identified it was immediately reported to HSE & Regulatory	X				
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below. ² Note personnel that completed work and date completed in the Corrective Action section below.					
Corrective Action				Personnel	Date

Page ___ of ___

Date Checked: _____

Checked by: _____



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Recycling Containment: SEV 2206 70M Permit Number: 3RF-30
 Qtr./Qtr. Or Lot: _____ Section: _____ Township: _____ Range: _____
 Date of Inspection: 6-17-19 Inspector: James M. [Signature]
 Time arrived on location: 3:00 Time left location: 3:30
 General Comments: _____

General Site Condition	Yes	No ¹	N/A	Comments
Containment currently contains fluids		X		
Fencing is in good condition and functional	X			
Gates are closed and locked ²	X			
Signage visible & compliant	X			
No signs of surface water run on	X			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
² only applicable if site is unattended by authorized personnel.				
Corrective Action	Personnel		Date	

Containment Compliance	Yes	No ¹	N/A	Comments
Containment is free of any visible layer of oil sheen	X			
Containment has at least three feet of freeboard	X			
Injection or withdrawal of fluids to/from containment is accomplished through a header, diverter or other hardware	X		X	
Oil absorbent booms or other device onsite, in good condition, and available for use for unanticipated release		X		
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action	Personnel		Date	

Page ____ of ____

Date Checked: _____

Checked by: _____



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Leak Detection System	Yes	No ¹	N/A	Comments						
Site is free from evidence of leaks, spills or releases	X									
Liner above waterline shows no evidence of damage	X									
Leak detection system was checked and shows no sign of leak via fluid present	X									
If fluid is present in leak detection system, it was removed and volume recorded		X		UPPER: Pond vertical depth (ft): _____ Leak detection diagonal depth (ft): _____ Pump run time (hours): _____ Volume removed (gallons): _____ LOWER: Pond vertical depth (ft): _____ Leak detection diagonal depth (ft): _____ Pump run time (hours): _____ Volume removed (gallons): _____						
Fluid was not present within leak detection two consecutive days in a row	X									
If fluid is present two consecutive days in a row, it has to be reported to HSE & Regulatory	X									
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.										
Corrective Action				<table border="1"> <thead> <tr> <th>Personnel</th> <th>Date</th> </tr> </thead> <tbody> <tr> <td></td> <td></td> </tr> <tr> <td></td> <td></td> </tr> </tbody> </table>	Personnel	Date				
Personnel	Date									

Page ____ of ____

Date Checked: _____

Checked by: _____



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Wildlife/Bird Deterrent System	Yes	No ¹	N/A	Comments	
Audio deterrent system in working order and operating		X		Not hooked up yet	
All visual deterrents in good working order and operating	X				
Any repairs or replacements of deterrents from previous inspections have been completed ²			X		
Entire location (perimeter and interior) was walked and inspected for evidence of bird/wildlife mortality or injury	X				
If evidence of bird/wildlife mortality or injury is identified it was immediately reported to HSE & Regulatory	X				
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below. ² Note personnel that completed work and date completed in the Corrective Action section below.					
Corrective Action				Personnel	Date

Page ___ of ___

Date Checked: _____

Checked by: _____



**ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET**

Recycling Containment: SEU 2206-20M Permit Number: 32E-30
 Qtr./Qtr. Or Lot: _____ Section: 20 Township: 22N Range: 6W
 Date of Inspection: 7-8-19 Inspector: James Martin
 Time arrived on location: 10:51 Time left location: 11:30
 General Comments: _____

General Site Condition	Yes	No ¹	N/A	Comments
Containment currently contains fluids		X		
Fencing is in good condition and functional	X			
Gates are closed and locked ²	X			
Signage visible & compliant	X			
No signs of surface water run on	X			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
² only applicable if site is unattended by authorized personnel.				
Corrective Action	Personnel		Date	

Containment Compliance	Yes	No ¹	N/A	Comments
Containment is free of any visible layer of oil sheen			X	
Containment has at least three feet of freeboard			X	
Injection or withdrawal of fluids to/from containment is accomplished through a header, diverter or other hardware			X	
Oil absorbent booms or other device onsite, in good condition, and available for use for unanticipated release			X	
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action	Personnel		Date	

Page ____ of ____

Date Checked: _____

Checked by: _____



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Leak Detection System	Yes	No ¹	N/A	Comments
Site is free from evidence of leaks, spills or releases	X			
Liner above waterline shows no evidence of damage	X			
Leak detection system was checked and shows no sign of leak via fluid present	X			
If fluid is present in leak detection system, it was removed and volume recorded			X	UPPER: Pond vertical depth (ft): _____ Leak detection diagonal depth (ft): _____ Pump run time (hours): _____ Volume removed (gallons): _____ LOWER: Pond vertical depth (ft): _____ Leak detection diagonal depth (ft): _____ Pump run time (hours): _____ Volume removed (gallons): _____
Fluid was not present within leak detection two consecutive days in a row	X			
If fluid is present two consecutive days in a row, it has to be reported to HSE & Regulatory	X			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action				Personnel
				Date

Page ____ of ____

Date Checked: _____

Checked by: _____



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Wildlife/Bird Deterrent System	Yes	No ¹	N/A	Comments	
Audio deterrent system in working order and operating		X		Not hooked up.	
All visual deterrents in good working order and operating	X				
Any repairs or replacements of deterrents from previous inspections have been completed ²			X		
Entire location (perimeter and interior) was walked and inspected for evidence of bird/wildlife mortality or injury	X				
If evidence of bird/wildlife mortality or injury is identified it was immediately reported to HSE & Regulatory	X				
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below. ² Note personnel that completed work and date completed in the Corrective Action section below.					
Corrective Action				Personnel	Date

Page ____ of ____

Date Checked: _____

Checked by: _____



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Recycling Containment: SE U 2206-20 m Permit Number: 3RF-30

Qtr./Qtr. Or Lot: _____ Section: 20 Township: 22W Range: 6W

Date of Inspection: 7-16-19 Inspector: James Martinez

Time arrived on location: 10:31 Time left location: 11:08

General Comments:

General Site Condition	Yes	No ¹	N/A	Comments
Containment currently contains fluids		<input checked="" type="checkbox"/>		
Fencing is in good condition and functional	<input checked="" type="checkbox"/>			
Gates are closed and locked ²	<input checked="" type="checkbox"/>			
Signage visible & compliant	<input checked="" type="checkbox"/>			
No signs of surface water run on	<input checked="" type="checkbox"/>			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
² only applicable if site is unattended by authorized personnel.				
Corrective Action	Personnel		Date	

Containment Compliance	Yes	No ¹	N/A	Comments
Containment is free of any visible layer of oil sheen			<input checked="" type="checkbox"/>	
Containment has at least three feet of freeboard			<input checked="" type="checkbox"/>	
Injection or withdrawal of fluids to/from containment is accomplished through a header, diverter or other hardware			<input checked="" type="checkbox"/>	
Oil absorbent booms or other device onsite, in good condition, and available for use for unanticipated release	<input checked="" type="checkbox"/>		<input checked="" type="checkbox"/>	
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action	Personnel		Date	

Page ____ of ____

Date Checked: _____

Checked by: _____



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Leak Detection System	Yes	No ¹	N/A	Comments
Site is free from evidence of leaks, spills or releases	<input checked="" type="checkbox"/>			
Liner above waterline shows no evidence of damage	<input checked="" type="checkbox"/>			
Leak detection system was checked and shows no sign of leak via fluid present	<input checked="" type="checkbox"/>			
If fluid is present in leak detection system, it was removed and volume recorded			<input checked="" type="checkbox"/>	UPPER: Pond vertical depth (ft): _____ Leak detection diagonal depth (ft): _____ Pump run time (hours): _____ Volume removed (gallons): _____ LOWER: Pond vertical depth (ft): _____ Leak detection diagonal depth (ft): _____ Pump run time (hours): _____ Volume removed (gallons): _____
Fluid was not present within leak detection two consecutive days in a row	<input checked="" type="checkbox"/>			
If fluid is present two consecutive days in a row, it has to be reported to HSE & Regulatory	<input checked="" type="checkbox"/>			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below.				
Corrective Action	Personnel		Date	

Page ____ of ____

Date Checked: _____

Checked by: _____



ENDURING RESOURCES IV, LLC
RECYCLING CONTAINMENT INSPECTION SHEET

Wildlife/Bird Deterrent System	Yes	No ¹	N/A	Comments
Audio deterrent system in working order and operating		X		Not hooked up
All visual deterrents in good working order and operating	X			
Any repairs or replacements of deterrents from previous inspections have been completed ²			X	
Entire location (perimeter and interior) was walked and inspected for evidence of bird/wildlife mortality or injury	X			
If evidence of bird/wildlife mortality or injury is identified it was immediately reported to HSE & Regulatory	X			
¹ For any category above checked "No" a corresponding Corrective Action must be filled out below. ² Note personnel that completed work and date completed in the Corrective Action section below.				
Corrective Action	Personnel		Date	

Page ___ of ___

Date Checked: _____

Checked by: _____



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2206-20M Permit Number 4301-P0D5
 Section 20 Township 22N Range 6W County Sandoval State NM
 Time Inspection Began 9:24 Time Inspection Ended 9:47
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 14' / 24

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of ULD (ft)	<input type="text"/>			
Depth to Water in ULD (ft)	<input type="text"/>			
Height of Water in ULD	<input type="text"/>			
Gallons of Water Removed	<input type="text"/>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of LLD (ft)	<u>102.3</u>			
Depth to Water in LLD (ft)	<u>102.3</u>			
Height of Water in LLD	<u>0</u>			
Gallons of Water Removed	<u>0</u>			

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 3-3-21

Name (Signature) [Signature]

Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2206-70M Permit Number 4301-Pod-5
 Section 20 Township 22N Range 6W County Sandoval State NM
 Time Inspection Began 1:36 Time Inspection Ended 2:45
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 214/24

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 101.4
 Depth to Water in ULD (ft) 101.4
 Height of Water in ULD 0
 Gallons of Water Removed 0

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft) ☐
 Depth to Water in LLD (ft) ☐
 Height of Water in LLD ☐
 Gallons of Water Removed ☐

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 3-10-21Name (Signature) [Signature]Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2206-20M Permit Number 4301-5
 Section 4 Township 20N Range 6W County Sandoval State NM
 Time Inspection Began 1:20 Time Inspection Ended 1:40
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 15 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew on location

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of ULD (ft)	<u>101.4</u>			
Depth to Water in ULD (ft)	<u>101.4</u>			
Height of Water in ULD	<u>0</u>			
Gallons of Water Removed	<u>0</u>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)	<input type="text"/>			
Depth to Water in LLD (ft)	<input type="text"/>			
Height of Water in LLD	<input type="text"/>			
Gallons of Water Removed	<input type="text"/>			

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

No thing to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tim HarrisDate 3-17-21Name (Signature) [Signature]Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU - 2205 - 20M Permit Number 4301-Pod 5
 Section 20 Township 22N Range 6W County Sanderval State NM
 Time Inspection Began 11:15 Time Inspection Ended 11:45
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 12 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 101.4
 Depth to Water in ULD (ft) 101.4
 Height of Water in ULD 0
 Gallons of Water Removed 0

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

COMMENTS

No water

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 3-31-21

Name (Signature) [Signature]

Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2205-20V1 Permit Number 4301 P8d-5
 Section 20 Township 22N Range 6W County Sandoval State NM
 Time Inspection Began 9:13 Time Inspection Ended 9:30
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 21 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 104.4
 Depth to Water in ULD (ft) 101.4
 Height of Water in ULD 0
 Gallons of Water Removed 0

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 4-7-21Name (Signature) [Signature]Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2206-20M Permit Number 4301-Pd 5
 Section 20 Township 22N Range 9W County Sandoval State NM
 Time Inspection Began 11:30 Time Inspection Ended 12:07
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 21ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 101.4
 Depth to Water in ULD (ft) 101.4
 Height of Water in ULD 0
 Gallons of Water Removed 0

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

COMMENTS

No water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print)

Tina Harris

Date

4-14-21

Name (Signature)

[Signature]

Company

ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 220-20M Permit Number 4301 Pod5
 Section 20 Township 22N Range 6W County Sandoval State NM
 Time Inspection Began 9:25 Time Inspection Ended 9:40
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 21 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of ULD (ft)	<u>101.4</u>			
Depth to Water in ULD (ft)	<u>101.4</u>			
Height of Water in ULD	<u>0</u>			
Gallons of Water Removed	<u>0</u>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)	<u> </u>			
Depth to Water in LLD (ft)	<u> </u>			
Height of Water in LLD	<u> </u>			
Gallons of Water Removed	<u> </u>			

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 2-21-20Name (Signature) [Signature]Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2206-20M Permit Number 4301-Pods
 Section 20 Township 22N Range 06W County Sandoval State NM
 Time Inspection Began 11:38 Time Inspection Ended 12:10
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 20 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 101.4
 Depth to Water in ULD (ft) 101.4
 Height of Water in ULD 0
 Gallons of Water Removed 0

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 4-28-21Name (Signature) [Signature]Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2204 20M Permit Number 4301-Pod5
 Section 20 Township 22 Range 6W County Sandoval State NM
 Time Inspection Began 10:50 Time Inspection Ended 11:34
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 20 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 101.4
 Depth to Water in ULD (ft) 101.4
 Height of Water in ULD 0
 Gallons of Water Removed 0

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 5-5-21Name (Signature) [Signature]Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2206-20M Permit Number 4301 Pcd5
 Section 20 Township 22N Range 6W County Sandoval State NM
 Time Inspection Began 1:35 Time Inspection Ended 1:55
 Recycling Facility ☐ Recycling Containment ☐ Water Level (Feet) 21 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 101.4
 Depth to Water in ULD (ft) 101.4
 Height of Water in ULD 0
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Electric is off so no audio birds

Name (Print) Tina HarrisDate 5-12-21

Name (Signature)

Company

ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2201 20M Permit Number 4301-Pod 5
 Section 20 Township 22N Range 6 County Sandoval State NM
 Time Inspection Began 9:45 Time Inspection Ended 10:15
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 20 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 101.4
 Depth to Water in ULD (ft) 101.4
 Height of Water in ULD 0
 Gallons of Water Removed 0

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

COMMENTS

No water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print)

Tina Harris

Date

5-19-21

Name (Signature)

Company

ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 20M Permit Number 4301-Pod 5
 Section 20 Township 22 Range 10 County Sandoval State NM
 Time Inspection Began 11:45 Time Inspection Ended 12:15
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 20ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 101.4
 Depth to Water in ULD (ft) 101.4
 Height of Water in ULD 0
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

COMMENTS

No water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 5-26-21Name (Signature) [Signature]Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2206 20M Permit Number 4301 Rod 5
 Section 4 Township 22 Range 4 County Sandoval State NM
 Time Inspection Began 7:16 Time Inspection Ended 7:40
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 20 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 101.4
 Depth to Water in ULD (ft) 101.4
 Height of Water in ULD 0
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in LLD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

COMMENTS

No water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tiller HarrisDate 6-3-21Name (Signature) [Signature]Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SFU 2206-20M Permit Number 4301 Pod-5
 Section 4 Township 20 Range 6 County Sandoval State NM
 Time Inspection Began 11:40 Time Inspection Ended 12:00
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 20ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 101.4
 Depth to Water in ULD (ft) 101.4
 Height of Water in ULD 0
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

COMMENTS

No water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 6-9-21

Name (Signature) [Signature]

Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2706 20M Permit Number 4301-Pod 5
 Section 26 Township 22 Range 6 County Sandwich State NM
 Time Inspection Began 8:57 Time Inspection Ended 9:20
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 20ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of ULD (ft)	<u>101.4</u>			
Depth to Water in ULD (ft)	<u>101.4</u>			
Height of Water in ULD	<u>0</u>			
Gallons of Water Removed	<u>0</u>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)	<input type="text"/>			
Depth to Water in LLD (ft)	<input type="text"/>			
Height of Water in LLD	<input type="text"/>			
Gallons of Water Removed	<input type="text"/>			

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 6-17-21Name (Signature) [Signature]Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2206-20M Permit Number 4301 Pod 5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 9:25 Time Inspection Ended 9:45
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 19 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 101.6
 Depth to Water in ULD (ft) 101.4
 Height of Water in ULD 8
 Gallons of Water Removed 0

Water Present in LLD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

COMMENTS

No water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 6-24-21Name (Signature) [Signature]Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2204-20M Permit Number 4301 Pad 5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 9:55 Time Inspection Ended 10:20
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 19 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 101.4
 Depth to Water in ULD (ft) 101.4
 Height of Water in ULD 8
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

COMMENTS

No water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Can't get Audio bird to wrk.

Name (Print) Tina Harris

Date 6-30-21

Name (Signature) [Signature]

Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2206-20M Permit Number 4301 Pod 5
 Section 20 Township 22 Range 10 County Sandoval State NM
 Time Inspection Began 12:25 Time Inspection Ended 12:45
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 19 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew going in and out with equipment

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 101.4
 Depth to Water in ULD (ft) 101.4
 Height of Water in ULD 0
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Need to get with electrician to get Audio bird going

Name (Print) Tina Harris

Date 7-8-21

Name (Signature) Tina Harris

Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2206 20M Permit Number 4307 Pod 5
 Section 20 Township 22 Range 0 County Sandoval State NM
 Time Inspection Began 10:30 Time Inspection Ended 10:45
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 19 FT.

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew on location

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of ULD (ft)	<u>101.4</u>			
Depth to Water in ULD (ft)	<u>101.4</u>			
Height of Water in ULD	<u>0</u>			
Gallons of Water Removed	<u>0</u>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)	<input type="text"/>			
Depth to Water in LLD (ft)	<input type="text"/>			
Height of Water in LLD	<input type="text"/>			
Gallons of Water Removed	<input type="text"/>			

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

No water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Got a hold of Lee to check out the Audio bird
Replaced two birds eye

Name (Print) Tina Harris

Date 9-13-21

Name (Signature) Tina Harris

Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2206-20M Permit Number 4301-Pod 5
 Section 20 Township 22 Range 4 County Sandoval State NM
 Time Inspection Began 10:58 Time Inspection Ended 11:30
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 19 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 101.4
 Depth to Water in ULD (ft) 101.4
 Height of Water in ULD 0
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

No Water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 7-21-21Name (Signature) [Signature]Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SE4 2206 20M Permit Number 4301 P&L 5
 Section 20 Township 22 Range 4 County Sandoval State NM
 Time Inspection Began 1:43 Time Inspection Ended 2:00
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 19.5 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew on location

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of ULD (ft)	<input type="text"/>			
Depth to Water in ULD (ft)	<input type="text"/>			
Height of Water in ULD	<input type="text"/>			
Gallons of Water Removed	<input type="text"/>			

Lower Leak Detection (LLD)

Water Present in LLD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)	<input type="text"/>			
Depth to Water in LLD (ft)	<input type="text"/>			
Height of Water in LLD	<input type="text"/>			
Gallons of Water Removed	<input type="text"/>			

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

*I didn't take reading equipment parked in front of
Leak detection*

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 7-27-21

Name (Signature) [Signature]

Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SE4 2206-20M Permit Number 4301 Pool 5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 12:28 Time Inspection Ended 12:50
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 19 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew on location

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 101.4
 Depth to Water in ULD (ft) 99.4
 Height of Water in ULD 2 ft
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of LLD (ft) 101.4
 Depth to Water in LLD (ft) 99.4
 Height of Water in LLD 2 ft
 Gallons of Water Removed 0

If leak detection contained liquid, was it removed? YES ☒ NO ☒ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

Need to rent pump to pump out water

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 8-4-21

Name (Signature) [Signature]

Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEY 2206 20M Permit Number 4301-Ped 5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 10:15 Time Inspection Ended 10:45
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 19 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew on location

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 101.4
 Depth to Water in ULD (ft) 94.2
 Height of Water in ULD 7 ft
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☒ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

Water pump need to be hooked up, contacted Lee

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 8-18-21

Name (Signature) [Signature]

Company ER

Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2206 20M Permit Number 4301 Pds 5
 Section 20 Township 22 Range 4 County Sandoval State NM
 Time Inspection Began 10:40 Time Inspection Ended 11:15
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 19ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 101.4
 Depth to Water in ULD (ft) 93.1
 Height of Water in ULD 8ft 3in
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in LLD? YES ☐ NO ☐
 Total Depth of LLD (ft) ☐
 Depth to Water in LLD (ft) ☐
 Height of Water in LLD ☐
 Gallons of Water Removed ☐

If leak detection contained liquid, was it removed? YES ☐ NO ☒ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

Need extension cord for pump.

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 8-27-21Name (Signature) [Signature]Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2206 20M Permit Number 4301 Mod 5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 11:26 Time Inspection Ended 11:45
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 19 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 101.4
 Depth to Water in ULD (ft) 93.1
 Height of Water in ULD 8 ft 3 in
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in LLD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

Geo tech is down, going off of last week's readings
 COMMENTS Nothing has changed.

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 9-2-21Name (Signature) [Signature]Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2206-20M Permit Number 4301 Rd 5
 Section 20 Township 22 Range 4 County Sandoval State NM
 Time Inspection Began 7:00 AM Time Inspection Ended 11:55
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 19 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew on location

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 101.3
 Depth to Water in ULD (ft) 97.3
 Height of Water in ULD 4.0
 Gallons of Water Removed 250

Lower Leak Detection (LLD)

Water Present in LLD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☒ NO ☐ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

First reading had 10.1 ft of water in leak detection, drained water @ 1 gal/min 7:45 - 11:30, down to 4ft of water, flow really slowed down.

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 9-10-21

Name (Signature) [Signature]

Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2204-20M Permit Number 4301 Pod 5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 7:00 Time Inspection Ended 2:04
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 23 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew going in and out of location

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	Water Present in LLD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of ULD (ft)	<u>101.3</u>				Total Depth of LLD (ft)	<u>101.3</u>			
Depth to Water in ULD (ft)	<u>100.6</u>				Depth to Water in LLD (ft)	<u>55.9</u>			
Height of Water in ULD	<u>6 in</u>				Height of Water in LLD	<u>45.4 ft</u>			
Gallons of Water Removed	<u>15</u>				Gallons of Water Removed	<u>2100</u>			

If leak detection contained liquid, was it removed? YES ☒ NO ☐ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

Check leak detection at 7AM, water was @ 45.4 ft, contractor hooked up pump ran pump @ 15 gal/min started @ 9:50AM Finished @ 2:00 PM. Removed 45.4 ft of water.

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 9-17-21

Name (Signature) [Signature]

Company ER

Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2206 20M Permit Number 4301 Pod 5
 Section 4 Township 20 Range 6 County Sandoval State NM
 Time Inspection Began 11:25 Time Inspection Ended 11:45
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 19 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of ULD (ft)	<u>105.3</u>			
Depth to Water in ULD (ft)	<u>105.4</u>			
Height of Water in ULD	<u>2 in</u>			
Gallons of Water Removed	<u>0</u>			

Water Present in LLD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)	<input type="text"/>			
Depth to Water in LLD (ft)	<input type="text"/>			
Height of Water in LLD	<input type="text"/>			
Gallons of Water Removed	<input type="text"/>			

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Not enough water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Oil on top of water Doug S. was contacted

Name (Print)

Theresa Harris

Date

9-24-21

Name (Signature)

[Signature]

Company

ER

Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2206 20M Permit Number 4304 Pod 5
 Section 20 Township 22 Range 06 County Sandoval State NM
 Time Inspection Began 12:24 Time Inspection Ended 12:48
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 21 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew on location HALO

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 104.3
 Depth to Water in ULD (ft) 97.5
 Height of Water in ULD 6.8 ft
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in LLD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☒ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

Water in Leak detection will drain 10-1-21

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print)

Tina Harris

Date

9-30-21

Name (Signature)

[Signature]

Company

ER

Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SFY 2206-20M Permit Number 4301 Pod 5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 8:56 Time Inspection Ended 9:25
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 23 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew on location

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 101.4
 Depth to Water in ULD (ft) 98.4
 Height of Water in ULD 3 ft
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☒ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

Tried to pump water, but no water came out

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 10-6-21Name (Signature) [Signature]Company EK

Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2256-20M Permit Number 4301 Pod 5
 Section 20 Township 22 Range 6 County Sandwich State NH
 Time Inspection Began 10:50 Time Inspection Ended 11:15
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 16 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew on location

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 101.3
 Depth to Water in ULD (ft) 101.3
 Height of Water in ULD 0
 Gallons of Water Removed 0

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 10-14-21Name (Signature) [Signature]Company EN

Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SE4 2266-20M Permit Number 4301-P025
 Section 20 Township 22 Range 6 County Sandwich State NH
 Time Inspection Began 12:00 Time Inspection Ended 12:25
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 3ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew on location

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 101.3
 Depth to Water in ULD (ft) 101.3
 Height of Water in ULD 0
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

COMMENTS

No water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print)

Tim Harris

Date

10-20-21

Name (Signature)

[Signature]

Company

Enduring Resources

Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SE4 2206-20M Permit Number 4301-Pad 5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 8:53 Time Inspection Ended 9:30
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 5ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew on location

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 101.3
 Depth to Water in ULD (ft) 100.9
 Height of Water in ULD 4in
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☒ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

No enough water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 10-27-21Name (Signature) [Signature]Company Enduring Resources

Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2204 20M Permit Number 436/Pod-S
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 11:40 Time Inspection Ended 12:30
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 17 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew going in and out of location

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 101.3
 Depth to Water in ULD (ft) 101.3
 Height of Water in ULD 0
 Gallons of Water Removed 0

Water Present in LLD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate Name (Signature) [Signature]Company Enduring Resources

Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2206-20M Permit Number 4301 P 25
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 8:10 Time Inspection Ended 9:15
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 17ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 101.3
 Depth to Water in ULD (ft) 101.3
 Height of Water in ULD 0
 Gallons of Water Removed 0

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

COMMENTS

No water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 11-11-21Name (Signature) TH

Company

Enduring Resources



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2206-20M Permit Number 430/Pod 5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 11:05 Time Inspection Ended 11:45
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 17 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input checked="" type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew going in and out of location

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of ULD (ft)	<u>101.3</u>			
Depth to Water in ULD (ft)	<u>101.3</u>			
Height of Water in ULD	<u>0</u>			
Gallons of Water Removed	<u>0</u>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)	<input type="text"/>			
Depth to Water in LLD (ft)	<input type="text"/>			
Height of Water in LLD	<input type="text"/>			
Gallons of Water Removed	<input type="text"/>			

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 11-18-21Name (Signature) [Signature]Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2206 20M Permit Number 4301-Pod 5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 10:45 Time Inspection Ended 11:15
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 17 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 101.3
 Depth to Water in ULD (ft) 101.3
 Height of Water in ULD 0
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 11-24-21

Name (Signature) [Signature]

Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2206-20M Permit Number 4301 P815
 Section 20 Township 22 Range 4 County Sandoval State NM
 Time Inspection Began 12:15 Time Inspection Ended 12:45
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 16.5 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew going in and out of location

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of ULD (ft)	<u>101.3</u>			
Depth to Water in ULD (ft)	<u>101.3</u>			
Height of Water in ULD	<u>0</u>			
Gallons of Water Removed	<input type="text"/>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)	<input type="text"/>			
Depth to Water in LLD (ft)	<input type="text"/>			
Height of Water in LLD	<input type="text"/>			
Gallons of Water Removed	<input type="text"/>			

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 12-1-21Name (Signature) [Signature]Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEC 2206-20M Permit Number 4381 Pod 5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 12:20 Time Inspection Ended 12:45
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 16.5 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of ULD (ft)	<u>101.3</u>			
Depth to Water in ULD (ft)	<u>101.3</u>			
Height of Water in ULD	<u>0</u>			
Gallons of Water Removed	<u>0</u>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)	<input type="text"/>			
Depth to Water in LLD (ft)	<input type="text"/>			
Height of Water in LLD	<input type="text"/>			
Gallons of Water Removed	<input type="text"/>			

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 12-8-21

Name (Signature) [Signature]

Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2206 20m Permit Number 4301 Pct 5
 Section 20 Township 22 Range 6 County Sandwich State NH
 Time Inspection Began 11:47 Time Inspection Ended 12:10
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 16 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 101.3
 Depth to Water in ULD (ft) 100.3
 Height of Water in ULD 1 ft
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☒ NO ☒ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

Not enough to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tim Harris

Date 12-15-21

Name (Signature) [Signature]

Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SE4 2206-20M Permit Number 4301 P015
 Section 20 Township 22 Range 6 County Sandwich State Ny
 Time Inspection Began 11:50 Time Inspection Ended 12:20
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 16 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of ULD (ft)	<u>103.1</u>			
Depth to Water in ULD (ft)	<u>103.1</u>			
Height of Water in ULD	<u>0</u>			
Gallons of Water Removed	<u>0</u>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)	<input type="text"/>			
Depth to Water in LLD (ft)	<input type="text"/>			
Height of Water in LLD	<input type="text"/>			
Gallons of Water Removed	<input type="text"/>			

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) T. Harris

Date 12-21-21

Name (Signature) [Signature]

Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 22026-20 m Permit Number 4301 Pcd 5
 Section 20 Township 22 Range 4 County Sandoval State NM
 Time Inspection Began 11:55 Time Inspection Ended 12:20
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 16.4

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew on location

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 101.3
 Depth to Water in ULD (ft) 101.3
 Height of Water in ULD 0
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

COMMENTS

Didn't take reading equipment parked in front of leak detection

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 12-29-21Name (Signature) [Signature]Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2206-20M Permit Number 4301P25
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 9:14 Time Inspection Ended 10:50
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew on location

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of ULD (ft)	<u>101.3</u>			
Depth to Water in ULD (ft)	<u>53.6</u>			
Height of Water in ULD	<u>47.7</u>			
Gallons of Water Removed	<u>870</u>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)				
Depth to Water in LLD (ft)				
Height of Water in LLD				
Gallons of Water Removed				

If leak detection contained liquid, was it removed?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Turn pump on @ 9:29 - 10:47 @ 10gal/min removed at least 870 gallons, still a lot of water coming out

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

Replaced 2 birds eye

COMMENTS

Pond need cleaning Doug S. was contacted.

Name (Print) Tina Harris

Date 1-5-22

Name (Signature) [Signature]

Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SE4 2206 20M Permit Number 4301 Pbd 5
 Section 20 Township 27 Range 6 County Sandoval State NM
 Time Inspection Began 9:30 Time Inspection Ended 9:45
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS Crew going in and out of location

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 101.3
 Depth to Water in ULD (ft)
 Height of Water in ULD
 Gallons of Water Removed

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☐

water level is over 19ft so water is going into leak detection, Doug has guys draining water every day.

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 1-12-21

Name (Signature) [Signature]

Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2206 2011 Permit Number 4301 Pod 5
 Section 20 Township 22 Range 10 County Sandoval State NM
 Time Inspection Began 12:00 Time Inspection Ended 12:20
 Recycling Facility ☐ Recycling Containment ☐ Water Level (Feet) 22 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew on location

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of ULD (ft)	<u>101.3</u>			
Depth to Water in ULD (ft)	<u>91.3</u>			
Height of Water in ULD	<u>10 ft</u>			
Gallons of Water Removed	<u>—</u>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)	<input type="text"/>			
Depth to Water in LLD (ft)	<input type="text"/>			
Height of Water in LLD	<input type="text"/>			
Gallons of Water Removed	<input type="text"/>			

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew have been draining leak detection, level is over 19 ft

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 1-20-22Name (Signature) [Signature]Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEC 2206-20M Permit Number 4301 Pool 5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 10:40 Time Inspection Ended 11:00
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 8 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew on location

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 101.3
 Depth to Water in ULD (ft) 101.3
 Height of Water in ULD 0
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

COMMENTS

Water was drained by crew

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print)

Tina Harris

Date

1-26-22

Name (Signature)

[Signature]

Company

ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 220620M Permit Number 4301 Pcd 5
 Section 20 Township 22 Range 6 County Sandwich State NH
 Time Inspection Began 11:00 Time Inspection Ended 11:30
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22.5

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew on location

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 101.3
 Depth to Water in ULD (ft) 83.3
 Height of Water in ULD 18 ft
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☒ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

Water frozen in leak detection hose.

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 2-4-22Name (Signature) [Signature]Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2206 20m Permit Number 3RF-30
 Section 20 Township 22N Range 6W County Sandwich State NH
 Time Inspection Began 9:30am Time Inspection Ended 11:20am
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 72 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of ULD (ft)	<input type="text"/>			
Depth to Water in ULD (ft)	<input type="text"/>			
Height of Water in ULD	<input type="text"/>			
Gallons of Water Removed	<input type="text"/>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)	<u>101.4</u>			
Depth to Water in LLD (ft)	<u>100.9</u>			
Height of Water in LLD	<u>0.5</u>			
Gallons of Water Removed	<u>0</u>			

If leak detection contained liquid, was it removed?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

Kicked on pump, pumped a few gallons and shut pump off.

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Chad Smith

Date 2-10-2022

Name (Signature) [Signature]

Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2106 com Permit Number 32E-30
 Section 70 Township 22N Range 6W County Randolph State Nm
 Time Inspection Began 1:15pm Time Inspection Ended 2:00pm
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 225ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of ULD (ft)	<input type="text"/>			
Depth to Water in ULD (ft)	<input type="text"/>			
Height of Water in ULD	<input type="text"/>			
Gallons of Water Removed	<input type="text"/>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of LLD (ft)	<u>101.4</u>			
Depth to Water in LLD (ft)	<input type="text"/>			
Height of Water in LLD	<input type="text"/>			
Gallons of Water Removed	<u>0</u>			

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

NO water in leak detection

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Chad Small

Date 2-15-22

Name (Signature) [Signature]

Company ER



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEC 2206-20M Permit Number 430/Pod 5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 11:50 Time Inspection Ended 1:20
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22.5 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew going in and out of location

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 101.3
 Depth to Water in ULD (ft) 35.66.3
 Height of Water in ULD 35.0
 Gallons of Water Removed 760 gal

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☐

COMMENTS

Ran pump @ 10 gal/min from 12:02 - 1:15

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print)

Tina Harris

Date

2-24-22

Name (Signature)

[Signature]

Company

ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2206 20M Permit Number 4301 Pools
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 10:25 Time Inspection Ended 11:45
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22f

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 101.3
 Depth to Water in ULD (ft) 86.3
 Height of Water in ULD 15f
 Gallons of Water Removed Abt 200

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft) ☐
 Depth to Water in LLD (ft) ☐
 Height of Water in LLD ☐
 Gallons of Water Removed ☐

If leak detection contained liquid, was it removed? YES ☒ NO ☐ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

Ran pump from 10:34 - 11:40

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 13-2-22

Name (Signature) [Signature]

Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2206-20M Permit Number 4305-Prod 6
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 11:25 Time Inspection Ended 12:15
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22.5 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 101.3
 Depth to Water in ULD (ft) 91.3
 Height of Water in ULD 10.4
 Gallons of Water Removed 167508

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☒ NO ☐ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

Ran pump for 37 mins.

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 3-7-22

Name (Signature) [Signature]

Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2267-20M Permit Number 4301 Pads
 Section 16 Township 22 Range 7 County Sandoval State NM
 Time Inspection Began 11:55 Time Inspection Ended 12:20
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew on location

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of ULD (ft)	<u>101.3</u>			
Depth to Water in ULD (ft)	<u>97.0</u>			
Height of Water in ULD	<u>4.3 ft</u>			
Gallons of Water Removed	<u>1650</u>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)	<input type="text"/>			
Depth to Water in LLD (ft)	<input type="text"/>			
Height of Water in LLD	<input type="text"/>			
Gallons of Water Removed	<input type="text"/>			

If leak detection contained liquid, was it removed?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Rampump for 10mins, got foam last 5mins,

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Replace 1 bird's eye

Name (Print) Tina HarrisDate 3-16-22Name (Signature) [Signature]Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2206-20M Permit Number 4301 Pds
 Section 20 Township 22 Range 4 County Sandoval State NM
 Time Inspection Began 11:27 Time Inspection Ended 11:50
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 21 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Lower Leak Detection (LLD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 101.3
 Depth to Water in ULD (ft) 96.3
 Height of Water in ULD 4 ft
 Gallons of Water Removed Abt 150

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☒ NO ☐ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

Ran pump for 15 mins

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 3-23-22Name (Signature) [Signature]Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2206-20M Permit Number 4301 Pod 5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 11:55 Time Inspection Ended 12:20
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☒
 Total Depth of ULD (ft) 105.1
 Depth to Water in ULD (ft) 105.1
 Height of Water in ULD 0
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 3-31-22Name (Signature) [Signature]Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SE4 2207-20M Permit Number 4301 PochS
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 11:50 Time Inspection Ended 12:15
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 21ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of ULD (ft)
 Depth to Water in ULD (ft)
 Height of Water in ULD
 Gallons of Water Removed

Water Present in ULD? YES ☒ NO ☐
 Total Depth of LLD (ft) 101.3
 Depth to Water in LLD (ft) 98.3
 Height of Water in LLD 3ft
 Gallons of Water Removed Abt 50?

If leak detection contained liquid, was it removed?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Ran pump for 20 mins

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 4-16-22Name (Signature) [Signature]Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SE4 2207-28M Permit Number 4301 Pod 5
 Section 26 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 8:30 Time Inspection Ended 8:47
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 21ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	Water Present in LLD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of ULD (ft)	<u>101.3</u>				Total Depth of LLD (ft)				
Depth to Water in ULD (ft)	<u>100.7</u>				Depth to Water in LLD (ft)				
Height of Water in ULD	<u>6 in</u>				Height of Water in LLD				
Gallons of Water Removed	<u>8</u>				Gallons of Water Removed				

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Not enough water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 4-14-22

Name (Signature) [Signature]

Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2207-20 M Permit Number 4301 Pcd 5
 Section 20 Township 22 Range 4 County Sandoval State NM
 Time Inspection Began 11:05 Time Inspection Ended 11:35
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 21 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 101.3
 Depth to Water in ULD (ft) 98.0
 Height of Water in ULD 3.3 ft
 Gallons of Water Removed abt 150

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☒ NO ☐ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

Ran pump for 20 mins

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 4-21-22Name (Signature) [Signature]Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2207 20 M Permit Number 4301 Pod 5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 11:50 Time Inspection Ended 12:20
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 21

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 101.3
 Depth to Water in ULD (ft) 2 ft
 Height of Water in ULD 99.3
 Gallons of Water Removed 16510

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☒ NO ☐ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

Ran pump 5mins
 Crew still draining leak detection (TETRA)

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 4-27-22

Name (Signature) [Signature]

Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2207 20M Permit Number 4301 Pod-B
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 9:45 Time Inspection Ended 10:10
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 21ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 101.0
 Depth to Water in ULD (ft) 98.0
 Height of Water in ULD 3 ft
 Gallons of Water Removed Abt 75

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☒ NO ☐ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

Run pump for 10 mins

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 5-31-22Name (Signature) [Signature]Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2207-20 m Permit Number 4301 Pad 5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 12:00 Time Inspection Ended 12:30
 Recycling Facility ☐ Recycling Containment ☐ Water Level (Feet) 21 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 101
 Depth to Water in ULD (ft) 100.4
 Height of Water in ULD 6 in
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 5-11-22

Name (Signature) [Signature]

Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2207 20M Permit Number 4301 Pod-5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 12:40 Time Inspection Ended 1:05
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 20.5 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 101.0
 Depth to Water in ULD (ft) 97.1
 Height of Water in ULD 4 ft
 Gallons of Water Removed Abt 200

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☒ NO ☐ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

Ran pump for 10 mins

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 5-17-22Name (Signature) [Signature]Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEL 2287-20M Permit Number 4301 Pod 5
 Section 20 Township 27 Range 6 County Sandoval State NM
 Time Inspection Began 10:10 Time Inspection Ended 10:30
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 20ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of ULD (ft)	<u>101.1</u>			
Depth to Water in ULD (ft)	<u>100.5</u>			
Height of Water in ULD	<u>6in</u>			
Gallons of Water Removed	<u>0</u>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)	<input type="text"/>			
Depth to Water in LLD (ft)	<input type="text"/>			
Height of Water in LLD	<input type="text"/>			
Gallons of Water Removed	<input type="text"/>			

If leak detection contained liquid, was it removed?	YES	<input checked="" type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Not enough water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 5-25-22

Name (Signature) Tina Harris

Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SE 4 2207 20M Permit Number 4301 Pct-5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 12:00 Time Inspection Ended 12:20
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 21 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	Water Present in LLD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of ULD (ft)		<u>101.0</u>			Total Depth of LLD (ft)				
Depth to Water in ULD (ft)		<u>100.5</u>			Depth to Water in LLD (ft)				
Height of Water in ULD		<u>6 in</u>			Height of Water in LLD				
Gallons of Water Removed		<u>0</u>			Gallons of Water Removed				

If leak detection contained liquid, was it removed?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

No enough water to remove, ext cord was stolen

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 6-1-22

Name (Signature) [Signature]

Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2207-20M Permit Number 4301 Pool 5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 9:30 Time Inspection Ended 9:45
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 21.5 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew going in and out of location

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Lower Leak Detection (LLD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 101.1
 Depth to Water in ULD (ft) 100.5
 Height of Water in ULD 6m
 Gallons of Water Removed 0

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☒ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

Not enough water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print)

Tina Harris

Date

6-8-22

Name (Signature)

Tina Harris

Company

ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2207-20M Permit Number 4301 Pcd 5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 12:07 Time Inspection Ended 12:30
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew going in and out of location

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 151.8
 Depth to Water in ULD (ft) 100.0
 Height of Water in ULD 1 ft
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☒ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 6-15-22Name (Signature) [Signature]Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2206-20M Permit Number 3RF-30
 Section 20 Township 22N Range 6W County Sandoval State NM
 Time Inspection Began 9:40 am Time Inspection Ended 10:20 am
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of ULD (ft)	<input type="text"/>			
Depth to Water in ULD (ft)	<input type="text"/>			
Height of Water in ULD	<input type="text"/>			
Gallons of Water Removed	<input type="text"/>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of LLD (ft)	<u>101.4</u>			
Depth to Water in LLD (ft)	<u>101.4</u>			
Height of Water in LLD	<u>0</u>			
Gallons of Water Removed	<u>0</u>			

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

Some oil on surface, contact facilities to remove

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Chad Snell

Date 6-23-22

Name (Signature) [Signature]

Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SE4 2207-20M Permit Number 4501605
 Section 20 Township 22 Range 10 County Sandoval State NM
 Time Inspection Began 11:15 Time Inspection Ended 11:35
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 23.5

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew on location

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 10
 Depth to Water in ULD (ft) 10
 Height of Water in ULD 0
 Gallons of Water Removed 0

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

COMMENTS

No water

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 6-29-22Name (Signature) [Signature]Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2207-20M Permit Number 4301 Rd 5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 12:07 Time Inspection Ended 12:25
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 23.5 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 101.0
 Depth to Water in ULD (ft) 101.0
 Height of Water in ULD 0
 Gallons of Water Removed 0

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 7-6-22Name (Signature) [Signature]Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2207 20M Permit Number 4301 Pcd-5
 Section 20 Township 22 Range 4 County Sandoval State NM
 Time Inspection Began 9:30 Time Inspection Ended 9:45
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 23

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

Crew going in and out of location

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of ULD (ft)	<u>101.0</u>			
Depth to Water in ULD (ft)	<u>.9</u>			
Height of Water in ULD	<u>100.1</u>			
Gallons of Water Removed	<u>0</u>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)				
Depth to Water in LLD (ft)				
Height of Water in LLD				
Gallons of Water Removed				

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS No enough water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 7-13-22

Name (Signature) [Signature]

Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2207-20M Permit Number 4301 Pod 5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 11:40 Time Inspection Ended 12:00
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 23 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 101
 Depth to Water in ULD (ft) 101
 Height of Water in ULD 0
 Gallons of Water Removed 0

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 7-20-22Name (Signature) [Signature]Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SE4 2207-20M Permit Number 4301 Pod 5
 Section 20 Township 20 Range 10 County Sandwich State NM
 Time Inspection Began 8:55 Time Inspection Ended 9:40
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 23

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 101
 Depth to Water in ULD (ft) 100
 Height of Water in ULD 1 ft
 Gallons of Water Removed Abt 120

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☒ NO ☐ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

Ran pump for 20 mins

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 7-27-22Name (Signature) [Signature]Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2207-20M Permit Number 4301 Add 5
 Section 20 Township 22 Range 4 County Sandoval State NM
 Time Inspection Began 12:42 Time Inspection Ended 1:20
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 23 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of ULD (ft) 101.0
 Depth to Water in ULD (ft)
 Height of Water in ULD
 Gallons of Water Removed

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☐

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 8-5-22

Name (Signature) [Signature]

Company ENDURING RESOURCES

Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SE4 2207-20 M Permit Number 4301 Pod-5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 1:00 Time Inspection Ended 1:30
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 23 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of ULD (ft)	<u>101</u>			
Depth to Water in ULD (ft)	<u>101</u>			
Height of Water in ULD	<u>0</u>			
Gallons of Water Removed	<u>0</u>			

Lower Leak Detection (LLD)

Water Present in LLD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)	<input type="text"/>			
Depth to Water in LLD (ft)	<input type="text"/>			
Height of Water in LLD	<input type="text"/>			
Gallons of Water Removed	<input type="text"/>			

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 8-10-22Name (Signature) [Signature]Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SE4 2207-20M Permit Number 4301 Pod-5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 9:37 Time Inspection Ended 10:04
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 23 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 10.1
 Depth to Water in ULD (ft) 10.1
 Height of Water in ULD 0
 Gallons of Water Removed

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 8-17-22

Name (Signature) [Signature]

Company ENDURING RESOURCES

Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2287-2041 Permit Number 4301 Pool 5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 1:07 Time Inspection Ended 1:30
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 23 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Pond needs to be skimmed

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of ULD (ft)	<u>16.1</u>			
Depth to Water in ULD (ft)	<u>10.1</u>			
Height of Water in ULD	<u>0</u>			
Gallons of Water Removed	<u>0</u>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)	<input type="text"/>			
Depth to Water in LLD (ft)	<input type="text"/>			
Height of Water in LLD	<input type="text"/>			
Gallons of Water Removed	<input type="text"/>			

If leak detection contained liquid, was it removed?	YES	<input checked="" type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Replaced 1 bird's eye

Name (Print)

Tina Harris

Date

8-24-22

Name (Signature)

[Signature]

Company

ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2207-20W1 Permit Number 4301 Pcd-5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 9:00 Time Inspection Ended 9:30
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22.5

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 101.1
 Depth to Water in ULD (ft) 100.4
 Height of Water in ULD 6 in
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☒ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

Not enough water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris Date 8-31-22
 Name (Signature) [Signature] Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2207 20M Permit Number 4301 pds
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 12:30 Time Inspection Ended 12:55
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22.5

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 101.0
 Depth to Water in ULD (ft) 101.0
 Height of Water in ULD 0
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☐

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 9-6-27

Name (Signature) [Signature]

Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2207-20W1 Permit Number 4301 Pal-5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 9:33 Time Inspection Ended 9:48
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22.5

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 101.1
 Depth to Water in ULD (ft) 101.1
 Height of Water in ULD 0
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 9-14-22

Name (Signature) Tina Harris

Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2267-210M Permit Number 4301 Post-5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 12:04 Time Inspection Ended 12:25
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22.5

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 101.0
 Depth to Water in ULD (ft) 180.06
 Height of Water in ULD 1ft
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☒ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

Not enough water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print)

Tina Harris

Date

9-22-22

Name (Signature)

Tina Harris

Company

ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SE4 2207-20M Permit Number 4361 R25
 Section 20 Township 22 Range 4 County Sandoval State NM
 Time Inspection Began 1:00 Time Inspection Ended 1:15
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22.5

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of ULD (ft)	<u>101.0</u>			
Depth to Water in ULD (ft)	<u>101.0</u>			
Height of Water in ULD	<u>0</u>			
Gallons of Water Removed	<u>0</u>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)	<input type="text"/>			
Depth to Water in LLD (ft)	<input type="text"/>			
Height of Water in LLD	<input type="text"/>			
Gallons of Water Removed	<input type="text"/>			

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print)

Tina Harris

Date

9-28-22

Name (Signature)

[Signature]

Company

ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2207-20M Permit Number 4301 Pod 5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 11:30 Time Inspection Ended 11:45
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22.5 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 10.1
 Depth to Water in ULD (ft) 10.1
 Height of Water in ULD 8
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

COMMENTS

No water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Replace 1 bird's eye

Name (Print) Tina Harris

Date 10-5-22

Name (Signature) [Signature]

Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name	SEU 2207-20M			Permit Number	4301 Rsd-5		
Section	20	Township	27	Range	6	County	Sandoval
Time Inspection Began	12:10			Time Inspection Ended	12:40		
Recycling Facility	<input type="checkbox"/>	Recycling Containment	<input checked="" type="checkbox"/>	Water Level (Feet)	27.5		

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of ULD (ft)	101			
Depth to Water in ULD (ft)	101			
Height of Water in ULD	0			
Gallons of Water Removed	0			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)				
Depth to Water in LLD (ft)				
Height of Water in LLD				
Gallons of Water Removed				

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

No water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print)

Tina Harris

Date

10-13-22

Name (Signature)

[Signature]

Company

ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2207-20M Permit Number 430/Pack 5
 Section 20 Township 22 Range 6 County Sanderson State NM
 Time Inspection Began 2:20 Time Inspection Ended 2:40
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 101.0
 Depth to Water in ULD (ft) 101.0
 Height of Water in ULD 0
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☒ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 10-19-22Name (Signature) [Signature]Company ENDURING RESOURCES

Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEC 2207 20M Permit Number 4301 Pod-B
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 12:59 Time Inspection Ended 1:15
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of ULD (ft)	<u>101</u>			
Depth to Water in ULD (ft)	<u>101</u>			
Height of Water in ULD	<u>0</u>			
Gallons of Water Removed	<u>0</u>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)	<input type="text"/>			
Depth to Water in LLD (ft)	<input type="text"/>			
Height of Water in LLD	<input type="text"/>			
Gallons of Water Removed	<input type="text"/>			

If leak detection contained liquid, was it removed?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 10-27-22Name (Signature) [Signature]Company ENDURING RESOURCES

Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SE4 2006-20M Permit Number 4301 Pad 5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 9:55 Time Inspection Ended 10:10
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 10.8
 Depth to Water in ULD (ft) 10.4
 Height of Water in ULD 0.4
 Gallons of Water Removed 0

Water Present in LLD? YES ☐ NO ☐
 Total Depth of LLD (ft) ☐
 Depth to Water in LLD (ft) ☐
 Height of Water in LLD ☐
 Gallons of Water Removed ☐

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☐

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 11-11-22Name (Signature) [Signature]Company ENDURING RESOURCES

Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2707-20M Permit Number 4301 Pad-5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 12:10 Time Inspection Ended 12:30
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 101.0
 Depth to Water in ULD (ft) 101.0
 Height of Water in ULD 0
 Gallons of Water Removed 0

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 11-17-22Name (Signature) [Signature]Company ENDURING RESOURCES

Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 207-20M Permit Number 4301 Bnd 5
 Section 26 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 10:45 Time Inspection Ended 11:20
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 10.0
 Depth to Water in ULD (ft) 10.0
 Height of Water in ULD 0
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☐

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 11-22-22Name (Signature) [Signature]Company ENDURING RESOURCES

Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2207 20M Permit Number 4301 P005
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 12:35 Time Inspection Ended 12:50
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 101
 Depth to Water in ULD (ft) 101
 Height of Water in ULD 0
 Gallons of Water Removed 0

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 11-30-22Name (Signature) [Signature]Company ENDURING RESOURCES

Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 220T-20M Permit Number 4301 Pod 5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 11:30 Time Inspection Ended 11:45
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 101.0
 Depth to Water in ULD (ft) 101.0
 Height of Water in ULD 0
 Gallons of Water Removed 0

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 12-12-22Name (Signature) Tina HarrisCompany ENDURING RESOURCES

Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2207 20m Permit Number 4301 Ped-5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 12:15 Time Inspection Ended 12:35
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 10.0
 Depth to Water in ULD (ft) 10.0
 Height of Water in ULD 0
 Gallons of Water Removed 0

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 12-22-22Name (Signature) [Signature]Company ENDURING RESOURCES

Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2207-20 M Permit Number 4301 Pod 5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 12:50 Time Inspection Ended 1:10
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 101.0
 Depth to Water in ULD (ft) 101.
 Height of Water in ULD 0
 Gallons of Water Removed 0

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft) ☐
 Depth to Water in LLD (ft) ☐
 Height of Water in LLD ☐
 Gallons of Water Removed ☐

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 12-27-22Name (Signature) [Signature]Company ENDURING RESOURCES

Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SE 4 2207-20M Permit Number 4301 Pool 5
 Section 20 Township 27 Range 6 County Sandoval State NM
 Time Inspection Began 1:00 Time Inspection Ended 1:30
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Lower Leak Detection (LLD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 101.0
 Depth to Water in ULD (ft) 100.00
 Height of Water in ULD 1 ft
 Gallons of Water Removed 0

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☒ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 1-21-23Name (Signature) [Signature]Company ENDURING RESOURCES

Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2207-20M Permit Number 430/Pod 5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 1:10 Time Inspection Ended 1:25
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of ULD (ft) 101.
 Depth to Water in ULD (ft) 101.
 Height of Water in ULD 8
 Gallons of Water Removed 8

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft) ☐
 Depth to Water in LLD (ft) ☐
 Height of Water in LLD ☐
 Gallons of Water Removed ☐

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 1-11-23Name (Signature) [Signature]Company ENDURING RESOURCES

Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2207-20M Permit Number 4301 P15
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 11:50 Time Inspection Ended 12:15
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 101.0
 Depth to Water in ULD (ft) 101.0
 Height of Water in ULD
 Gallons of Water Removed

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

Didn't take reading, can't find tubing in snow

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 1-18-23Name (Signature) [Signature]Company ENDURING RESOURCES

Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SEU 2207-20M Permit Number 4301 Pcd-5
 Section 20 Township 27 Range 6 County Sandoval State NM
 Time Inspection Began 9:50 - Time Inspection Ended 10:20
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Lower Leak Detection (LLD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 101.0
 Depth to Water in ULD (ft) 100.4
 Height of Water in ULD 6 in
 Gallons of Water Removed 0

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☒ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Pond needs to be skimmed

Name (Print) Tina HarrisDate 1-24-23Name (Signature) [Signature]Company ENDURING RESOURCES

Enduring Resources, LLC
Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name SE4 2207-20W1 Permit Number 4301 Pod-5
Section 20 Township 22 Range 10 County Sandoval State NM
Time Inspection Began 11:41 Time Inspection Ended 12:00
Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 22 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

Crew going in and out of location

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of ULD (ft)	<u>101.1</u>			
Depth to Water in ULD (ft)	<u>101.1</u>			
Height of Water in ULD	<u>0</u>			
Gallons of Water Removed	<u>0</u>			

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)				
Depth to Water in LLD (ft)				
Height of Water in LLD				
Gallons of Water Removed				

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 2-1-23Name (Signature) Tina HarrisCompany ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility AVO Inspection Sheet

SITE INFORMATION

Location Name SEU 2207-20m Permit Number 4301 Pods
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 1:15 Time Inspection Ended 1:30
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 20 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew going in and out of location

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Audio inspection conducted for pressure and liquid leaks	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Olfactory inspection conducted for unusual or strong odor	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of ULD (ft)	<u>101.0</u>			
Depth to Water in ULD (ft)	<u>101.0</u>			
Height of Water in ULD	<u>18</u>			
Gallons of Water Removed	<u>0</u>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)				
Depth to Water in LLD (ft)				
Height of Water in LLD				
Gallons of Water Removed				

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 2-8-23

Name (Signature) [Signature]

Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility AVO Inspection Sheet

SITE INFORMATION

Location Name SEU 2207-20 W1 Permit Number 4301/1005
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 1:30 Time Inspection Ended 1:45
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 19 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

crews going in and out of location

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Audio inspection conducted for pressure and liquid leaks	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Olfactory inspection conducted for unusual or strong odor	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of ULD (ft) 10/0
 Depth to Water in ULD (ft)
 Height of Water in ULD
 Gallons of Water Removed

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

Didn't take reading, equipment park in front of leak detection.

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

CDH taking water samples

Name (Print) Tina Harris

Date 2-15-23

Name (Signature) [Signature]

Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility AVO Inspection Sheet

SITE INFORMATION

Location Name SE 4 2207-20M Permit Number 4301805
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 11:40 Time Inspection Ended 12:10
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 17 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew on location

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Audio inspection conducted for pressure and liquid leaks	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Olfactory inspection conducted for unusual or strong odor	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of ULD (ft) 101.1
 Depth to Water in ULD (ft)
 Height of Water in ULD
 Gallons of Water Removed

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☒ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☒ NA ☐

COMMENTS

Equipment parked in front of LD to take readings

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Name (Print)

Tina Harris

Date

2-23-23

Name (Signature)

[Signature]

Company

ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility AVO Inspection Sheet

SITE INFORMATION

Location Name SEU 2207 20M Permit Number 430605
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 2:09 Time Inspection Ended 2:30
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 17 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew working on cuspstone

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Audio inspection conducted for pressure and liquid leaks	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Olfactory inspection conducted for unusual or strong odor	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of ULD (ft)	<u>101.</u>			
Depth to Water in ULD (ft)	<u>101</u>			
Height of Water in ULD	<u>8</u>			
Gallons of Water Removed	<u>0</u>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)				
Depth to Water in LLD (ft)				
Height of Water in LLD				
Gallons of Water Removed				

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Didn't take reading, my tubing is bent, need new tubing.

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Bird's eye need to be replace, too windy today

Name (Print)

Tina Harris

Date

3-1-23

Name (Signature)

[Signature]

Company

ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility AVO Inspection Sheet

SITE INFORMATION

Location Name SEU 2207-20M Permit Number 4301Pd-5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 2:05 Time Inspection Ended 2:20
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 17 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

News going in and out of location

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Audio inspection conducted for pressure and liquid leaks	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Olfactory inspection conducted for unusual or strong odor	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 101.7
 Depth to Water in ULD (ft) 100.7
 Height of Water in ULD 3:11
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☒ NA ☐
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

Not enough water to remove

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris
 Name (Signature) [Signature]

Date 3-8-23
 Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility AVO Inspection Sheet

SITE INFORMATION

Location Name 564 2207-2041 Permit Number 4301 Pod 5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 12:50 Time Inspection Ended 1:15
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 17 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Audio inspection conducted for pressure and liquid leaks	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Olfactory inspection conducted for unusual or strong odor	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 101
 Depth to Water in ULD (ft) 101
 Height of Water in ULD 0
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in LLD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

Didn't take reading due to mud

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 3-16-23

Name (Signature) [Signature]

Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility AVO Inspection Sheet

SITE INFORMATION

Location Name SEU 2207-20M Permit Number U301 Ppt 5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 11:40 Time Inspection Ended 12:00
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 17 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Audio inspection conducted for pressure and liquid leaks	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Olfactory inspection conducted for unusual or strong odor	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 101.0
 Depth to Water in ULD (ft) 101.
 Height of Water in ULD
 Gallons of Water Removed

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

Didn't take readings due to mud,

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

All looks good, getting alot of moisture

Name (Print) Tina Harris

Date 3-22-23

Name (Signature) Tina Harris

Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility AVO Inspection Sheet

SITE INFORMATION

Location Name SEU 2207 20M Permit Number 1130/Pod-5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 10:15 Time Inspection Ended 10:45
 Recycling Facility ☐ Recycling Containment ☐ Water Level (Feet) 17ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crews going in and out of location

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Audio Inspection conducted for pressure and liquid leaks	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Olfactory inspection conducted for unusual or strong odor	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of ULD (ft)	<u>101.0</u>			
Depth to Water in ULD (ft)	<u>101.0</u>			
Height of Water in ULD	<u>0</u>			
Gallons of Water Removed	<u>0</u>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)	<input type="text"/>			
Depth to Water in LLD (ft)	<input type="text"/>			
Height of Water in LLD	<input type="text"/>			
Gallons of Water Removed	<input type="text"/>			

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 3-30-23Name (Signature) [Signature]Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility AVO Inspection Sheet

SITE INFORMATION

Location Name SEU 2207-20M Permit Number 4301Bd-5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 10:47 Time Inspection Ended 11:15
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 17ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Audio inspection conducted for pressure and liquid leaks	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Olfactory inspection conducted for unusual or strong odor	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of ULD (ft)	<u>101.0</u>			
Depth to Water in ULD (ft)	<u>101.0</u>			
Height of Water in ULD	<u>8</u>			
Gallons of Water Removed	<u>8</u>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)	<input type="text"/>			
Depth to Water in LLD (ft)	<input type="text"/>			
Height of Water in LLD	<input type="text"/>			
Gallons of Water Removed	<input type="text"/>			

If leak detection contained liquid, was it removed?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

Replaced 3 birds eye

COMMENTS

Name (Print) Tina Harris

Date 4-5-23

Name (Signature) [Signature]

Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility AVO Inspection Sheet

SITE INFORMATION

Location Name SEU 2207-20 M Permit Number 4361 Pcd-5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 1:31 Time Inspection Ended 1:50
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 17 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Audio inspection conducted for pressure and liquid leaks	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Olfactory inspection conducted for unusual or strong odor	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☒ NO ☐
 Total Depth of ULD (ft) 101.0
 Depth to Water in ULD (ft) 101.0
 Height of Water in ULD 0
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☐ NO ☐ NA ☒

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 4-13-23

Name (Signature) [Signature]

Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility AVO Inspection Sheet

SITE INFORMATION

Location Name SE4 2207-20 M Permit Number 4304-Pod 5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 12:30 Time Inspection Ended 1:15
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 17.5

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Audio inspection conducted for pressure and liquid leaks	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Olfactory inspection conducted for unusual or strong odor	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 101.0
 Depth to Water in ULD (ft) 101.0
 Height of Water in ULD 0
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 4-20-23

Name (Signature) [Signature]

Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility AVO Inspection Sheet

SITE INFORMATION

Location Name SEU 2207 20M Permit Number 4301 Pod-5
 Section 20 Township 27 Range 6 County Sandoval State NM
 Time Inspection Began 10:30 Time Inspection Ended 10:50
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 16.5 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

closed gate.

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Audio inspection conducted for pressure and liquid leaks	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Olfactory inspection conducted for unusual or strong odor	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of ULD (ft)	<u>101</u>			
Depth to Water in ULD (ft)	<u>101</u>			
Height of Water in ULD	<u>0</u>			
Gallons of Water Removed	<u>0</u>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)				
Depth to Water in LLD (ft)				
Height of Water in LLD				
Gallons of Water Removed				

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Replaced 2 bird's eyeName (Print) Tina HarrisDate 4-26-23Name (Signature) [Signature]Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility AVO Inspection Sheet

SITE INFORMATION

Location Name SEU 2207-20M Permit Number 4301 Hpt 5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 9:15 Time Inspection Ended 9:30
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 16.5

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew going in and out of location

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Audio inspection conducted for pressure and liquid leaks	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Olfactory inspection conducted for unusual or strong odor	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of ULD (ft)	<u>101.0</u>			
Depth to Water in ULD (ft)	<u>101.0</u>			
Height of Water in ULD	<u>0</u>			
Gallons of Water Removed	<u>0</u>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)	<input type="text"/>			
Depth to Water in LLD (ft)	<input type="text"/>			
Height of Water in LLD	<input type="text"/>			
Gallons of Water Removed	<input type="text"/>			

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 5-3-23Name (Signature) Tina HarrisCompany ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility AVO Inspection Sheet

SITE INFORMATION

Location Name SEU 2207-20M Permit Number 43018d-5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 10:30 Time Inspection Ended 11:15
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 16.5 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew going in and out of location

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Audio inspection conducted for pressure and liquid leaks	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Olfactory inspection conducted for unusual or strong odor	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 10.5
 Depth to Water in ULD (ft) 10.0
 Height of Water in ULD 0
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Replace tubing for taking measurements.

Name (Print) Tina Harris

Date 5-10-23

Name (Signature) [Signature]

Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility AVO Inspection Sheet

SITE INFORMATION

Location Name SEU 2207-20M Permit Number 4301-16d 5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 9:55 Time Inspection Ended 10:20
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 16 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Audio inspection conducted for pressure and liquid leaks	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Olfactory inspection conducted for unusual or strong odor	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of ULD (ft)	<u>101.0</u>			
Depth to Water in ULD (ft)	<u>701</u>			
Height of Water in ULD	<u>0</u>			
Gallons of Water Removed	<u>0</u>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)	<input type="text"/>			
Depth to Water in LLD (ft)	<input type="text"/>			
Height of Water in LLD	<input type="text"/>			
Gallons of Water Removed	<input type="text"/>			

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 5-17-23Name (Signature) [Signature]Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility AVO Inspection Sheet

SITE INFORMATION

Location Name SEU 2207-20M Permit Number 4301 Pod-5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 1:30 Time Inspection Ended 2:00
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 16.5 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Audio inspection conducted for pressure and liquid leaks	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Olfactory inspection conducted for unusual or strong odor	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of ULD (ft)	<u>101.0</u>			
Depth to Water in ULD (ft)	<u>101.0</u>			
Height of Water in ULD	<u>8</u>			
Gallons of Water Removed	<u>8</u>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)				
Depth to Water in LLD (ft)				
Height of Water in LLD				
Gallons of Water Removed				

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 5-24-23

Name (Signature) [Signature]

Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility AVO Inspection Sheet

SITE INFORMATION

Location Name SEU 2207-20W Permit Number 4301 Rod 5
 Section 20 Township 22 Range 4 County Sandoval State NM
 Time Inspection Began 12:40 Time Inspection Ended 1:10
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 16.5 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew going in and out of location

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Audio inspection conducted for pressure and liquid leaks	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Olfactory inspection conducted for unusual or strong odor	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 101.0
 Depth to Water in ULD (ft) 101.0
 Height of Water in ULD 0
 Gallons of Water Removed 0

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 6-1-23Name (Signature) [Signature]Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility AVO Inspection Sheet

SITE INFORMATION

Location Name SEU 2207-20M Permit Number 4301 Bod 5
 Section 26 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 8:05 Time Inspection Ended 8:35
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 15 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew going in and out of location

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Audio inspection conducted for pressure and liquid leaks	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Olfactory inspection conducted for unusual or strong odor	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 101.0
 Depth to Water in ULD (ft) 101.0
 Height of Water in ULD 8
 Gallons of Water Removed 20

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 6-7-23

Name (Signature) [Signature]

Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility AVO Inspection Sheet

SITE INFORMATION

Location Name SEU 2267-20M Permit Number 4301 Pod-5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 12:00 Time Inspection Ended 12:20
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 16ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew going in and out of location

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Audio Inspection conducted for pressure and liquid leaks	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Olfactory inspection conducted for unusual or strong odor	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of ULD (ft)	<u>101</u>			
Depth to Water in ULD (ft)	<u>101</u>			
Height of Water in ULD	<u>0</u>			
Gallons of Water Removed	<u>0</u>			

Lower Leak Detection (LLD)

Water Present in LLD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)	<input type="text"/>			
Depth to Water in LLD (ft)	<input type="text"/>			
Height of Water in LLD	<input type="text"/>			
Gallons of Water Removed	<input type="text"/>			

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 6-15-23

Name (Signature) [Signature]

Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility AVO Inspection Sheet

SITE INFORMATION

Location Name SEU 2207 20M Permit Number 4301 Bcd5
 Section 20 Township 22 Range 6 County sandoval State NM
 Time Inspection Began 10:35 Time Inspection Ended 11:10
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 16.7

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

Crew going in and out of location

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Audio inspection conducted for pressure and liquid leaks	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Olfactory inspection conducted for unusual or strong odor	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of ULD (ft)	<u>101.7</u>			
Depth to Water in ULD (ft)	<u>101.1</u>			
Height of Water in ULD	<u>0</u>			
Gallons of Water Removed	<u>0</u>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)	<input type="text"/>			
Depth to Water in LLD (ft)	<input type="text"/>			
Height of Water in LLD	<input type="text"/>			
Gallons of Water Removed	<input type="text"/>			

If leak detection contained liquid, was it removed?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 6-21-23

Name (Signature) [Signature]

Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility AVO Inspection Sheet

SITE INFORMATION

Location Name SE4 2207-20M Permit Number 430186d5
 Section 20 Township 22 Range 10 County Sandoval State NM
 Time Inspection Began 11:30 Time Inspection Ended 12:00
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 15 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Audio Inspection conducted for pressure and liquid leaks	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Olfactory inspection conducted for unusual or strong odor	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD? YES ☐ NO ☒
 Total Depth of ULD (ft) 60.0
 Depth to Water in ULD (ft) 101.1
 Height of Water in ULD 0
 Gallons of Water Removed 05

Lower Leak Detection (LLD)

Water Present in ULD? YES ☐ NO ☐
 Total Depth of LLD (ft)
 Depth to Water in LLD (ft)
 Height of Water in LLD
 Gallons of Water Removed

If leak detection contained liquid, was it removed? YES ☐ NO ☐ NA ☒
 If leak detection contained liquid, was HSE notified? YES ☒ NO ☐ NA ☐

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 6-28-23

Name (Signature) [Signature]

Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility AVO Inspection Sheet

SITE INFORMATION

Location Name SE4 2207-20W1 Permit Number 4301 Ref-5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 8:30 Time Inspection Ended 8:50
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 15 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Audio inspection conducted for pressure and liquid leaks	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Olfactory inspection conducted for unusual or strong odor	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of ULD (ft)	<u>101</u>			
Depth to Water in ULD (ft)	<u>101</u>			
Height of Water in ULD	<u>0</u>			
Gallons of Water Removed	<u>0</u>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)	<input type="text"/>			
Depth to Water in LLD (ft)	<input type="text"/>			
Height of Water in LLD	<input type="text"/>			
Gallons of Water Removed	<input type="text"/>			

If leak detection contained liquid, was it removed?	YES	<input checked="" type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 8-6-23Name (Signature) [Signature]Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility AVO Inspection Sheet

SITE INFORMATION

Location Name SELL 2207-20M Permit Number 4301 Pool-5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 10:15 Time Inspection Ended _____
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 15 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Audio inspection conducted for pressure and liquid leaks	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Olfactory inspection conducted for unusual or strong odor	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of ULD (ft)	<u>101.0</u>			
Depth to Water in ULD (ft)	<u>101.0</u>			
Height of Water in ULD	<u>0</u>			
Gallons of Water Removed	<u>0</u>			

Lower Leak Detection (LLD)

Water Present in LLD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)				
Depth to Water in LLD (ft)				
Height of Water in LLD				
Gallons of Water Removed				

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 7-13-23

Name (Signature) [Signature]

Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility AVO Inspection Sheet

SITE INFORMATION

Location Name SFU 2207-20M Permit Number 4301 Pod 5
 Section 20 Township 27 Range 6 County Sandoval State NM
 Time Inspection Began 10:25 Time Inspection Ended 10:50
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 15 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runoff?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Audio inspection conducted for pressure and liquid leaks	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Olfactory inspection conducted for unusual or strong odor	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of ULD (ft)	<u>101.0</u>			
Depth to Water in ULD (ft)	<u>101.0</u>			
Height of Water in ULD	<u>0</u>			
Gallons of Water Removed	<u>0</u>			

Lower Leak Detection (LLD)

Water Present in LLD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)	<input type="text"/>			
Depth to Water in LLD (ft)	<input type="text"/>			
Height of Water in LLD	<input type="text"/>			
Gallons of Water Removed	<input type="text"/>			

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 7-21-23

Name (Signature) [Signature]

Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility AVO Inspection Sheet

SITE INFORMATION

Location Name SEU 2207-20M Permit Number 4301 Pct 5
 Section 20 Township 22 Range 1e County Sandoval State NM
 Time Inspection Began 9:08 Time Inspection Ended 9:25
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 15 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Audio inspection conducted for pressure and liquid leaks	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Olfactory inspection conducted for unusual or strong odor	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of ULD (ft)		<u>101.0</u>		
Depth to Water in ULD (ft)		<u>101.0</u>		
Height of Water in ULD		<u>0</u>		
Gallons of Water Removed		<u>0</u>		

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)				
Depth to Water in LLD (ft)				
Height of Water in LLD				
Gallons of Water Removed				

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina HarrisDate 7-27-23Name (Signature) [Signature]Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility AVO Inspection Sheet

SITE INFORMATION

Location Name SELP 2207 20M Permit Number 43016d5
 Section 20 Township 22 Range 6 County Sandoval State NM
 Time Inspection Began 9:00 Time Inspection Ended 9:20
 Recycling Facility ☐ Recycling Containment ☒ Water Level (Feet) 15 ft

GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Audio inspection conducted for pressure and liquid leaks	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Olfactory inspection conducted for unusual or strong odor	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

Upper Leak Detection (ULD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Total Depth of ULD (ft)	<u>101.0</u>			
Depth to Water in ULD (ft)	<u>101.0</u>			
Height of Water in ULD	<u>0</u>			
Gallons of Water Removed	<input type="checkbox"/>			

Lower Leak Detection (LLD)

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Total Depth of LLD (ft)	<input type="checkbox"/>			
Depth to Water in LLD (ft)	<input type="checkbox"/>			
Height of Water in LLD	<input type="checkbox"/>			
Gallons of Water Removed	<input type="checkbox"/>			

If leak detection contained liquid, was it removed?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

COMMENTS

BIRD MITIGATION SYSTEM

Audio Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Visual Bird Deterrents are present and in working order	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected, and no evidence of bird mortality was found	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found, HSE was notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print) Tina Harris

Date 8-2-23

Name (Signature) [Signature]

Company ENDURING RESOURCES

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 250354

CONDITIONS

Operator: ENDURING RESOURCES, LLC 6300 S Syracuse Way, Suite 525 Centennial, CO 80111	OGRID: 372286
	Action Number: 250354
	Action Type: [C-147] Water Recycle Long (C-147L)

CONDITIONS

Created By	Condition	Condition Date
vvenegas	• 3RF-30 - SEU 2206 - 20M FACILITY ID [FVF1828850052] is approved for one (1) year of operation from the date of the previous registration/permit expiration date of October 18, 2023. The new registration/permit expiration date is October 18, 2024. • If [372286] ENDURING RESOURCES, LLC wishes to extend the registration/permit past October 18, 2024, a registration/permit extension request must be submitted to OCD no later than September 18, 2024. • PLEASE NOTE: 3RF-30 - SEU 2206 - 20M FACILITY ID [FVF1828850052] has an extension of cessation of operations approved from September 1/2023 to March 1/2024. However, if after this 6-month period, the containment was not utilized at a minimum of 20% fluid capacity, no additional extensions would be granted, this annual extension will be revoked, and the operator would be directed to remove all fluids and proceed with the closure requirements.	8/24/2023