

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Department  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-147  
Revised April 3, 2017

## Recycling Facility and/or Recycling Containment

Type of Facility:  Recycling Facility  Recycling Containment\*  
Type of action:  Permit  Registration  
 Modification  Extension  
 Closure  Other (explain) Request for cessation of operations from 11/23 to 4/24

\* At the time C-147 is submitted to the division for a Recycling Containment, a copy shall be provided to the surface owner.

Be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances.

1.  
Operator: Enduring Resources IV, LLC (For multiple operators attach page with information) OGRID #: 372286  
Address: 200 Energy Court, Farmington, New Mexico 87401  
Facility or well name (include API# if associated with a well): WEU 300H Water Recycle Facility / Containment  
OCD Permit Number: #3RF-50 (For new facilities the permit number will be assigned by the district office)  
U/L or Qtr/Qtr A Section 17 Township 22N Range 7W County: Sandoval  
Surface Owner:  Federal  State  Private  Tribal Trust or Indian Allotment

2.  
 **Recycling Facility:**  
Location of recycling facility (if applicable): Latitude 36.143847 Longitude -107.589762 NAD83  
Proposed Use:  Drilling\*  Completion\*  Production\*  Plugging \*  
*\*The re-use of produced water may NOT be used until fresh water zones are cased and cemented*  
 Other, *requires permit for other uses. Describe use, process, testing, volume of produced water and ensure there will be no adverse impact on groundwater or surface water.*  
 Fluid Storage  
 Above ground tanks  Recycling containment  Activity permitted under 19.15.17 NMAC explain type \_\_\_\_\_  
 Activity permitted under 19.15.36 NMAC explain type: \_\_\_\_\_  Other explain \_\_\_\_\_  
 For multiple or additional recycling containments, attach design and location information of each containment  
 **Closure Report (required within 60 days of closure completion):**  Recycling Facility Closure Completion Date: \_\_\_\_\_

3.  
 **Recycling Containment:**  
 Annual Extension after initial 5 years (attach summary of monthly leak detection inspections for previous year)  
Center of Recycling Containment (if applicable): Latitude 36.143847 Longitude -107.589762 NAD83  
 For multiple or additional recycling containments, attach design and location information of each containment  
 Lined  Liner type: Thickness 45 mil  LLDPE  HDPE  PVC  Other Secondary Liner - 30 mil  
 String-Reinforced  
Liner Seams:  Welded  Factory  Other \_\_\_\_\_ Volume: 50K & 60K bbl Dimensions: see tank attachment  
 Recycling Containment Closure Completion Date: \_\_\_\_\_

4.

**Bonding:**

Covered under bonding pursuant to 19.15.8 NMAC per 19.15.34.15(A)(2) NMAC (These containments are limited to only the wells owned or operated by the owners of the containment.)

Bonding in accordance with 19.15.34.15(A)(1). Amount of bond \$ \_\_\_\_\_ (work on these facilities cannot commence until bonding amounts are approved)

Attach closure cost estimate and documentation on how the closure cost was calculated.

5.

**Fencing:**

Four foot height, four strands of barbed wire evenly spaced between one and four feet

Alternate. Please specify \_\_\_\_\_

6.

**Signs:**

12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers

Signed in compliance with 19.15.16.8 NMAC

7.

**Variances:**

Justifications and/or demonstrations that the proposed variance will afford reasonable protection against contamination of fresh water, human health, and the environment.

**Check the below box only if a variance is requested:**

Variance(s): Requests must be submitted to the appropriate division district for consideration of approval. If a Variance is requested, include the variance information on a separate page and attach it to the C-147 as part of the application.

**If a Variance is requested, it must be approved prior to implementation.**

8.

**Siting Criteria for Recycling Containment**

*Instructions: The applicant must provide attachments that demonstrate compliance for each siting criteria below as part of the application. Potential examples of the siting attachment source material are provided below under each criteria.*

<b>General siting</b>	
<b>Ground water is less than 50 feet below the bottom of the Recycling Containment.</b> NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> NA
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended. - Written confirmation or verification from the municipality; written approval obtained from the municipality	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> NA
Within the area overlying a subsurface mine. - Written confirmation or verification or map from the NM EMNRD-Mining and Minerals Division	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Within an unstable area. - Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; topographic map	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Within a 100-year floodplain. FEMA map	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; visual inspection (certification) of the proposed site	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. - Visual inspection (certification) of the proposed site; aerial photo; satellite image	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application. - NM Office of the State Engineer - iWATERS database search; visual inspection (certification) of the proposed site	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Within 500 feet of a wetland. - US Fish and Wildlife Wetland Identification map; topographic map; visual inspection (certification) of the proposed site	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No

9.

**Recycling Facility and/or Containment Checklist:**

**Instructions:** Each of the following items must be attached to the application. Indicate, by a check mark in the box, that the documents are attached.

- Design Plan - based upon the appropriate requirements.
- Operating and Maintenance Plan - based upon the appropriate requirements.
- Closure Plan - based upon the appropriate requirements.
- Site Specific Groundwater Data -
- Siting Criteria Compliance Demonstrations -
- Certify that notice of the C-147 (only) has been sent to the surface owner(s)

10.

**Operator Application Certification:**

I hereby certify that the information and attachments submitted with this application are true, accurate and complete to the best of my knowledge and belief.

Name (Print): Heather Huntington Title: Permitting Technician  
 Signature:  Date: 10/6/2023  
 e-mail address: hhuntington@enduringresources.com Telephone: (970) 749-0124

11.

OCD Representative Signature: Victoria Venegas Approval Date: 10/13/2023

Title: Environmental Specialist OCD Permit Number: 3RF-50

- OCD Conditions
- Additional OCD Conditions on Attachment



## Enduring Resources, LLC AST Recycling Facility Inspection Sheet

### SITE INFORMATION

Location Name	WEU #300H 50K	Permit Number	3RF-50
Section	17 Township 22N	Range 7W	County SANDAVOL State <u>NM</u>
Time Inspection Began	13:10	Time Inspection Ended	13:15
Recycling Facility	<input checked="" type="checkbox"/>	Recycling Containment	<input checked="" type="checkbox"/> Water Level (Feet) <span style="float: right;"><input type="text" value="8"/></span>

### GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

### INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

#### Leak Detection

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	
Total Depth of ULD (ft)		<input type="text"/>			
Depth to Water in ULD (ft)		<input type="text"/>			
Height of Water in ULD		<input type="text"/>			
Gallons of Water Removed		<input type="text"/>			<i>COMMENTS</i>
If leak detection contained liquid, was it removed	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA <input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA <input checked="" type="checkbox"/>
If leak detection contained liquid was it analyzed for conductance to determine origin Produced Water or condensation	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA <input checked="" type="checkbox"/>
<i>COMMENTS</i>					

### BIRD MITIGATION SYSTEM

Is Bird netting in good condition and completely covers AST?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected and no evidence of bird mortality was found?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
* If evidence of bird mortality was found, NMOCD must be notified by HSE						
<i>COMMENTS</i>						

Name (Print)	Klint Gideon	Date	4/5/2023
Name (Signature)	<i>Klint Gideon</i>	Company	<u>ENDURING RESOURCES</u>



## Enduring Resources, LLC AST Recycling Facility Inspection Sheet

### SITE INFORMATION

Location Name	WEU #300H 50K	Permit Number	3RF-50
Section	17 Township 22N	Range 7W	County SANDAVOL State <u>NM</u>
Time Inspection Began	13:10	Time Inspection Ended	13:15
Recycling Facility	<input checked="" type="checkbox"/>	Recycling Containment	<input checked="" type="checkbox"/>
		Water Level (Feet)	<input type="text" value="8"/>

### GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

*AST Set Anchor Fluid*

### INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawl of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

#### Leak Detection

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	
Total Depth of ULD (ft)		<input type="text"/>			COMMENTS
Depth to Water in ULD (ft)		<input type="text"/>			
Height of Water in ULD		<input type="text"/>			
Gallons of Water Removed		<input type="text"/>			

If leak detection contained liquid, was it removed	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid was it analyzed for conductance to determine origin Produced Water or condensation	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

*COMMENTS*

### BIRD MITIGATION SYSTEM

Is Bird netting in good condition and completely covers AST?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected and no evidence of bird mortality was found?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

\* If evidence of bird mortality was found, NMOCD must be notified by HSE

*COMMENTS*

Name (Print)	Richard Rogers	Date	4/12/2023
Name (Signature)	<i>Richard Rogers</i>	Company	<u>ENDURING RESOURCES</u>



## Enduring Resources, LLC AST Recycling Facility Inspection Sheet

### SITE INFORMATION

Location Name	WEU #300H 50K	Permit Number	3RF-50
Section	17 Township 22N	Range 7W	County SANDAVOL State <u>NM</u>
Time Inspection Began	13:10	Time Inspection Ended	13:15
Recycling Facility	<input checked="" type="checkbox"/>	Recycling Containment	<input checked="" type="checkbox"/>
		Water Level (Feet)	<input type="text" value="8"/>

### GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

*AST Set Anchor Fluid*

### INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawl of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

#### Leak Detection

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	
Total Depth of ULD (ft)		<input type="text"/>			COMMENTS
Depth to Water in ULD (ft)		<input type="text"/>			
Height of Water in ULD		<input type="text"/>			
Gallons of Water Removed		<input type="text"/>			

If leak detection contained liquid, was it removed	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid was it analyzed for conductance to determine origin Produced Water or condensation	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

*COMMENTS*

### BIRD MITIGATION SYSTEM

Is Bird netting in good condition and completely covers AST?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected and no evidence of bird mortality was found?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

\* If evidence of bird mortality was found, NMOCD must be notified by HSE

*COMMENTS*

Name (Print)	Richard Rogers	Date	4/19/2023
Name (Signature)	<i>Richard Rogers</i>	Company	<u>ENDURING RESOURCES</u>



## Enduring Resources, LLC AST Recycling Facility Inspection Sheet

### SITE INFORMATION

Location Name	WEU #300H 50K	Permit Number	3RF-50
Section	17 Township 22N	Range 7W	County SANDAVOL State <u>NM</u>
Time Inspection Began	13:10	Time Inspection Ended	13:15
Recycling Facility	<input checked="" type="checkbox"/>	Recycling Containment	<input checked="" type="checkbox"/>
		Water Level (Feet)	<input type="text" value="7"/>

### GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

*AST Set Anchor Fluid*

### INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawl of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

#### Leak Detection

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	
Total Depth of ULD (ft)		<input type="text"/>			
Depth to Water in ULD (ft)		<input type="text"/>			
Height of Water in ULD		<input type="text"/>			
Gallons of Water Removed		<input type="text"/>			<i>COMMENTS</i>

If leak detection contained liquid, was it removed	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid was it analyzed for conductance to determine origin Produced Water or condensation	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

*COMMENTS*

### BIRD MITIGATION SYSTEM

Is Bird netting in good condition and completely covers AST?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected and no evidence of bird mortality was found?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

\* If evidence of bird mortality was found, NMOCD must be notified by HSE

*COMMENTS*

Name (Print)	Klint Gideon	Date	4/26/2023
Name (Signature)	<i>Klint Gideon</i>	Company	<u>ENDURING RESOURCES</u>



## Enduring Resources, LLC AST Recycling Facility Inspection Sheet

### SITE INFORMATION

Location Name	WEU #300H 50K	Permit Number	3RF-50
Section	17 Township 22N	Range 7W	County SANDAVOL State <u>NM</u>
Time Inspection Began	13:10	Time Inspection Ended	13:15
Recycling Facility	<input checked="" type="checkbox"/>	Recycling Containment	<input checked="" type="checkbox"/>
		Water Level (Feet)	<input type="text" value="5"/>

### GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

AST Set Anchor Fluid

### INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawl of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

#### Leak Detection

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	
Total Depth of ULD (ft)		<input type="text"/>			
Depth to Water in ULD (ft)		<input type="text"/>			
Height of Water in ULD		<input type="text"/>			
Gallons of Water Removed		<input type="text"/>			<i>COMMENTS</i>

If leak detection contained liquid, was it removed	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid was it analyzed for conductance to determine origin Produced Water or condensation	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

### BIRD MITIGATION SYSTEM

Is Bird netting in good condition and completely covers AST?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected and no evidence of bird mortality was found?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

\* If evidence of bird mortality was found, NMOCD must be notified by HSE

COMMENTS

Name (Print)	Klint Gideon	Date	5/3/2023
Name (Signature)	<i>Klint Gideon</i>	Company	<u>ENDURING RESOURCES</u>



## Enduring Resources, LLC AST Recycling Facility Inspection Sheet

### SITE INFORMATION

Location Name	WEU #300H 50K	Permit Number	3RF-50
Section	17 Township 22N	Range 7W	County SANDAVOL State <u>NM</u>
Time Inspection Began	13:10	Time Inspection Ended	13:15
Recycling Facility	<input checked="" type="checkbox"/>	Recycling Containment	<input checked="" type="checkbox"/>
		Water Level (Feet)	<input type="text" value="3"/>

### GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

### INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

#### Leak Detection

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	
Total Depth of ULD (ft)		<input type="text"/>			
Depth to Water in ULD (ft)		<input type="text"/>			
Height of Water in ULD		<input type="text"/>			
Gallons of Water Removed		<input type="text"/>			<small>COMMENTS</small>

If leak detection contained liquid, was it removed	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid was it analyzed for conductance to determine origin Produced Water or condensation	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

### BIRD MITIGATION SYSTEM

Is Bird netting in good condition and completely covers AST?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected and no evidence of bird mortality was found?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

Name (Print)	Richard Rogers	Date	5/10/2023
Name (Signature)	<i>Richard Rogers</i>	Company	<u>ENDURING RESOURCES</u>



## Enduring Resources, LLC AST Recycling Facility Inspection Sheet

### SITE INFORMATION

Location Name	WEU #300H 50K	Permit Number	3RF-50
Section	17 Township 22N	Range 7W	County SANDAVOL State <u>NM</u>
Time Inspection Began	13:10	Time Inspection Ended	13:15
Recycling Facility	<input checked="" type="checkbox"/>	Recycling Containment	<input checked="" type="checkbox"/>
		Water Level (Feet)	<input type="text" value="3"/>

### GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

### INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

#### Leak Detection

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>		
Total Depth of ULD (ft)	<input type="text"/>					
Depth to Water in ULD (ft)	<input type="text"/>					
Height of Water in ULD	<input type="text"/>					
Gallons of Water Removed	<input type="text"/>					
<i>COMMENTS</i>						
If leak detection contained liquid, was it removed	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid was it analyzed for conductance to determine origin Produced Water or condensation	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

*COMMENTS*

### BIRD MITIGATION SYSTEM

Is Bird netting in good condition and completely covers AST?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected and no evidence of bird mortality was found?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

\* If evidence of bird mortality was found, NMOCD must be notified by HSE

*COMMENTS*

Name (Print)	Richard Rogers	Date	5/17/2023
Name (Signature)	<i>Richard Rogers</i>	Company	<u>ENDURING RESOURCES</u>



## Enduring Resources, LLC AST Recycling Facility Inspection Sheet

### SITE INFORMATION

Location Name	WEU #300H 50K	Permit Number	3RF-50
Section	17 Township 22N	Range 7W	County SANDAVOL State <u>NM</u>
Time Inspection Began	13:10	Time Inspection Ended	13:15
Recycling Facility	<input checked="" type="checkbox"/>	Recycling Containment	<input checked="" type="checkbox"/>
		Water Level (Feet)	<input type="text" value="3"/>

### GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

### INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

#### Leak Detection

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	
Total Depth of ULD (ft)	<input type="text"/>				
Depth to Water in ULD (ft)	<input type="text"/>				
Height of Water in ULD	<input type="text"/>				
Gallons of Water Removed	<input type="text"/>				
<i>COMMENTS</i>					

If leak detection contained liquid, was it removed	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid was it analyzed for conductance to determine origin Produced Water or condensation	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

*COMMENTS*

### BIRD MITIGATION SYSTEM

Is Bird netting in good condition and completely covers AST?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected and no evidence of bird mortality was found?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

\* If evidence of bird mortality was found, NMOCD must be notified by HSE

*COMMENTS*

Name (Print)	Klint Gideon	Date	5/24/2023
Name (Signature)	<i>Klint Gideon</i>	Company	<u>ENDURING RESOURCES</u>



## Enduring Resources, LLC AST Recycling Facility Inspection Sheet

### SITE INFORMATION

Location Name	WEU #300H 50K	Permit Number	3RF-50
Section	17 Township 22N	Range 7W	County SANDAVOL State <u>NM</u>
Time Inspection Began	13:10	Time Inspection Ended	13:15
Recycling Facility	<input checked="" type="checkbox"/>	Recycling Containment	<input checked="" type="checkbox"/>
		Water Level (Feet)	<input type="text" value="3"/>

### GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

### INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

#### Leak Detection

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	
Total Depth of ULD (ft)		<input type="text"/>			
Depth to Water in ULD (ft)		<input type="text"/>			
Height of Water in ULD		<input type="text"/>			
Gallons of Water Removed		<input type="text"/>			<small>COMMENTS</small>

If leak detection contained liquid, was it removed	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid was it analyzed for conductance to determine origin Produced Water or condensation	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

### BIRD MITIGATION SYSTEM

Is Bird netting in good condition and completely covers AST?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected and no evidence of bird mortality was found?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

\* If evidence of bird mortality was found, NMOCD must be notified by HSE

COMMENTS

Name (Print)	Klint Gideon	Date	5/31/2023
Name (Signature)	<i>Klint Gideon</i>	Company	<u>ENDURING RESOURCES</u>



## Enduring Resources, LLC AST Recycling Facility Inspection Sheet

### SITE INFORMATION

Location Name	WEU #300H 50K	Permit Number	3RF-50
Section	17 Township 22N	Range 7W	County SANDAVOL State <u>NM</u>
Time Inspection Began	13:10	Time Inspection Ended	13:15
Recycling Facility	<input checked="" type="checkbox"/>	Recycling Containment	<input checked="" type="checkbox"/>
		Water Level (Feet)	<input type="text" value="3"/>

### GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

### INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

#### Leak Detection

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	
Total Depth of ULD (ft)	<input type="text"/>				
Depth to Water in ULD (ft)	<input type="text"/>				
Height of Water in ULD	<input type="text"/>				
Gallons of Water Removed	<input type="text"/>				
<i>COMMENTS</i>					

If leak detection contained liquid, was it removed	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid was it analyzed for conductance to determine origin Produced Water or condensation	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

*COMMENTS*

### BIRD MITIGATION SYSTEM

Is Bird netting in good condition and completely covers AST?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected and no evidence of bird mortality was found?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

\* If evidence of bird mortality was found, NMOCD must be notified by HSE

*COMMENTS*

Name (Print)	Richard Rogers	Date	6/7/2023
Name (Signature)	<i>Richard Rogers</i>	Company	<u>ENDURING RESOURCES</u>



## Enduring Resources, LLC AST Recycling Facility Inspection Sheet

### SITE INFORMATION

Location Name	WEU #300H 50K	Permit Number	3RF-50
Section	17 Township 22N	Range 7W	County SANDAVOL State <u>NM</u>
Time Inspection Began	13:10	Time Inspection Ended	13:15
Recycling Facility	<input checked="" type="checkbox"/>	Recycling Containment	<input checked="" type="checkbox"/>
		Water Level (Feet)	<input type="text" value="3"/>

### GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

### INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

#### Leak Detection

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	
Total Depth of ULD (ft)		<input type="text"/>			
Depth to Water in ULD (ft)		<input type="text"/>			
Height of Water in ULD		<input type="text"/>			
Gallons of Water Removed		<input type="text"/>			<i>COMMENTS</i>

If leak detection contained liquid, was it removed	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid was it analyzed for conductance to determine origin Produced Water or condensation	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

*COMMENTS*

### BIRD MITIGATION SYSTEM

Is Bird netting in good condition and completely covers AST?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected and no evidence of bird mortality was found?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

\* If evidence of bird mortality was found, NMOCD must be notified by HSE

*COMMENTS*

Name (Print)	Richard Rogers	Date	6/14/2023
Name (Signature)	<i>Richard Rogers</i>	Company	<u>ENDURING RESOURCES</u>



## Enduring Resources, LLC AST Recycling Facility Inspection Sheet

### SITE INFORMATION

Location Name	WEU #300H 50K	Permit Number	3RF-50
Section	17 Township 22N	Range 7W	County SANDAVOL State <u>NM</u>
Time Inspection Began	13:10	Time Inspection Ended	13:15
Recycling Facility	<input checked="" type="checkbox"/>	Recycling Containment	<input checked="" type="checkbox"/>
		Water Level (Feet)	<input type="text" value="3"/>

### GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

### INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

#### Leak Detection

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	
Total Depth of ULD (ft)		<input type="text"/>			
Depth to Water in ULD (ft)		<input type="text"/>			
Height of Water in ULD		<input type="text"/>			
Gallons of Water Removed		<input type="text"/>			<i>COMMENTS</i>

If leak detection contained liquid, was it removed	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid was it analyzed for conductance to determine origin Produced Water or condensation	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

*COMMENTS*

### BIRD MITIGATION SYSTEM

Is Bird netting in good condition and completely covers AST?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected and no evidence of bird mortality was found?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

\* If evidence of bird mortality was found, NMOCD must be notified by HSE

*COMMENTS*

Name (Print)	Klint Gideon	Date	6/21/2023
Name (Signature)	<i>Klint Gideon</i>	Company	<u>ENDURING RESOURCES</u>



## Enduring Resources, LLC AST Recycling Facility Inspection Sheet

### SITE INFORMATION

Location Name	WEU #300H 50K	Permit Number	3RF-50
Section	17 Township 22N	Range 7W	County SANDAVOL State <u>NM</u>
Time Inspection Began	13:10	Time Inspection Ended	13:15
Recycling Facility	<input checked="" type="checkbox"/>	Recycling Containment	<input checked="" type="checkbox"/>
		Water Level (Feet)	<input type="text" value="3"/>

### GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

### INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

#### Leak Detection

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	
Total Depth of ULD (ft)		<input type="text"/>			
Depth to Water in ULD (ft)		<input type="text"/>			
Height of Water in ULD		<input type="text"/>			
Gallons of Water Removed		<input type="text"/>			<small>COMMENTS</small>

If leak detection contained liquid, was it removed	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid was it analyzed for conductance to determine origin Produced Water or condensation	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

### BIRD MITIGATION SYSTEM

Is Bird netting in good condition and completely covers AST?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected and no evidence of bird mortality was found?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

\* If evidence of bird mortality was found, NMOCD must be notified by HSE

COMMENTS

Name (Print)	Klint Gideon	Date	6/28/2023
Name (Signature)	<i>Klint Gideon</i>	Company	<u>ENDURING RESOURCES</u>



## Enduring Resources, LLC AST Recycling Facility Inspection Sheet

### SITE INFORMATION

Location Name	WEU #300H 50K	Permit Number	3RF-50
Section	17 Township 22N	Range 7W	County SANDAVOL State <u>NM</u>
Time Inspection Began	13:10	Time Inspection Ended	13:15
Recycling Facility	<input checked="" type="checkbox"/>	Recycling Containment	<input checked="" type="checkbox"/>
		Water Level (Feet)	<input type="text" value="3"/>

### GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

### INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

#### Leak Detection

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	
Total Depth of ULD (ft)		<input type="text"/>			
Depth to Water in ULD (ft)		<input type="text"/>			
Height of Water in ULD		<input type="text"/>			
Gallons of Water Removed		<input type="text"/>			<i>COMMENTS</i>

If leak detection contained liquid, was it removed	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid was it analyzed for conductance to determine origin Produced Water or condensation	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

*COMMENTS*

### BIRD MITIGATION SYSTEM

Is Bird netting in good condition and completely covers AST?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected and no evidence of bird mortality was found?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

\* If evidence of bird mortality was found, NMOCD must be notified by HSE

*COMMENTS*

Name (Print)	Richard Rogers	Date	7/5/2023
Name (Signature)	<i>Richard Rogers</i>	Company	<u>ENDURING RESOURCES</u>



## Enduring Resources, LLC AST Recycling Facility Inspection Sheet

### SITE INFORMATION

Location Name	WEU #300H 50K	Permit Number	3RF-50
Section	17 Township 22N	Range 7W	County SANDAVOL State <u>NM</u>
Time Inspection Began	13:10	Time Inspection Ended	13:15
Recycling Facility	<input checked="" type="checkbox"/>	Recycling Containment	<input checked="" type="checkbox"/>
		Water Level (Feet)	<input type="text" value="3"/>

### GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

### INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

#### Leak Detection

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	
Total Depth of ULD (ft)	<input type="text"/>				
Depth to Water in ULD (ft)	<input type="text"/>				
Height of Water in ULD	<input type="text"/>				
Gallons of Water Removed	<input type="text"/>				
<i>COMMENTS</i>					
If leak detection contained liquid, was it removed	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA <input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA <input checked="" type="checkbox"/>
If leak detection contained liquid was it analyzed for conductance to determine origin Produced Water or condensation	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA <input checked="" type="checkbox"/>

*COMMENTS*

### BIRD MITIGATION SYSTEM

Is Bird netting in good condition and completely covers AST?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected and no evidence of bird mortality was found?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

\* If evidence of bird mortality was found, NMOCD must be notified by HSE

*COMMENTS*

Name (Print)	Richard Rogers	Date	7/12/2023
Name (Signature)	<i>Richard Rogers</i>	Company	<u>ENDURING RESOURCES</u>



## Enduring Resources, LLC AST Recycling Facility Inspection Sheet

### SITE INFORMATION

Location Name	WEU #300H 50K	Permit Number	3RF-50
Section	17 Township 22N	Range 7W	County SANDAVOL State <u>NM</u>
Time Inspection Began	13:10	Time Inspection Ended	13:15
Recycling Facility	<input checked="" type="checkbox"/>	Recycling Containment	<input checked="" type="checkbox"/>
		Water Level (Feet)	<input type="text" value="3"/>

### GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

### INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

#### Leak Detection

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>		
Total Depth of ULD (ft)	<input type="text"/>					
Depth to Water in ULD (ft)	<input type="text"/>					
Height of Water in ULD	<input type="text"/>					
Gallons of Water Removed	<input type="text"/>					
<i>COMMENTS</i>						
If leak detection contained liquid, was it removed	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid was it analyzed for conductance to determine origin Produced Water or condensation	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
<i>COMMENTS</i>						

### BIRD MITIGATION SYSTEM

Is Bird netting in good condition and completely covers AST?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected and no evidence of bird mortality was found?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
* If evidence of bird mortality was found, NMOCD must be notified by HSE						
<i>COMMENTS</i>						

Name (Print)	Klint Gideon	Date	7/19/2023
Name (Signature)	<i>Klint Gideon</i>	Company	<u>ENDURING RESOURCES</u>



## Enduring Resources, LLC AST Recycling Facility Inspection Sheet

### SITE INFORMATION

Location Name	WEU #300H 50K	Permit Number	3RF-50
Section	17 Township 22N	Range 7W	County SANDAVOL State <u>NM</u>
Time Inspection Began	13:10	Time Inspection Ended	13:15
Recycling Facility	<input checked="" type="checkbox"/>	Recycling Containment	<input checked="" type="checkbox"/>
		Water Level (Feet)	<input type="text" value="3"/>

### GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

### INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

#### Leak Detection

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	
Total Depth of ULD (ft)		<input type="text"/>			
Depth to Water in ULD (ft)		<input type="text"/>			
Height of Water in ULD		<input type="text"/>			
Gallons of Water Removed		<input type="text"/>			<small>COMMENTS</small>

If leak detection contained liquid, was it removed	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid was it analyzed for conductance to determine origin Produced Water or condensation	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

### BIRD MITIGATION SYSTEM

Is Bird netting in good condition and completely covers AST?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected and no evidence of bird mortality was found?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

\* If evidence of bird mortality was found, NMOCD must be notified by HSE

COMMENTS

Name (Print)	Klint Gideon	Date	7/26/2023
Name (Signature)	<i>Klint Gideon</i>	Company	<u>ENDURING RESOURCES</u>



## Enduring Resources, LLC AST Recycling Facility Inspection Sheet

### SITE INFORMATION

Location Name	WEU #300H 50K	Permit Number	3RF-50
Section	17 Township 22N	Range 7W	County SANDAVOL State <u>NM</u>
Time Inspection Began	13:10	Time Inspection Ended	13:15
Recycling Facility	<input checked="" type="checkbox"/>	Recycling Containment	<input checked="" type="checkbox"/>
		Water Level (Feet)	<input type="text" value="3"/>

### GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

### INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

#### Leak Detection

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>		
Total Depth of ULD (ft)						
Depth to Water in ULD (ft)						
Height of Water in ULD						
Gallons of Water Removed				<i>COMMENTS</i>		
If leak detection contained liquid, was it removed	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid was it analyzed for conductance to determine origin Produced Water or condensation	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

*COMMENTS*

### BIRD MITIGATION SYSTEM

Is Bird netting in good condition and completely covers AST?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected and no evidence of bird mortality was found?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

\* If evidence of bird mortality was found, NMOCD must be notified by HSE

*COMMENTS*

Name (Print)	Richard Rogers	Date	8/2/2023
Name (Signature)	<i>Richard Rogers</i>	Company	<u>ENDURING RESOURCES</u>



## Enduring Resources, LLC AST Recycling Facility Inspection Sheet

### SITE INFORMATION

Location Name	WEU #300H 50K	Permit Number	3RF-50
Section	17 Township 22N	Range 7W	County SANDAVOL State <u>NM</u>
Time Inspection Began	13:10	Time Inspection Ended	13:15
Recycling Facility	<input checked="" type="checkbox"/>	Recycling Containment	<input checked="" type="checkbox"/>
		Water Level (Feet)	<input type="text" value="3"/>

### GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

### INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

#### Leak Detection

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	
Total Depth of ULD (ft)		<input type="text"/>			
Depth to Water in ULD (ft)		<input type="text"/>			
Height of Water in ULD		<input type="text"/>			
Gallons of Water Removed		<input type="text"/>			<i>COMMENTS</i>

If leak detection contained liquid, was it removed	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid was it analyzed for conductance to determine origin Produced Water or condensation	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

*COMMENTS*

### BIRD MITIGATION SYSTEM

Is Bird netting in good condition and completely covers AST?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected and no evidence of bird mortality was found?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

\* If evidence of bird mortality was found, NMOCD must be notified by HSE

*COMMENTS*

Name (Print)	Richard Rogers	Date	8/9/2023
Name (Signature)	<i>Richard Rogers</i>	Company	<u>ENDURING RESOURCES</u>



## Enduring Resources, LLC AST Recycling Facility Inspection Sheet

### SITE INFORMATION

Location Name	WEU #300H 50K	Permit Number	3RF-50
Section	17 Township 22N	Range 7W	County SANDAVOL State <u>NM</u>
Time Inspection Began	13:10	Time Inspection Ended	13:15
Recycling Facility	<input checked="" type="checkbox"/>	Recycling Containment	<input checked="" type="checkbox"/>
		Water Level (Feet)	<input type="text" value="3"/>

### GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

### INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

#### Leak Detection

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	
Total Depth of ULD (ft)		<input type="text"/>			
Depth to Water in ULD (ft)		<input type="text"/>			
Height of Water in ULD		<input type="text"/>			
Gallons of Water Removed		<input type="text"/>			<i>COMMENTS</i>

If leak detection contained liquid, was it removed	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid was it analyzed for conductance to determine origin Produced Water or condensation	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

*COMMENTS*

### BIRD MITIGATION SYSTEM

Is Bird netting in good condition and completely covers AST?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected and no evidence of bird mortality was found?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

\* If evidence of bird mortality was found, NMOCD must be notified by HSE

*COMMENTS*

Name (Print)	Klint Gideon	Date	8/16/2023
Name (Signature)	<i>Klint Gideon</i>	Company	<u>ENDURING RESOURCES</u>



## Enduring Resources, LLC AST Recycling Facility Inspection Sheet

### SITE INFORMATION

Location Name	WEU #300H 50K	Permit Number	3RF-50
Section	17 Township 22N	Range 7W	County SANDAVOL State <u>NM</u>
Time Inspection Began	13:10	Time Inspection Ended	13:15
Recycling Facility	<input checked="" type="checkbox"/>	Recycling Containment	<input checked="" type="checkbox"/>
		Water Level (Feet)	<input type="text" value="3"/>

### GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

### INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

#### Leak Detection

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	
Total Depth of ULD (ft)	<input type="text"/>				
Depth to Water in ULD (ft)	<input type="text"/>				
Height of Water in ULD	<input type="text"/>				
Gallons of Water Removed	<input type="text"/>				

COMMENTS

If leak detection contained liquid, was it removed	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid was it analyzed for conductance to determine origin Produced Water or condensation	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

### BIRD MITIGATION SYSTEM

Is Bird netting in good condition and completely covers AST?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected and no evidence of bird mortality was found?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

\* If evidence of bird mortality was found, NMOCD must be notified by HSE

COMMENTS

Name (Print)	Klint Gideon	Date	8/23/2023
Name (Signature)	<i>Klint Gideon</i>	Company	<u>ENDURING RESOURCES</u>



## Enduring Resources, LLC AST Recycling Facility Inspection Sheet

### SITE INFORMATION

Location Name	WEU #300H 50K	Permit Number	3RF-50
Section	17 Township 22N	Range 7W	County SANDAVOL State <u>NM</u>
Time Inspection Began	13:10	Time Inspection Ended	13:15
Recycling Facility	<input checked="" type="checkbox"/>	Recycling Containment	<input checked="" type="checkbox"/>
		Water Level (Feet)	<input type="text" value="3"/>

### GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

### INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

#### Leak Detection

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	
Total Depth of ULD (ft)		<input type="text"/>			
Depth to Water in ULD (ft)		<input type="text"/>			
Height of Water in ULD		<input type="text"/>			
Gallons of Water Removed		<input type="text"/>			<i>COMMENTS</i>
If leak detection contained liquid, was it removed	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA <input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA <input checked="" type="checkbox"/>
If leak detection contained liquid was it analyzed for conductance to determine origin Produced Water or condensation	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA <input checked="" type="checkbox"/>

*COMMENTS*

### BIRD MITIGATION SYSTEM

Is Bird netting in good condition and completely covers AST?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected and no evidence of bird mortality was found?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

\* If evidence of bird mortality was found, NMOCD must be notified by HSE

*COMMENTS*

Name (Print)	Richard Rogers	Date	8/30/2023
Name (Signature)	<i>Richard Rogers</i>	Company	<u>ENDURING RESOURCES</u>



## Enduring Resources, LLC AST Recycling Facility Inspection Sheet

### SITE INFORMATION

Location Name	WEU #300H 50K	Permit Number	3RF-50
Section	17 Township 22N	Range 7W	County SANDAVOL State <u>NM</u>
Time Inspection Began	13:10	Time Inspection Ended	13:15
Recycling Facility	<input checked="" type="checkbox"/>	Recycling Containment	<input checked="" type="checkbox"/>
		Water Level (Feet)	<input type="text" value="3"/>

### GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

### INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

#### Leak Detection

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	
Total Depth of ULD (ft)		<input type="text"/>			
Depth to Water in ULD (ft)		<input type="text"/>			
Height of Water in ULD		<input type="text"/>			
Gallons of Water Removed		<input type="text"/>			<small>COMMENTS</small>

If leak detection contained liquid, was it removed	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid was it analyzed for conductance to determine origin Produced Water or condensation	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

COMMENTS

### BIRD MITIGATION SYSTEM

Is Bird netting in good condition and completely covers AST?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected and no evidence of bird mortality was found?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

\* If evidence of bird mortality was found, NMOCD must be notified by HSE

COMMENTS

Name (Print)	Klint Gideon	Date	9/6/2023
Name (Signature)	<i>Klint Gideon</i>	Company	<u>ENDURING RESOURCES</u>



## Enduring Resources, LLC AST Recycling Facility Inspection Sheet

### SITE INFORMATION

Location Name	WEU #300H 50K	Permit Number	3RF-50
Section	17 Township 22N	Range 7W	County SANDAVOL State <u>NM</u>
Time Inspection Began	13:10	Time Inspection Ended	13:15
Recycling Facility	<input checked="" type="checkbox"/>	Recycling Containment	<input checked="" type="checkbox"/>
		Water Level (Feet)	<input type="text" value="3"/>

### GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

### INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

#### Leak Detection

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	
Total Depth of ULD (ft)		<input type="text"/>			
Depth to Water in ULD (ft)		<input type="text"/>			
Height of Water in ULD		<input type="text"/>			
Gallons of Water Removed		<input type="text"/>			<i>COMMENTS</i>

If leak detection contained liquid, was it removed	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid was it analyzed for conductance to determine origin Produced Water or condensation	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

*COMMENTS*

### BIRD MITIGATION SYSTEM

Is Bird netting in good condition and completely covers AST?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected and no evidence of bird mortality was found?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

\* If evidence of bird mortality was found, NMOCD must be notified by HSE

*COMMENTS*

Name (Print)	Klint Gideon	Date	9/13/2023
Name (Signature)	<i>Klint Gideon</i>	Company	<u>ENDURING RESOURCES</u>



## Enduring Resources, LLC AST Recycling Facility Inspection Sheet

### SITE INFORMATION

Location Name	WEU #300H 50K	Permit Number	3RF-50
Section	17 Township 22N	Range 7W	County SANDAVOL State <u>NM</u>
Time Inspection Began	13:10	Time Inspection Ended	13:15
Recycling Facility	<input checked="" type="checkbox"/>	Recycling Containment	<input checked="" type="checkbox"/>
		Water Level (Feet)	<input type="text" value="3"/>

### GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

### INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

#### Leak Detection

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	
Total Depth of ULD (ft)		<input type="text"/>			
Depth to Water in ULD (ft)		<input type="text"/>			
Height of Water in ULD		<input type="text"/>			
Gallons of Water Removed		<input type="text"/>			<i>COMMENTS</i>
If leak detection contained liquid, was it removed	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA <input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA <input checked="" type="checkbox"/>
If leak detection contained liquid was it analyzed for conductance to determine origin Produced Water or condensation	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA <input checked="" type="checkbox"/>
<i>COMMENTS</i>					

### BIRD MITIGATION SYSTEM

Is Bird netting in good condition and completely covers AST?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected and no evidence of bird mortality was found?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
* If evidence of bird mortality was found, NMOCD must be notified by HSE						
<i>COMMENTS</i>						

Name (Print)	Klint Gideon	Date	9/20/2023
Name (Signature)	<i>Klint Gideon</i>	Company	<u>ENDURING RESOURCES</u>



## Enduring Resources, LLC AST Recycling Facility Inspection Sheet

### SITE INFORMATION

Location Name	WEU #300H 50K	Permit Number	3RF-50
Section	17 Township 22N	Range 7W	County SANDAVOL State <u>NM</u>
Time Inspection Began	13:10	Time Inspection Ended	13:15
Recycling Facility	<input checked="" type="checkbox"/>	Recycling Containment	<input checked="" type="checkbox"/>
		Water Level (Feet)	<input type="text" value="3"/>

### GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

### INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

#### Leak Detection

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	
Total Depth of ULD (ft)	<input type="text"/>				
Depth to Water in ULD (ft)	<input type="text"/>				
Height of Water in ULD	<input type="text"/>				
Gallons of Water Removed	<input type="text"/>				
<i>COMMENTS</i>					

If leak detection contained liquid, was it removed	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid was it analyzed for conductance to determine origin Produced Water or condensation	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

*COMMENTS*

### BIRD MITIGATION SYSTEM

Is Bird netting in good condition and completely covers AST?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected and no evidence of bird mortality was found?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

\* If evidence of bird mortality was found, NMOCD must be notified by HSE

*COMMENTS*

Name (Print)	Richard Rogers	Date	9/27/2023
Name (Signature)	<i>Richard Rogers</i>	Company	<u>ENDURING RESOURCES</u>



## Enduring Resources, LLC AST Recycling Facility Inspection Sheet

### SITE INFORMATION

Location Name	WEU #300H 50K	Permit Number	3RF-50
Section	17 Township 22N	Range 7W	County SANDAVOL State <u>NM</u>
Time Inspection Began	13:10	Time Inspection Ended	13:15
Recycling Facility	<input checked="" type="checkbox"/>	Recycling Containment	<input checked="" type="checkbox"/>
		Water Level (Feet)	<input type="text" value="3"/>

### GENERAL INFORMATION

Containment Currently Contains Fluids	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Fencing is in Good condition and Functional	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Gates are Closed and locked	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Signs of Surface Water Runon?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>

### INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Injection and withdrawl of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
Is there evidence of a leak in the liner above the waterline	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	NA	<input type="checkbox"/>
Site is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>

#### Leak Detection

Water Present in ULD?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	
Total Depth of ULD (ft)		<input type="text"/>			
Depth to Water in ULD (ft)		<input type="text"/>			
Height of Water in ULD		<input type="text"/>			
Gallons of Water Removed		<input type="text"/>			<i>COMMENTS</i>

If leak detection contained liquid, was it removed	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid, was HSE notified	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>
If leak detection contained liquid was it analyzed for conductance to determine origin Produced Water or condensation	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

*COMMENTS*

### BIRD MITIGATION SYSTEM

Is Bird netting in good condition and completely covers AST?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
Facility was inspected and no evidence of bird mortality was found?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input type="checkbox"/>
If evidence of bird mortality was found was HSE notified?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>	NA	<input checked="" type="checkbox"/>

\* If evidence of bird mortality was found, NMOCD must be notified by HSE

*COMMENTS*

Name (Print)	Klint Gideon	Date	10/4/2023
Name (Signature)	<i>Klint Gideon</i>	Company	<u>ENDURING RESOURCES</u>



*ENDURING RESOURCES IV LLC*

200 Energy Court Farmington, NM 87401  
Field Office: 505.636.9720 | Main Office: 303.573.1222

Enduring Resources, LLC  
WEU 300 – 3RF-50  
Recycling Facility/Containment  
Cessation Request for 19.15.34 NMAC

New Mexico Oil Conservation Division  
Attn: Victoria Venegas

Enduring Resources is requesting a cessation of operations for the WEU 300 (3RF-50) Water Recycling Facility. In accordance with 19.15.34.13.C NMAC, *“A recycling containment shall be deemed to have ceased operations if less than twenty percent of the total fluid capacity is used every six months following the first withdrawal of produced water for use. The operator must report cessation of operations to the division.”*

Enduring is requesting a cessation of operations from 11/2023 through the end of 4/2024. The division may grant an extension to this determination of cessation of operations not to exceed six months. Enduring has included records for the last 6 months of inspections at this facility.

Thank you,

A handwritten signature in blue ink, appearing to read "Heather Huntington", is located below the "Thank you," text.

Heather Huntington  
Permitting Technician  
Enduring Resources, LLC.  
[hhuntington@enduringresources.com](mailto:hhuntington@enduringresources.com)

**Venegas, Victoria, EMNRD**

---

**From:** Venegas, Victoria, EMNRD  
**Sent:** Friday, October 13, 2023 11:03 AM  
**To:** Kayla White; Heather Huntington  
**Subject:** 3RF-50 - W ESCAVADA UNIT 300H – FACILITY ID [fVV2123855557]  
**Attachments:** C-147. 3RF-50 - W ESCAVADA Extension Cessation of Operations. 10.13.2023.pdf

**3RF-50 - W ESCAVADA UNIT 300H – FACILITY ID [fVV2123855557]**

Good morning,

NMOCD has reviewed the cessation of operations extension request for 3RF-50 - W ESCAVADA UNIT 300H – FACILITY ID [fVV2123855557] received from [372286] ENDURING RESOURCES, LLC 10/6/2023. The extension of the cessation of operations is approved with the following conditions of approval:

- 3RF-50 - W ESCAVADA UNIT 300H – FACILITY ID [fVV2123855557] extension of cessation of operations is approved from November 1<sup>st</sup>, 2023, to May 1<sup>st</sup>, 2024. Per NMAC 19.15.34.13.C extensions are considered for a maximum length of six months.
- **However, if after this 6-month period, the containment was not utilized at a minimum of 20% fluid capacity, no additional extensions would be granted, and the operator would be directed to remove all fluids and proceed with the closure requirements.**
- [372286] ENDURING RESOURCES, LLC will maintain a liquid level in the containment that is at least equal to the weight of the liner plus 20%. [372286] ENDURING RESOURCES, LLC may maintain a higher liquid level if they choose.
- [372286] ENDURING RESOURCES, LLC will provide written notice to [OCD Online](#) at least 72 hours, but no more than one week, prior to the recommencement of operations. Recommencement of recycling operations means that the operator plans to resume moving fluids through the containment and discharging fluids from the containment.
  - At the resumption of recycling operations, [372286] ENDURING RESOURCES, LLC is required to perform an incremental fluid level test for containment liquid levels above the minimum liquid level.
  - [372286] ENDURING RESOURCES, LLC will fill the containment. [372286] ENDURING RESOURCES, LLC will pause filling operations at every 10% of total fluid capacity above the minimum level.
  - [372286] ENDURING RESOURCES, LLC will maintain the liquid level for each 10% volume increase for 24 hours and inspect and operation the leak detection system at the end of the 24-hour period.
  - If there are no liquids present in the leak detection system, [372286] ENDURING RESOURCES, LLC may proceed to fill the next 10% volume and repeat the process until the containment full design capacity minus the 3-feet of freeboard is reached.
  - If liquids are present, [372286] ENDURING RESOURCES, LLC should immediately cease the incremental fill test and perform a liner inspection. [372286] ENDURING RESOURCES, LLC should provide written notice of the fluid detection and liner inspection findings to OCD via [OCD Online](#) using a C-147 (long form) with the “Other” box checked and “Notice of fluid detection” written as the explanation of “Other.”
  - Upon notification of fluid detection in the leak detection system, the OCD will verify the source of water (condensation versus produced water).
  - If the detected fluid is confirmed to be condensation, the OCD will issue a written approval to proceed with the incremental fluid level test.
  - If the detected fluid is confirmed to be produced water, [372286] ENDURING RESOURCES, LLC must comply with 19.15.34.13 NMAC. [372286] ENDURING RESOURCES, LLC must provide written notification to [OCD Online](#) on the actions taken to comply with 19.15.34.13 NMAC.
  - After fluid is detected in the leak detection system, the incremental fill test cannot continue until after a written approval to proceed is issued by the OCD.

- [372286] ENDURING RESOURCES, LLC must submit copies of the detailed containment inspection records for the prior three months and a report detailing the incremental fluid level test process and results through the [OCD Online](#) system using a C-147 (long form) with the “Other” box checked. “Recommendation of Operations - Incremental Fluid Level Test” should be written as the explanation of “Other.” Form C-147 must be completed and include information in sections 1 General Information, 2 Recycling Facility, 3 Recycling Containment, 4 Bonding, and 10 Operator Application Certification. Section 9 Recycling Facility and/or Containment Checklist may also need to be partially completed. Operators should verify that the resumption of operations notification does not result in any changes to the recycling containment operating and maintenance plan or the closure plan. If the recommencement of operations will affect the operating and maintenance plan or closure plan, operators should check those boxes in section 9 and provide updated plans or plan addendums as attachments to the C-147.
- [372286] ENDURING RESOURCES, LLC will continue to operate, maintain, and close 3RF-50 - W ESCAVADA UNIT 300H – FACILITY ID [fVV2123855557] in compliance with 19.15.34 NMAC, to include but not limited detailed inspection records, removal of trash/oil from containment, and monthly C-148 reporting (even if there is zero activity).
- A minimum of 3-feet freeboard must always be maintained in the recycling containment during operations.

Please let me know if you have any other questions.

Regards,

**Victoria Venegas** • Environmental Specialist

Environmental Bureau

EMNRD - Oil Conservation Division

506 W. Texas Ave. Artesia, NM 88210

(575) 909-0269 | [Victoria.Venegas@emnrd.nm.gov](mailto:Victoria.Venegas@emnrd.nm.gov)

<https://www.emnrd.nm.gov/oed/>



**District I**  
 1625 N. French Dr., Hobbs, NM 88240  
 Phone:(575) 393-6161 Fax:(575) 393-0720  
**District II**  
 811 S. First St., Artesia, NM 88210  
 Phone:(575) 748-1283 Fax:(575) 748-9720  
**District III**  
 1000 Rio Brazos Rd., Aztec, NM 87410  
 Phone:(505) 334-6178 Fax:(505) 334-6170  
**District IV**  
 1220 S. St Francis Dr., Santa Fe, NM 87505  
 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 273327

**CONDITIONS**

Operator: ENDURING RESOURCES, LLC 6300 S Syracuse Way, Suite 525 Centennial, CO 80111	OGRID: 372286
	Action Number: 273327
	Action Type: [C-147] Water Recycle Long (C-147L)

**CONDITIONS**

Created By	Condition	Condition Date
vvenegas	<ul style="list-style-type: none"> <li>• 3RF-50 - W ESCAVADA UNIT 300H – FACILITY ID [FVV2123855557] extension of cessation of operations is approved from November 1st, 2023, to May 1st, 2024. Per NMAC 19.15.34.13.C extensions are considered for a maximum length of six months. • However, if after this 6-month period, the containment was not utilized at a minimum of 20% fluid capacity, no additional extensions would be granted, and the operator would be directed to remove all fluids and proceed with the closure requirements.</li> </ul>	10/13/2023