



Oxy USA Inc.  
1600 Gehrig Drive  
Midland, TX 79706

State of New Mexico  
Energy, Minerals, and Natural Resources Department  
Oil Conservation Division, District II  
811 S. First St.  
Artesia, NM 88210

July 28, 2025

**Re: Cedar Canyon Recycling Facility and Containments (2RF-144) C-147 Annual Registration Extension**

To Whom It May Concern,

Oxy USA Inc. submits the enclosed C-147 form and summary of monthly containment and leak detection inspections for the Cedar Canyon Recycling Facility and Containments (2RF-144). In accordance with *NMAC 19.15.34.10 Recycling Containments*, Oxy USA Inc. requests a one-year registration extension, valid from August 10, 2025, through August 10, 2026, for the Cedar Canyon Recycling Facility and Containments (2RF-144).

Included with this submittal is a summary of the monthly inspections, including the monitoring of the leak detection system, showing the containment's integrity has not been compromised, from when the facility was constructed, to the present. For original site plans and supporting documents, please refer to the facility's original registration application and modifications.

Should you have any questions or require additional information, please contact me at your convenience.

Sincerely,

A handwritten signature in black ink, appearing to read "Justin Steinmann", with a long horizontal flourish extending to the right.

**Justin Steinmann**

ENVIRONMENTAL ADVISOR

OXY USA INC.

✉ justin\_steinmann@oxy.com

☎ (713) 350-4633

State of New Mexico  
Energy Minerals and Natural Resources  
Department Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-147  
Revised October 11, 2022

<https://www.emnrd.nm.gov/ocd/ocd-e-permitting/>

## Recycling Facility and/or Recycling Containment

**Type of Facility:**    ☒ Recycling Facility    ☒ Recycling Containment\*

**Type of action:**    ☐ Permit    ☐ Registration  
                               ☐ Modification    ☒ Extension    Annual Extension 8/10/2025-8/10/2026  
                               ☐ Closure    ☐ Other (explain) \_\_\_\_\_

**\* At the time C-147 is submitted to the division for a Recycling Containment, a copy shall be provided to the surface owner.**

Be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances.

1.  
 Operator: OXY USA Inc. (For multiple operators attach page with information) OGRID #: 16696  
 Address: 5 Greenway Plaza, Ste. 110, Houston, TX 77046  
 Facility or well name (include API# if associated with a well): Cedar Canyon Recycling Facility A and B  
 OCD Permit Number: 2RF-144 (For new facilities the permit number will be assigned by the district office)  
 U/L or Qtr/Qtr K Section 15 Township 24S Range 29E County: Eddy  
 Surface Owner: ☐ Federal ☐ State ☒ Private ☐ Tribal Trust or Indian Allotment

2.  
☒ **Recycling Facility:**  
 Location of recycling facility (if applicable): Latitude 32.216187 Longitude -103.975685 NAD83  
 Proposed Use: ☒ Drilling\* ☒ Completion\* ☐ Production\* ☐ Plugging\*  
*\*The re-use of produced water may NOT be used until fresh water zones are cased and cemented*  
☐ Other, *requires permit for other uses. Describe use, process, testing, volume of produced water and ensure there will be no adverse impact on groundwater or surface water.*  
☒ Fluid Storage  
                   ☒ Above ground tanks    ☒ Recycling containment ☐ Activity permitted under 19.15.17 NMAC explain type \_\_\_\_\_  
                   ☐ Activity permitted under 19.15.36 NMAC explain type: \_\_\_\_\_ ☐ Other explain \_\_\_\_\_  
                   ☐ For multiple or additional recycling containments, attach design and location information of each containment  
☐ **Closure Report (required within 60 days of closure completion):** ☐ Recycling Facility Closure Completion Date: \_\_\_\_\_

3.  
☒ **Recycling Containment:** \*See Attachment for Containment Details.  
☒ Annual Extension after initial 5 years (attach summary of monthly leak detection inspections for previous year)  
 Center of Recycling Containment (if applicable): Latitude \_\_\_\_\_ Longitude \_\_\_\_\_ NAD83  
☒ For multiple or additional recycling containments, attach design and location information of each containment  
☐ Lined    ☐ Liner type: Thickness \_\_\_\_\_ mil    ☐ LLDPE ☐ HDPE ☐ PVC ☐ Other \_\_\_\_\_  
☐ String-Reinforced  
 Liner Seams: ☐ Welded ☐ Factory ☐ Other \_\_\_\_\_ Volume: \_\_\_\_\_ bbl Dimensions: L \_\_\_\_\_ x W \_\_\_\_\_ x D \_\_\_\_\_  
☐ Recycling Containment Closure Completion Date: \_\_\_\_\_



4.

**Bonding:**

- ☒ Covered under bonding pursuant to 19.15.8 NMAC per 19.15.34.15(A)(2) NMAC (These containments are limited to only the wells owned or operated by the owners of the containment.)
- ☐ Bonding in accordance with 19.15.34.15(A)(1). Amount of bond \$ \_\_\_\_\_ (work on these facilities cannot commence until bonding amounts are approved)
- ☐ Attach closure cost estimate and documentation on how the closure cost was calculated.

5.

**Fencing:**

- ☐ Four foot height, four strands of barbed wire evenly spaced between one and four feet
- ☒ Alternate. Please specify 6 ft. chain-link with barbed wire top

6.

**Signs:**

- ☒ 12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers
- ☐ Signed in compliance with 19.15.16.8 NMAC

7.

**Variances:**

Justifications and/or demonstrations that the proposed variance will afford reasonable protection against contamination of fresh water, human health, and the environment.

***Check the below box only if a variance is requested:***

☐ Variance(s): Requests must be submitted to the appropriate division district for consideration of approval. If a Variance is requested, include the variance information on a separate page and attach it to the C-147 as part of the application.

**If a Variance is requested, it must be approved prior to implementation.**

8.

**Siting Criteria for Recycling Containment**

**Instructions:** The applicant must provide attachments that demonstrate compliance for each siting criteria below as part of the application. Potential examples of the siting attachment source material are provided below under each criteria.

**General siting****Ground water is less than 50 feet below the bottom of the Recycling Containment.**

NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells

☒ Yes ☐ No  
☐ NA

Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended.

- Written confirmation or verification from the municipality; written approval obtained from the municipality

☐ Yes ☒ No  
☐ NA

Within the area overlying a subsurface mine.

- Written confirmation or verification or map from the NM EMNRD-Mining and Minerals Division

☐ Yes ☒ No

Within an unstable area.

- Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; topographic map

☐ Yes ☒ No

Within a 100-year floodplain. FEMA map

☐ Yes ☒ No

Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark).

- Topographic map; visual inspection (certification) of the proposed site

☐ Yes ☒ No

Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application.

- Visual inspection (certification) of the proposed site; aerial photo; satellite image

☐ Yes ☒ No

Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application.

- NM Office of the State Engineer - iWATERS database search; visual inspection (certification) of the proposed site

☐ Yes ☒ No

Within 500 feet of a wetland.

- US Fish and Wildlife Wetland Identification map; topographic map; visual inspection (certification) of the proposed site

☐ Yes ☒ No

9.

**Recycling Facility and/or Containment Checklist:**


**Instructions:** Each of the following items must be attached to the application. Indicate, by a check mark in the box, that the documents are attached.

- ☒ Design Plan - based upon the appropriate requirements.
- ☒ Operating and Maintenance Plan - based upon the appropriate requirements.
- ☒ Closure Plan - based upon the appropriate requirements.
- ☒ Site Specific Groundwater Data -
- ☒ Siting Criteria Compliance Demonstrations -
- ☒ Certify that notice of the C-147 (only) has been sent to the surface owner(s)

10.

**Operator Application Certification:**

I hereby certify that the information and attachments submitted with this application are true, accurate and complete to the best of my knowledge and belief.

Name (Print): Justin Steinmann Title: Environmental Advisor  
Signature:  Date: 07/28/2025  
e-mail address: Justin\_Steinmann@oxy.com Telephone: (713)350-4633

11.

OCD Representative Signature: Victoria Venegas Approval Date: 08/11/2025

Title: Environmental Specialist OCD Permit Number: 2RF-144

- ☐ OCD Conditions
- ☒ Additional OCD Conditions on Attachment

Oxy USA, Inc. Cedar Canyon Recycling Facility (ZRF-144): Additional Containments

C-147 Annual Extension (2023)

3.

☒ **Recycling Containment:** Cedar Canyon – East Recycling Containment "A" (U/L: L, Section 10, T24S, R29E, Eddy County)☒ Annual Extension after initial 5 years (attach summary of monthly leak detection inspections for previous year)Center of Recycling Containment (if applicable): Latitude 32.229015 Longitude -103.978186 NAD83☐ For multiple or additional recycling containments, attach design and location information of each containment☒ Lined ☐ Liner type: Thickness 60 mil ☒ LLDPE ☐ HDPE ☐ PVC ☐ Other \_\_\_\_\_☐ String-ReinforcedLiner Seams: ☒ Welded ☐ Factory ☐ Other \_\_\_\_\_ Volume: 194,000 bbl Dimensions: L 300" x W 400" x D 27.5"☐ Recycling Containment Closure Completion Date: \_\_\_\_\_

3.

☒ **Recycling Containment:** Cedar Canyon – West Recycling Containment "B" (U/L: L, Section 10, T24S, R29E, Eddy County)☒ Annual Extension after initial 5 years (attach summary of monthly leak detection inspections for previous year)Center of Recycling Containment (if applicable): Latitude 32.228489 Longitude -103.978922 NAD83☐ For multiple or additional recycling containments, attach design and location information of each containment☒ Lined ☒ Liner type: Thickness 60 mil ☐ LLDPE ☒ HDPE ☐ PVC ☐ Other \_\_\_\_\_☐ String-ReinforcedLiner Seams: ☒ Welded ☐ Factory ☐ Other \_\_\_\_\_ Volume: 194,000 bbl Dimensions: L 300" x W 400" x D 27.5"☐ Recycling Containment Closure Completion Date: \_\_\_\_\_

**Venegas, Victoria, EMNRD**

---

**From:** Venegas, Victoria, EMNRD  
**Sent:** Monday, August 11, 2025 1:30 PM  
**To:** Steinmann, Justin W  
**Subject:** 2RF-144 - CEDAR CANYON RECYCLING FACILITY A AND B [fBGB1922049166]  
**Attachments:** C-147 2RF-144 - CEDAR CANYON RECYCLING FACILITY A & B [fBGB1922049166]  
08.11.2025.pdf

**2RF-144 - CEDAR CANYON RECYCLING FACILITY A AND B [fBGB1922049166]**


Good afternoon Mr. Steinmann.


NMOCD has reviewed the annual registration/permit extension request for 2RF-144 - CEDAR CANYON RECYCLING FACILITY A & B [fBGB1922049166] received from [16696] OXY USA INC on 07/28/2025, Application ID **489044**. The registration/permit annual extension request is approved with the following conditions of approval:


- 2RF-144 - CEDAR CANYON RECYCLING FACILITY A & B [fBGB1922049166] is approved for one (1) year of operation from the date of the previous registration/permit expiration date of August 10, 2025. The new registration/permit expiration date is August 10, 2026.
- [16696] OXY USA INC will continue to operate, maintain, and close 2RF-144 - CEDAR CANYON RECYCLING FACILITY A & B [fBGB1922049166] in compliance with 19.15.34 NMAC, to include but not limited to the performance of weekly inspections regardless of fluid levels in the containment; recording of detailed inspection reports; removal of debris, foreign objects and oil from the containment; and monthly reporting of recycling and reuse of produced water, drilling fluids, and liquid oil field waste via from C-148.
- [16696] OXY USA INC will maintain a liquid level in the containment that is at least equal to the weight of the liner plus 20%. [16696] OXY USA INC may maintain a higher liquid level if they choose.
- If less than 20% of the total fluid capacity is utilized every consecutive six months, operation of the facility is considered ceased and a notification of cessation of operations should be sent electronically through OCD Permitting. An extension to extend the cessation of operations, not to exceed six months, may be submitted using a C-147 form through the OCD Online system.
- If after that 6-month extension period, the containment is not utilized at a minimum of 20% fluid capacity, no additional extensions would be granted, and the operator would be directed to remove all fluids and proceed with the closure requirements.
- The recycling containment is bonded pursuant to 19.15.8 NMAC per 19.15.34.15(A)(2) NMAC. Water reuse and recycling from 2RF-144 - CEDAR CANYON RECYCLING FACILITY A & B [fBGB1922049166] is limited to wells owned or operated by [16696] OXY USA INC.
- A minimum of 3-feet freeboard must be maintained in the recycling containment at all times.
- [16696] OXY USA INC will comply with 19.15.29 NMAC Releases in the event of any release of produced water or produced water or other oil field wastes at 2RF-144 - CEDAR CANYON RECYCLING FACILITY A & B [fBGB1922049166]. [16696] OXY USA INC will comply with all other OCD rules.
- [16696] OXY USA INC must perform weekly inspections of the containment and leak detection system.
- If [16696] OXY USA INC wishes to extend the registration/permit past August 10, 2026, a registration/permit extension request must be submitted to OCD. Extension requests are reviewed on a case-by-case basis and evaluated on their merit. Extensions are considered for a maximum length of one year. Additional requests must be submitted to OCD through OCD Online on a Form C-147 (long form) as an Extension request and should include a formal extension request letter, a summary of the prior registration/permit period inspection reports, and the copies of the detailed inspection records for the prior permit period. The extension request should be submitted no later than July 10, 2026.

Please let me know if you have any additional questions.  
Best regards,


**Victoria Venegas** ● Environmental Specialist Advanced  
EMNRD - Oil Conservation Division  
506 W. Texas Ave. Artesia, NM 88210  
575.909.0269 | [Victoria.Venegas@emnrd.nm.gov](mailto:Victoria.Venegas@emnrd.nm.gov)


		<h2 style="text-align: center;">Monthly Inspection Report</h2> <p style="text-align: center;">Treated Water Containment / Pond</p>		
Work Order No:				
Inspected by (name and signature): <span style="color: blue;">Marcos Montano</span> <i>Marcos Montano</i>				Date/Time: <span style="color: blue;">6-2024</span>
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	<span style="color: blue;">X</span>			
Equipment Description	Yes or No	Working condition? (Good / Needs Repairs)	Comments	
Are diversion ditches and berms around the containment secure? (check for erosion and collection of surface water run-on)	<span style="color: blue;">YES</span>	<span style="color: blue;">GOOD</span>		
Is the leak detection system intact? (check for evidence of damage or malfunction and monitor for leakage).	<span style="color: blue;">YES</span>	<span style="color: blue;">GOOD</span>		
Are there any dead migratory birds and other wildlife inside pond/treated water?*	<span style="color: blue;">NO</span>	<span style="color: blue;">GOOD</span>		
Are the sources and disposition of all recycled water recorded?**	<span style="color: blue;">YES</span>	<span style="color: blue;">GOOD</span>		
<p>* Within 30 days of discovery, report the discovery of dead migratory birds or other wildlife to the appropriate wildlife agency and to the division district office in order to facilitate assessment and implementation of measures to prevent incidents from reoccurring</p> <p>** Report to the division the total volume of water received for recycling, with the amount of fresh water received listed separately, and the total volume of water leaving the facility for disposition by use of the form C-148</p>				
Additional Comments (including any equipment not checked off):	<span style="color: blue;">2RF-144 NORTHEAST RC</span>			


		<h2 style="text-align: center;">Monthly Inspection Report</h2> <p style="text-align: center;">Treated Water Containment / Pond</p>		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	Date/Time: 06-2024
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Yes or No	Working condition? (Good / Needs Repairs)	Comments	
Are diversion ditches and berms around the containment secure? (check for erosion and collection of surface water run-on)	YES	GOOD		
Is the leak detection system intact? (check for evidence of damage or malfunction and monitor for leakage).	YES	GOOD		
Are there any dead migratory birds and other wildlife inside pond/treated water?*	NO	GOOD		
Are the sources and disposition of all recycled water recorded?**	YES	GOOD		
<p>* Within 30 days of discovery, report the discovery of dead migratory birds or other wildlife to the appropriate wildlife agency and to the division district office in order to facilitate assessment and implementation of measures to prevent incidents from reoccurring</p> <p>** Report to the division the total volume of water received for recycling, with the amount of fresh water received listed separately, and the total volume of water leaving the facility for disposition by use of the form C-148</p>				
Additional Comments (including any equipment not checked off):	2RF-144 SOUTHWEST RC			


		<h2 style="text-align: center;">Monthly Inspection Report</h2> <p style="text-align: center;">Treated Water Containment / Pond</p>		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	
			Date/Time: 07-2024	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Yes or No	Working condition? (Good / Needs Repairs)	Comments	
Are diversion ditches and berms around the containment secure? (check for erosion and collection of surface water run-on)	YES	GOOD		
Is the leak detection system intact? (check for evidence of damage or malfunction and monitor for leakage).	YES	GOOD		
Are there any dead migratory birds and other wildlife inside pond/treated water?*	NO	GOOD		
Are the sources and disposition of all recycled water recorded?**	YES	GOOD		
<p>* Within 30 days of discovery, report the discovery of dead migratory birds or other wildlife to the appropriate wildlife agency and to the division district office in order to facilitate assessment and implementation of measures to prevent incidents from reoccurring</p> <p>** Report to the division the total volume of water received for recycling, with the amount of fresh water received listed separately, and the total volume of water leaving the facility for disposition by use of the form C-148</p>				
Additional Comments (including any equipment not checked off):	2RF-144 NORTHEAST RC			





		<h2 style="text-align: center;">Monthly Inspection Report</h2> <p style="text-align: center;">Treated Water Containment / Pond</p>		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	
			Date/Time: 07-2024	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Yes or No	Working condition? (Good / Needs Repairs)	Comments	
Are diversion ditches and berms around the containment secure? (check for erosion and collection of surface water run-on)	YES	GOOD		
Is the leak detection system intact? (check for evidence of damage or malfunction and monitor for leakage).	YES	GOOD		
Are there any dead migratory birds and other wildlife inside pond/treated water?*	NO	GOOD		
Are the sources and disposition of all recycled water recorded?**	YES	GOOD		
<p>* Within 30 days of discovery, report the discovery of dead migratory birds or other wildlife to the appropriate wildlife agency and to the division district office in order to facilitate assessment and implementation of measures to prevent incidents from reoccurring</p> <p>** Report to the division the total volume of water received for recycling, with the amount of fresh water received listed separately, and the total volume of water leaving the facility for disposition by use of the form C-148</p>				
Additional Comments (including any equipment not checked off):	2RF-144 SOUTHWEST RC			


		<h2 style="text-align: center;">Monthly Inspection Report</h2> <p style="text-align: center;">Treated Water Containment / Pond</p>		
Work Order No:				
Inspected by (name and signature): <span style="color: blue;">Marcos Montano</span> <i>Marcos Montano</i>				Date/Time: <span style="color: blue;">09-2024</span>
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	<span style="color: blue;">X</span>			
Equipment Description	Yes or No	Working condition? (Good / Needs Repairs)	Comments	
Are diversion ditches and berms around the containment secure? (check for erosion and collection of surface water run-on)	<span style="color: blue;">YES</span>	<span style="color: blue;">GOOD</span>		
Is the leak detection system intact? (check for evidence of damage or malfunction and monitor for leakage).	<span style="color: blue;">YES</span>	<span style="color: blue;">GOOD</span>		
Are there any dead migratory birds and other wildlife inside pond/treated water?*	<span style="color: blue;">NO</span>	<span style="color: blue;">GOOD</span>		
Are the sources and disposition of all recycled water recorded?**	<span style="color: blue;">YES</span>	<span style="color: blue;">GOOD</span>		
<p>* Within 30 days of discovery, report the discovery of dead migratory birds or other wildlife to the appropriate wildlife agency and to the division district office in order to facilitate assessment and implementation of measures to prevent incidents from reoccurring</p> <p>** Report to the division the total volume of water received for recycling, with the amount of fresh water received listed separately, and the total volume of water leaving the facility for disposition by use of the form C-148</p>				
Additional Comments (including any equipment not checked off):	<span style="color: blue;">2RF-144 NORTHEAST RC</span>			


		<h2 style="text-align: center;">Monthly Inspection Report</h2> <p style="text-align: center;">Treated Water Containment / Pond</p>		
Work Order No:				
Inspected by (name and signature): <span style="color: blue;">Marcos Montano</span> <i>Marcos Montano</i>				Date/Time: <span style="color: blue;">09-2024</span>
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Yes or No	Working condition? (Good / Needs Repairs)	Comments	
Are diversion ditches and berms around the containment secure? (check for erosion and collection of surface water run-on)	YES	GOOD		
Is the leak detection system intact? (check for evidence of damage or malfunction and monitor for leakage).	YES	GOOD		
Are there any dead migratory birds and other wildlife inside pond/treated water?*	NO	GOOD		
Are the sources and disposition of all recycled water recorded?**	YES	GOOD		
<p>* Within 30 days of discovery, report the discovery of dead migratory birds or other wildlife to the appropriate wildlife agency and to the division district office in order to facilitate assessment and implementation of measures to prevent incidents from reoccurring</p> <p>** Report to the division the total volume of water received for recycling, with the amount of fresh water received listed separately, and the total volume of water leaving the facility for disposition by use of the form C-148</p>				
Additional Comments (including any equipment not checked off):	2RF-144 SOUTHWEST RC			

		<h2 style="text-align: center;">Monthly Inspection Report</h2> <p style="text-align: center;">Treated Water Containment / Pond</p>		
Work Order No:				
Inspected by (name and signature): <span style="color: blue;">Marcos Montano</span> <i>Marcos Montano</i>				Date/Time: <span style="color: blue;">10-2024</span>
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	<span style="color: blue;">X</span>			
Equipment Description	Yes or No	Working condition? (Good / Needs Repairs)	Comments	
Are diversion ditches and berms around the containment secure? (check for erosion and collection of surface water run-on)	<span style="color: blue;">YES</span>	<span style="color: blue;">GOOD</span>		
Is the leak detection system intact? (check for evidence of damage or malfunction and monitor for leakage).	<span style="color: blue;">YES</span>	<span style="color: blue;">GOOD</span>		
Are there any dead migratory birds and other wildlife inside pond/treated water?*	<span style="color: blue;">NO</span>	<span style="color: blue;">GOOD</span>		
Are the sources and disposition of all recycled water recorded?**	<span style="color: blue;">YES</span>	<span style="color: blue;">GOOD</span>		
<p>* Within 30 days of discovery, report the discovery of dead migratory birds or other wildlife to the appropriate wildlife agency and to the division district office in order to facilitate assessment and implementation of measures to prevent incidents from reoccurring</p> <p>** Report to the division the total volume of water received for recycling, with the amount of fresh water received listed separately, and the total volume of water leaving the facility for disposition by use of the form C-148</p>				
Additional Comments (including any equipment not checked off):	<span style="color: blue;">2RF-144 NORTHEAST RC</span>			


		<h2 style="text-align: center;">Monthly Inspection Report</h2> <p style="text-align: center;">Treated Water Containment / Pond</p>		
Work Order No:				
Inspected by (name and signature): <span style="color: blue;">Marcos Montano</span> <i>Marcos Montano</i>				Date/Time: <span style="color: blue;">10-2024</span>
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	<span style="color: blue;">X</span>			
Equipment Description	Yes or No	Working condition? (Good / Needs Repairs)	Comments	
Are diversion ditches and berms around the containment secure? (check for erosion and collection of surface water run-on)	<span style="color: blue;">YES</span>	<span style="color: blue;">GOOD</span>		
Is the leak detection system intact? (check for evidence of damage or malfunction and monitor for leakage).	<span style="color: blue;">YES</span>	<span style="color: blue;">GOOD</span>		
Are there any dead migratory birds and other wildlife inside pond/treated water?*	<span style="color: blue;">NO</span>	<span style="color: blue;">GOOD</span>		
Are the sources and disposition of all recycled water recorded?**	<span style="color: blue;">YES</span>	<span style="color: blue;">GOOD</span>		
<p><i>* Within 30 days of discovery, report the discovery of dead migratory birds or other wildlife to the appropriate wildlife agency and to the division district office in order to facilitate assessment and implementation of measures to prevent incidents from reoccurring</i></p> <p><i>** Report to the division the total volume of water received for recycling, with the amount of fresh water received listed separately, and the total volume of water leaving the facility for disposition by use of the form C-148</i></p>				
Additional Comments (including any equipment not checked off):	<span style="color: blue;">2RF-144 SOUTHWEST RC</span>			


		<h2 style="text-align: center;">Monthly Inspection Report</h2> <p style="text-align: center;">Treated Water Containment / Pond</p>		
Work Order No:				
Inspected by (name and signature): <span style="color: blue;">Marcos Montano</span> <i>Marcos Montano</i>				Date/Time: <span style="color: blue;">11-2024</span>
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	<span style="color: blue;">X</span>			
Equipment Description	Yes or No	Working condition? (Good / Needs Repairs)	Comments	
Are diversion ditches and berms around the containment secure? (check for erosion and collection of surface water run-on)	<span style="color: blue;">YES</span>	<span style="color: blue;">GOOD</span>		
Is the leak detection system intact? (check for evidence of damage or malfunction and monitor for leakage).	<span style="color: blue;">YES</span>	<span style="color: blue;">GOOD</span>		
Are there any dead migratory birds and other wildlife inside pond/treated water?*	<span style="color: blue;">NO</span>	<span style="color: blue;">GOOD</span>		
Are the sources and disposition of all recycled water recorded?**	<span style="color: blue;">YES</span>	<span style="color: blue;">GOOD</span>		
<p>* Within 30 days of discovery, report the discovery of dead migratory birds or other wildlife to the appropriate wildlife agency and to the division district office in order to facilitate assessment and implementation of measures to prevent incidents from reoccurring</p> <p>** Report to the division the total volume of water received for recycling, with the amount of fresh water received listed separately, and the total volume of water leaving the facility for disposition by use of the form C-148</p>				
Additional Comments (including any equipment not checked off):	<span style="color: blue;">2RF-144 NORTHEAST RC</span>			


		<h2 style="text-align: center;">Monthly Inspection Report</h2> <p style="text-align: center;">Treated Water Containment / Pond</p>		
Work Order No:				
Inspected by (name and signature): <span style="color: blue;">Marcos Montano</span> <i>Marcos Montano</i>				Date/Time: <span style="color: blue;">11-2024</span>
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	<span style="color: blue;">X</span>			
Equipment Description	Yes or No	Working condition? (Good / Needs Repairs)	Comments	
Are diversion ditches and berms around the containment secure? (check for erosion and collection of surface water run-on)	<span style="color: blue;">YES</span>	<span style="color: blue;">GOOD</span>		
Is the leak detection system intact? (check for evidence of damage or malfunction and monitor for leakage).	<span style="color: blue;">YES</span>	<span style="color: blue;">GOOD</span>		
Are there any dead migratory birds and other wildlife inside pond/treated water?*	<span style="color: blue;">NO</span>	<span style="color: blue;">GOOD</span>		
Are the sources and disposition of all recycled water recorded?**	<span style="color: blue;">YES</span>	<span style="color: blue;">GOOD</span>		
<p>* Within 30 days of discovery, report the discovery of dead migratory birds or other wildlife to the appropriate wildlife agency and to the division district office in order to facilitate assessment and implementation of measures to prevent incidents from reoccurring</p> <p>** Report to the division the total volume of water received for recycling, with the amount of fresh water received listed separately, and the total volume of water leaving the facility for disposition by use of the form C-148</p>				
Additional Comments (including any equipment not checked off):	<span style="color: blue;">2RF-144 SOUTHWEST RC</span>			


		<h2 style="text-align: center;">Monthly Inspection Report</h2> <p style="text-align: center;">Treated Water Containment / Pond</p>		
Work Order No:				
Inspected by (name and signature): <span style="color: blue;">Marcos Montano</span> <i>Marcos Montano</i>				Date/Time: <span style="color: blue;">12-2024</span>
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	<span style="color: blue;">X</span>			
Equipment Description	Yes or No	Working condition? (Good / Needs Repairs)	Comments	
Are diversion ditches and berms around the containment secure? (check for erosion and collection of surface water run-on)	<span style="color: blue;">YES</span>	<span style="color: blue;">GOOD</span>		
Is the leak detection system intact? (check for evidence of damage or malfunction and monitor for leakage).	<span style="color: blue;">YES</span>	<span style="color: blue;">GOOD</span>		
Are there any dead migratory birds and other wildlife inside pond/treated water?*	<span style="color: blue;">NO</span>	<span style="color: blue;">GOOD</span>		
Are the sources and disposition of all recycled water recorded?**	<span style="color: blue;">YES</span>	<span style="color: blue;">GOOD</span>		
<p>* Within 30 days of discovery, report the discovery of dead migratory birds or other wildlife to the appropriate wildlife agency and to the division district office in order to facilitate assessment and implementation of measures to prevent incidents from reoccurring</p> <p>** Report to the division the total volume of water received for recycling, with the amount of fresh water received listed separately, and the total volume of water leaving the facility for disposition by use of the form C-148</p>				
Additional Comments (including any equipment not checked off):	<span style="color: blue;">2RF-144 NORTHEAST RC</span>			





		<h2 style="text-align: center;">Monthly Inspection Report</h2> <p style="text-align: center;">Treated Water Containment / Pond</p>		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	
			Date/Time: 12-2024	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Yes or No	Working condition? (Good / Needs Repairs)	Comments	
Are diversion ditches and berms around the containment secure? (check for erosion and collection of surface water run-on)	YES	GOOD		
Is the leak detection system intact? (check for evidence of damage or malfunction and monitor for leakage).	YES	GOOD		
Are there any dead migratory birds and other wildlife inside pond/treated water?*	NO	GOOD		
Are the sources and disposition of all recycled water recorded?**	YES	GOOD		
<p>* Within 30 days of discovery, report the discovery of dead migratory birds or other wildlife to the appropriate wildlife agency and to the division district office in order to facilitate assessment and implementation of measures to prevent incidents from reoccurring</p> <p>** Report to the division the total volume of water received for recycling, with the amount of fresh water received listed separately, and the total volume of water leaving the facility for disposition by use of the form C-148</p>				
Additional Comments (including any equipment not checked off):	ID# 2RF-144			


		<h2 style="text-align: center;">Monthly Inspection Report</h2> <p style="text-align: center;">Treated Water Containment / Pond</p>		
Work Order No:				
Inspected by (name and signature): <span style="color: blue;">Marcos Montano</span> <i>Marcos Montano</i>				Date/Time: <span style="color: blue;">01-2025</span>
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	<span style="color: blue;">X</span>			
Equipment Description	Yes or No	Working condition? (Good / Needs Repairs)	Comments	
Are diversion ditches and berms around the containment secure? (check for erosion and collection of surface water run-on)	<span style="color: blue;">YES</span>	<span style="color: blue;">GOOD</span>		
Is the leak detection system intact? (check for evidence of damage or malfunction and monitor for leakage).	<span style="color: blue;">YES</span>	<span style="color: blue;">GOOD</span>		
Are there any dead migratory birds and other wildlife inside pond/treated water?*	<span style="color: blue;">NO</span>	<span style="color: blue;">GOOD</span>		
Are the sources and disposition of all recycled water recorded?**	<span style="color: blue;">YES</span>	<span style="color: blue;">GOOD</span>		
<p>* Within 30 days of discovery, report the discovery of dead migratory birds or other wildlife to the appropriate wildlife agency and to the division district office in order to facilitate assessment and implementation of measures to prevent incidents from reoccurring</p> <p>** Report to the division the total volume of water received for recycling, with the amount of fresh water received listed separately, and the total volume of water leaving the facility for disposition by use of the form C-148</p>				
Additional Comments (including any equipment not checked off):	<span style="color: blue;">2RF-144 NORTHEAST RC</span>			


		<h2 style="text-align: center;">Monthly Inspection Report</h2> <p style="text-align: center;">Treated Water Containment / Pond</p>		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	
			Date/Time: 01-2025	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Yes or No	Working condition? (Good / Needs Repairs)	Comments	
Are diversion ditches and berms around the containment secure? (check for erosion and collection of surface water run-on)	YES	GOOD		
Is the leak detection system intact? (check for evidence of damage or malfunction and monitor for leakage).	YES	GOOD		
Are there any dead migratory birds and other wildlife inside pond/treated water?*	NO	GOOD		
Are the sources and disposition of all recycled water recorded?**	YES	GOOD		
<p>* Within 30 days of discovery, report the discovery of dead migratory birds or other wildlife to the appropriate wildlife agency and to the division district office in order to facilitate assessment and implementation of measures to prevent incidents from reoccurring</p> <p>** Report to the division the total volume of water received for recycling, with the amount of fresh water received listed separately, and the total volume of water leaving the facility for disposition by use of the form C-148</p>				
Additional Comments (including any equipment not checked off):	ID# 2RF-144			

		<h2 style="text-align: center;">Monthly Inspection Report</h2> <p style="text-align: center;">Treated Water Containment / Pond</p>		
Work Order No:				
Inspected by (name and signature): <span style="color: blue;">Marcos Montano</span> <i>Marcos Montano</i>				Date/Time: <span style="color: blue;">02-2025</span>
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	<span style="color: blue;">X</span>			
Equipment Description	Yes or No	Working condition? (Good / Needs Repairs)	Comments	
Are diversion ditches and berms around the containment secure? (check for erosion and collection of surface water run-on)	<span style="color: blue;">YES</span>	<span style="color: blue;">GOOD</span>		
Is the leak detection system intact? (check for evidence of damage or malfunction and monitor for leakage).	<span style="color: blue;">YES</span>	<span style="color: blue;">GOOD</span>		
Are there any dead migratory birds and other wildlife inside pond/treated water?*	<span style="color: blue;">NO</span>	<span style="color: blue;">GOOD</span>		
Are the sources and disposition of all recycled water recorded?**	<span style="color: blue;">YES</span>	<span style="color: blue;">GOOD</span>		
<p>* Within 30 days of discovery, report the discovery of dead migratory birds or other wildlife to the appropriate wildlife agency and to the division district office in order to facilitate assessment and implementation of measures to prevent incidents from reoccurring</p> <p>** Report to the division the total volume of water received for recycling, with the amount of fresh water received listed separately, and the total volume of water leaving the facility for disposition by use of the form C-148</p>				
Additional Comments (including any equipment not checked off):	<span style="color: blue;">2RF-144 NORTHEAST RC</span>			


		<h2 style="text-align: center;">Monthly Inspection Report</h2> <p style="text-align: center;">Treated Water Containment / Pond</p>		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	
			Date/Time: 02-2025	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Yes or No	Working condition? (Good / Needs Repairs)	Comments	
Are diversion ditches and berms around the containment secure? (check for erosion and collection of surface water run-on)	YES	GOOD		
Is the leak detection system intact? (check for evidence of damage or malfunction and monitor for leakage).	YES	GOOD		
Are there any dead migratory birds and other wildlife inside pond/treated water?*	NO	GOOD		
Are the sources and disposition of all recycled water recorded?**	YES	GOOD		
<p>* Within 30 days of discovery, report the discovery of dead migratory birds or other wildlife to the appropriate wildlife agency and to the division district office in order to facilitate assessment and implementation of measures to prevent incidents from reoccurring</p> <p>** Report to the division the total volume of water received for recycling, with the amount of fresh water received listed separately, and the total volume of water leaving the facility for disposition by use of the form C-148</p>				
Additional Comments (including any equipment not checked off):	ID# 2RF-144			


		<h2 style="text-align: center;">Monthly Inspection Report</h2> <p style="text-align: center;">Treated Water Containment / Pond</p>		
Work Order No:				
Inspected by (name and signature): <span style="color: blue;">Marcos Montano</span> <i>Marcos Montano</i>				Date/Time: <span style="color: blue;">03-2025</span>
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	<span style="color: blue;">X</span>			
Equipment Description	Yes or No	Working condition? (Good / Needs Repairs)	Comments	
Are diversion ditches and berms around the containment secure? (check for erosion and collection of surface water run-on)	<span style="color: blue;">YES</span>	<span style="color: blue;">GOOD</span>		
Is the leak detection system intact? (check for evidence of damage or malfunction and monitor for leakage).	<span style="color: blue;">YES</span>	<span style="color: blue;">GOOD</span>		
Are there any dead migratory birds and other wildlife inside pond/treated water?*	<span style="color: blue;">NO</span>	<span style="color: blue;">GOOD</span>		
Are the sources and disposition of all recycled water recorded?**	<span style="color: blue;">YES</span>	<span style="color: blue;">GOOD</span>		
<p>* Within 30 days of discovery, report the discovery of dead migratory birds or other wildlife to the appropriate wildlife agency and to the division district office in order to facilitate assessment and implementation of measures to prevent incidents from reoccurring</p> <p>** Report to the division the total volume of water received for recycling, with the amount of fresh water received listed separately, and the total volume of water leaving the facility for disposition by use of the form C-148</p>				
Additional Comments (including any equipment not checked off):	<span style="color: blue;">2RF-144 NORTHEAST RC</span>			


		<h2 style="text-align: center;">Monthly Inspection Report</h2> <p style="text-align: center;">Treated Water Containment / Pond</p>		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	
			Date/Time: 03-2025	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Yes or No	Working condition? (Good / Needs Repairs)	Comments	
Are diversion ditches and berms around the containment secure? (check for erosion and collection of surface water run-on)	YES	GOOD		
Is the leak detection system intact? (check for evidence of damage or malfunction and monitor for leakage).	YES	GOOD		
Are there any dead migratory birds and other wildlife inside pond/treated water?*	NO	GOOD		
Are the sources and disposition of all recycled water recorded?**	YES	GOOD		
<p>* Within 30 days of discovery, report the discovery of dead migratory birds or other wildlife to the appropriate wildlife agency and to the division district office in order to facilitate assessment and implementation of measures to prevent incidents from reoccurring</p> <p>** Report to the division the total volume of water received for recycling, with the amount of fresh water received listed separately, and the total volume of water leaving the facility for disposition by use of the form C-148</p>				
Additional Comments (including any equipment not checked off):	ID# 2RF-144			


		<h2 style="text-align: center;">Monthly Inspection Report</h2> <p style="text-align: center;">Treated Water Containment / Pond</p>		
Work Order No:				
Inspected by (name and signature): <span style="color: blue;">Marcos Montano</span> <i>Marcos Montano</i>				Date/Time: <span style="color: blue;">04-2025</span>
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	<span style="color: blue;">X</span>			
Equipment Description	Yes or No	Working condition? (Good / Needs Repairs)	Comments	
Are diversion ditches and berms around the containment secure? (check for erosion and collection of surface water run-on)	<span style="color: blue;">YES</span>	<span style="color: blue;">GOOD</span>		
Is the leak detection system intact? (check for evidence of damage or malfunction and monitor for leakage).	<span style="color: blue;">YES</span>	<span style="color: blue;">GOOD</span>		
Are there any dead migratory birds and other wildlife inside pond/treated water?*	<span style="color: blue;">NO</span>	<span style="color: blue;">GOOD</span>		
Are the sources and disposition of all recycled water recorded?**	<span style="color: blue;">YES</span>	<span style="color: blue;">GOOD</span>		
<p>* Within 30 days of discovery, report the discovery of dead migratory birds or other wildlife to the appropriate wildlife agency and to the division district office in order to facilitate assessment and implementation of measures to prevent incidents from reoccurring</p> <p>** Report to the division the total volume of water received for recycling, with the amount of fresh water received listed separately, and the total volume of water leaving the facility for disposition by use of the form C-148</p>				
Additional Comments (including any equipment not checked off):	<span style="color: blue;">2RF-144 NORTHEAST RC</span>			





		<h2 style="text-align: center;">Monthly Inspection Report</h2> <p style="text-align: center;">Treated Water Containment / Pond</p>		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	
			Date/Time: 04-2025	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Yes or No	Working condition? (Good / Needs Repairs)	Comments	
Are diversion ditches and berms around the containment secure? (check for erosion and collection of surface water run-on)	YES	GOOD		
Is the leak detection system intact? (check for evidence of damage or malfunction and monitor for leakage).	YES	GOOD		
Are there any dead migratory birds and other wildlife inside pond/treated water?*	NO	GOOD		
Are the sources and disposition of all recycled water recorded?**	YES	GOOD		
<p>* Within 30 days of discovery, report the discovery of dead migratory birds or other wildlife to the appropriate wildlife agency and to the division district office in order to facilitate assessment and implementation of measures to prevent incidents from reoccurring</p> <p>** Report to the division the total volume of water received for recycling, with the amount of fresh water received listed separately, and the total volume of water leaving the facility for disposition by use of the form C-148</p>				
Additional Comments (including any equipment not checked off):	ID# 2RF-144			

		<h2 style="text-align: center;">Monthly Inspection Report</h2> <p style="text-align: center;">Treated Water Containment / Pond</p>		
Work Order No:				
Inspected by (name and signature): <b>Marcos Montano</b> <i>Marcos Montano</i>				Date/Time: <b>05-2025</b>
<b>Review of Prior Corrections</b>	<b>Yes</b>	<b>No</b>	<b>N/A</b>	<b>Comments</b>
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
<b>Equipment Description</b>	<b>Yes or No</b>	<b>Working condition? (Good / Needs Repairs)</b>	<b>Comments</b>	
Are diversion ditches and berms around the containment secure? (check for erosion and collection of surface water run-on)	YES	GOOD		
Is the leak detection system intact? (check for evidence of damage or malfunction and monitor for leakage).	YES	GOOD		
Are there any dead migratory birds and other wildlife inside pond/treated water?*	NO	GOOD		
Are the sources and disposition of all recycled water recorded?**	YES	GOOD		
<p>* Within 30 days of discovery, report the discovery of dead migratory birds or other wildlife to the appropriate wildlife agency and to the division district office in order to facilitate assessment and implementation of measures to prevent incidents from reoccurring</p> <p>** Report to the division the total volume of water received for recycling, with the amount of fresh water received listed separately, and the total volume of water leaving the facility for disposition by use of the form C-148</p>				
<b>Additional Comments (including any equipment not checked off):</b>	2RF-144 NORTHEAST RC			

		<h2 style="text-align: center;">Monthly Inspection Report</h2> <p style="text-align: center;">Treated Water Containment / Pond</p>		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	
			Date/Time: 05-2025	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Yes or No	Working condition? (Good / Needs Repairs)	Comments	
Are diversion ditches and berms around the containment secure? (check for erosion and collection of surface water run-on)	YES	GOOD		
Is the leak detection system intact? (check for evidence of damage or malfunction and monitor for leakage).	YES	GOOD		
Are there any dead migratory birds and other wildlife inside pond/treated water?*	NO	GOOD		
Are the sources and disposition of all recycled water recorded?**	YES	GOOD		
<p>* Within 30 days of discovery, report the discovery of dead migratory birds or other wildlife to the appropriate wildlife agency and to the division district office in order to facilitate assessment and implementation of measures to prevent incidents from reoccurring</p> <p>** Report to the division the total volume of water received for recycling, with the amount of fresh water received listed separately, and the total volume of water leaving the facility for disposition by use of the form C-148</p>				
Additional Comments (including any equipment not checked off):	ID# 2RF-144			


		<h2 style="text-align: center;">Monthly Inspection Report</h2> <p style="text-align: center;">Treated Water Containment / Pond</p>		
Work Order No:				
Inspected by (name and signature): <span style="color: blue;">Marcos Montano</span> <i>Marcos Montano</i>				Date/Time: <span style="color: blue;">06-2025</span>
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	<span style="color: blue;">X</span>			
Equipment Description	Yes or No	Working condition? (Good / Needs Repairs)	Comments	
Are diversion ditches and berms around the containment secure? (check for erosion and collection of surface water run-on)	<span style="color: blue;">YES</span>	<span style="color: blue;">GOOD</span>		
Is the leak detection system intact? (check for evidence of damage or malfunction and monitor for leakage).	<span style="color: blue;">YES</span>	<span style="color: blue;">GOOD</span>		
Are there any dead migratory birds and other wildlife inside pond/treated water?*	<span style="color: blue;">NO</span>	<span style="color: blue;">GOOD</span>		
Are the sources and disposition of all recycled water recorded?**	<span style="color: blue;">YES</span>	<span style="color: blue;">GOOD</span>		
<p>* Within 30 days of discovery, report the discovery of dead migratory birds or other wildlife to the appropriate wildlife agency and to the division district office in order to facilitate assessment and implementation of measures to prevent incidents from reoccurring</p> <p>** Report to the division the total volume of water received for recycling, with the amount of fresh water received listed separately, and the total volume of water leaving the facility for disposition by use of the form C-148</p>				
Additional Comments (including any equipment not checked off):	<span style="color: blue;">2RF-144 NORTHEAST RC</span>			


		<h2 style="text-align: center;">Monthly Inspection Report</h2> <p style="text-align: center;">Treated Water Containment / Pond</p>		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	Date/Time: 06-2025
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Yes or No	Working condition? (Good / Needs Repairs)	Comments	
Are diversion ditches and berms around the containment secure? (check for erosion and collection of surface water run-on)	YES	GOOD		
Is the leak detection system intact? (check for evidence of damage or malfunction and monitor for leakage).	YES	GOOD		
Are there any dead migratory birds and other wildlife inside pond/treated water?*	NO	GOOD		
Are the sources and disposition of all recycled water recorded?**	YES	GOOD		
<p>* Within 30 days of discovery, report the discovery of dead migratory birds or other wildlife to the appropriate wildlife agency and to the division district office in order to facilitate assessment and implementation of measures to prevent incidents from reoccurring</p> <p>** Report to the division the total volume of water received for recycling, with the amount of fresh water received listed separately, and the total volume of water leaving the facility for disposition by use of the form C-148</p>				
Additional Comments (including any equipment not checked off):	ID# 2RF-144			

		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>				Date/Time: 6-05-24
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		


CC RW North  
144  
2024





		<h2 style="text-align: center;">Weekly Inspection Report</h2> <h3 style="text-align: center;">Water Treatment Facility and Containment</h3>		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>				Date/Time: 6-12-24
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		


		<h2 style="text-align: center;">Weekly Inspection Report</h2> <h3 style="text-align: center;">Water Treatment Facility and Containment</h3>		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>			Date/Time: 6-19-24	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		




		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcoa Montano</i>				Date/Time: 6-26-24
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		


		<h2 style="text-align: center;">Weekly Inspection Report</h2> <h3 style="text-align: center;">Water Treatment Facility and Containment</h3>		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>				Date/Time: 7-3-24
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		


		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>			Date/Time: 7-10-24	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		


		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>				Date/Time: 7-17-24
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		




		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	Date/Time: 7-24-24
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		


		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>			Date/Time: 7-31-24	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		


		<h2 style="text-align: center;">Weekly Inspection Report</h2> <p style="text-align: center;">Water Treatment Facility and Containment</p>		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>				Date/Time: 8-07-24
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		


		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>				Date/Time: 8-14-24
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		




		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>			Date/Time: 8-21-24	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		


		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	Date/Time: 8-28-24
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		


		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	Date/Time: 9-4-24
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		


		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>			Date/Time: 9-11-24	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		




		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>				Date/Time: 9-18-24
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		


		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	Date/Time: 9-25-24
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		


		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	Date/Time: 10-2-24
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		


		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	Date/Time: 10-9-24
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		




		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>			Date/Time: 10-16-24	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		


		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	Date/Time: 10-23-24
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		


		<b>Weekly Inspection Report</b> <b>Water Treatment Facility and Containment</b>		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	Date/Time: 10-30-24
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		


		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	Date/Time: 11-06-24
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		




		<h2 style="text-align: center;">Weekly Inspection Report</h2> <h3 style="text-align: center;">Water Treatment Facility and Containment</h3>		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>				Date/Time: 11-13-24
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		


		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>				Date/Time: 11-20-24
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		


		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>				Date/Time: 11-27-24
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		

		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	Date/Time: 12-04-24
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		




		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>				Date/Time: 12-11-24
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		

		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>				Date/Time: 12-18-24
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		

		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>				Date/Time: 12-25-24
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		





		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>			Date/Time: 01-01-25	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact		GOOD		
Does surface show visible				
Fluid Height of Staff Gau				
* If a liner's integrity is compromised, notify the District office with			ter surface, then the operator will	
Additional Comments (in any equipment not checked)				

CC RW North


144


2025

		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>				Date/Time: 01-07-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		


		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>				Date/Time: 01-15-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		





		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>				Date/Time: 01-22-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		


		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>				Date/Time: 01-29-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		




		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>				Date/Time: 02-05-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		


		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>				Date/Time: 02-12-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		

		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	Date/Time: 02-19-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		


		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>				Date/Time: 02-26-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		





		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>				Date/Time: 03-05-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		


		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>				Date/Time: 03-12-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		




		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>				Date/Time: 03-19-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		


		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>				Date/Time: 03-26-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		

		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>				Date/Time: 04-02-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		


		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>				Date/Time: 04-09-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		





		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	Date/Time: 04-23-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		


		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	Date/Time: 04-30-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		




		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>				Date/Time: 05-07-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		


		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	Date/Time: 05-14-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		

		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	Date/Time: 05-21-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		


		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	Date/Time: 05-28-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		




		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>				Date/Time: 06-04-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		


		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>				Date/Time: 06-11-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		




		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>			Date/Time: 06-25-25	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144		



		<h2 style="text-align: center;">Weekly Inspection Report</h2> <h3 style="text-align: center;">Water Treatment Facility and Containment</h3>		
Work Order No:				
Inspected by (name and signature): Nathaniel Martinez <i>Nathaniel Martinez</i>				Date/Time: 7-16-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):	2RF-144- b			

CC RW  
 south  
 144B  
 2025


		<h2 style="text-align: center;">Weekly Inspection Report</h2> <h3 style="text-align: center;">Water Treatment Facility and Containment</h3>		
Work Order No:				
Inspected by (name and signature): Nathaniel Martinez <i>Nathaniel Martinez</i>				Date/Time: 7-9-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144-b		






		<h2 style="text-align: center;">Weekly Inspection Report</h2> <p style="text-align: center;">Water Treatment Facility and Containment</p>		
Work Order No:				
Inspected by (name and signature): Nathaniel Martinez <i>Nathaniel Martinez</i>				Date/Time: 07-03-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144-b		


		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>				Date/Time: 06-25-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144 		





		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>				Date/Time: 06-18-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144 B		

		<h2 style="text-align: center;">Weekly Inspection Report</h2> <h3 style="text-align: center;">Water Treatment Facility and Containment</h3>		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>				Date/Time: 06-04-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144 		


		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>				Date/Time: 05-21-25
<b>Review of Prior Corrections</b>	<b>Yes</b>	<b>No</b>	<b>N/A</b>	<b>Comments</b>
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
<b>Equipment Description</b>	<b>Leak or spill? (Y/N)</b>	<b>Working condition? (Good / Needs Repairs)</b>	<b>Comments</b>	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144 <i>B</i>		


		<h2 style="text-align: center;">Weekly Inspection Report</h2> <h3 style="text-align: center;">Water Treatment Facility and Containment</h3>		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	Date/Time: 05-14-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144 B		





		<h2 style="text-align: center;">Weekly Inspection Report</h2> <p style="text-align: center;">Water Treatment Facility and Containment</p>		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>			Date/Time: 05-07-25	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144 		




		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>				Date/Time: 04-30-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144 B		

		<h2 style="text-align: center;">Weekly Inspection Report</h2> <p style="text-align: center;">Water Treatment Facility and Containment</p>		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	Date/Time: 04-23-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s):	-			
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):	2RF-144 B			


		<h2 style="text-align: center;">Weekly Inspection Report</h2> <h3 style="text-align: center;">Water Treatment Facility and Containment</h3>		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>				Date/Time: 04-16-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s):	-			
<small>* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).</small>				
Additional Comments (including any equipment not checked off):	2RF-144 B			


		<h2 style="text-align: center;">Weekly Inspection Report</h2> <h3 style="text-align: center;">Water Treatment Facility and Containment</h3>		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	Date/Time: 04-09-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s):	-			
<small>* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).</small>				
Additional Comments (including any equipment not checked off):	2RF-144 <i>B</i>			





		<h2 style="text-align: center;">Weekly Inspection Report</h2> <h3 style="text-align: center;">Water Treatment Facility and Containment</h3>		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	Date/Time: 04-02-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s):	-			
<small>* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).</small>				
Additional Comments (including any equipment not checked off):	2RF-144 B			




		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>			Date/Time: 03-26-25	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144 <i>B</i>		

		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	Date/Time: 03-19-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144 <i>B</i>		


		<h2 style="text-align: center;">Weekly Inspection Report</h2> <p style="text-align: center;">Water Treatment Facility and Containment</p>		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	Date/Time: 03-12-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144 <i>B</i>		


		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>			Date/Time: 03-05-25	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144 B		





		<h2 style="text-align: center;">Weekly Inspection Report</h2> <p style="text-align: center;">Water Treatment Facility and Containment</p>		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	Date/Time: 02-26-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144B		




		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>			Date/Time: 02-19-25	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144 B		

		<h2 style="text-align: center;">Weekly Inspection Report</h2> <p style="text-align: center;">Water Treatment Facility and Containment</p>		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>			Date/Time: 02-12-25	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144 B		


		<h2 style="text-align: center;">Weekly Inspection Report</h2> <h3 style="text-align: center;">Water Treatment Facility and Containment</h3>		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>				Date/Time: 02-05-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144 B		


		<h2 style="text-align: center;">Weekly Inspection Report</h2> <p style="text-align: center;">Water Treatment Facility and Containment</p>		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	Date/Time: 01-29-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144 B		





		<h2 style="text-align: center;">Weekly Inspection Report</h2> <h3 style="text-align: center;">Water Treatment Facility and Containment</h3>		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>			Date/Time: 01-22-25	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144 B		




		<h2 style="text-align: center;">Weekly Inspection Report</h2> <p style="text-align: center;">Water Treatment Facility and Containment</p>		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>			Date/Time: 01-15-25	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144 B		

		<h2 style="text-align: center;">Weekly Inspection Report</h2> <h3 style="text-align: center;">Water Treatment Facility and Containment</h3>		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	Date/Time: 01-07-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144 <i>B</i>		


		<h2 style="text-align: center;">Weekly Inspection Report</h2> <h3 style="text-align: center;">Water Treatment Facility and Containment</h3>		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	Date/Time: 01-01-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144 B		


		<h2 style="text-align: center;">Weekly Inspection Report</h2> <h3 style="text-align: center;">Water Treatment Facility and Containment</h3>		
Work Order No:				
Inspected by (name and signature): Nathaniel Martinez <i>Nathaniel Martinez</i>				Date/Time: 7-16-25
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s):	-			
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):	2RF-144- b			




		<b>Weekly Inspection Report</b> <b>Water Treatment Facility and Containment</b>		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>			Date/Time: 12-25-24	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144-b		

CC RW  
 South  
 144B  
 2024


		<b>Weekly Inspection Report</b> <b>Water Treatment Facility and Containment</b>		
<b>Work Order No:</b>				
<b>Inspected by (name and signature):</b> Marcos Montano <i>Marcos Montano</i>			<b>Date/Time:</b> 12-18-24	
<b>Review of Prior Corrections</b>	<b>Yes</b>	<b>No</b>	<b>N/A</b>	<b>Comments</b>
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
<b>Equipment Description</b>	<b>Leak or spill? (Y/N)</b>	<b>Working condition? (Good / Needs Repairs)</b>	<b>Comments</b>	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
<b>Additional Comments (including any equipment not checked off):</b>		2RF-144-b		


		<h2 style="text-align: center;">Weekly Inspection Report</h2> <h3 style="text-align: center;">Water Treatment Facility and Containment</h3>		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>			Date/Time: 12-11-24	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144-b		





		<b>Weekly Inspection Report</b> <b>Water Treatment Facility and Containment</b>		
<b>Work Order No:</b>				
<b>Inspected by (name and signature):</b> Marcos Montano <i>Marcos Montano</i>			<b>Date/Time:</b> 11-27-24	
<b>Review of Prior Corrections</b>	<b>Yes</b>	<b>No</b>	<b>N/A</b>	<b>Comments</b>
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
<b>Equipment Description</b>	<b>Leak or spill? (Y/N)</b>	<b>Working condition? (Good / Needs Repairs)</b>	<b>Comments</b>	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
<b>Additional Comments (including any equipment not checked off):</b>	2RF-144-b			




		<h2 style="text-align: center;">Weekly Inspection Report</h2> <h3 style="text-align: center;">Water Treatment Facility and Containment</h3>		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	Date/Time: 11-20-24
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144-b		


		<b>Weekly Inspection Report</b> <b>Water Treatment Facility and Containment</b>		
<b>Work Order No:</b>				
<b>Inspected by (name and signature):</b> Marcos Montano <i>Marcos Montano</i>			<b>Date/Time:</b> 11-13-24	
<b>Review of Prior Corrections</b>	<b>Yes</b>	<b>No</b>	<b>N/A</b>	<b>Comments</b>
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
<b>Equipment Description</b>	<b>Leak or spill? (Y/N)</b>	<b>Working condition? (Good / Needs Repairs)</b>	<b>Comments</b>	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
<b>Additional Comments (including any equipment not checked off):</b>	2RF-144-b			


		<h2 style="text-align: center;">Weekly Inspection Report</h2> <h3 style="text-align: center;">Water Treatment Facility and Containment</h3>		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	Date/Time: 11-06-24
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144-b		


		<b>Weekly Inspection Report</b> <b>Water Treatment Facility and Containment</b>		
<b>Work Order No:</b>				
<b>Inspected by (name and signature):</b> Marcos Montano <i>Marcos Montano</i>			<b>Date/Time:</b> 10-30-24	
<b>Review of Prior Corrections</b>	<b>Yes</b>	<b>No</b>	<b>N/A</b>	<b>Comments</b>
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
<b>Equipment Description</b>	<b>Leak or spill? (Y/N)</b>	<b>Working condition? (Good / Needs Repairs)</b>	<b>Comments</b>	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
<b>Additional Comments (including any equipment not checked off):</b>		2RF-144-b		




		<b>Weekly Inspection Report</b> <b>Water Treatment Facility and Containment</b>		
<b>Work Order No:</b>				
<b>Inspected by (name and signature):</b> Marcos Montano <i>Marcos Montano</i>			<b>Date/Time:</b> 10-23-24	
<b>Review of Prior Corrections</b>	<b>Yes</b>	<b>No</b>	<b>N/A</b>	<b>Comments</b>
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
<b>Equipment Description</b>	<b>Leak or spill? (Y/N)</b>	<b>Working condition? (Good / Needs Repairs)</b>	<b>Comments</b>	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
<b>Additional Comments (including any equipment not checked off):</b>		2RF-144-b		


		<b>Weekly Inspection Report</b> <b>Water Treatment Facility and Containment</b>		
<b>Work Order No:</b>				
<b>Inspected by (name and signature):</b> Marcos Montano <i>Marcos Montano</i>			<b>Date/Time:</b> 10-16-24	
<b>Review of Prior Corrections</b>	<b>Yes</b>	<b>No</b>	<b>N/A</b>	<b>Comments</b>
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
<b>Equipment Description</b>	<b>Leak or spill? (Y/N)</b>	<b>Working condition? (Good / Needs Repairs)</b>	<b>Comments</b>	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
<b>Additional Comments (including any equipment not checked off):</b>	2RF-144-b			


		<b>Weekly Inspection Report</b> <b>Water Treatment Facility and Containment</b>		
<b>Work Order No:</b>				
<b>Inspected by (name and signature):</b> Marcos Montano <i>Marcos Montano</i>			<b>Date/Time:</b> 10-2-24	
<b>Review of Prior Corrections</b>	<b>Yes</b>	<b>No</b>	<b>N/A</b>	<b>Comments</b>
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
<b>Equipment Description</b>	<b>Leak or spill? (Y/N)</b>	<b>Working condition? (Good / Needs Repairs)</b>	<b>Comments</b>	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
<b>Additional Comments (including any equipment not checked off):</b>	2RF-144-b			


		<h2 style="text-align: center;">Weekly Inspection Report</h2> <h3 style="text-align: center;">Water Treatment Facility and Containment</h3>		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	Date/Time: 10-9-24
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144-b		




		<h2 style="text-align: center;">Weekly Inspection Report</h2> <h3 style="text-align: center;">Water Treatment Facility and Containment</h3>		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	Date/Time: 9-25-24
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144-b		


		<b>Weekly Inspection Report</b> <b>Water Treatment Facility and Containment</b>		
<b>Work Order No:</b>				
<b>Inspected by (name and signature):</b> Marcos Montano <i>Marcos Montano</i>			<b>Date/Time:</b> 9-18-24	
<b>Review of Prior Corrections</b>	<b>Yes</b>	<b>No</b>	<b>N/A</b>	<b>Comments</b>
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
<b>Equipment Description</b>	<b>Leak or spill? (Y/N)</b>	<b>Working condition? (Good / Needs Repairs)</b>	<b>Comments</b>	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
<b>Additional Comments (including any equipment not checked off):</b>		2RF-144-b		


		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>			Date/Time: 9-11-24	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144-b		


		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>			Date/Time: 9-4-24	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144-b		




		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	Date/Time: 8-28-24
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144-b		


		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>			Date/Time: 8-21-24	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144-b		


		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>			Date/Time: 8-14-24	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144-b		


		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>			Date/Time: 8-07-24	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144-b		




		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>			Date/Time: 8-07-24	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144-b		


		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>			Date/Time: 7-31-24	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144-b		


		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>			Date/Time: 7-24-24	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144-b		


		<h2 style="text-align: center;">Weekly Inspection Report</h2> <p style="text-align: center;">Water Treatment Facility and Containment</p>		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>			Date/Time: 7-17-24	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144-b		




		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>			Date/Time: 7-10-24	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144-b		


		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>			Date/Time: 7-3-24	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144-b		

		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>			Date/Time: 6-26-24	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144-b		

		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>			Date/Time: 6-19-24	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144-b		



		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature): Marcos Montano <i>Marcos Montano</i>			Date/Time: 6-05-24	
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144-b		

		<b>Weekly Inspection Report</b> Water Treatment Facility and Containment		
Work Order No:				
Inspected by (name and signature):			Marcos Montano <i>Marcos Montano</i>	Date/Time: 6-05-24
Review of Prior Corrections	Yes	No	N/A	Comments
Have all identified issues from the previous facility inspection report been corrected and noted?	X			
Equipment Description	Leak or spill? (Y/N)	Working condition? (Good / Needs Repairs)	Comments	
<b>Water Treatment Facility</b>				
Upstream Pump (20 HP)	N	GOOD		
Flow Line to Reaction Tanks	N	GOOD		
Reaction Tanks	N	GOOD		
Treatment pump (50 HP)	N	GOOD		
Weir Tanks	N	GOOD		
Manifold at Weir Tank	N	GOOD		
Recycle & Flowback Lines	N	GOOD		
Downstream Pump (20 HP)	N	GOOD		
Flow Line to Treated Water Pond	N	GOOD		
<b>Treated Water Containment(s) / Pond(s)</b>				
Manifold	N	GOOD		
Leak Detection System*	N	GOOD		
Are exposed liners intact?*	y	GOOD		
Does surface show visible oil?	N	GOOD		
Fluid Height of Staff Gauge(s): -				
* If a liner's integrity is compromised, or if any penetration of the liner occurs above the water surface, then the operator will notify the District office within 48 hours (phone or email).				
Additional Comments (including any equipment not checked off):		2RF-144-b		

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505

CONDITIONS

Action 489044

CONDITIONS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 489044
	Action Type: [C-147] Water Recycle Long (C-147L)

CONDITIONS

Created By	Condition	Condition Date
vvenegas	• 2RF-144 - CEDAR CANYON RECYCLING FACILITY A & B [fBGB1922049166] is approved for one (1) year of operation from the date of the previous registration/permit expiration date of August 10, 2025. The new registration/permit expiration date is August 10, 2026. If [16696] OXY USA INC wishes to extend the registration/permit past August 10, 2026, a registration/permit extension request must be submitted to OCD no later than July 10, 2026.	8/11/2025