

**From:** [Shelly Cowden](#)  
**To:** "Venegas, Victoria, EMNRD"  
**Subject:** RE: 1RF-463 - JAVELINA FACILITY [FVV2108855989]  
**Date:** Monday, March 30, 2026 12:14:00 PM

---

Victoria,

I wanted to follow up regarding the inspection structure for the Javelina Recycling Facility and clarify how our current practices align with the approved permit requirements.

The inspection frequencies and level of detail are defined within the permit and are being implemented accordingly:

**Weekly Inspections (Permit-Defined Requirements):**

Weekly inspections are conducted as a site-level operational review and include:

- Reading and recording fluid levels from staff gauges
- Documenting any visible oil on the pond surface
- Visual inspection of exposed liners
- Checking the leak detection system for indications of loss of primary liner integrity

Per the permit, any compromise to liner integrity or penetration above the water surface is reported to the District Office within 48 hours.

**Monthly Inspections (Permit-Defined Detailed Requirements):**

The permit specifies that the following items are to be addressed on a monthly basis:

- Inspection of diversion ditches and berms for erosion and run-on
- Inspection of the leak detection system for damage or malfunction and monitoring for leakage
- Inspection for dead migratory birds and wildlife, with required reporting within 30 days
- Reporting of water volumes received and disposed of via Form C-148
- Recording sources and disposition of recycled water

Additionally, inspection logs are maintained and made available to the Division upon request, as required by the permit.

Based on the above, equipment-level and detailed inspection elements are specifically assigned to the monthly inspection frequency within the permit, while weekly inspections are intended to remain a higher-level operational check.

We want to ensure we remain fully aligned with the permit as written. If there has been a revision or additional guidance requiring equipment-level detail at a weekly frequency, please

feel free to share, and we can review and adjust accordingly.  
Otherwise, we will continue to follow the inspection structure as defined in the approved permit.

Please let me know if you would like to discuss further.

Thank you,  
Shelly Cowden

---

**From:** Shelly Cowden  
**Sent:** Tuesday, March 24, 2026 11:53 AM  
**To:** 'Venegas, Victoria, EMNRD' <Victoria.Venegas@emnrd.nm.gov>  
**Subject:** RE: 1RF-463 - JAVELINA FACILITY [fVV2108855989]

Hello Ms. Venegas,

Addressing each discrepancy/concern:

- I will review the data submitted and supply the missing information.
- The renewal package will be reorganized as requested.
- The inspection reports are for the entire facility and all ancillary equipment.
- My apologies for the oversight with the additional inspections.

This will be updated and resubmitted ASAP.

Thank you,  
Shelly Cowden

---

**From:** Venegas, Victoria, EMNRD <Victoria.Venegas@emnrd.nm.gov>  
**Sent:** Tuesday, March 24, 2026 11:46 AM  
**To:** Shelly Cowden <Shelly.Cowden@pilotwater.com>  
**Subject:** 1RF-463 - JAVELINA FACILITY [fVV2108855989]

**CAUTION:** External Sender Email: Use caution with links / attachments.

**1RF-463 - JAVELINA FACILITY [fVV2108855989]**

Good morning Ms. Cowden.

The NMOCD has reviewed the recycling containment annual extension request, submitted by [308339] OWL SWD OPERATING, LLC on 3/12/2026, Application ID **562417**, for 1RF-463 - JAVELINA FACILITY [fVV2108855989] in H-18-26S-35E, Lea County, New Mexico. The annual extension request is denied for the following reasons:

Missing information. Please, include the reports March 2025 through February 2026.

- Keep monthly and weekly reports separate for clarity; list all monthly reports first, followed by all weekly reports in chronological order.
- Please specify the name of the containment (AST or pond) in each inspection report. All containments are required to be inspected in accordance with the conditions of approval
- Do not include any inspection reports associated with the Fulfer facility.
- Please correct and resubmit.

Please let me know if you have any additional questions.

Regards,

**Victoria Venegas** • Senior Environmental Scientist  
EMNRD - Oil Conservation Division  
506 W. Texas Ave. Artesia, NM 88210  
575.909.0269 | [Victoria.Venegas@emnrd.nm.gov](mailto:Victoria.Venegas@emnrd.nm.gov)

State of New Mexico
Energy Minerals and Natural Resources
Department Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505
https://www.emnrd.nm.gov/ocd/ocd-e-permitting/

Recycling Facility and/or Recycling Containment

Type of Facility: [ ] Recycling Facility [ ] Recycling Containment\*
Type of action: [x] Permit [ ] Registration
[ ] Modification [x] Extension
[ ] Closure [x] Other (explain) Annual Renewal

\* At the time C-147 is submitted to the division for a Recycling Containment, a copy shall be provided to the surface owner.

Be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances.

1. Operator: OWL SWD Operating LLC (For multiple operators attach page with information) OGRID #: 308339
Address: 20 Greenway Plaza, Suite 500 Houston, TX 77046
Facility or well name (include API# if associated with a well): Javelina Facility AST
OCD Permit Number: 1RF-463 (For new facilities the permit number will be assigned by the district office)
U/L or Qtr/Qtr E1/2 pf NE1/4 Section 18 Township 26 South Range 35 East County: Lea County
Surface Owner: [x] Federal [ ] State [ ] Private [ ] Tribal Trust or Indian Allotment

2. [x] Recycling Facility:
Location of recycling facility (if applicable): Latitude 32.048956 Longitude -103.401212 NAD83
Proposed Use: [ ] Drilling\* [x] Completion\* [ ] Production\* [ ] Plugging \*
\*The re-use of produced water may NOT be used until fresh water zones are cased and cemented
[ ] Other, requires permit for other uses. Describe use, process, testing, volume of produced water and ensure there will be no adverse impact on groundwater or surface water.
[x] Fluid Storage
[x] Above ground tanks [x] Recycling containment [ ] Activity permitted under 19.15.17 NMAC explain type
[ ] Activity permitted under 19.15.36 NMAC explain type: [ ] Other explain
[ ] For multiple or additional recycling containments, attach design and location information of each containment
[ ] Closure Report (required within 60 days of closure completion): [ ] Recycling Facility Closure Completion Date:

3. [x] Recycling Containment:
[ ] Annual Extension after initial 5 years (attach summary of monthly leak detection inspections for previous year)
Center of Recycling Containment (if applicable): Latitude Longitude NAD83
[ ] For multiple or additional recycling containments, attach design and location information of each containment
[ ] Lined [ ] Liner type: Thickness 60/40 mil [ ] LLDPE [x] HDPE [ ] PVC [ ] Other With Leak Detection
[ ] String-Reinforced Round AST: 190' Diameter
Liner Seams: [ ] Welded [ ] Factory [ ] Other Volume: 48,000 bbl Dimensions: L x W x D
[ ] Recycling Containment Closure Completion Date:

4.

**Bonding:**

Covered under bonding pursuant to 19.15.8 NMAC per 19.15.34.15(A)(2) NMAC (These containments are limited to only the wells owned or operated by the owners of the containment.)

Bonding in accordance with 19.15.34.15(A)(1). Amount of bond \$ 58,000 (work on these facilities cannot commence until bonding amounts are approved)

Attach closure cost estimate and documentation on how the closure cost was calculated.

5.

**Fencing:**

Four foot height, four strands of barbed wire evenly spaced between one and four feet

Alternate. Please specify 6' Chain Link Dence

6.

**Signs:**

12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers

Signed in compliance with 19.15.16.8 NMAC

7.

**Variances:**

Justifications and/or demonstrations that the proposed variance will afford reasonable protection against contamination of fresh water, human health, and the environment.

**Check the below box only if a variance is requested:**

Variance(s): Requests must be submitted to the appropriate division district for consideration of approval. If a Variance is requested, include the variance information on a separate page and attach it to the C-147 as part of the application.

**If a Variance is requested, it must be approved prior to implementation.**

8.

**Siting Criteria for Recycling Containment**

*Instructions: The applicant must provide attachments that demonstrate compliance for each siting criteria below as part of the application. Potential examples of the siting attachment source material are provided below under each criteria.*

<b>General siting</b>	
<b>Ground water is less than 50 feet below the bottom of the Recycling Containment.</b> NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> NA
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended. - Written confirmation or verification from the municipality; written approval obtained from the municipality	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> NA
Within the area overlying a subsurface mine. - Written confirmation or verification or map from the NM EMNRD-Mining and Minerals Division	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Within an unstable area. - Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; topographic map	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Within a 100-year floodplain. FEMA map	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; visual inspection (certification) of the proposed site	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. - Visual inspection (certification) of the proposed site; aerial photo; satellite image	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application. - NM Office of the State Engineer - iWATERS database search; visual inspection (certification) of the proposed site	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Within 500 feet of a wetland. - US Fish and Wildlife Wetland Identification map; topographic map; visual inspection (certification) of the proposed site	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No

9.

**Recycling Facility and/or Containment Checklist:**

**Instructions:** Each of the following items must be attached to the application. Indicate, by a check mark in the box, that the documents are attached.

- Design Plan - based upon the appropriate requirements.
- Operating and Maintenance Plan - based upon the appropriate requirements.
- Closure Plan - based upon the appropriate requirements.
- Site Specific Groundwater Data -
- Siting Criteria Compliance Demonstrations -
- Certify that notice of the C-147 (only) has been sent to the surface owner(s)

10.

**Operator Application Certification:**

I hereby certify that the information and attachments submitted with this application are true, accurate and complete to the best of my knowledge and belief.

Name (Print): David Grounds Title: VP Regulatory  
 Signature: David Grounds Date: 03/24/2026  
 e-mail address: David.Grounds@pilotwater.com Telephone: (817) 897-0135

11.

OCD Representative Signature: Victoria Venegas Approval Date: 04/02/2026

Title: Senior Environmental Scientist OCD Permit Number: 1RF-463

- OCD Conditions \_\_\_\_\_
- Additional OCD Conditions on Attachment \_\_\_\_\_

State of New Mexico
Energy Minerals and Natural Resources
Department Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505
https://www.emnrd.nm.gov/ocd/ocd-e-permitting/

Recycling Facility and/or Recycling Containment

Type of Facility: [ ] Recycling Facility [ ] Recycling Containment\*
Type of action: [x] Permit [ ] Registration
[ ] Modification [x] Extension
[ ] Closure [x] Other (explain) Annual Renewal

\* At the time C-147 is submitted to the division for a Recycling Containment, a copy shall be provided to the surface owner.

Be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances.

1. Operator: OWL SWD Operating LLC (For multiple operators attach page with information) OGRID #: 308339
Address: 20 Greenway Plaza, Suite 500 Houston, TX 77046
Facility or well name (include API# if associated with a well): Javelina Facility North Pit
OCD Permit Number: 1RF-463 (For new facilities the permit number will be assigned by the district office)
U/L or Qtr/Qtr E1/2 of NE1/4 Section 18 Township 26 South Range 35 East County: Lea County
Surface Owner: [ ] Federal [ ] State [ ] Private [ ] Tribal Trust or Indian Allotment

2. [x] Recycling Facility:
Location of recycling facility (if applicable): Latitude 32.048477 Longitude -103.400286 NAD83
Proposed Use: [ ] Drilling\* [x] Completion\* [ ] Production\* [ ] Plugging \*
\*The re-use of produced water may NOT be used until fresh water zones are cased and cemented
[ ] Other, requires permit for other uses. Describe use, process, testing, volume of produced water and ensure there will be no adverse impact on groundwater or surface water.
[x] Fluid Storage
[x] Above ground tanks [x] Recycling containment [ ] Activity permitted under 19.15.17 NMAC explain type
[ ] Activity permitted under 19.15.36 NMAC explain type: [ ] Other explain
[ ] For multiple or additional recycling containments, attach design and location information of each containment
[ ] Closure Report (required within 60 days of closure completion): [ ] Recycling Facility Closure Completion Date:

3. [x] Recycling Containment:
[ ] Annual Extension after initial 5 years (attach summary of monthly leak detection inspections for previous year)
Center of Recycling Containment (if applicable): Latitude Longitude NAD83
[ ] For multiple or additional recycling containments, attach design and location information of each containment
[x] Lined [ ] Liner type: Thickness 60/40 mil [ ] LLDPE [x] HDPE [ ] PVC [ ] Other With Leak Detection
[ ] String-Reinforced
Liner Seams: [x] Welded [ ] Factory [ ] Other Volume: 346,000 bbl Dimensions: L 320 x W 565 x D 18
[ ] Recycling Containment Closure Completion Date:

4.

**Bonding:**

Covered under bonding pursuant to 19.15.8 NMAC per 19.15.34.15(A)(2) NMAC (These containments are limited to only the wells owned or operated by the owners of the containment.)

Bonding in accordance with 19.15.34.15(A)(1). Amount of bond \$ 442,500 (work on these facilities cannot commence until bonding amounts are approved)

Attach closure cost estimate and documentation on how the closure cost was calculated.

5.

**Fencing:**

Four foot height, four strands of barbed wire evenly spaced between one and four feet

Alternate. Please specify 6' Chain Link Fence

6.

**Signs:**

12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers

Signed in compliance with 19.15.16.8 NMAC

7.

**Variances:**

Justifications and/or demonstrations that the proposed variance will afford reasonable protection against contamination of fresh water, human health, and the environment.

**Check the below box only if a variance is requested:**

Variance(s): Requests must be submitted to the appropriate division district for consideration of approval. If a Variance is requested, include the variance information on a separate page and attach it to the C-147 as part of the application.

**If a Variance is requested, it must be approved prior to implementation.**

8.

**Siting Criteria for Recycling Containment**

*Instructions: The applicant must provide attachments that demonstrate compliance for each siting criteria below as part of the application. Potential examples of the siting attachment source material are provided below under each criteria.*

<b>General siting</b>	
<b>Ground water is less than 50 feet below the bottom of the Recycling Containment.</b> NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> NA
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended. - Written confirmation or verification from the municipality; written approval obtained from the municipality	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> NA
Within the area overlying a subsurface mine. - Written confirmation or verification or map from the NM EMNRD-Mining and Minerals Division	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Within an unstable area. - Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; topographic map	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Within a 100-year floodplain. FEMA map	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; visual inspection (certification) of the proposed site	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. - Visual inspection (certification) of the proposed site; aerial photo; satellite image	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application. - NM Office of the State Engineer - iWATERS database search; visual inspection (certification) of the proposed site	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Within 500 feet of a wetland. - US Fish and Wildlife Wetland Identification map; topographic map; visual inspection (certification) of the proposed site	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No

9.

**Recycling Facility and/or Containment Checklist:**

*Instructions: Each of the following items must be attached to the application. Indicate, by a check mark in the box, that the documents are attached.*

- Design Plan - based upon the appropriate requirements.
- Operating and Maintenance Plan - based upon the appropriate requirements.
- Closure Plan - based upon the appropriate requirements.
- Site Specific Groundwater Data -
- Siting Criteria Compliance Demonstrations -
- Certify that notice of the C-147 (only) has been sent to the surface owner(s)**

10.

**Operator Application Certification:**

I hereby certify that the information and attachments submitted with this application are true, accurate and complete to the best of my knowledge and belief.

Name (Print): David Grounds Title: VP Regulatory  
 Signature: *David Grounds* Date: 03/24/2026  
 e-mail address: David.Grounds@pilotwater.com Telephone: (817) 897-0135

11.

OCD Representative Signature: *Victoria Venegas* Approval Date: 04/02/2026

Title: Senior Environmental Scientist OCD Permit Number: 1RF-463

- OCD Conditions \_\_\_\_\_
- Additional OCD Conditions on Attachment

State of New Mexico
Energy Minerals and Natural Resources
Department Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

https://www.emnrd.nm.gov/ocd/ocd-e-permitting/

Recycling Facility and/or Recycling Containment

Type of Facility: [ ] Recycling Facility [ ] Recycling Containment\*
Type of action: [x] Permit [ ] Registration
[ ] Modification [x] Extension
[ ] Closure [x] Other (explain) Annual Renewal

\* At the time C-147 is submitted to the division for a Recycling Containment, a copy shall be provided to the surface owner.

Be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances.

1. Operator: OWL SWD Operating LLC (For multiple operators attach page with information) OGRID #: 308339
Address: 20 Greenway Plaza, Suite 500 Houston, TX 77046
Facility or well name (include API# if associated with a well): Javelina Facility South Pit
OCD Permit Number: 1RF-463 (For new facilities the permit number will be assigned by the district office)
U/L or Qtr/Qtr E1/2 of NE1/4 Section 18 Township 26 South Range 35 East County: Lea County
Surface Owner: [ ] Federal [ ] State [ ] Private [ ] Tribal Trust or Indian Allotment

2. [x] Recycling Facility:
Location of recycling facility (if applicable): Latitude 32.046680 Longitude -103.400658 NAD83
Proposed Use: [ ] Drilling\* [x] Completion\* [ ] Production\* [ ] Plugging \*
\*The re-use of produced water may NOT be used until fresh water zones are cased and cemented
[ ] Other, requires permit for other uses. Describe use, process, testing, volume of produced water and ensure there will be no adverse impact on groundwater or surface water.
[x] Fluid Storage
[x] Above ground tanks [x] Recycling containment [ ] Activity permitted under 19.15.17 NMAC explain type
[ ] Activity permitted under 19.15.36 NMAC explain type: [ ] Other explain
[ ] For multiple or additional recycling containments, attach design and location information of each containment
[ ] Closure Report (required within 60 days of closure completion): [ ] Recycling Facility Closure Completion Date:

3. [x] Recycling Containment:
[ ] Annual Extension after initial 5 years (attach summary of monthly leak detection inspections for previous year)
Center of Recycling Containment (if applicable): Latitude Longitude NAD83
[ ] For multiple or additional recycling containments, attach design and location information of each containment
[x] Lined [ ] Liner type: Thickness 60/40 mil [ ] LLDPE [ ] HDPE [ ] PVC [ ] Other With Leak Detection
[ ] String-Reinforced
Liner Seams: [x] Welded [ ] Factory [ ] Other Volume: 512,000 bbl Dimensions: L 500' x W 500' x D 18'
[ ] Recycling Containment Closure Completion Date:

4.

**Bonding:**

Covered under bonding pursuant to 19.15.8 NMAC per 19.15.34.15(A)(2) NMAC (These containments are limited to only the wells owned or operated by the owners of the containment.)

Bonding in accordance with 19.15.34.15(A)(1). Amount of bond \$ 654,000 (work on these facilities cannot commence until bonding amounts are approved)

Attach closure cost estimate and documentation on how the closure cost was calculated.

5.

**Fencing:**

Four foot height, four strands of barbed wire evenly spaced between one and four feet

Alternate. Please specify 6' Chain Link Fence

6.

**Signs:**

12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers

Signed in compliance with 19.15.16.8 NMAC

7.

**Variances:**

Justifications and/or demonstrations that the proposed variance will afford reasonable protection against contamination of fresh water, human health, and the environment.

**Check the below box only if a variance is requested:**

Variance(s): Requests must be submitted to the appropriate division district for consideration of approval. If a Variance is requested, include the variance information on a separate page and attach it to the C-147 as part of the application.

**If a Variance is requested, it must be approved prior to implementation.**

8.

**Siting Criteria for Recycling Containment**

*Instructions: The applicant must provide attachments that demonstrate compliance for each siting criteria below as part of the application. Potential examples of the siting attachment source material are provided below under each criteria.*

<b>General siting</b>	
<b>Ground water is less than 50 feet below the bottom of the Recycling Containment.</b> NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> NA
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended. - Written confirmation or verification from the municipality; written approval obtained from the municipality	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> NA
Within the area overlying a subsurface mine. - Written confirmation or verification or map from the NM EMNRD-Mining and Minerals Division	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Within an unstable area. - Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; topographic map	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Within a 100-year floodplain. FEMA map	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; visual inspection (certification) of the proposed site	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. - Visual inspection (certification) of the proposed site; aerial photo; satellite image	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application. - NM Office of the State Engineer - iWATERS database search; visual inspection (certification) of the proposed site	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Within 500 feet of a wetland. - US Fish and Wildlife Wetland Identification map; topographic map; visual inspection (certification) of the proposed site	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No

9.

**Recycling Facility and/or Containment Checklist:**

*Instructions: Each of the following items must be attached to the application. Indicate, by a check mark in the box, that the documents are attached.*

- Design Plan - based upon the appropriate requirements.
- Operating and Maintenance Plan - based upon the appropriate requirements.
- Closure Plan - based upon the appropriate requirements.
- Site Specific Groundwater Data -
- Siting Criteria Compliance Demonstrations -
- Certify that notice of the C-147 (only) has been sent to the surface owner(s)**

10.

**Operator Application Certification:**

I hereby certify that the information and attachments submitted with this application are true, accurate and complete to the best of my knowledge and belief.

Name (Print): David Grounds Title: VP Regulatory  
 Signature: David Grounds Date: 03/24/2026  
 e-mail address: David.Grounds@pilotwater.com Telephone: (817) 897-0135

11.

**OCD Representative Signature:** Victoria Venegas **Approval Date:** 04/02/2026

**Title:** Senior Environmental Specialist **OCD Permit Number:** 1RF-463

- OCD Conditions** \_\_\_\_\_
- Additional OCD Conditions on Attachment**



**New Mexico Recycling Facility Monthly Inspection**

**Location**

Submitted By  [Mario Lopez](#)

*Location was not collected for this report.*

Surrogate  [Mario Lopez](#)

Started On	April 10 2025, 9:36am
Submitted On	April 10 2025, 3:51pm (6 hours)
Weather	NaN°,
Version	V2 (latest)
Updated	April 10 2025, 4:29pm
Report No.	56780234

**New Mexico Recycling Facility Monthly Inspection**

**GENERAL DETAILS**

Date	March 22nd 2025 9:36 AM CDT
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA_RECYCLE_FACILITY</a>

**INLET AST**

Is there fluid in the leak detection system?	N/A
Any migratory birds or wildlife discovered in the AST?	No
Is bird netting in good condition?	N/A
Is there any evidence of cracking or subsidence of the pad around the AST?	No
Is there oil to be skimmed?	No

**EFFLUENT AST**

Is there fluid in the leak detection system?	N/A
Any migratory birds or wildlife discovered in the AST?	No
Is there any evidence of cracking or subsidence of the pad around the AST?	No
Comments	Not in use






**SOUTH POND**

Is there fluid in the leak detection system?	Yes
--	-----

Has the fluid been pumped out or is it scheduled?	Yes
Are pond level markers visible?	Yes
Is pond level sensor working?	N/A
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	No
Is pond aeration system functional?	Yes
Comments	missing life vest, will get replacement

TREATMENT FACILITY

Is fencing and cattleguard in good condition?	Yes
Is there any evidence of spills or soil staining that have not been cleaned up?	No
Any migratory birds or wildlife discovered in the facility?	No
Are there any holes found in the containment liner?	Yes



---

<b>Any evidence of erosion on the outside slope of the facility?</b>	No
<b>Comments</b>	Liner sustained some wind damage and we've completed repairs

---

**SUMMARY**

**# of Action Item(s)** 0

**Inspector** [Mario Lopez](#)

**Signature** 

---

Generated Monday, April 14th 2025, 12:10pm CDT.

powered by  KPA



**New Mexico Recycling Facility Monthly Inspection**

**Location**

Submitted By  [Mario Lopez](#)

*Location was not collected for this report.*

Surrogate  [Mario Lopez](#)

Started On	April 8 2025, 1:46pm
Submitted On	April 9 2025, 9:11am (19 hours)
Weather	NaN°,
Version	V1 (latest)
Updated	April 9 2025, 9:11am
Report No.	56673885

**New Mexico Recycling Facility Monthly Inspection**

**GENERAL DETAILS**

Date	April 9th 2025 8:44 AM CDT
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA_RECYCLE_FACILITY</a>

**INLET AST**

Is there fluid in the leak detection system?	N/A
Any migratory birds or wildlife discovered in the AST?	No
Is bird netting in good condition?	N/A
Is there any evidence of cracking or subsidence of the pad around the AST?	No
Is there oil to be skimmed?	No

**EFFLUENT AST**

Is there fluid in the leak detection system?	N/A
Any migratory birds or wildlife discovered in the AST?	N/A
Is there any evidence of cracking or subsidence of the pad around the AST?	N/A

**SOUTH POND**



Is there fluid in the leak detection system?	Yes
Has the fluid been pumped out or is it scheduled?	N/A
Are pond level markers visible?	Yes
Is pond level sensor working?	N/A
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	No
Is pond aeration system functional?	Yes

TREATMENT FACILITY



Is fencing and cattle guard in good condition?	Yes
Is there any evidence of spills or soil staining that have not been cleaned up?	Yes
Any migratory birds or wildlife discovered in the facility?	No
Are there any holes found in the containment liner?	No

---

<b>Any evidence of erosion on the outside slope of the facility?</b>	N/A
<b>Comments</b>	We are working on getting quotes to fix berm around facility


---

**SUMMARY**

<b># of Action Item(s)</b>	0
<b>Inspector</b>	<a href="#">Mario Lopez</a>

---

**Signature**





---



**New Mexico Recycling Facility Monthly Inspection**

**Location**

Submitted By	 <a href="#">Mario Lopez</a>
Surrogate	 <a href="#">Mario Lopez</a>
Started On	May 7 2025, 4:04pm
Submitted On	May 7 2025, 4:06pm (2 minutes)
Weather	74°, clear
Version	V1 (latest)
Updated	May 7 2025, 4:06pm
Report No.	58492910



**New Mexico Recycling Facility Monthly Inspection**

**GENERAL DETAILS**

Date	May 7th 2025 4:04 PM CDT
Area	<a href="#">West Texas</a>
Recycle Facility	<a href="#">JAVELINA RECYCLE FACILITY</a>

**INLET AST**

Is there fluid in the leak detection system?	N/A
Any migratory birds or wildlife discovered in the AST?	No
Is bird netting in good condition?	N/A
Is there any evidence of cracking or subsidence of the pad around the AST?	No
Is there oil to be skimmed?	No

**EFFLUENT AST**

Is there fluid in the leak detection system?	N/A
Any migratory birds or wildlife discovered in the AST?	No
Is there any evidence of cracking or subsidence of the pad around the AST?	N/A

**SOUTH POND**

Is there fluid in the leak detection system?	No
Are pond level markers visible?	Yes

Is pond level sensor working?	N/A
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	Yes
Is pond aeration system functional?	Yes

TREATMENT FACILITY

Is fencing and cattleguard in good condition?	Yes
Is there any evidence of spills or soil staining that have not been cleaned up?	No
Any migratory birds or wildlife discovered in the facility?	No
Are there any holes found in the containment liner?	No
Any evidence of erosion on the outside slope of the facility?	Yes



SUMMARY

# of Action Item(s)	0
Inspector	<a href="#">Mario Lopez</a>


Signature 



**New Mexico Recycling Facility Monthly Inspection**

Submitted By	 <a href="#">Mario Nevarez</a>
Surrogate	 <a href="#">Mario Nevarez</a>
Started On	June 6 2025, 9:22am
Submitted On	June 6 2025, 9:24am (2 minutes)
Weather	73°, clear
Version	V1 (latest)
Updated	June 6 2025, 9:24am
Report No.	60216772

**Location**



**New Mexico Recycling Facility Monthly Inspection**

**GENERAL DETAILS**

Date	June 6th 2025 8:22 AM MDT
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA_RECYCLE_FACILITY</a>

**INLET AST**

Is there fluid in the leak detection system?	No
Any migratory birds or wildlife discovered in the AST?	No
Is bird netting in good condition?	Yes
Is there any evidence of cracking or subsidence of the pad around the AST?	No
Is there oil to be skimmed?	No

**EFFLUENT AST**

Is there fluid in the leak detection system?	No
Any migratory birds or wildlife discovered in the AST?	No
Is there any evidence of cracking or subsidence of the pad around the AST?	No

**SOUTH POND**

Is there fluid in the leak detection system?	Yes
--	-----

Has the fluid been pumped out or is it scheduled?	Yes
Are pond level markers visible?	Yes
Is pond level sensor working?	Yes
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	Yes
Is pond aeration system functional?	None

TREATMENT FACILITY

Is fencing and catterguard in good condition?	Yes
Is there any evidence of spills or soil staining that have not been cleaned up?	No
Any migratory birds or wildlife discovered in the facility?	No
Are there any holes found in the containment liner?	No
Any evidence of erosion on the outside slope of the facility?	No

SUMMARY



# of Action Item(s)	0
Inspector	None


Signature



**New Mexico Recycling Facility Monthly Inspection**

**Location**

Submitted By	 <a href="#">Mario Nevarez</a>
Surrogate	 <a href="#">Mario Nevarez</a>
Started On	July 7 2025, 10:56am
Submitted On	July 7 2025, 10:58am (a minute)
Weather	79°, cloudy
Version	V1 (latest)
Updated	July 7 2025, 10:58am
Report No.	61906370



**New Mexico Recycling Facility Monthly Inspection**

**GENERAL DETAILS**

Date	July 7th 2025 10:56 AM CDT
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA RECYCLE FACILITY</a>

**INLET AST**

Is there fluid in the leak detection system?	No
Any migratory birds or wildlife discovered in the AST?	No
Is bird netting in good condition?	Yes
Is there any evidence of cracking or subsidence of the pad around the AST?	No
Is there oil to be skimmed?	No

**EFFLUENT AST**

Is there fluid in the leak detection system?	No
Any migratory birds or wildlife discovered in the AST?	No
Is there any evidence of cracking or subsidence of the pad around the AST?	No

**SOUTH POND**

Is there fluid in the leak detection system?	No
Are pond level markers visible?	Yes

Is pond level sensor working?	Yes
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	Yes
Is pond aeration system functional?	Yes

TREATMENT FACILITY

Is fencing and catterguard in good condition?	Yes
Is there any evidence of spills or soil staining that have not been cleaned up?	No
Any migratory birds or wildlife discovered in the facility?	No
Are there any holes found in the containment liner?	No
Any evidence of erosion on the outside slope of the facility?	No

SUMMARY



# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>


Signature



**New Mexico Recycling Facility Monthly Inspection**

**Location**

Submitted By	 <a href="#">Mario Nevarez</a>
Surrogate	 <a href="#">Mario Nevarez</a>
Started On	July 28 2025, 12:03pm
Submitted On	July 28 2025, 12:05pm (2 minutes)
Weather	86°, cloudy
Version	V1 (latest)
Updated	July 28 2025, 12:05pm
Report No.	63138565



**New Mexico Recycling Facility Monthly Inspection**

**GENERAL DETAILS**

Date	July 28th 2025 11:03 AM MDT
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA_RECYCLE_FACILITY</a>

**INLET AST**

Is there fluid in the leak detection system?	No
Any migratory birds or wildlife discovered in the AST?	No
Is bird netting in good condition?	Yes
Is there any evidence of cracking or subsidence of the pad around the AST?	No
Is there oil to be skimmed?	No

**EFFLUENT AST**

Is there fluid in the leak detection system?	No
Any migratory birds or wildlife discovered in the AST?	No
Is there any evidence of cracking or subsidence of the pad around the AST?	No

**SOUTH POND**

Is there fluid in the leak detection system?	No
Are pond level markers visible?	Yes

Is pond level sensor working?	Yes
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	Yes
Is pond aeration system functional?	Yes


TREATMENT FACILITY

Is fencing and cattleguard in good condition?	Yes
Is there any evidence of spills or soil staining that have not been cleaned up?	No
Any migratory birds or wildlife discovered in the facility?	No
Are there any holes found in the containment liner?	No
Any evidence of erosion on the outside slope of the facility?	No

SUMMARY



# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>


Signature





**New Mexico Recycling Facility Monthly Inspection** **Location**

Submitted By	 <a href="#">Mario Nevarez</a>
Surrogate	 <a href="#">Mario Nevarez</a>
Started On	August 25 2025, 11:33am
Submitted On	August 25 2025, 11:35am (2 minutes)
Weather	84°, clear
Version	V1 (latest)
Updated	August 25 2025, 11:35am
Report No.	64964331



**New Mexico Recycling Facility Monthly Inspection**

**GENERAL DETAILS**

Date	August 25th 2025 11:33 AM
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA_RECYCLE_FACILITY</a>

**INLET AST**

Is there fluid in the leak detection system?	No
Any migratory birds or wildlife discovered in the AST?	No
Is bird netting in good condition?	Yes
Is there any evidence of cracking or subsidence of the pad around the AST?	No
Is there oil to be skimmed?	No

**EFFLUENT AST**

Is there fluid in the leak detection system?	No
Any migratory birds or wildlife discovered in the AST?	No
Is there any evidence of cracking or subsidence of the pad around the AST?	No

**SOUTH POND**

Is there fluid in the leak detection system?	No
Are pond level markers visible?	Yes

Is pond level sensor working?	Yes
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	Yes
Is pond aeration system functional?	Yes

TREATMENT FACILITY

Is fencing and cattleguard in good condition?	Yes
Is there any evidence of spills or soil staining that have not been cleaned up?	No
Any migratory birds or wildlife discovered in the facility?	No
Are there any holes found in the containment liner?	No
Any evidence of erosion on the outside slope of the facility?	No

SUMMARY



# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>


Signature





**New Mexico Recycling Facility Monthly Inspection** **Location**

Submitted By	 <a href="#">Mario Nevarez</a>
Surrogate	 <a href="#">Mario Nevarez</a>
Started On	October 2 2025, 10:00am
Submitted On	October 2 2025, 10:02am (2 minutes)
Weather	72°, clear
Version	V1 (latest)
Updated	October 2 2025, 10:02am
Report No.	67297256



**New Mexico Recycling Facility Monthly Inspection**

**GENERAL DETAILS**

Date	October 2nd 2025 10:00 AM
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA RECYCLE FACILITY</a>

**INLET AST**

Is there fluid in the leak detection system?	No
Any migratory birds or wildlife discovered in the AST?	No
Is bird netting in good condition?	Yes
Is there any evidence of cracking or subsidence of the pad around the AST?	No
Is there oil to be skimmed?	No

**EFFLUENT AST**

Is there fluid in the leak detection system?	N/A
Any migratory birds or wildlife discovered in the AST?	N/A
Is there any evidence of cracking or subsidence of the pad around the AST?	N/A

**SOUTH POND**

Is there fluid in the leak detection system?	No
Are pond level markers visible?	Yes

Is pond level sensor working?	Yes
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	Yes
Is pond aeration system functional?	Yes

TREATMENT FACILITY

Is fencing and cattleguard in good condition?	Yes
Is there any evidence of spills or soil staining that have not been cleaned up?	No
Any migratory birds or wildlife discovered in the facility?	No
Are there any holes found in the containment liner?	No
Any evidence of erosion on the outside slope of the facility?	No

SUMMARY



# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>


Signature



**New Mexico Recycling Facility Monthly Inspection**

**Location**

Submitted By	 <a href="#">Mario Nevarez</a>
Surrogate	 <a href="#">Mario Nevarez</a>
Started On	October 29 2025, 8:55am
Submitted On	October 29 2025, 8:57am (2 minutes)
Weather	40°, clear
Version	V1 (latest)
Updated	October 29 2025, 8:57am
Report No.	68931332



**New Mexico Recycling Facility Monthly Inspection**

**GENERAL DETAILS**

Date	October 29th 2025 8:55 AM CDT
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA RECYCLE FACILITY</a>

**INLET AST**

Is there fluid in the leak detection system?	No
Any migratory birds or wildlife discovered in the AST?	No
Is bird netting in good condition?	Yes
Is there any evidence of cracking or subsidence of the pad around the AST?	No
Is there oil to be skimmed?	No

**EFFLUENT AST**

Is there fluid in the leak detection system?	N/A
Any migratory birds or wildlife discovered in the AST?	N/A
Is there any evidence of cracking or subsidence of the pad around the AST?	N/A

**SOUTH POND**

Is there fluid in the leak detection system?	No
Are pond level markers visible?	Yes

Is pond level sensor working?	Yes
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	Yes
Is pond aeration system functional?	Yes

TREATMENT FACILITY

Is fencing and cattleguard in good condition?	Yes
Is there any evidence of spills or soil staining that have not been cleaned up?	No
Any migratory birds or wildlife discovered in the facility?	No
Are there any holes found in the containment liner?	No
Any evidence of erosion on the outside slope of the facility?	No

SUMMARY



# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>


Signature



**New Mexico Recycling Facility Monthly Inspection**

**Location**

<b>Submitted By</b>	 <a href="#">Mario Nevarez</a>
<b>Surrogate</b>	 <a href="#">Mario Nevarez</a>
<b>Started On</b>	November 26 2025, 3:29pm
<b>Submitted On</b>	November 26 2025, 3:31pm (3 minutes)
<b>Weather</b>	57°, cloudy
<b>Version</b>	V1 (latest)
<b>Updated</b>	November 26 2025, 3:31pm
<b>Report No.</b>	70730285



**New Mexico Recycling Facility Monthly Inspection**

**GENERAL DETAILS**

<b>Date</b>	November 26th 2025 3:29 PM CST
<b>Area</b>	<a href="#">New Mexico</a>
<b>Recycle Facility</b>	<a href="#">JAVELINA RECYCLE FACILITY</a>

**INLET AST**

<b>Is there fluid in the leak detection system?</b>	No
<b>Any migratory birds or wildlife discovered in the AST?</b>	No
<b>Is bird netting in good condition?</b>	N/A
<b>Is there any evidence of cracking or subsidence of the pad around the AST?</b>	No
<b>Is there oil to be skimmed?</b>	Yes
<b>How many inches?</b>	2-3"

**EFFLUENT AST**

<b>Is there fluid in the leak detection system?</b>	N/A
<b>Any migratory birds or wildlife discovered in the AST?</b>	N/A
<b>Is there any evidence of cracking or subsidence of the pad around the AST?</b>	N/A

**SOUTH POND**

<b>Is there fluid in the leak detection system?</b>	No
---	----

Are pond level markers visible?	Yes
Is pond level sensor working?	Yes
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	Yes
Is pond aeration system functional?	Yes

TREATMENT FACILITY

Is fencing and cattleguard in good condition?	Yes
Is there any evidence of spills or soil staining that have not been cleaned up?	No
Any migratory birds or wildlife discovered in the facility?	No
Are there any holes found in the containment liner?	No
Any evidence of erosion on the outside slope of the facility?	No

SUMMARY



# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>


Signature



**New Mexico Recycling Facility Monthly Inspection**

**Location**

Submitted By	 <a href="#">Mario Nevarez</a>
Surrogate	 <a href="#">Mario Nevarez</a>
Started On	December 30 2025, 8:51am
Submitted On	December 30 2025, 8:53am (2 minutes)
Weather	27°, cloudy
Version	V1 (latest)
Updated	December 30 2025, 8:53am
Report No.	72399653



**New Mexico Recycling Facility Monthly Inspection**

**GENERAL DETAILS**

Date	December 30th 2025 8:51 AM CST
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA RECYCLE FACILITY</a>

**INLET AST**

Is there fluid in the leak detection system?	No
Any migratory birds or wildlife discovered in the AST?	No
Is bird netting in good condition?	No
Is there any evidence of cracking or subsidence of the pad around the AST?	No
Is there oil to be skimmed?	No

**EFFLUENT AST**

Is there fluid in the leak detection system?	N/A
Any migratory birds or wildlife discovered in the AST?	N/A
Is there any evidence of cracking or subsidence of the pad around the AST?	N/A

**SOUTH POND**

Is there fluid in the leak detection system?	No
Are pond level markers visible?	Yes

Is pond level sensor working?	Yes
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	Yes
Is pond aeration system functional?	Yes

TREATMENT FACILITY

Is fencing and cattleguard in good condition?	Yes
Is there any evidence of spills or soil staining that have not been cleaned up?	No
Any migratory birds or wildlife discovered in the facility?	No
Are there any holes found in the containment liner?	No
Any evidence of erosion on the outside slope of the facility?	No



SUMMARY


# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>

Signature



**New Mexico Recycling Facility Monthly Inspection** **Location**

<b>Submitted By</b>	 <a href="#">Mario Nevarez</a>
<b>Surrogate</b>	 <a href="#">Mario Nevarez</a>
<b>Started On</b>	January 27 2026, 2:03pm
<b>Submitted On</b>	January 27 2026, 2:05pm (2 minutes)
<b>Weather</b>	40°, cloudy
<b>Version</b>	V1 (latest)
<b>Updated</b>	January 27 2026, 2:05pm
<b>Report No.</b>	73974336



**New Mexico Recycling Facility Monthly Inspection**

**GENERAL DETAILS**

<b>Date</b>	January 27th 2026 2:03 PM CST
<b>Area</b>	<a href="#">New Mexico</a>
<b>Recycle Facility</b>	<a href="#">JAVELINA RECYCLE FACILITY</a>

**INLET AST**

<b>Is there fluid in the leak detection system?</b>	No
<b>Any migratory birds or wildlife discovered in the AST?</b>	No
<b>Is bird netting in good condition?</b>	No
<b>Is there any evidence of cracking or subsidence of the pad around the AST?</b>	No
<b>Is there oil to be skimmed?</b>	Yes
<b>How many inches?</b>	2-3"

**EFFLUENT AST**

<b>Is there fluid in the leak detection system?</b>	No
<b>Any migratory birds or wildlife discovered in the AST?</b>	No
<b>Is there any evidence of cracking or subsidence of the pad around the AST?</b>	No

**SOUTH POND**

<b>Is there fluid in the leak detection system?</b>	No
---	----

Are pond level markers visible?	Yes
Is pond level sensor working?	Yes
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	Yes
Is pond aeration system functional?	Yes

TREATMENT FACILITY

Is fencing and cattleguard in good condition?	Yes
Is there any evidence of spills or soil staining that have not been cleaned up?	No
Any migratory birds or wildlife discovered in the facility?	No
Are there any holes found in the containment liner?	No
Any evidence of erosion on the outside slope of the facility?	No



SUMMARY


# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>

Signature



**New Mexico Recycling Facility Monthly Inspection** **Location**

<b>Submitted By</b>	 <a href="#">Mario Nevarez</a>
<b>Surrogate</b>	 <a href="#">Mario Nevarez</a>
<b>Started On</b>	February 25 2026, 2:42pm
<b>Submitted On</b>	February 25 2026, 2:43pm (a minute)
<b>Weather</b>	88°, clear
<b>Version</b>	V1 (latest)
<b>Updated</b>	February 25 2026, 2:43pm
<b>Report No.</b>	75918332



**New Mexico Recycling Facility Monthly Inspection**

**GENERAL DETAILS**

<b>Date</b>	February 25th 2026 2:42 PM CST
<b>Area</b>	<a href="#">New Mexico</a>
<b>Recycle Facility</b>	<a href="#">JAVELINA RECYCLE FACILITY</a>

**INLET AST**

<b>Is there fluid in the leak detection system?</b>	No
<b>Any migratory birds or wildlife discovered in the AST?</b>	No
<b>Is bird netting in good condition?</b>	No
<b>Is there any evidence of cracking or subsidence of the pad around the AST?</b>	No
<b>Is there oil to be skimmed?</b>	No

**EFFLUENT AST**

<b>Is there fluid in the leak detection system?</b>	N/A
<b>Any migratory birds or wildlife discovered in the AST?</b>	N/A
<b>Is there any evidence of cracking or subsidence of the pad around the AST?</b>	N/A

**SOUTH POND**

<b>Is there fluid in the leak detection system?</b>	No
<b>Are pond level markers visible?</b>	Yes

Is pond level sensor working?	Yes
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	Yes
Is pond aeration system functional?	Yes

TREATMENT FACILITY

Is fencing and cattleguard in good condition?	Yes
Is there any evidence of spills or soil staining that have not been cleaned up?	No
Any migratory birds or wildlife discovered in the facility?	No
Are there any holes found in the containment liner?	No
Any evidence of erosion on the outside slope of the facility?	No

SUMMARY

# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>

Signature



**New Mexico Recycling Facility Weekly Inspection**

**Location**

Submitted By  [Mario Lopez](#)

*Location was not collected for this report.*

Surrogate  [Mario Lopez](#)

Started On	April 11 2025, 2:40pm
Submitted On	April 11 2025, 2:46pm (7 minutes)
Weather	NaN°
Version	V1 (latest)
Updated	April 11 2025, 2:47pm
Report No.	56848898

**New Mexico Recycling Facility Weekly Inspection**

**GENERAL DETAILS**

Date	March 3rd 2025
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA_RECYCLE_FACILITY</a>

**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges	6'
Does the pond surface show visible oil?	No
Visually inspect containments liner	All look good
Check leak detection system for any evidence of a loss of integrity of the primary liner	no leaks detected

**SUMMARY**

# of Action Item(s)	0
Inspector	<a href="#">Mario Lopez</a>

Signature 

Generated Monday, April 14th 2025, 12:01pm CDT.

powered by 



**New Mexico Recycling Facility Weekly Inspection** **Location**

Submitted By  [Mario Lopez](#)

*Location was not collected for this report.*

Surrogate  [Mario Lopez](#)

Started On	April 11 2025, 2:47pm
Submitted On	April 11 2025, 2:59pm (12 minutes)
Weather	NaN°
Version	V1 (latest)
Updated	April 11 2025, 2:59pm
Report No.	56849552

**New Mexico Recycling Facility Weekly Inspection**

**GENERAL DETAILS**

Date	March 10th 2025
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA_RECYCLE_FACILITY</a>

**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges	6'
Does the pond surface show visible oil?	No
Visually inspect containments liner	all look good
Check leak detection system for any evidence of a loss of integrity of the primary liner	no leaks detected

**SUMMARY**

# of Action Item(s)	0
Inspector	<a href="#">Mario Lopez</a>

Signature 



**New Mexico Recycling Facility Weekly Inspection**

**Location**

Submitted By  [Mario Lopez](#)

*Location was not collected for this report.*

Surrogate  [Mario Lopez](#)

Started On	April 11 2025, 3:04pm
Submitted On	April 11 2025, 3:11pm (8 minutes)
Weather	NaN°,
Version	V1 (latest)
Updated	April 11 2025, 3:11pm
Report No.	56850070



**New Mexico Recycling Facility Weekly Inspection**

**GENERAL DETAILS**

Date	March 17th 2025
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA_RECYCLE_FACILITY</a>

**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges	6'
Does the pond surface show visible oil?	No
Visually inspect containments liner	Wind damage on some of the liners, will schedule liner crew to fix



Check leak detection system for any evidence of a loss of integrity of the primary liner working properly no leaks detected

**SUMMARY**

---

# of Action Item(s) 0

---

Inspector [Mario Lopez](#)

---

Signature



---

Generated Monday, April 14th 2025, 12:00pm CDT.

powered by  KPA



**New Mexico Recycling Facility Weekly Inspection**

**Location**

Submitted By  [Mario Lopez](#)

*Location was not collected for this report.*

Surrogate  [Mario Lopez](#)

Started On	April 11 2025, 3:11pm
Submitted On	April 11 2025, 3:13pm (2 minutes)
Weather	NaN°
Version	V1 (latest)
Updated	April 11 2025, 3:13pm
Report No.	56850166


**New Mexico Recycling Facility Weekly Inspection**

**GENERAL DETAILS**

Date	March 24th 2025
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA_RECYCLE_FACILITY</a>

**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges	6'
Does the pond surface show visible oil?	No
Visually inspect containments liner	all containments/liners fixed



Check leak detection system for any evidence of a loss of integrity of the primary liner no leaks detected

**SUMMARY**

---

# of Action Item(s)	0
Inspector	<a href="#">Mario Lopez</a>
Signature	

---

Generated Monday, April 14th 2025, 11:59am CDT.

powered by  KPA



**New Mexico Recycling Facility Weekly Inspection**

**Location**

Submitted By  [Mario Lopez](#)

*Location was not collected for this report.*

Surrogate  [Mario Lopez](#)

Started On	April 11 2025, 3:13pm
Submitted On	April 11 2025, 3:14pm (37 seconds)
Weather	NaN°
Version	V1 (latest)
Updated	April 11 2025, 3:14pm
Report No.	56850207

**New Mexico Recycling Facility Weekly Inspection**

**GENERAL DETAILS**

Date	March 31st 2025
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA_RECYCLE_FACILITY</a>

**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges	6'
Does the pond surface show visible oil?	No
Visually inspect containments liner	all look good
Check leak detection system for any evidence of a loss of integrity of the primary liner	no leaks detected

**SUMMARY**

# of Action Item(s)	0
Inspector	<a href="#">Mario Lopez</a>

Signature 



Generated Monday, April 14th 2025, 11:57am CDT.

powered by 



**New Mexico Recycling Facility Weekly Inspection**

**Location**

Submitted By	 <a href="#">Mario Lopez</a>
Surrogate	 <a href="#">Mario Lopez</a>
Started On	May 7 2025, 4:01pm
Submitted On	May 7 2025, 4:02pm (42 seconds)
Weather	74°, clear
Version	V1 (latest)
Updated	May 7 2025, 4:02pm
Report No.	58492746



**New Mexico Recycling Facility Weekly Inspection**

**GENERAL DETAILS**

Date	May 2nd 2025
Area	<a href="#">West Texas</a>
Recycle Facility	<a href="#">JAVELINA_RECYCLE_FACILITY</a>

**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges	0
Does the pond surface show visible oil?	No
Visually inspect containments liner	All looks good
Check leak detection system for any evidence of a loss of integrity of the primary liner	No water in pond

**SUMMARY**

# of Action Item(s)	0
Inspector	<a href="#">Mario Lopez</a>
Signature	None

Generated Tuesday, May 13th 2025, 9:06am CDT.

powered by  KPA



New Mexico Recycling Facility Weekly Inspection

Location

Submitted By  [Mario Lopez](#)

Location was not collected for this report.

Surrogate  [Mario Lopez](#)

Started On	May 14 2025, 8:44am
Submitted On	May 14 2025, 8:46am (2 minutes)
Weather	NaN°
Version	V1 (latest)
Updated	May 14 2025, 8:46am
Report No.	58862177

New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date	May 13th 2025
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA_RECYCLE_FACILITY</a>

WEEKLY INSPECTION

Read and record the fluid height of staff gauges	0 at pond, around 6' at AST
Does the pond surface show visible oil?	No
Visually inspect containments liner	all look good
Check leak detection system for any evidence of a loss of integrity of the primary liner	no water on pond

SUMMARY



# of Action Item(s)	0
Inspector	<a href="#">Mario Lopez</a>


Signature 



**New Mexico Recycling Facility Weekly Inspection**

**Location**

Submitted By	 <a href="#">Mario Nevarez</a>
Surrogate	 <a href="#">Mario Nevarez</a>
Started On	June 11 2025, 11:26am
Submitted On	June 11 2025, 11:27am (27 seconds)
Weather	70°, cloudy
Version	V1 (latest)
Updated	June 11 2025, 11:27am
Report No.	60486163



**New Mexico Recycling Facility Weekly Inspection**

**GENERAL DETAILS**

Date	June 11th 2025
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA RECYCLE FACILITY</a>

**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges	Yes
Does the pond surface show visible oil?	No
Visually inspect containments liner	Yes
Check leak detection system for any evidence of a loss of integrity of the primary liner	Yes

**SUMMARY**



# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>


Signature



**New Mexico Recycling Facility Weekly Inspection**

**Location**

Submitted By	 <a href="#">Mario Nevarez</a>
Surrogate	 <a href="#">Mario Nevarez</a>
Started On	June 30 2025, 1:34pm
Submitted On	June 30 2025, 1:34pm (23 seconds)
Weather	87°, cloudy
Version	V1 (latest)
Updated	June 30 2025, 1:34pm
Report No.	61555366



**New Mexico Recycling Facility Weekly Inspection**

**GENERAL DETAILS**

Date	June 30th 2025
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA_RECYCLE_FACILITY</a>

**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges	Yes
Does the pond surface show visible oil?	No
Visually inspect containments liner	Yes
Check leak detection system for any evidence of a loss of integrity of the primary liner	Yes

**SUMMARY**



# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>


Signature



**New Mexico Recycling Facility Weekly Inspection**

**Location**

Submitted By	 <a href="#">Mario Nevarez</a>
Surrogate	 <a href="#">Mario Nevarez</a>
Started On	July 7 2025, 9:38am
Submitted On	July 7 2025, 9:38am (26 seconds)
Weather	76°, clear
Version	V1 (latest)
Updated	July 7 2025, 9:38am
Report No.	61898569



**New Mexico Recycling Facility Weekly Inspection**

**GENERAL DETAILS**

Date	July 7th 2025
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA_RECYCLE_FACILITY</a>

**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges	Yes
Does the pond surface show visible oil?	No
Visually inspect containments liner	Yes
Check leak detection system for any evidence of a loss of integrity of the primary liner	Yes

**SUMMARY**



# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>


Signature



**New Mexico Recycling Facility Weekly Inspection**

**Location**

Submitted By	 <a href="#">Mario Nevarez</a>
Surrogate	 <a href="#">Mario Nevarez</a>
Started On	July 21 2025, 11:48am
Submitted On	July 21 2025, 11:49am (25 seconds)
Weather	86°, clear
Version	V1 (latest)
Updated	July 21 2025, 11:49am
Report No.	62717554



**New Mexico Recycling Facility Weekly Inspection**

**GENERAL DETAILS**

Date	July 21st 2025
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA RECYCLE FACILITY</a>

**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges	Yes
Does the pond surface show visible oil?	No
Visually inspect containments liner	Yes
Check leak detection system for any evidence of a loss of integrity of the primary liner	Yes

**SUMMARY**

# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>

Signature



Generated Monday, July 21st 2025, 1:15pm CDT.


powered by  KPA



**New Mexico Recycling Facility Weekly Inspection**

**Location**

Submitted By	 <a href="#">Mario Nevarez</a>
Surrogate	 <a href="#">Mario Nevarez</a>
Started On	July 28 2025, 12:03pm
Submitted On	July 28 2025, 12:06pm (3 minutes)
Weather	86°, cloudy
Version	V1 (latest)
Updated	July 28 2025, 12:06pm
Report No.	63138615



**New Mexico Recycling Facility Weekly Inspection**

**GENERAL DETAILS**

Date	July 28th 2025
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA_RECYCLE_FACILITY</a>

**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges	Yes
Does the pond surface show visible oil?	No
Visually inspect containments liner	Yes
Check leak detection system for any evidence of a loss of integrity of the primary liner	Yes

**SUMMARY**



# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>


Signature



**New Mexico Recycling Facility Weekly Inspection**

**Location**

Submitted By	 <a href="#">Mario Nevarez</a>
Surrogate	 <a href="#">Mario Nevarez</a>
Started On	August 7 2025, 10:59am
Submitted On	August 7 2025, 11:00am (45 seconds)
Weather	84°, clear
Version	V1 (latest)
Updated	August 7 2025, 11:00am
Report No.	63886862



**New Mexico Recycling Facility Weekly Inspection**

**GENERAL DETAILS**

Date	August 7th 2025
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA_RECYCLE_FACILITY</a>

**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges	Yes
Does the pond surface show visible oil?	No
Visually inspect containments liner	Yes
Check leak detection system for any evidence of a loss of integrity of the primary liner	Yes

**SUMMARY**



# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>


Signature



**New Mexico Recycling Facility Weekly Inspection**

**Location**

Submitted By	 <a href="#">Mario Nevarez</a>
Surrogate	 <a href="#">Mario Nevarez</a>
Started On	August 11 2025, 1:05pm
Submitted On	August 11 2025, 1:06pm (21 seconds)
Weather	93°, cloudy
Version	V1 (latest)
Updated	August 11 2025, 1:06pm
Report No.	64089565



**New Mexico Recycling Facility Weekly Inspection**

**GENERAL DETAILS**

Date	August 11th 2025
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA RECYCLE FACILITY</a>

**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges	Yes
Does the pond surface show visible oil?	No
Visually inspect containments liner	Yes
Check leak detection system for any evidence of a loss of integrity of the primary liner	Yes

**SUMMARY**



# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>


Signature



**New Mexico Recycling Facility Weekly Inspection**

**Location**

Submitted By	 <a href="#">Mario Nevarez</a>
Surrogate	 <a href="#">Mario Nevarez</a>
Started On	August 20 2025, 10:44am
Submitted On	August 20 2025, 10:44am (21 seconds)
Weather	78°, clear
Version	V1 (latest)
Updated	August 20 2025, 10:44am
Report No.	64671888



**New Mexico Recycling Facility Weekly Inspection**

**GENERAL DETAILS**

Date	August 20th 2025
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA_RECYCLE_FACILITY</a>

**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges	Yes
Does the pond surface show visible oil?	No
Visually inspect containments liner	Yes
Check leak detection system for any evidence of a loss of integrity of the primary liner	Yes

**SUMMARY**



# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>

Signature



**New Mexico Recycling Facility Weekly Inspection**

**Location**

Submitted By	 <a href="#">Mario Nevarez</a>
Surrogate	 <a href="#">Mario Nevarez</a>
Started On	August 25 2025, 11:31am
Submitted On	August 25 2025, 11:32am (41 seconds)
Weather	84°, clear
Version	V1 (latest)
Updated	August 25 2025, 11:32am
Report No.	64964138



**New Mexico Recycling Facility Weekly Inspection**

**GENERAL DETAILS**

Date	August 25th 2025
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA_RECYCLE_FACILITY</a>

**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges	Yes
Does the pond surface show visible oil?	No
Visually inspect containments liner	Yes
Check leak detection system for any evidence of a loss of integrity of the primary liner	Yes

**SUMMARY**



# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>


Signature



**New Mexico Recycling Facility Weekly Inspection**

**Location**

Submitted By	 <a href="#">Mario Nevarez</a>
Surrogate	 <a href="#">Mario Nevarez</a>
Started On	September 2 2025, 10:59am
Submitted On	September 2 2025, 10:59am (23 seconds)
Weather	81°, cloudy
Version	V1 (latest)
Updated	September 2 2025, 10:59am
Report No.	65409434



**New Mexico Recycling Facility Weekly Inspection**

**GENERAL DETAILS**

Date	September 2nd 2025
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA RECYCLE FACILITY</a>

**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges	Yes
Does the pond surface show visible oil?	No
Visually inspect containments liner	Yes
Check leak detection system for any evidence of a loss of integrity of the primary liner	Yes

**SUMMARY**

# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>
Signature	None



Generated Tuesday, September 2nd 2025, 11:04am CDT.


powered by 



**New Mexico Recycling Facility Weekly Inspection**

**Location**

Submitted By	 <a href="#">Mario Nevarez</a>
Surrogate	 <a href="#">Mario Nevarez</a>
Started On	September 9 2025, 10:30am
Submitted On	September 9 2025, 10:30am (24 seconds)
Weather	74°, clear
Version	V1 (latest)
Updated	September 9 2025, 10:30am
Report No.	65847085



**New Mexico Recycling Facility Weekly Inspection**

**GENERAL DETAILS**

Date	September 9th 2025
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA_RECYCLE_FACILITY</a>

**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges	Yes
Does the pond surface show visible oil?	No
Visually inspect containments liner	Yes
Check leak detection system for any evidence of a loss of integrity of the primary liner	Yes

**SUMMARY**

# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>

Signature





New Mexico Recycling Facility Weekly Inspection

Location

Submitted By  [Mario Nevarez](#)

Location was not collected for this report.

Surrogate  [Mario Nevarez](#)

Started On	September 16 2025, 11:31am
Submitted On	September 16 2025, 11:31am (24 seconds)
Weather	NaN°
Version	V1 (latest)
Updated	September 16 2025, 11:31am
Report No.	66269716

New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date	September 16th 2025
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA RECYCLE FACILITY</a>

WEEKLY INSPECTION

Read and record the fluid height of staff gauges	Yes
Does the pond surface show visible oil?	No
Visually inspect containments liner	Yes
Check leak detection system for any evidence of a loss of integrity of the primary liner	Yes

SUMMARY

# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>



Signature






**New Mexico Recycling Facility Weekly Inspection**

**Location**

<b>Submitted By</b>	 <a href="#">Mario Nevarez</a>
<b>Surrogate</b>	 <a href="#">Mario Nevarez</a>
<b>Started On</b>	September 23 2025, 10:13am
<b>Submitted On</b>	September 23 2025, 10:13am (24 seconds)
<b>Weather</b>	80°, clear
<b>Version</b>	V1 (latest)
<b>Updated</b>	September 23 2025, 10:13am
<b>Report No.</b>	66677920



**New Mexico Recycling Facility Weekly Inspection**

**GENERAL DETAILS**

<b>Date</b>	September 23rd 2025
<b>Area</b>	<a href="#">New Mexico</a>
<b>Recycle Facility</b>	<a href="#">JAVELINA RECYCLE FACILITY</a>


**WEEKLY INSPECTION**

<b>Read and record the fluid height of staff gauges</b>	Yes
<b>Does the pond surface show visible oil?</b>	No
<b>Visually inspect containments liner</b>	Yes
<b>Check leak detection system for any evidence of a loss of integrity of the primary liner</b>	Yes

**SUMMARY**

<b># of Action Item(s)</b>	0
<b>Inspector</b>	<a href="#">Mario Nevarez</a>

Signature



A handwritten signature in blue ink is written over a horizontal grey line. The signature is stylized and appears to be a combination of letters, possibly 'K' and 'A'.


Generated Tuesday, September 23rd 2025, 3:28pm CDT.

powered by  KPA



**New Mexico Recycling Facility Weekly Inspection** **Location**

<b>Submitted By</b>	 <a href="#">Mario Nevarez</a>
<b>Surrogate</b>	 <a href="#">Mario Nevarez</a>
<b>Started On</b>	September 29 2025, 1:06pm
<b>Submitted On</b>	September 29 2025, 1:06pm (25 seconds)
<b>Weather</b>	77°, cloudy
<b>Version</b>	V1 (latest)
<b>Updated</b>	September 29 2025, 1:06pm
<b>Report No.</b>	67056779



**New Mexico Recycling Facility Weekly Inspection**

**GENERAL DETAILS**

<b>Date</b>	September 29th 2025
<b>Area</b>	<a href="#">New Mexico</a>
<b>Recycle Facility</b>	<a href="#">JAVELINA RECYCLE FACILITY</a>

**WEEKLY INSPECTION**

<b>Read and record the fluid height of staff gauges</b>	Yes
<b>Does the pond surface show visible oil?</b>	No
<b>Visually inspect containments liner</b>	Yes
<b>Check leak detection system for any evidence of a loss of integrity of the primary liner</b>	Yes

**SUMMARY**

<b># of Action Item(s)</b>	0
<b>Inspector</b>	<a href="#">Mario Nevarez</a>



**Signature**






**New Mexico Recycling Facility Weekly Inspection**

**Location**

Submitted By	 <a href="#">Mario Nevarez</a>
Surrogate	 <a href="#">Mario Nevarez</a>
Started On	October 8 2025, 1:55pm
Submitted On	October 8 2025, 1:55pm (22 seconds)
Weather	78°, cloudy
Version	V1 (latest)
Updated	October 8 2025, 1:55pm
Report No.	67677941



**New Mexico Recycling Facility Weekly Inspection**

**GENERAL DETAILS**

Date	October 8th 2025
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA_RECYCLE_FACILITY</a>

**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges	Yes
Does the pond surface show visible oil?	No
Visually inspect containments liner	Yes
Check leak detection system for any evidence of a loss of integrity of the primary liner	Yes

**SUMMARY**



# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>


Signature



**New Mexico Recycling Facility Weekly Inspection**

**Location**

Submitted By	 <a href="#">Mario Nevarez</a>
Surrogate	 <a href="#">Mario Nevarez</a>
Started On	October 13 2025, 3:26pm
Submitted On	October 13 2025, 3:26pm (38 seconds)
Weather	78°, clear
Version	V1 (latest)
Updated	October 13 2025, 3:26pm
Report No.	67944542



**New Mexico Recycling Facility Weekly Inspection**

**GENERAL DETAILS**

Date	October 13th 2025
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA_RECYCLE_FACILITY</a>


**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges	Yes
Does the pond surface show visible oil?	No
Visually inspect containments liner	Yes
Check leak detection system for any evidence of a loss of integrity of the primary liner	Yes

**SUMMARY**

# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>

Signature

A handwritten signature in blue ink is written over a horizontal grey line. The signature is stylized and appears to be a name starting with 'K'.



Generated Wednesday, October 22nd 2025, 10:20am CDT.

powered by  KPA



**New Mexico Recycling Facility Weekly Inspection**

**Location**

Submitted By	 <a href="#">Mario Nevarez</a>
Surrogate	 <a href="#">Mario Nevarez</a>
Started On	October 21 2025, 1:35pm
Submitted On	October 21 2025, 1:35pm (23 seconds)
Weather	67°, clear
Version	V1 (latest)
Updated	October 21 2025, 1:35pm
Report No.	68449585



**New Mexico Recycling Facility Weekly Inspection**

**GENERAL DETAILS**

Date	October 21st 2025
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA RECYCLE FACILITY</a>

**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges	Yes
Does the pond surface show visible oil?	No
Visually inspect containments liner	Yes
Check leak detection system for any evidence of a loss of integrity of the primary liner	Yes

**SUMMARY**

# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>

Signature



**New Mexico Recycling Facility Weekly Inspection** **Location**

Submitted By	 <a href="#">Mario Nevarez</a>
Surrogate	 <a href="#">Mario Nevarez</a>
Started On	October 27 2025, 1:57pm
Submitted On	October 27 2025, 1:58pm (24 seconds)
Weather	NaN°
Version	V1 (latest)
Updated	October 27 2025, 1:58pm
Report No.	68802117

Location was not collected for this report.

**New Mexico Recycling Facility Weekly Inspection**

**GENERAL DETAILS**

Date	October 27th 2025
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA_RECYCLE_FACILITY</a>


**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges	Yes
Does the pond surface show visible oil?	No
Visually inspect containments liner	Yes
Check leak detection system for any evidence of a loss of integrity of the primary liner	Yes

**SUMMARY**

# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>

Signature

A handwritten signature in blue ink is positioned above a horizontal line. The signature is stylized and appears to be a single word or a short phrase, possibly starting with a capital letter that has a large loop. The ink is a vibrant blue color.

Generated Tuesday, November 4th 2025, 11:06am CST.

powered by  KPA



**New Mexico Recycling Facility Weekly Inspection** **Location**

Submitted By  [Mario Nevarez](#)

*Location was not collected for this report.*

Surrogate  [Mario Nevarez](#)

Started On	November 5 2025, 3:11pm
Submitted On	November 5 2025, 3:12pm (19 seconds)
Weather	NaN°
Version	V1 (latest)
Updated	November 5 2025, 3:12pm
Report No.	69423649

**New Mexico Recycling Facility Weekly Inspection**

GENERAL DETAILS

Date	November 5th 2025
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA_RECYCLE_FACILITY</a>

WEEKLY INSPECTION

Read and record the fluid height of staff gauges	Yes
Does the pond surface show visible oil?	No
Visually inspect containments liner	Yes
Check leak detection system for any evidence of a loss of integrity of the primary liner	Yes

SUMMARY



# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>


Signature



**New Mexico Recycling Facility Weekly Inspection**

**Location**

Submitted By	 <a href="#">Mario Nevarez</a>
Surrogate	 <a href="#">Mario Nevarez</a>
Started On	November 10 2025, 3:44pm
Submitted On	November 10 2025, 3:45pm (26 seconds)
Weather	62°, clear
Version	V1 (latest)
Updated	November 10 2025, 3:45pm
Report No.	69706573



**New Mexico Recycling Facility Weekly Inspection**

**GENERAL DETAILS**

Date	November 10th 2025
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA_RECYCLE_FACILITY</a>

**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges	Yes
Does the pond surface show visible oil?	No
Visually inspect containments liner	Yes
Check leak detection system for any evidence of a loss of integrity of the primary liner	Yes

**SUMMARY**

# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>



Signature






New Mexico Recycling Facility Weekly Inspection

Location

Submitted By	 <a href="#">Mario Nevarez</a>
Surrogate	 <a href="#">Mario Nevarez</a>
Started On	November 18 2025, 1:49pm
Submitted On	November 18 2025, 1:49pm (21 seconds)
Weather	78°, clear
Version	V1 (latest)
Updated	November 18 2025, 1:49pm
Report No.	70220267



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date	November 18th 2025
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA_RECYCLE_FACILITY</a>

WEEKLY INSPECTION

Read and record the fluid height of staff gauges	Yes
Does the pond surface show visible oil?	No
Visually inspect containments liner	Yes
Check leak detection system for any evidence of a loss of integrity of the primary liner	Yes

SUMMARY



# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>


Signature



**New Mexico Recycling Facility Weekly Inspection**

**Location**

Submitted By	 <a href="#">Mario Nevarez</a>
Surrogate	 <a href="#">Mario Nevarez</a>
Started On	November 26 2025, 3:33pm
Submitted On	November 26 2025, 3:34pm (32 seconds)
Weather	57°, cloudy
Version	V1 (latest)
Updated	November 26 2025, 3:34pm
Report No.	70730399



**New Mexico Recycling Facility Weekly Inspection**

**GENERAL DETAILS**

Date	November 26th 2025
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA RECYCLE FACILITY</a>


**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges	Yes
Does the pond surface show visible oil?	No
Visually inspect containments liner	Yes
Check leak detection system for any evidence of a loss of integrity of the primary liner	Yes

**SUMMARY**

# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>

Signature

A handwritten signature in blue ink, consisting of several overlapping strokes, positioned above a horizontal line.



Generated Wednesday, December 3rd 2025, 8:52am CST.

powered by  KPA



**New Mexico Recycling Facility Weekly Inspection**

**Location**

Submitted By	 <a href="#">Mario Nevarez</a>
Surrogate	 <a href="#">Mario Nevarez</a>
Started On	December 1 2025, 9:52am
Submitted On	December 1 2025, 9:52am (24 seconds)
Weather	31°, clear
Version	V1 (latest)
Updated	December 1 2025, 9:53am
Report No.	70869815



**New Mexico Recycling Facility Weekly Inspection**

**GENERAL DETAILS**

Date	December 1st 2025
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA_RECYCLE_FACILITY</a>

**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges	Yes
Does the pond surface show visible oil?	No
Visually inspect containments liner	Yes
Check leak detection system for any evidence of a loss of integrity of the primary liner	Yes

**SUMMARY**



# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>


Signature



**New Mexico Recycling Facility Weekly Inspection**

**Location**

Submitted By	 <a href="#">Mario Nevarez</a>
Surrogate	 <a href="#">Mario Nevarez</a>
Started On	December 9 2025, 6:57am
Submitted On	December 9 2025, 6:57am (22 seconds)
Weather	41°, clear
Version	V1 (latest)
Updated	December 9 2025, 6:57am
Report No.	71352534



**New Mexico Recycling Facility Weekly Inspection**

**GENERAL DETAILS**

Date	December 9th 2025
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA RECYCLE FACILITY</a>

**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges	Yes
Does the pond surface show visible oil?	No
Visually inspect containments liner	Yes
Check leak detection system for any evidence of a loss of integrity of the primary liner	Yes

**SUMMARY**

# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>



Signature






New Mexico Recycling Facility Weekly Inspection

Location

Submitted By	 <a href="#">Mario Nevarez</a>
Surrogate	 <a href="#">Mario Nevarez</a>
Started On	December 16 2025, 4:13pm
Submitted On	December 16 2025, 4:13pm (22 seconds)
Weather	70°, clear
Version	V1 (latest)
Updated	December 16 2025, 4:13pm
Report No.	71816111



New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS

Date	December 16th 2025
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA RECYCLE FACILITY</a>

WEEKLY INSPECTION

Read and record the fluid height of staff gauges	Yes
Does the pond surface show visible oil?	No
Visually inspect containments liner	Yes
Check leak detection system for any evidence of a loss of integrity of the primary liner	Yes

SUMMARY



# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>


Signature



**New Mexico Recycling Facility Weekly Inspection**

**Location**

Submitted By	 <a href="#">Mario Nevarez</a>
Surrogate	 <a href="#">Mario Nevarez</a>
Started On	December 22 2025, 8:15am
Submitted On	December 22 2025, 8:16am (21 seconds)
Weather	39°, clear
Version	V1 (latest)
Updated	December 22 2025, 8:16am
Report No.	72103889



**New Mexico Recycling Facility Weekly Inspection**

**GENERAL DETAILS**

Date	December 22nd 2025
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA RECYCLE FACILITY</a>

**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges	Yes
Does the pond surface show visible oil?	No
Visually inspect containments liner	Yes
Check leak detection system for any evidence of a loss of integrity of the primary liner	Yes

**SUMMARY**

# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>



Signature






**New Mexico Recycling Facility Weekly Inspection**

**Location**

Submitted By	 <a href="#">Mario Nevarez</a>
Surrogate	 <a href="#">Mario Nevarez</a>
Started On	December 22 2025, 1:41pm
Submitted On	December 30 2025, 8:53am (8 days)
Weather	27°, cloudy
Version	V1 (latest)
Updated	December 30 2025, 8:53am
Report No.	72399705



**New Mexico Recycling Facility Weekly Inspection**

**GENERAL DETAILS**

Date	December 30th 2025
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA_RECYCLE_FACILITY</a>


**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges	Yes
Does the pond surface show visible oil?	No
Visually inspect containments liner	Yes
Check leak detection system for any evidence of a loss of integrity of the primary liner	Yes

**SUMMARY**

# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>

Signature

A handwritten signature in blue ink, consisting of several overlapping loops and a long downward stroke, positioned above a horizontal line.



Generated Monday, January 5th 2026, 10:09am CST.


powered by  KPA



**New Mexico Recycling Facility Weekly Inspection**

**Location**

Submitted By	 <a href="#">Mario Nevarez</a>
Surrogate	 <a href="#">Mario Nevarez</a>
Started On	January 6 2026, 7:31am
Submitted On	January 6 2026, 7:32am (21 seconds)
Weather	46°, clear
Version	V1 (latest)
Updated	January 6 2026, 7:32am
Report No.	72706662



**New Mexico Recycling Facility Weekly Inspection**

**GENERAL DETAILS**

Date	January 6th 2026
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA RECYCLE FACILITY</a>

**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges	Yes
Does the pond surface show visible oil?	No
Visually inspect containments liner	Yes
Check leak detection system for any evidence of a loss of integrity of the primary liner	Yes

**SUMMARY**



# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>


Signature



**New Mexico Recycling Facility Weekly Inspection**

**Location**

Submitted By	 <a href="#">Mario Nevarez</a>
Surrogate	 <a href="#">Mario Nevarez</a>
Started On	January 12 2026, 2:32pm
Submitted On	January 12 2026, 2:32pm (24 seconds)
Weather	54°, clear
Version	V1 (latest)
Updated	January 12 2026, 2:32pm
Report No.	73113728



**New Mexico Recycling Facility Weekly Inspection**

**GENERAL DETAILS**

Date	None
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA_RECYCLE_FACILITY</a>


**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges	Yes
Does the pond surface show visible oil?	No
Visually inspect containments liner	Yes
Check leak detection system for any evidence of a loss of integrity of the primary liner	Yes

**SUMMARY**

# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>

Signature

A handwritten signature in blue ink, consisting of several overlapping strokes that form a complex, abstract shape. The signature is positioned above a horizontal line.



Generated Monday, January 12th 2026, 2:33pm CST.

powered by  KPA



**New Mexico Recycling Facility Weekly Inspection**

**Location**

Submitted By	 <a href="#">Mario Nevarez</a>
Surrogate	 <a href="#">Mario Nevarez</a>
Started On	January 20 2026, 1:07pm
Submitted On	January 20 2026, 1:08pm (23 seconds)
Weather	50°, clear
Version	V1 (latest)
Updated	January 20 2026, 1:08pm
Report No.	73601797



**New Mexico Recycling Facility Weekly Inspection**

**GENERAL DETAILS**

Date	January 20th 2026
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA_RECYCLE_FACILITY</a>

**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges	Yes
Does the pond surface show visible oil?	No
Visually inspect containments liner	Yes
Check leak detection system for any evidence of a loss of integrity of the primary liner	Yes

**SUMMARY**



# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>


Signature



**New Mexico Recycling Facility Weekly Inspection**

**Location**

Submitted By	 <a href="#">Mario Nevarez</a>
Surrogate	 <a href="#">Mario Nevarez</a>
Started On	January 27 2026, 2:02pm
Submitted On	January 27 2026, 2:02pm (19 seconds)
Weather	40°, cloudy
Version	V1 (latest)
Updated	January 27 2026, 2:02pm
Report No.	73974215



**New Mexico Recycling Facility Weekly Inspection**

**GENERAL DETAILS**

Date	January 27th 2026
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA_RECYCLE_FACILITY</a>

**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges	Yes
Does the pond surface show visible oil?	No
Visually inspect containments liner	Yes
Check leak detection system for any evidence of a loss of integrity of the primary liner	Yes

**SUMMARY**

# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>



Signature





**New Mexico Recycling Facility Weekly Inspection**

**Location**

Submitted By	 <a href="#">Mario Nevarez</a>
Surrogate	 <a href="#">Mario Nevarez</a>
Started On	February 2 2026, 2:27pm
Submitted On	February 2 2026, 2:27pm (21 seconds)
Weather	62°, cloudy
Version	V1 (latest)
Updated	February 2 2026, 2:27pm
Report No.	74352891



**New Mexico Recycling Facility Weekly Inspection**

**GENERAL DETAILS**

Date	February 2nd 2026
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA_RECYCLE_FACILITY</a>

**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges	Yes
Does the pond surface show visible oil?	No
Visually inspect containments liner	Yes
Check leak detection system for any evidence of a loss of integrity of the primary liner	Yes

**SUMMARY**



# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>

Signature



**New Mexico Recycling Facility Weekly Inspection**

**Location**

Submitted By	 <a href="#">Mario Nevarez</a>
Surrogate	 <a href="#">Mario Nevarez</a>
Started On	February 8 2026, 8:35am
Submitted On	February 8 2026, 8:36am (24 seconds)
Weather	46°, clear
Version	V1 (latest)
Updated	February 8 2026, 8:36am
Report No.	74747501



**New Mexico Recycling Facility Weekly Inspection**

**GENERAL DETAILS**

Date	February 8th 2026
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA_RECYCLE_FACILITY</a>

**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges	Yes
Does the pond surface show visible oil?	No
Visually inspect containments liner	Yes
Check leak detection system for any evidence of a loss of integrity of the primary liner	Yes

**SUMMARY**



# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>


Signature



**New Mexico Recycling Facility Weekly Inspection**

**Location**

Submitted By	 <a href="#">Mario Nevarez</a>
Surrogate	 <a href="#">Mario Nevarez</a>
Started On	February 17 2026, 9:50am
Submitted On	February 17 2026, 9:50am (21 seconds)
Weather	47°, clear
Version	V1 (latest)
Updated	February 17 2026, 9:50am
Report No.	75346199



**New Mexico Recycling Facility Weekly Inspection**

**GENERAL DETAILS**

Date	February 17th 2026
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA_RECYCLE_FACILITY</a>

**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges	Yes
Does the pond surface show visible oil?	No
Visually inspect containments liner	Yes
Check leak detection system for any evidence of a loss of integrity of the primary liner	Yes

**SUMMARY**

# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>

Signature



Generated Wednesday, February 25th 2026, 9:34am CST.


powered by  KPA



**New Mexico Recycling Facility Weekly Inspection**

**Location**

Submitted By	 <a href="#">Mario Nevarez</a>
Surrogate	 <a href="#">Mario Nevarez</a>
Started On	February 25 2026, 6:38am
Submitted On	February 25 2026, 6:38am (23 seconds)
Weather	56°, clear
Version	V1 (latest)
Updated	February 25 2026, 6:38am
Report No.	75868038



**New Mexico Recycling Facility Weekly Inspection**

**GENERAL DETAILS**

Date	February 25th 2026
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA RECYCLE FACILITY</a>

**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges	Yes
Does the pond surface show visible oil?	No
Visually inspect containments liner	Yes
Check leak detection system for any evidence of a loss of integrity of the primary liner	Yes

**SUMMARY**

# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>

Signature

**Venegas, Victoria, EMNRD**

---

**From:** Venegas, Victoria, EMNRD  
**Sent:** Thursday, April 2, 2026 2:57 PM  
**To:** Shelly Cowden; David Grounds  
**Subject:** 1RF-463 - JAVELINA FACILITY [fVV2108855989]  
**Attachments:** C-147 1RF-463 JAVELINA FACILITY [fVV2108855989] 04.02.2026.pdf

**1RF-463 - JAVELINA FACILITY [fVV2108855989]**

Good morning Mr. Bruening.

The NMOCD has reviewed the annual extension request for 1RF-463 - JAVELINA FACILITY [fVV2108855989] received from [308339] OWL SWD OPERATING, LLC on 03/31/2026, Action ID **569290**. The registration/permit extension request is approved with the following conditions of approval:

- The 1RF-463 - JAVELINA FACILITY [fVV2108855989] is approved for one (1) year of operation from the date of the previous registration/permit expiration date of March 23, 2026. The new registration/permit expiration date is March 23, 2027.
- [308339] OWL SWD OPERATING, LLC will continue to operate, maintain, and close the 1RF-463 - JAVELINA FACILITY [fVV2108855989] in compliance with 19.15.34 NMAC, to include but not limited to the performance of weekly inspections regardless of fluid levels in the containment; recording of detailed inspection reports; removal of debris, foreign objects and oil from the containment; and monthly reporting of recycling and reuse of produced water, drilling fluids, and liquid oil field waste via from C-148.
- [308339] OWL SWD OPERATING, LLC will maintain a liquid level in the containment that is at least equal to the weight of the liner plus 20%. [308339] OWL SWD OPERATING, LLC may maintain a higher liquid level if they choose.
- If less than 20% of the total fluid capacity is utilized every consecutive six months, operation of the facility is considered ceased and notification of cessation of operations should be sent electronically to OCD Permitting. An extension to extend the cessation of operations, not to exceed six months, may be submitted using a C-147 form to OCD Permitting. However, if after this 6-month period, the containment was not utilized at a minimum of 20% fluid capacity, no additional extensions would be granted, and the operator would be directed to remove all fluids and proceed with the closure requirements.
- A minimum of 3-feet freeboard must be maintained in the recycling containment at all times.
- [308339] OWL SWD OPERATING, LLC will comply with 19.15.29 NMAC Releases in the event of any release of produced water or produced water or other oil field waste at 1RF-463 - JAVELINA FACILITY [fVV2108855989]. [308339] OWL SWD OPERATING, LLC will comply with all other OCD rules.
- [308339] OWL SWD OPERATING, LLC must perform weekly inspections of the containment and leak detection system.
- If [308339] OWL SWD OPERATING, LLC wishes to extend the registration/permit past March 23, 2027, a registration/permit extension request must be submitted to OCD. Extension requests are reviewed on a case-by-case basis and evaluated on their merit. Extensions are considered for a maximum length of one year. Additional requests must be submitted to OCD Permitting on Form C-147 as an Extension request and should include a formal extension request letter, a summary of the prior registration/permit period inspection reports, and the copies of the detailed inspection records for the prior permit period. The extension request should be submitted no later than February 23, 2027.

**NOTE:** Per the approved original application, this facility is comprised of three containments, each equipped with an independent leak detection system. For your next extension request, please ensure that the corresponding

inspection report clearly identifies the specific containment by name, i.e.: Javelina Facility South Pit, Javelina Facility North Pit (not yet constructed), and Javelina Facility AST.

Please let me know if you have any further questions or concerns.

Regards,

**Victoria Venegas** • Senior Environmental Scientist  
EMNRD - Oil Conservation Division  
506 W. Texas Ave. Artesia, NM 88210  
575.909.0269 | [Victoria.Venegas@emnrd.nm.gov](mailto:Victoria.Venegas@emnrd.nm.gov)

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 569290

**CONDITIONS**

Operator: OWL SWD OPERATING, LLC 20 Greenway Plaza Houston, TX 77046	OGRID: 308339
	Action Number: 569290
	Action Type: [C-147] Water Recycle Long (C-147L)

**CONDITIONS**

Created By	Condition	Condition Date
vvenegas	The NMOCD has reviewed the annual extension request for 1RF-463 - JAVELINA FACILITY [FV2108855989] received from [308339] OWL SWD OPERATING, LLC on 03/31/2026, Action ID 569290. The registration/permit extension request is approved	4/2/2026