



Certificate of Analysis

Number: 6030-21060187-001A

Artesia Laboratory

200 E Main St.
Artesia, NM 88210
Phone 575-746-3481Chandler Montgomery
Occidental Petroleum
1502 W Commerce Dr.
Carlsbad, NM 88220

June 21, 2021

Field:	Lost Tank	Sampled By:	Michael Mirabal
Station Name:	Lost Tank 30-19 Fed Com 1H	Sample Of:	Gas Spot
Station Number:	16102T	Sample Date:	06/16/2021 02:20
Station Location:	CTB	Sample Conditions:	113 psia, @ 92 °F Ambient: 95 °F
Sample Point:	Meter	Effective Date:	06/16/2021 02:20
Formation:	Quarterly	Method:	GPA-2261M
County:	Lea	Cylinder No:	1111-002369
Type of Sample:	Spot-Cylinder	Instrument:	70104124 (Inficon GC-MicroFusion)
Heat Trace Used:	N/A	Last Inst. Cal.:	06/21/2021 0:00 AM
Sampling Method:	Fill and Purge	Analyzed:	06/21/2021 12:21:17 by EJ R
Sampling Company:	SPL		

Analytical Data

Components	Un-normalized Mol %	Mol. %	Wt. %	GPM at 14.65 psia		
Hydrogen Sulfide	0.000	0.000	0.000		GPM TOTAL C2+	5.748
Nitrogen	3.714	3.705	4.543		GPM TOTAL C3+	2.964
Methane	72.207	72.042	50.591		GPM TOTAL iC5+	0.710
Carbon Dioxide	4.233	4.223	8.135			
Ethane	10.455	10.431	13.730	2.784		
Propane	5.365	5.353	10.332	1.472		
Iso-butane	0.671	0.669	1.702	0.219		
n-Butane	1.794	1.790	4.554	0.563		
Iso-pentane	0.444	0.443	1.399	0.162		
n-Pentane	0.510	0.509	1.608	0.184		
Hexanes Plus	0.837	0.835	3.406	0.364		
	100.230	100.000	100.000	5.748		

Calculated Physical Properties	Total	C6+
Relative Density Real Gas	0.7915	3.2176
Calculated Molecular Weight	22.84	93.19
Compressibility Factor	0.9962	

GPA 2172 Calculation:

Calculated Gross BTU per ft³ @ 14.65 psia & 60°F

Real Gas Dry BTU	1209	5113
Water Sat. Gas Base BTU	1188	5024
Ideal, Gross HV - Dry at 14.65 psia	1204.2	5113.2
Ideal, Gross HV - Wet	1183.1	5023.7
Net BTU Dry Gas - real gas	1098	
Net BTU Wet Gas - real gas	1079	

Comments: H₂S Field Content 0 ppm
Mcf/day 3276

Jesus Escobedo

Eric Ramirez

Data reviewed by: Eric Ramirez, Analyst

Quality Assurance: The above analyses are performed in accordance with ASTM, UOP, GPA guidelines for quality assurance, unless otherwise stated.

UPSET FLARING EVENT SPECIFIC JUSTIFICATIONS FORM**Facility:** Lost Tank 30-19 Fed 31H CTB**Flare Date:** 07/06/2021**Duration of event:** 10 Hours 45 Minutes**MCF Flared:** 1180.4**Start Time:** 04:00 AM**End Time:** 02:45 PM**Cause:** Downstream Activity Issue > DCP > Zia Gas Plant Power Outage**Method of Flared Gas Measurement:** Gas Flare Meter**Well API Associated with Facility:** 30-025-45182 Lost Tank 30-19 Federal Com 31H

Comments: This upset event was not caused by any wells associated with the facility. The emissions event was caused by the unforeseen, unexpected, sudden, and unavoidable interruption, restriction or complete shut-in of a gas pipeline by a third-party pipeline operator, which impacted Oxy's ability to send gas to a third-party gas pipeline.

1. Reason why this event was beyond Operator's control:

This emissions event was caused by the unforeseen, unexpected, sudden, and unavoidable interruption, restriction or complete shut-in of a gas pipeline by a third-party pipeline operator, which impacted Oxy's ability to send gas to a third-party gas pipeline. This interruption, restriction or complete shut-in of the gas pipeline by a third-party pipeline operator is downstream of Oxy's custody transfer point and out of Oxy's control to avoid or prevent from happening and did not stem from any of Oxy's upstream facility activity that could have been foreseen and avoided, and could not have been avoided by good design, operation, and preventative maintenance practices.

In this case, the high line pressure spike in DCP's gas pipeline impacted Oxy's ability to send gas to them, as their downstream facility was unable to handle the gas loads sent to them as a result of DCP's, Zia Gas Plant, having a power outage. Until DCP's downstream facilities were able to handle the volume of gas sent to them, the spike in line pressure forced Oxy's upstream facility to route all its stranded gas to a flare, as it was not able to push all its gas into DCP's gas pipeline. No advance warning was provided to Oxy personnel from DCP regarding issues with their gas system pipeline or their Zia Gas Plant.

2. Steps Taken to limit duration and magnitude of venting or flaring:

In this case, it is OXY's policy to route all stranded sales gas to a flare during an unforeseen and unavoidable emergency or malfunction, as part of the steps to take to limit duration and magnitude of flaring. Upon flaring alarms being received by the on-call Oxy production tech, DCP personnel were contacted about the unforeseeable pipeline restriction and/or shut-in and when normal gas service would be restored. Oxy was informed that the cause of the spike in DCP's pipeline pressure was due to an issue with their downstream facility, Zia Gas Plant, and no estimation of when normal gas service would be restored. The flare at this facility has a 98% combustion efficiency in order to lessen emissions as much as possible. The flare is regularly monitored to ensure flame is lit and

meeting opacity requirements. Oxy strives to take additional steps, when possible, to minimize the volume of gas flared by choking back well production and maintaining continual communication with DCP to ensure that gas is safely directed back to sales as soon as DCP resumes normal gas services.

3. Corrective Actions taken to eliminate the cause and reoccurrence of venting or flaring:

Oxy is limited in the corrective actions to eliminate the cause and potential reoccurrence of an interruption, restriction or complete shut-in of the gas pipeline by a third-party pipeline operator, as this issue is downstream of Oxy's custody transfer point and out of Oxy's control to avoid or prevent from happening again. DCP's downstream facility issues will re-occur from time to time and which in turn, directly impacts Oxy's ability to send gas to them. When DCP's downstream facility equipment has issues or greatly struggles to handle the volume of gas being sent to them by Oxy, DCP then restricts Oxy's ability to send gas, which then initiates Oxy to route all of its stranded gas not pushed into the DCP gas pipeline, to flare. OXY makes every effort to control and minimize emissions as much as possible. The only actions that Oxy can take and handle that is within its control, is to keep continually communicate with DCP personnel during these types of circumstances and whenever possible, choke back well production to reduce volume of gas flared.

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 51576

QUESTIONS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 51576
	Action Type: [C-129] Venting and/or Flaring (C-129)

QUESTIONS**Prerequisites**

Any messages presented in this section, will prevent submission of this application. Please resolve these issues before continuing with the rest of the questions.

Incident Well	[30-025-45182] LOST TANK 30 19 FEDERAL COM #031H
Incident Facility	Not answered.

Determination of Reporting Requirements

Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.

Was or is this venting and/or flaring caused by an emergency or malfunction	Yes
Did or will this venting and/or flaring last eight hours or more cumulatively within any 24-hour period from a single event	Yes
Is this considered a submission for a venting and/or flaring event	Yes, major venting and/or flaring of natural gas.
An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during venting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.	
Was there or will there be at least 50 MCF of natural gas vented and/or flared during this event	Yes
Did this venting and/or flaring result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No
Was the venting and/or flaring within an incorporated municipal boundary or withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No

Equipment Involved

Primary Equipment Involved	Other (Specify)
Additional details for Equipment Involved. Please specify	Emergency Flare > Downstream Activity Issue > DCP > Zia Gas Plant Power Outage

Representative Compositional Analysis of Vented or Flared Natural Gas

Please provide the mole percent for the percentage questions in this group.

Methane (CH4) percentage	72
Nitrogen (N2) percentage, if greater than one percent	4
Hydrogen Sulfide (H2S) PPM, rounded up	0
Carbon Dioxide (CO2) percentage, if greater than one percent	4
Oxygen (O2) percentage, if greater than one percent	0
If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.	
Methane (CH4) percentage quality requirement	Not answered.
Nitrogen (N2) percentage quality requirement	Not answered.
Hydrogen Sulfide (H2S) PPM quality requirement	Not answered.
Carbon Dioxide (CO2) percentage quality requirement	Not answered.
Oxygen (O2) percentage quality requirement	Not answered.

Date(s) and Time(s)

Date venting and/or flaring was discovered or commenced	07/06/2021
Time venting and/or flaring was discovered or commenced	04:00 AM
Time venting and/or flaring was terminated	02:45 PM
Cumulative hours during this event	11

Measured or Estimated Volume of Vented or Flared Natural Gas

Natural Gas Vented (Mcf) Details	Not answered.
----------------------------------	---------------

Natural Gas Flared (Mcf) Details	Cause: Other Other (Specify) Natural Gas Flared Released: 1,180 Mcf Recovered: 0 Mcf Lost: 1,180 Mcf]
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Gas Flare Meter
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity	
Was or is this venting and/or flaring a result of downstream activity	Yes
Was notification of downstream activity received by you or your operator	No
Downstream OGRID that should have notified you or your operator	[229527] DCP MIDSTREAM, L.P.
Date notified of downstream activity requiring this venting and/or flaring	Not answered.
Time notified of downstream activity requiring this venting and/or flaring	Not answered.

Steps and Actions to Prevent Waste	
For this event, the operator could not have reasonably anticipated the current event and it was beyond the operator's control.	True
Please explain reason for why this event was beyond your operator's control	In this case, the high line pressure spike in DCP's gas pipeline impacted Oxy's ability to send gas to them, as their downstream facility was unable to handle the gas loads sent to them as a result of DCP's, Zia Gas Plant, having a power outage. Until DCP's downstream facilities were able to handle the volume of gas sent to them, the spike in line pressure forced Oxy's upstream facility to route all its stranded gas to a flare, as it was not able to push all its gas into DCP's gas pipeline. No advance warning was provided to Oxy personnel from DCP regarding issues with their gas system pipeline or their Zia Gas Plant.
Steps taken to limit the duration and magnitude of venting and/or flaring	In this case, it is OXY's policy to route all stranded sales gas to a flare during an unforeseen and unavoidable emergency or malfunction, as part of the steps to take to limit duration and magnitude of flaring. Upon flaring alarms being received by the on-call Oxy production tech, DCP personnel were contacted about the unforeseeable pipeline restriction and/or shut-in and when normal gas service would be restored. Oxy was informed that the cause of the spike in DCP's pipeline pressure was due to an issue with their downstream facility, Zia Gas Plant, and no estimation of when normal gas service would be restored. The flare at this facility has a 98% combustion efficiency in order to lessen emissions as much as possible. The flare is regularly monitored to ensure flame is lit and meeting opacity requirements. Oxy strives to take additional steps, when possible, to minimize the volume of gas flared by choking back well production and maintaining continual communication with DCP to ensure that gas is safely directed back to sales as soon as DCP resumes normal gas services.
Corrective actions taken to eliminate the cause and reoccurrence of venting and/or flaring	Oxy is limited in the corrective actions to eliminate the cause and potential reoccurrence of an interruption, restriction or complete shut-in of the gas pipeline by a third-party pipeline operator, as this issue is downstream of Oxy's custody transfer point and out of Oxy's control to avoid or prevent from happening again. DCP's downstream facility issues will re-occur from time to time and which in turn, directly impacts Oxy's ability to send gas to them. When DCP's downstream facility equipment has issues or greatly struggles to handle the volume of gas being sent to them by Oxy, DCP then restricts Oxy's ability to send gas, which then initiates Oxy to route all of its stranded gas not pushed into the DCP gas pipeline, to flare. OXY makes every effort to control and minimize emissions as much as possible. The only actions that Oxy can take and handle that is within its control, is to keep continually communicate with DCP personnel during these types of circumstances and whenever possible, choke back well production to reduce volume of gas flared.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 51576

CONDITIONS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 51576
	Action Type: [C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
marialuna	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	9/23/2021