

Pima Environmental Services 5614 N. Lovington Highway Hobbs, NM 88240 575-964-7740

June 21, 2022

Bureau of Land Management 620 East Green Street Carlsbad, NM 88220

NMOCD District 2 811 S. First St Artesia, NM, 88210

RE: Liner Inspection and Closure Report

Marwari 28 CTB 1 API No. N/A

GPS: Latitude 32.105923 Longitude -103.687701 UL- D, Section 28, Township 25S, Range 32E NMOCD Reference No. NAPP2035244659

Devon Energy Production Company (Devon) has contracted Pima Environmental Services, LLC (Pima) to perform a liner inspection and prepare this closure report for a crude oil release that happened at the Marwari 28 CTB 1 (Marwari). An initial C-141 was submitted on December 18, 2020, and can be found in Appendix B. This incident was assigned Incident ID NAPP2035244659, by the New Mexico Oil Conservation Division (NMOCD).

Site Information and Site Characterization

The Marwari is located approximately twenty-nine (29) miles West of Jal, NM. This spill site is in Unit D, Section 28, Township 25S, Range 32E, Latitude 32.105923 Longitude -103.687701, Lea County, NM. A Location Map can be found in Figure 1.

Based upon New Mexico Office of the State Engineer well water data, depth to the nearest groundwater in this area is 350 feet below grade surface (BGS). According to the United States Geological Survey well water data, depth to the nearest groundwater in this area is greater than 291 feet BGS. See Appendix A for referenced water surveys. The Marwari is in a low karst area (Figure 3). A Topographic Map can be found in Figure 2.

Release Information

NAPP2035244659: On November 29, 2020, A valve was left cracked open causing fluid released into lined containment. Approximately 17.65 barrels (bbls) of crude oil was released. A vacuum truck was dispatched and recovered all 17.65 bbls of fluid from the lined SPCC containment ring. Once fluids were removed, the liner was visually inspected by Devon field staff for any pinholes or punctures, and none were found. Based on this inspection there is no evidence that the spilled fluids left containment.

A Site Map can be found in Figure 4.

Site Assessment and Liner Inspection

On June 13, 2022, after sending the 48-hour notification via email, Pima Environmental conducted a liner inspection at this location. We concluded that this liner and containment maintained its integrity and was able to retain the fluids. The liner inspection form and photographic documentation can be found in Appendix C.

Closure Request

After careful review, Pima requests that this incident NAPP2035244659 be closed. Devon has complied with the applicable closure requirements.

Should you have any questions or need additional information, please feel free to contact Tom Bynum at 575-964-7740 or tom@pimaoil.com.

Respectfully,

Tom Bynum

Tom Bynum
Project Manager
Pima Environmental Services, LLC

Attachments

Figures:

- 1- Location Map
- 2- Topographic Map
- 3- Karst Map
- 4- Site Map

Appendices:

Appendix A- Referenced Water Surveys

Appendix B- C-141 Form & 48 Hour Notification

Appendix C- Liner Inspection Form & Photographic Documentation




Figures:


1-Location Map


2-Topographic Map


3-Karst Map

4-Site Map











Appendix A

Water Surveys:

OSE

USGS



New Mexico Office of the State Engineer

Water Column/Average Depth to Water

(A CLW##### in the POD suffix indicates the POD has been replaced & no longer serves a water right file.)

POD Number

C 03829 POD1

C 03554 POD1

(R=POD has been replaced, O=orphaned,

C=the file is

(quarters are 1=NW 2=NE 3=SW 4=SE)

closed) (quarters are smallest to largest)

(NAD83 UTM in meters) (

(In feet)

POD

Sub-Q Q QWater basin County 64 16 4 Sec Tws Rng X Y DistanceDepthWellDepthWater Column Code **CUB** LE 3 3 1 06 26S 32E 620628 3549186 4916 646 350 296 **CUB** ED 2 1 4 01 26S 31E 620547 3549148 4998 630 300 330

Average Depth to Water:

325 feet

Minimum Depth:

300 feet

Maximum Depth: 350 feet

Record Count: 2

UTMNAD83 Radius Search (in meters):

Easting (X): 623816.56

Northing (Y): 3552929.67

Radius: 5000

The data is furnished by the NMOSE/ISC and is accepted by the recipient with the expressed understanding that the OSE/ISC make no warranties, expressed or implied, concerning the accuracy, completeness, reliability, usability, or suitability for any particular purpose of the data.

6/17/22 9:44 AM

WATER COLUMN/ AVERAGE DEPTH TO WATER



USGS Home Contact USGS Search USGS

National Water Information System: Web Interface

USGS Water Resources

Data Category:	Geographic Area:		
Groundwater ~	✓ United States	~	GO

Click to hideNews Bulletins

- Explore the NEW <u>USGS National Water Dashboard</u> interactive map to access real-time water data from over 13,500 stations nationwide.
- Full News 🔊

Groundwater levels for the Nation

Important: <u>Next Generation Monitoring Location Page</u>

Search Results -- 1 sites found

site_no list =

• 321005103402301

Minimum number of levels = 1

Save file of selected sites to local disk for future upload

USGS 321005103402301 24S.32E.33.42241

Available data for this site Groundwater: Field measurements GO

Lea County, New Mexico

Hydrologic Unit Code 13070001

Latitude 32°10'21.6", Longitude 103°40'18.9" NAD83

Land-surface elevation 3,499.00 feet above NGVD29

The depth of the well is 367 feet below land surface.

This well is completed in the Other aquifers (N9999OTHER) national aquifer.

Released to Imaging: 9/1/2022 1:39:00 PM


.

This well is completed in the Chinle Formation (231CHNL) local aquifer.

Output formats

Table of data	
Tab-separated data	
Graph of data	
Reselect period	





Breaks in the plot represent a gap of at least one year between field measurements. <u>Download a presentation-quality graph</u>

Questions about sites/data?
Feedback on this web site
Automated retrievals
Help
Data Tips
Explanation of terms



Appendix B

C-141 Form

48-Hour Notification

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	NAPP2035244659
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party OGRID							
Contact Name Contact T			elephone				
Contact email Incide			Incident #	# (assigned by OCD)			
Contact maili	ng address			1			
Latitude				of Release So			
			(NAD 83 in dec	imal degrees to 5 decim	nal places)		
Site Name				Site Type			
Date Release	Discovered			API# (if app	licable)		
Unit Letter	Section	Township	Range	Coun	ty		
Crude Oil		(s) Released (Select all	I that apply and attach	Volume of I		volumes provided below)	
Produced		Volume Release			Volume Recov		
Птошиси		Is the concentrat	ion of total dissolv water >10,000 mg/	` /	☐ Yes ☐ No		
Condensar	te	Volume Release			Volume Recovered (bbls)		
Natural G	as	Volume Release	d (Mcf)		Volume Recovered (Mcf)		
Other (des	scribe)	Volume/Weight	Released (provide	units)	Volume/Weigh	nt Recovered (provide units)	
Cause of Rele	ease						

Received by OCD: 8/29/2022/1944:50 PMI State of New Mexico
Page 2 Oil Conservation Division

Page 14 of 24

Incident ID	NAPP2035244659
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? ☐ Yes ☐ No	If YES, for what reason(s) does the responsible party consider this a major release?
TOTAL TOTAL	
If YES, was immediate r	notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?
	Initial Response
The responsible	party must undertake the following actions immediately unless they could create a safety hazard that would result in injury
☐ The source of the rel	ease has been stopped.
☐ The impacted area ha	as been secured to protect human health and the environment.
Released materials h	ave been contained via the use of berms or dikes, absorbent pads, or other containment devices.
☐ All free liquids and r	recoverable materials have been removed and managed appropriately.
If all the actions describe	ed above have <u>not</u> been undertaken, explain why:
has begun, please attach	AAC the responsible party may commence remediation immediately after discovery of a release. If remediation a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred nt area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.
regulations all operators are public health or the environ failed to adequately investig	ormation given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and required to report and/or file certain release notifications and perform corrective actions for releases which may endanger ment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have gate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws
	Title:
Signature: Kendra	DeHoyos Date:
email:	Telephone:
OCD Only	
Received by:	Date:

Spills In Line	d Containment
Measurements	Of Standing Fluid
Length(Ft)	26
Width(Ft)	45
Depth(in.)	1.5
Total Capacity without tank displacements (bbls)	26.05
No. of 500 bbl Tanks In Standing Fluid	2
No. of Other Tanks In Standing Fluid	
OD Of Other Tanks In Standing Fluid(feet)	
Total Volume of standing fluid accounting for tank displacement.	17.65

NAPP2035244659

Incident ID District RP Facility ID Application ID

Site Assessment/Characterization

This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

What is the shallowest depth to groundwater beneath the area affected by the release?	291 (ft bgs)
Did this release impact groundwater or surface water?	☐ Yes ☒ No
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?	☐ Yes 🏻 No
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?	☐ Yes 🔀 No
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?	☐ Yes 🔀 No
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	☐ Yes 🔀 No
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	☐ Yes ☒ No
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?	☐ Yes ☒ No
Are the lateral extents of the release within 300 feet of a wetland?	☐ Yes ☒ No
Are the lateral extents of the release overlying a subsurface mine?	☐ Yes ☒ No
Are the lateral extents of the release overlying an unstable area such as karst geology?	☐ Yes ☒ No
Are the lateral extents of the release within a 100-year floodplain?	☐ Yes ☒ No
Did the release impact areas not on an exploration, development, production, or storage site?	☐ Yes 🛛 No
Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and ver contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.	tical extents of soil
Characterization Report Checklist: Each of the following items must be included in the report.	
Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring well Field data Data table of soil contaminant concentration data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographs including date and GIS information Topographic/Aerial maps Laboratory data including chain of custody	s.

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

Received by OCD: 8/29/2022 1:44:50 PM Form C-141 State of New Mexico Page 4 Oil Conservation Division

Incident ID NAPP2035244659
District RP
Facility ID
Application ID

I hereby certify that the information given above is true and complete to the regulations all operators are required to report and/or file certain release not public health or the environment. The acceptance of a C-141 report by the failed to adequately investigate and remediate contamination that pose a thr addition, OCD acceptance of a C-141 report does not relieve the operator of and/or regulations.	tifications and perform corrective actions for releases which may endanger OCD does not relieve the operator of liability should their operations have reat to groundwater, surface water, human health or the environment. In
Printed Name: Wes Mathews	Title: EHS Professional
Signature: Wesley Mathews	Date: 6/21/2022
email: wesley.mathews@dvn.com	Telephone: <u>575-513-8608</u>
OCD OI.	
OCD Only Received by: Jocelyn Harimon	Date:08/29/2022

Page 18 of 24

Incident ID	NAPP2035244659
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following in	tems must be included in the closure report.
X A scaled site and sampling diagram as described in 19.15.29.1	1 NMAC
x Photographs of the remediated site prior to backfill or photos must be notified 2 days prior to liner inspection)	of the liner integrity if applicable (Note: appropriate OCD District office
☐ Laboratory analyses of final sampling (Note: appropriate ODC	C District office must be notified 2 days prior to final sampling)
Description of remediation activities	
and regulations all operators are required to report and/or file certain may endanger public health or the environment. The acceptance of	ntions. The responsible party acknowledges they must substantially nditions that existed prior to the release or their final land use in
Signature: Wesley Mathews	
	Date: 6/21/2022
email: wesley.mathews@dvn.com	Telephone: <u>575-513-8608</u>
OCD Only	
Received by:	Date:08/29/2022
	of liability should their operations have failed to adequately investigate and water, human health, or the environment nor does not relieve the responsible or regulations.
Closure Approved by:	Date: 09/01/2022
Closure Approved by:	Title: Environmental Specialist A



Gio PimaOil <gio@pimaoil.com>

Marwari 28 CTB Liner Inspection

1 message

Gio PimaOil <gio@pimaoil.com>

Thu, Jun 9, 2022 at 10:54 AM

To: ocdonline@state.nm.us, Tom Pima Oil <tom@pimaoil.com>

Good Morning,

Pima Environmental would like to notify you that we will be conducting a liner Inspection at the Marwari 28 CTB 1 for incident NAPP2035244659. Pima personnel are scheduled to be on site for this Inspection event at approximately 8:00 a.m. On Monday, June 13, 2022. If you have any questions or concerns, please let me know. Thank you.

Gio Gomez Environmental Project Manager cell-806-782-1151 Office- 575-964-7740 Pima Environmental Services, LLC.



Appendix C

Liner Inspection Form

Photographic Documentation



Liner Inspection Form

Company Name:	Devon E	Energy				
Site:	<u>Mar</u>	wari 28	3 CTB 1		=	
Lat/Long:	32.2	95341,	-103.554565			
NMOCD Incident ID & Incident Date:	NA	<u> </u>	5244659	11/29/2020		
2-Day Notification Sent:	via E	mail by	y Gio Gomez	6/9/2022		
Inspection Date:	6/13	/2022_				
Liner Type:	Earthen	w/line	r	Earthen no liner		Polystar
	Steel w/	poly li	ner	Steel w/spray epoxy	y	No Liner
Other:						
Visualization	Yes	No		Commer	nts	
Is there a tear in the liner?		X				
Are there holes in the liner?		X				
Is the liner retaining any fluids?		X				
Does the liner have integrity to contain a leak?	X					
Comments:						
Inspector Name:Ne	ed Roger	<u>s</u>	Inst	ector Signature: _ <i>Ne</i>	rd Rogers_	



SITE PHOTOGRAPHS DEVON ENERGY – LINER INSPECTION

MARWARI 28 CTB 1



















District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III 1000 Rio Brazos Rd., Aztec, NM 87410

Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 138941

CONDITIONS

Operator:	OGRID:
DEVON ENERGY PRODUCTION COMPANY, LP	6137
	Action Number:
Oklahoma City, OK 73102	138941
	Action Type:
	[C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
jnobui	Closure Approved.	9/1/2022