

SITE INFORMATION

Closure Report
Boo Radley 21 CTB (08.05.22)
Incident #: NAPP2223044639
Eddy County, New Mexico
Unit C Sec 21 T26S R28E
32.033700°, -104.092900°

Produced Water Release
Point of Release: Hole in Transfer Pump

Release Date: 08.05.22

Volume Released: 14 barrels of Produced Water Volume Recovered: 13 barrels of Produced Water

CARMONA RESOURCES

Prepared for: Concho Operating, LLC 15 West London Road Loving, New Mexico 88256

Prepared by: Carmona Resources, LLC 310 West Wall Street Suite 415 Midland, Texas 79701

> 310 West Wall Street, Suite 415 Midland TX, 79701 432.813.1992



TABLE OF CONTENTS

1.0 SITE INFORMATION AND BACKGROUND

2.0 SITE CHARACTERIZATION AND GROUNDWATER

3.0 NMAC REGULATORY CRITERIA

4.0 LINER INSPECTION ACTIVITIES

5.0 CONCLUSIONS

FIGURES

FIGURE 1	OVERVIEW	FIGURE 2	TOPOGRAPHIC

FIGURE 3 SECONDARY CONTAINMENT MAP

APPENDICES

APPENDIX A PHOTOS

APPENDIX B INITIAL C-141 AND FINAL/NMOCD CORRESPONDENCE

APPENDIX C SITE CHARACTERIZATION AND GROUNDWATER



September 13, 2022

Mike Bratcher District Supervisor Oil Conservation Division, District 2 811 S. First Street Artesia, New Mexico 88210

Re: Closure Report

Boo Radley 21 CTB (08.05.22) Concho Operating, LLC Incident ID NAPP2223044639 Site Location: Unit C, S21, T26S, R28E

Site Location: Unit C, S21, T26S, R28E (Lat 32.033700°, Long -104.092900°)

Eddy County, New Mexico

Mr. Bratcher:

On behalf of Concho Operating, LLC (COG), Carmona Resources, LLC has prepared this letter to document site activities for Boo Radley 21 CTB (08.05.22). The site is located at 32.033700°, -104.092900° within Unit C, S21, T26S, R28E, in Eddy County, New Mexico (Figures 1 and 2).

1.0 Site information and Background

Based on the initial C-141 obtained from the New Mexico Oil Conservation Division (NMOCD), the release was discovered on August 5, 2022, due to a development in the transfer pump. It resulted in approximately fourteen (14) barrels of produced water and thirteen (13) barrels of produced water recovered. See figure 3. The initial C-141 form is attached in Appendix B.

2.0 Site Characterization and Groundwater

The site is located within a high karst area. Based on a review of the New Mexico Office of State Engineers and USGS databases, no known water source within a 0.50-mile radius of the location. The closest well is located approximately 0.70 miles Southeast of the site in S22, T26S, R28E and was drilled in 1964. The well has a reported depth to groundwater of 120' feet below ground surface (ft bgs). A copy of the associated point of diversion is attached in Appendix C.

3.0 Site Characterization and Groundwater

Per the NMOCD regulatory criteria established in 19.15.29.12 NMAC, the following criteria were utilized in assessing the site.

- Benzene: 10 milligrams per kilogram (mg/kg).
- Benzene, toluene, ethylbenzene, and total xylenes (BTEX): 50 mg/kg.
- TPH: 100 mg/kg (GRO + DRO + MRO).
- Chloride: 600 mg/kg.



4.0 Liner Inspection Activities

Before performing the liner inspection, the NMOCD division office was notified via email on August 16, 2022, per Subsection D of 19.15.29.12 NMAC. See Appendix B. On August 18, 2022, Carmona Resources, LLC conducted liner inspection activities to assess the liner's integrity within the facility and determined the liner was intact with no integrity issues. Refer to the Photolog.

5.0 Conclusions

Based on the liner inspection throughout the facility, no further actions are required at the site. The final C-141 is attached, and COG formally requests closure of the spill. If you have any questions regarding this report or need additional information, don't hesitate to contact us at 432-813-1992. Sincerely,

Carmona Resources, LLC


Mike Carmona


Environmental Manager

Conner Moehring Sr. Project Manager

FIGURES

CARMONA RESOURCES







APPENDIX A

CARMONA RESOURCES

PHOTOGRAPHIC LOG

Concho Operating, LLC

Photograph No. 1

Facility: Boo Radley 21 CTB (08.05.22)

County: Eddy County, New Mexico

Description:

View of the secondary containment.



Photograph No. 2

Facility: Boo Radley 21 CTB (08.05.22)

County: Eddy County, New Mexico

Description:

View of the secondary containment.



Photograph No. 3

Facility: Boo Radley 21 CTB (08.05.22)

County: Eddy County, New Mexico

Description:

View of the secondary containment.





PHOTOGRAPHIC LOG

Concho Operating, LLC

Photograph No. 4

Facility: Boo Radley 21 CTB (08.05.22)

County: Eddy County, New Mexico

Description:

View of the secondary containment.



Photograph No. 5

Facility: Boo Radley 21 CTB (08.05.22)

County: Eddy County, New Mexico

Description:

View of the secondary containment.



Photograph No. 6

Facility: Boo Radley 21 CTB (08.05.22)

County: Eddy County, New Mexico

Description:

View of the secondary containment.



APPENDIX B

CARMONA RESOURCES

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party OGRID			OGRID			
Contact Name Co			Contact T	ontact Telephone		
Contact email Inc			Incident #	cident # (assigned by OCD)		
Contact mail	ing address					
			Location	of Release S	ource	
Latitude			(NAD 83 in dec	Longitude imal degrees to 5 decir	mal places)	
Site Name				Site Type		
Date Release	Discovered			API# (if app	plicable)	
Unit Letter	Section	Township	Range	Cour	nty	
Crude Oil	Material	Federal Tr	Nature and	Volume of	justification for t	he volumes provided below) covered (bbls)
Produced		Volume Release				covered (bbls)
Troduced	Water		ion of dissolved cl	nloride in the	☐ Yes ☐ No	
Condensa	te	Volume Released	d (bbls)		Volume Recovered (bbls)	
☐ Natural G	Natural Gas Volume Released (Mcf)				Volume Recovered (Mcf)	
Other (des	er (describe) Volume/Weight Released (provide units)			units)	Volume/We	ight Recovered (provide units)
Cause of Rela	ease					

Received by OCD: 11/10/2022 2:35:49 PM Form C-141 State of New Mexico Page 2 Oil Conservation Division

Daga	4 1		C 20
Page	14	nı	-30
1 1180	1.7	v_{j}	_00

Incident ID	
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC? ☐ Yes ☐ No	If YES, for what reason(s) does the resp	onsible party consider this a major release?
If YES, was immediate no	otice given to the OCD? By whom? To v	rhom? When and by what means (phone, email, etc)?
	Initial F	Response
The responsible	party must undertake the following actions immediat	ely unless they could create a safety hazard that would result in injury
☐ The impacted area ha☐ Released materials ha	ease has been stopped. Is been secured to protect human health an ave been contained via the use of berms or ecoverable materials have been removed a	dikes, absorbent pads, or other containment devices.
It all the actions described	d above have <u>not</u> been undertaken, explair	why:
has begun, please attach	a narrative of actions to date. If remedia	remediation immediately after discovery of a release. If remediation efforts have been successfully completed or if the release occurred please attach all information needed for closure evaluation.
regulations all operators are public health or the environr failed to adequately investig	required to report and/or file certain release no ment. The acceptance of a C-141 report by the ate and remediate contamination that pose a th	e best of my knowledge and understand that pursuant to OCD rules and tifications and perform corrective actions for releases which may endanger OCD does not relieve the operator of liability should their operations have reat to groundwater, surface water, human health or the environment. In f responsibility for compliance with any other federal, state, or local laws
Printed Name	Donarne	Title:
Signature:	tanezoparze	Date:
email:		Telephone:
OCD Only Received by:	celyn Harimon	Date:11/10/2022

L48 Spill Volume Estimate Form				_					
	Facility Name & Number: Boo Radley 21 CTB								
			Asset Area:	DBW					
	Relea	ase Disco	overy Date & Time:	8.5.22					
			Release Type:	Produced Water					
Provide	e any kno	wn deta	ils about the event:	Hole in transfer Pum	р				
					Sp	oill Calculation	- On Pad Surface	Pool Spill	
Convert Irregular shape into a series of rectangles	Length (ft.)	Width (ft.)	Deepest point in each of the areas (in.)	No. of boundaries of "shore" in each area	Estimated <u>Pool</u> Area (sq. ft.)	Estimated Average Depth (ft.)	Estimated volume of each pool area (bbl.)	Penetration allowance (ft.)	Total Estimated Volume of Spill (bbl.)
Rectangle A	39.0	65.0	1.50	4	2535.000	0.031	14.101	0.002	14.123
Rectangle B					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!
Rectangle C					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!
Rectangle D					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!
Rectangle E					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!
Rectangle F					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!
Rectangle G					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!
Rectangle H					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!
Rectangle I					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!
Rectangle J					0.000	#DIV/0!	#DIV/0!	#DIV/0!	#DIV/0!
								Total Volume Release:	14.123

Received by OCD: 11/10/2022 2:35:49 PM Form C-141 State of New Mexico Page 3 Oil Conservation Division

	Page 16 of 30
Incident ID	
District RP	
Facility ID	
Application ID	

Site Assessment/Characterization

This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

What is the shallowest depth to groundwater beneath the area affected by the release?	(ft bgs)			
Did this release impact groundwater or surface water?	☐ Yes ☐ No			
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?	☐ Yes ☐ No			
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?	☐ Yes ☐ No			
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?	☐ Yes ☐ No			
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	☐ Yes ☐ No			
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	☐ Yes ☐ No			
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?	☐ Yes ☐ No			
Are the lateral extents of the release within 300 feet of a wetland?	☐ Yes ☐ No			
Are the lateral extents of the release overlying a subsurface mine?	☐ Yes ☐ No			
Are the lateral extents of the release overlying an unstable area such as karst geology?	☐ Yes ☐ No			
Are the lateral extents of the release within a 100-year floodplain?	☐ Yes ☐ No			
Did the release impact areas not on an exploration, development, production, or storage site?	☐ Yes ☐ No			
Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soi contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.				
Characterization Report Checklist: Each of the following items must be included in the report.				
Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring well Field data Data table of soil contaminant concentration data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographs including date and GIS information Topographic/Aerial maps Laboratory data including chain of custody	ls.			

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

Received by OCD: 11/10/2022 2:35:49 PM Form C-141 State of New Mexico Page 4 Oil Conservation Division

	Page 17 of .	<i>30</i>
Incident ID		
District RP		
Facility ID		
Application ID		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.			
Printed Name:	_ Title:		
Signature: Jacque Thoris	Date:		
email:	Telephone:		
OCD Only			
Received by: Jocelyn Harimon	Date:11/10/2022		

Received by OCD: 11/10/2022 2:35:49 PM Form C-141 State of New Mexico Page 6 Oil Conservation Division

	Page 18 of 30
Incident ID	
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.

☐ A scaled site and sampling diagram as described in 19.15.29.1	1 NMAC
Photographs of the remediated site prior to backfill or photos must be notified 2 days prior to liner inspection)	of the liner integrity if applicable (Note: appropriate OCD District office
☐ Laboratory analyses of final sampling (Note: appropriate ODG	C District office must be notified 2 days prior to final sampling)
☐ Description of remediation activities	
and regulations all operators are required to report and/or file certain may endanger public health or the environment. The acceptance of	ntions. The responsible party acknowledges they must substantially nditions that existed prior to the release or their final land use in
Printed Name:	
Signature: Jacque Thoris	Date:
email:	Telephone:
OCD Only	
Received by: Jocelyn Harimon	Date:11/10/2022
	of liability should their operations have failed to adequately investigate and water, human health, or the environment nor does not relieve the responsible or regulations.
Closure Approved by:	Date:
Printed Name:	

From: Mike Carmona

Sent: Tuesday, August 16, 2022 3:01 PM

To: OCD.Enviro@state.nm.us

Cc: Conner Moehring

Subject: RE: COG - BOO RADLEY 21CTB (08.05.22) Notification

Good Afternoon,

On behalf of COG, Carmona Resources will conduct a liner inspection at the below-referenced site on 08/18/2022. Please let me know if you have any questions.

COG - BOO RADLEY 21CTB (08.05.22) Sec 21 T26S R28E Unit C 32.0337, -104.0929 Eddy County, New Mexico

Mike J. Carmona 310 West Wall Street, Suite 415 Midland TX, 79701 M: 432-813-1992 Mcarmona@carmonaresources.com

CARMONA RESOURCES



Sent: Tuesday, August 16, 2022 3:00 PM

To: OCD.Enviro@state.nm.us

Cc: Conner Moehring; Harris, Jacqui

Subject: COG - BOO RADLEY 21CTB (08.05.22) Notification

Good Afternoon,


On behalf of COG, Carmona Resources will conduct a liner inspection at the below-referenced site on 08/18/2022. Please let me know if you have any questions.


COG - BOO RADLEY 21CTB (08.05.22) Sec 21 T26S R28E Unit C 32.0337, -104.0929 Eddy County, New Mexico

Mike J. Carmona 310 West Wall Street, Suite 415 Midland TX, 79701

APPENDIX C

CARMONA RESOURCES







New Mexico Office of the State Engineer Water Column/Average Depth to Water

(A CLW##### in the POD suffix indicates the POD has been replaced & no longer serves a water right file.) (R=POD has been replaced, O=orphaned, C=the file is

closed)

(quarters are 1=NW 2=NE 3=SW 4=SE)

(quarters are smallest to largest) (NAD83 UTM in meters)

(In feet)

		``						· ·		,	`	/	
	POD Sub-		Q	Q ()						Depth	Depth	Water
POD Number	Code basin (County	64	16 4	Sec	Tws	Rng	Х	Υ	Distance	-	-	Column
C 02160 S7	CUB	ED	3	3 ′	1 22	26S	28E	586638	3543998* 🎒	1121	300	120	180
C 04466 POD1	CUB	ED	3	3 2	2 29	26S	28E	584327	3542357 🌍	2544	96	33	63
C 04022 POD1	CUB	ED	4	4 2	2 15	26S	28E	588082	3545647 🌍	2675	220	175	45
C 02160 S6	CUB	ED	3	3 ′	1 14	26S	28E	588232	3545635* 🎒	2807	300	120	180
C 04022 POD2	CUB	ED	2	2 2	2 27	26S	28E	588106	3543082 🎒	2851	250	145	105
C 02479	CUB	ED		4 4	1 10	26S	28E	587909	3546534*	3018	200		
C 02480	CUB	ED		4 4	1 10	26S	28E	587909	3546534*	3018	150		
C 02160 S5	CUB	ED	1	1 '	1 14	26S	28E	588225	3546237*	3088	300	120	180
C 02481	CUB	ED		1 '	1 14	26S	28E	588326	3546138* 🎒	3121	200		
C 02160 S3	CUB	ED	2	2 ′	1 14	26S	28E	588834	3546241* 🎒	3613	300	120	180
C 02160 S4	CUB	ED	2	2 ′	1 14	26S	28E	588834	3546241*	3613	300	120	180
C 02160 S	CUB	ED	1	1 2	2 14	26S	28E	589043	3546244* 🎒	3800	300	120	180
C 02160 S2	CUB	ED	1	1 2	2 14	26S	28E	589043	3546244*	3800	300	120	180
<u>C 02160</u>	CUB	ED	4	1 2	2 14	26S	28E	589243	3546044*	3898	300	120	180

Average Depth to Water: 119 feet

Minimum Depth:

33 feet

Maximum Depth:

175 feet

Record Count: 14

UTMNAD83 Radius Search (in meters):

Easting (X): 585650.67 **Northing (Y):** 3544530.74 **Radius:** 4000

*UTM location was derived from PLSS - see Help

The data is furnished by the NMOSE/ISC and is accepted by the recipient with the expressed understanding that the OSE/ISC make no warranties, expressed or implied, concerning the accuracy, completeness, reliability, usability, or suitability for any particular purpose of the data.



New Mexico Office of the State Engineer

Point of Diversion Summary

22 26S 28E

(quarters are 1=NW 2=NE 3=SW 4=SE)

(quarters are smallest to largest)

(NAD83 UTM in meters)

Well Tag **POD Number** Q64 Q16 Q4 Sec Tws Rng

X

C 02160 S7

HEMLER

586638 3543998*

Driller License:

Driller Company:

Driller Name:

Drill Finish Date:

01/01/1961

Plug Date:

Drill Start Date: Log File Date:

PCW Rcv Date:

Source:

Shallow

Pump Type:

Pipe Discharge Size:

Estimated Yield:

Casing Size:

Depth Well:

300 feet

Depth Water: 120 feet

The data is furnished by the NMOSE/ISC and is accepted by the recipient with the expressed understanding that the OSE/ISC make no warranties, expressed or implied, concerning the accuracy, completeness, reliability, or suitability for any particular purpose of the data.

8/12/22 8:29 AM

POINT OF DIVERSION SUMMARY

^{*}UTM location was derived from PLSS - see Help



USGS Home Contact USGS Search USGS

National Water Information System: Web Interface

USGS Water Resources

Data Category:		Geographic Area:		
Groundwater	~	New Mexico	~	GO

Click to hideNews Bulletins

- Explore the NEW <u>USGS National Water Dashboard</u> interactive map to access real-time water data from over 13,500 stations nationwide.
- Full News

Groundwater levels for New Mexico

Click to hide state-specific text

Important: <u>Next Generation Monitoring Location Page</u>

Search Results -- 1 sites found

Agency code = usgs

site_no list =

320230104060601

Minimum number of levels = 1

Save file of selected sites to local disk for future upload

USGS 320230104060601 26S.28E.18.33111

Eddy County, New Mexico

Table of data

Latitude 32°02'30", Longitude 104°06'06" NAD27

Land-surface elevation 3,070 feet above NAVD88

This well is completed in the Other aquifers (N9999OTHER) national aquifer.

This well is completed in the Castile Formation (312CSTL) local aquifer.

Output formats

ab-separat	ted data									
Graph of da	ata									
Reselect pe	<u>riod</u>									
Date	Time	? Water- level date- time accuracy	? Parameter code	Water level, feet below land surface	Water level, feet above specific vertical datum	Referenced vertical datum	? Status	? Method of measurement	? Measuring agency	? Source measu
1981-05-0	1	D	62610		3050.88	NGVD29	1	Z		
1981-05-0	1	D	62611		3052.48	NAVD88	1	Z		
1981-05-0	1	D	72019	17.52			1	Z		
1983-01-2	.5	D	62610		3052.15	NGVD29	1	Z		
1983-01-2	.5	D	62611		3053.75	NAVD88	1	Z		
1983-01-2	.5	D	72019	16.25			1	Z		
1987-10-1	.3	D	62610		3053.27	NGVD29	1	Z		
1987-10-1	.3	D	62611		3054.87	NAVD88	1	Z		
1987-10-1	.3	D	72019	15.13			1	Z		
1992-11-0	3	D	62610		3050.77	NGVD29	1	S		
1992-11-0	3	D	62611		3052.37	NAVD88	1	S		
1992-11-0	13	D	72019	17.63			1	S		
1998-01-2	.2	D	62610		3052.05	NGVD29	1	S		
1998-01-2	.2	D	62611		3053.65	NAVD88	1	S		
1998-01-2	.2	D	72019	16.35			1	S		

Explanation

Section	Code	Description
Water-level date-time accuracy	D	Date is accurate to the Day
Parameter code	62610	Groundwater level above NGVD 1929, feet
Parameter code	62611	Groundwater level above NAVD 1988, feet
Parameter code	72019	Depth to water level, feet below land surface
Referenced vertical datum	NAVD88	North American Vertical Datum of 1988
Referenced vertical datum	NGVD29	National Geodetic Vertical Datum of 1929
Status	1	Static
Method of measurement	S	Steel-tape measurement.
Method of measurement	Z	Other.
Measuring agency		Not determined
Source of measurement		Not determined
Water-level approval status	Α	Approved for publication Processing and review completed.

Questions about sites/data? Feedback on this web site Automated retrievals <u>Help</u> Data Tips **Explanation of terms** Subscribe for system changes **News**

Accessibility FOIA Privacy Policies and Notices

U.S. Department of the Interior | U.S. Geological Survey

Title: Groundwater for New Mexico: Water Levels URL: https://nwis.waterdata.usgs.gov/nm/nwis/gwlevels?

Page Contact Information: New Mexico Water Data Maintainer Page Last Modified: 2022-08-12 10:46:02 EDT

0.27 0.24 nadww01





USGS Home Contact USGS Search USGS

National Water Information System: Web Interface

USGS Water Resources



Click to hideNews Bulletins

- Explore the NEW <u>USGS National Water Dashboard</u> interactive map to access real-time water data from over 13,500 stations nationwide.
- Full News

Groundwater levels for New Mexico

Click to hide state-specific text

Important: Next Generation Monitoring Location Page

Search Results -- 1 sites found

Agency code = usgs

site_no list =

• 320145104041701

Minimum number of levels = 1

Save file of selected sites to local disk for future upload

USGS 320145104041701 26S.28E.22.234431

Eddy County, New Mexico

Latitude 32°01'45", Longitude 104°04'17" NAD27

Land-surface elevation 2,980 feet above NGVD29

The depth of the well is 23.00 feet below land surface.

This well is completed in the Other aguifers (N9999OTHER) national aguifer.

This well is completed in the Alluvium, Bolson Deposits and Other Surface Deposits (110AVMB) local aquifer.

Output formats

Table of data	
Tab-separated data	
Graph of data	
Reselect period	

Date	Time	? Water- level date- time accuracy	? Parameter code	Water level, feet below land surface	Water level, feet above specific vertical datum	Referenced vertical datum	? Status	? Method of measurement	? Measuring agency	? Source measu
1987-12-12		D	62610		2958.98	NGVD29	1	S		
1987-12-12		D	62611		2960.55	NAVD88	1	S		
1987-12-12		D	72019	21.02			1	S		
1998-01-22		D	62610		2957.65	NGVD29	1	S		
1998-01-22		D	62611		2959.22	NAVD88	1	S		
1998-01-22		D	72019	22.35			1	S		

Explanation

Section	Code	Description
Water-level date-time accuracy	D	Date is accurate to the Day
Parameter code	62610	Groundwater level above NGVD 1929, feet
Parameter code	62611	Groundwater level above NAVD 1988, feet
Parameter code	72019	Depth to water level, feet below land surface

Section	Code	Description
Referenced vertical datum	NAVD88	North American Vertical Datum of 1988
Referenced vertical datum	NGVD29	National Geodetic Vertical Datum of 1929
Status	1	Static
Method of measurement	S	Steel-tape measurement.
Measuring agency		Not determined
Source of measurement		Not determined
Water-level approval status	Α	Approved for publication Processing and review completed.

Questions about sites/data? Feedback on this web site **Automated retrievals** <u>Help</u> Data Tips **Explanation of terms** Subscribe for system changes <u>News</u>

Accessibility FOIA Privacy Policies and Notices

U.S. Department of the Interior | U.S. Geological Survey Title: Groundwater for New Mexico: Water Levels


URL: https://nwis.waterdata.usgs.gov/nm/nwis/gwlevels?

Page Contact Information: New Mexico Water Data Maintainer Page Last Modified: 2022-08-12 10:44:06 EDT

0.27 0.24 nadww02



New Mexico NFHL Data



FEMA, Sources: Esri, HERE, Garmin, Intermap, increment P Corp., GEBCO, USGS, FAO, NPS, NRCAN, GeoBase, IGN, Kadaster NL, Ordnance Survey,

0.4

8.0

1.6 km

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 157830

CONDITIONS

Operator:	OGRID:
COG OPERATING LLC	229137
600 W Illinois Ave	Action Number:
Midland, TX 79701	157830
	Action Type:
	[C-141] Release Corrective Action (C-141)

CONDITIONS

Created By		Condition Date
jnobui	Closure Report Approved.	1/12/2023