

Pima Environmental Services 5614 N. Lovington Highway Hobbs, NM 88240 575-964-7740

July 9, 2023

RE: Liner Inspection and Closure Report

Puckett 13 Fed Com 8H Battery

API No. N/A

GPS: Latitude 32.84250 Longitude -103.81630 UL -P, Section 12, Township 17S, Range 31E NMOCD Reference No. NAPP2311029282

Spur Energy Partners LLC (Spur) has contracted Pima Environmental Services, LLC (Pima) to perform a liner inspection and prepare this closure report for a produced water release that happened at the Puckett 13 Fed Com 8H Battery (Puckett). An initial C-141 was submitted on April 20, 2023, and can be found in Appendix B. This incident was assigned Incident ID NAPP2311029282, by the New Mexico Oil Conservation Division (NMOCD).

Site Information and Site Characterization

The Puckett is located approximately three (3) miles west of Maljamar, NM. This spill site is in Unit P, Section 12, Township 17S, Range 31E, Latitude 32.84250 Longitude -103.81630, Eddy County, NM. A Location Map can be found in Figure 1.

Based upon New Mexico Office of the State Engineer well water data, depth to the nearest groundwater in this area is 96 feet below grade surface (BGS). According to the United States Geological Survey well water data, depth to the nearest groundwater in this area is 139 feet BGS. See Appendix A for referenced water surveys. The Puckett is in a low karst area (Figure 3). A Topographic Map can be found in Figure 2.

Release Information

<u>MAPP2311029282</u>: On April 18, 2023, a failure of a transfer pump caused the tank to overflow releasing an oil and produced water mix into lined containment releasing of approximately 80 barrels (bbls) of produced water and 80 barrels (bbls) of crude oil into the lined secondary containment. 159 bbls of fluid were recovered from containment. The liner was visually inspected by Spur field staff for any pinholes or punctures, and none were found. Based on this inspection there is no evidence that the spilled fluids left containment.

A Site Map can be found in Figure 4.

Site Assessment and Liner Inspection

On May 15, 2023, Pima Environmental mobilized personnel and equipment to the location to begin removal of all gravel inside of the lined, secondary containment. Approximately 48 cubic yards of stained gravel was hauled to Lea Land, LLC., an NMOCD-approved, lined disposal facility.

On June 27, 2023, Pima Environmental returned to the site to conduct a power wash of the lined containment.

On July 8, 2023, after sending the 48-hour notification email, Pima Environmental conducted a liner inspection at this location. The liner inspection form and photographic documentation can be found in Appendix C.

Closure Request

After careful review, Pima requests that this incident, NAPP2311029282, be closed. Spur has complied with the applicable closure requirements.

Should you have any questions or need additional information, please feel free to contact Gio Gomez at 806-782-1151 or gio@pimaoil.com.

Respectfully,

Gio Gomez Gio Gomez

Project Manager

Pima Environmental Services, LLC

Attachments

Figures:

- 1. Location Map
- 2. Topographic Map
- 3. Karst Map
- 4. Site Map

Appendices:

Appendix A- Referenced Water Survey

Appendix B- C-141 Form & 48 Hour Notification

Appendix C- Liner Inspection Form & Photographic Documentation




Figures:


1-Location Map


2-Topographic Map

3-Karst Map

4-Site Map











Appendix A

Water Surveys:

OSE

USGS

Surface Water Map

Wetlands Map



New Mexico Office of the State Engineer

Water Column/Average Depth to Water

(A CLW##### in the POD suffix indicates the POD has been replaced & no longer serves a water right file.)

(R=POD has been replaced, O=orphaned, C=the file is

closed)

(quarters are 1=NW 2=NE 3=SW 4=SE)

(quarters are smallest to largest) (NAD83 UTM in meters) (In feet)

		POD		_	_	_									
POD Number	Code	Sub-	County		Q		Saa	Twe	Dng	X	Y	DistanceDeptl	WallDanthW		Vater
RA 13286 POD1	Coue	RA	ED				12	17S	31E	610742	3634697	253	101	aterCo	num
<u>RA 13234 POD1</u>		RA	LE	1	4	1	19	17S	32E	611435	3632294	2250	104		
RA 12042 POD1		RA	LE	2	2	1	28	17S	32E	614891	3631181	5252	400		
L 14207 POD3		L	LE	2	3	3	31	16S	37E	606117	3636977	5302	240	96	144
<u>RA 10175</u>		RA	LE		2	1	28	17S	32E	614814	3631005*	5305	158		
RA 12522 POD1		RA	LE	3	3	4	21	17S	32E	614941	3631122	5328	100		
RA 12020 POD1		RA	LE	2	2	1	28	17S	32E	614828	3630954	5348	120	81	39
RA 12522 POD2		RA	LE	2	2	1	28	17S	32E	614949	3631098	5349	100		
RA 12522 POD3		RA	LE	4	4	3	28	17S	32E	614980	3631093	5377	100		
RA 12521 POD1		RA	LE	3	3	4	21	17S	32E	615127	3631271	5386	105	92	13
RA 08855		RA	LE	4	1	1	10	17S	32E	616061	3635742*	5440	158		
RA 12020 POD3		RA	LE	2	1	2	28	17S	32E	615152	3631019	5557	112	83	29
RA 12721 POD1		RA	LE	3	2	3	28	17S	32E	614645	3630141	5787	125		
RA 09505		RA	LE	2	2	1	10	17S	32E	616462	3635944	5879	147		
L 13050 POD1		L	LE	2	2	1	10	17S	32E	616463	3635945*	5880	156	132	24
RA 09505 S		RA	LE	2	2	1	10	17S	32E	616463	3635945*	5880	144		
RA 12721 POD2		RA	LE	1	1	4	28	17S	32E	615055	3630407	5884	124	75	49
RA 11734 POD1		RA	LE	2	2	1	10	17S	32E	616556	3635929	5966	165		
<u>RA 12436 POD1</u>		RA	LE	2	2	1	10	17S	32E	616556	3635929	5966	160	125	35
											Avera	ge Depth to Water:		97 fe	et

Minimum Depth:

75 feet

Maximum Depth:

132 feet

Record Count: 19

UTMNAD83 Radius Search (in meters):

Easting (X): 610776.51 **Northing (Y):** 3634446.74 **Radius:** 6000

*UTM location was derived from PLSS - see Help

The data is furnished by the NMOSE/ISC and is accepted by the recipient with the expressed understanding that the OSE/ISC make no warranties, expressed or implied, concerning the accuracy, completeness, reliability, usability, or suitability for any particular purpose of the data.

4/20/23 9:24 AM

WATER COLUMN/ AVERAGE DEPTH TO WATER

Released to Imaging: 8/31/2023 9:53:08 AM



OSE 00 APR 5 2023 #11:14

-	POD1 (TW-1			N/A	/	PHONE (OPTIO		3286	
	Spur Energy				832-930-850				
	WELL OWNER 9655 Katy Fr	cae andred			CITY Houston		TX 77024	ZIP	
F	WELL LOCATION	LAT	DEC	GREES MINUTES SECO. 32 50 41	ONDS .14 N	* ACCURACY	REQUIRED: ONE TENT	TH OF A SECOND	
	(FROM GPS)	LO	NGITUDE 103 >	48 59	0.88 W	* DATUM REC	QUIRED: WGS 84		
-			NG WELL LOCATION TO 17S R31E, NMPM	STREET ADDRESS AND COMMON LAND	MARKS – PLS	SS (SECTION, TO	WNSHJIP, RANGE) WH	ERE AVAILABLE	
T	LICENSE NO. 1249		NAME OF LICENSED	DRILLER Jackie D. Atkins			NAME OF WELL DRI Atkins Eng	LLING COMPANY ineering Associates,	Inc.
1	DRILLING STA 03/23/20		DRILLING ENDED 03/23/2023	DEPTH OF COMPLETED WELL (FT)		LE DEPTH (FT) ±101	DEPTH WATER FIRS	T ENCOUNTERED (FT N/A	7)
T	COMPLETED V	ELL IS:	ARTESIAN	P DRY HOLE SHALLOW (UNC	ONFINED)		WATER LEVEL PLETED WELL N/	A DATE STATIC 04/03	MEASUREI 3/2023
t	DRILLING FLU	D:	AIR	MUD ADDITIVES – SPI	ECIFY				
	DRILLING METHOD: ROTARY HAMMER CABLE TOOL OTHER-SPECIFY: Hollow Stem Auger CHECK HERE IF PITLESS ADAPTER INSTALLED								
F	DEPTH (feet bgl)		BORE HOLE	CASING MATERIAL AND/OR GRADE		ASING	CASING	CASING WALL	SLOT
	FROM TO DIAM (inches)			(include each casing string, and note sections of screen)	1	NECTION FYPE ling diameter)	INSIDE DIAM. (inches)	THICKNESS (inches)	SIZE (inches
L	0	101	6.25"	Soil Borning		**			-
+									1
1									
-									-
ŀ	-		+						-
1									
T	DEPTH (fe	et bgl)	BORE HOLE	LIST ANNULAR SEAL M.	AND	AMOUNT		METHOD OF PLACEMENT	
	FROM	ТО	DIAM. (inches)	GRAVEL PACK SIZE-RANG	ERVAL	(cubic feet)	PLACE		
-									
+			-						
t									
I									
-									
1						(A1814)	. Dullandarium	1522.00	202020
	OSE INTERNA	TICE		and the second second		WR -2	0 WELL RECORD &	LOG (Version 01/	78/20221

PAGE 2 OF 2

WELL TAG ID NO.

	DEPTH (f	eet bgl)		COLOR AND TYPE OF MATERIAL ENCOUNTERED -	WATER	ESTIMATED YIELD FOR
	FROM	то	THICKNESS (feet)	INCLUDE WATER-BEARING CAVITIES OR FRACTURE ZONES (attach supplemental sheets to fully describe all units)	BEARING? (YES / NO)	WATER- BEARING ZONES (gpm
1	0	4	4	Sand, fine-grained, poorly graded, Light Bown	Y /N	
	4	40	36	Caliche and fine-grained sand, Tan/Off White	Y ✓N	
	40	90	50	Sand, medium/fi negrained, poorly graded, semi-consolidated, Reddish Bro	own Y ✓N	
	90	101	11	Clay, stiff, consolidated, with silt, Dark Brown/ Red	Y ✓N	
					Y N	
4					Y N	
WE					Y N	
5					Y N	
3					Y N	
2					Y N	
3		7			Y N	
9					Y N	
1 80					Y N	
4. HYDROGEOLOGIC LOG OF WELL					Y N	
4					Y N	
					Y N	
					Y N	4
					Y N	
					Y N	
					Y N	
					Y N	
	METHOD U	SED TO E	STIMATE YIELD		TOTAL ESTIMATED	
	PUMI		AIR LIFT	BAILER OTHER - SPECIFY:	WELL YIELD (gpm):	0.00
Z	WELL TES			ACH A COPY OF DATA COLLECTED DURING WELL TESTING, INCL ME, AND A TABLE SHOWING DISCHARGE AND DRAWDOWN OVER		
TEST; RIG SUPERVISION	MISCELLAI	NEOUS IN	be	emoved temporary well material from soil boring, backfilled with dri elow ground surface, then placed hydrated bentonite from 10 feet to g ecord.	Il cutting from total de round surface. See att	ached pluggii
<i>-</i>	PRINT NAM			RVISOR(S) THAT PROVIDED ONSITE SUPERVISION OF WELL CONS	TRUCTION OTHER TE	IAN LICENSE
6. SIGNALUKE	CORRECT I	RECORD C ERMIT HO	F THE ABOVE I	FIES THAT, TO THE BEST OF HIS OR HER KNOWLEDGE AND BELIE DESCRIBED HOLE AND THAT HE OR SHE WILL FILE THIS WELL RE 30 DAYS AFTER COMPLETION OF WELL DRILLING:	EF, THE FOREGOING ECORD WITH THE ST	IS A TRUE AN
SIG.	Jack At	kins		Jackie D. Atkins	04/04/2023	
0		CICNIAT	TIRE OF DRILL	ER / PRINT SIGNEE NAME	DATE	

LOCATION MON



USGS Home Contact USGS Search USGS

National Water Information System: Web Interface

USGS Water Resources

Data Category:		Geographic Area:		
Groundwater	~	United States	~	GO

Click to hideNews Bulletins

- Explore the NEW <u>USGS National Water Dashboard</u> interactive map to access realtime water <u>data</u> from over 13,500 stations nationwide.
- Full News 🔊

Groundwater levels for the Nation

Important: <u>Next Generation Monitoring Location Page</u>

Search Results -- 1 sites found

site_no list =

• 325119103450101

Minimum number of levels = 1

Save file of selected sites to local disk for future upload

USGS 325119103450101 17S.32E.03.43333


Available data for this site Groundwater: Field measurements GO

Lea County, New Mexico
Hydrologic Unit Code 13060011
Latitude 32°51'23", Longitude 103°45'12" NAD27
Land-surface elevation 4,206.30 feet above NGVD29
This well is completed in the High Plains aquifer (N100HGHPLN) national aquifer.
This well is completed in the Ogallala Formation (1210GLL) local aquifer.

Output formats

Table of data	
<u>Tab-separated data</u>	
Graph of data	
Reselect period	

USGS 325119103450101 175.32E.03.43333



Breaks in the plot represent a gap of at least one year between field measurements. <u>Download a presentation-quality graph</u>

Questions about sites/data?
Feedback on this web site
Automated retrievals
Help
Data Tips
Explanation of terms
Subscribe for system changes
News

Accessibility

FOIA

Privacy

Policies and Notices

U.S. Department of the Interior | U.S. Geological Survey

Title: Groundwater for USA: Water Levels


URL: https://nwis.waterdata.usgs.gov/nwis/gwlevels?

Page Contact Information: <u>USGS Water Data Support Team</u>

Page Last Modified: 2023-04-20 11:23:18 EDT

0.65 0.56 nadww02







Wetlands Map



April 20, 2023

Wetlands

Estuarine and Marine Deepwater

Estuarine and Marine Wetland

Freshwater Emergent Wetland

Freshwater Forested/Shrub Wetland

Freshwater Pond

Lake

Other

Riverine

This map is for general reference only. The US Fish and Wildlife Service is not responsible for the accuracy or currentness of the base data shown on this map. All wetlands related data should be used in accordance with the layer metadata found on the Wetlands Mapper web site.



Appendix B

C-141 Form

48-Hour Notification

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	nAPP2311029282
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party	Spur Energy Partners LLC	OGRID	328947		
Contact Name	Katherine Purvis	Contact Telephone	(575) 441-8619		
Contact email	katherine.purvis@spurenergy.com	Incident # (assigned by OCD)	nAPP2311029282		
Contact mailing address	9655 Katy Freeway; Houston, TX 77024				

Location of Release Source									
Latitude	32.8425	50			Longitude10	03.81	630		
			(NAD 83 in dec	imal de	grees to 5 decimal places	s)			
Site Name		PUCKETT 13 FI	ED COM 8H BATT	ERY	Site Type	BATT	ERY		
Date Release	Discovered	04/18/2023			API# (if applicable)	N/A			
							=		
Unit Letter	Section	Township	Range		County				
Р	12	17S	31E	EDDY					
Surface Owne	er: State	■ Federal □ Tr	ribal Private (A	lame:)	

Crude Oil	rial(s) Released (Select all that apply and attach calculations or special Volume Released (bbls) 80 BBLS	Volume Recovered (bbls) 79 BBLS
Produced Water	Volume Released (bbls) 80 BBLS	Volume Recovered (bbls) 80 BBLS
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	☐ Yes ■ No
Condensate	Volume Released (bbls)	Volume Recovered (bbls)
Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)
Cause of Release		
	RANSFER PUMP CAUSED THE TANK T FER MIX INTO LINED CONTAINMENT	O OVERFLOW RELEASING AN OIL &

Received by OCD: 7/11/2023 11250255 AM State of New Mexico
Page 2 Oil Conservation Division

Page 18 of 27

Incident ID	nAPP2311029282
District RP	
Facility ID	
Application ID	

Was this a major	If YES, for what reason(s) does the respon	
release as defined by 19.15.29.7(A) NMAC?	THE RELEASE IS GREATER T	HAN 25 BBLS.
` ,		
Yes No		
· ·	•	nom? When and by what means (phone, email, etc)?
	IRVIS OF SPUR ENERGY TO N TAL ON 04/20/2023	MOCD VIA NOR SUBMISSION TO THE
PERIVITI TING FOR	TAL ON 04/20/2023	
	Initial R	esponse
The responsible p	party must undertake the following actions immediate	y unless they could create a safety hazard that would result in injury
	1 1 1	
The source of the rele	**	41-2
	s been secured to protect human health and	
		likes, absorbent pads, or other containment devices.
-	ecoverable materials have been removed an	
	d above have <u>not</u> been undertaken, explain	why:
N/A		
		emediation immediately after discovery of a release. If remediation efforts have been successfully completed or if the release occurred
		please attach all information needed for closure evaluation.
I hereby certify that the infor	rmation given above is true and complete to the	best of my knowledge and understand that pursuant to OCD rules and
regulations all operators are	required to report and/or file certain release noti	fications and perform corrective actions for releases which may endanger
		OCD does not relieve the operator of liability should their operations have at to groundwater, surface water, human health or the environment. In
addition, OCD acceptance of		responsibility for compliance with any other federal, state, or local laws
and/or regulations.	rina Purvis	EHS Coordinator
Printed Name: Kathe	Tille I divis	Title: EHS Coordinator
Signature: <u>Katherin</u>		Date: 04/20/2023 Telephone: (575) 441-8619
email. katherine.pur	rvis@spurenergy.com	Telephone: (575) 441-8619
OCD Only		
Received by:	lyn Harimon	Date: 04/20/2023

	Page 19 of 2	7
Incident ID	nAPP2311029282	
District RP		
Facility ID		
Application ID		

Site Assessment/Characterization

This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

What is the shallowest depth to groundwater beneath the area affected by the release?	<u>>100'</u> (ft bgs)			
Did this release impact groundwater or surface water?	Yes X No			
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?	Yes X No			
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?	Yes No			
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?	Yes No			
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	Yes No			
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	Yes No			
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?	☐ Yes k☐ No			
Are the lateral extents of the release within 300 feet of a wetland?	Yes X No			
Are the lateral extents of the release overlying a subsurface mine?	Yes X No			
Are the lateral extents of the release overlying an unstable area such as karst geology?	Yes No			
Are the lateral extents of the release within a 100-year floodplain?	Yes No			
Did the release impact areas not on an exploration, development, production, or storage site?	Yes No			
Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.				
Characterization Report Checklist: Each of the following items must be included in the report.				
 Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring well Field data Data table of soil contaminant concentration data 	ls.			
Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release				
Boring or excavation logs				
Photographs including date and GIS information				
Topographic/Aerial maps Laboratory data including chain of custody				

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

Received by OCD: 7/11/2023 11:50:55 AM Form C-141 State of New Mexico Page 4 Oil Conservation Division

	Page 20 of	27
Incident ID	nAPP2311029282	
District RP		
Facility ID		
Application ID		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.				
Printed Name: Katherine Purvis Title:	EHS Coordinator			
Signature: Katherine Purvis	Date: 7/11/23			
email: <u>katherine.purvis@spurenergy.com</u> Telephone	575-441-8619			
OCD Only				
Received by: Shelly Wells	Date: 7/11/2023			

Page 21 of 27

Incident ID	nAPP2311029282
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following	ing items must be included in the closure report.
X A scaled site and sampling diagram as described in 19.15.	.29.11 NMAC
x Photographs of the remediated site prior to backfill or phomust be notified 2 days prior to liner inspection)	otos of the liner integrity if applicable (Note: appropriate OCD District office
X Laboratory analyses of final sampling (Note: appropriate of	ODC District office must be notified 2 days prior to final sampling)
Description of remediation activities	
and regulations all operators are required to report and/or file comay endanger public health or the environment. The acceptance should their operations have failed to adequately investigate and human health or the environment. In addition, OCD acceptance compliance with any other federal, state, or local laws and/or refrestore, reclaim, and re-vegetate the impacted surface area to the accordance with 19.15.29.13 NMAC including notification to the	EHS Coordinator
OCD Only	
Received by: Shelly Wells	Date: 7/11/2023
	party of liability should their operations have failed to adequately investigate and face water, human health, or the environment nor does not relieve the responsible and/or regulations.
Closure Approved by: Shelly Wells	Date: 8/31/2023
Printed Name: Shelly Wells	Title: Environmental Specialist-Advanced



Appendix C

Liner Inspection Form

Photographic Documentation



Liner Inspection Form


Company Name:	Spur En	ergy_			
Site:	Puckett	13 Fee	l Com 8H Bat	tery	
Lat/Long:	32.8	4250, -	103.81630		-
NMOCD Incident ID & Incident Date:	<u>NA</u>	.PP231	1029282	4/18/2023	
2-Day Notification Sent:	via E	mail by	y Gio Gomez	7/5/2023	
Inspection Date:	7/8/2	2023_			
Liner Type:	Earthen	w/lineı	-	Earthen no liner	Polystar
	Steel w/	poly lii	ner	Steel w/spray epoxy	No Liner
Other:					
Visualization	Yes	No		Comments	S
Is there a tear in the liner?		X			
Are there holes in the liner?	;	X			
Is the liner retaining any fluids?		X			
Does the liner have integrity to contain a leak?	X				
Comments:					
Inspector Name: <u>Do</u>	minick (<u>Gonzal</u>	<u>es</u> I	nspector Signature: <u>@</u>	miniek Gonzales



LINER INSPECTION SPUR ENERGY PARTNERS PUCKETT 13 FED COM 8H BATTERY














District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 238497

CONDITIONS

Operator:	OGRID:	
Spur Energy Partners LLC	328947	
9655 Katy Freeway	Action Number:	
Houston, TX 77024	238497	
	Action Type:	
	[C-141] Release Corrective Action (C-141)	

CONDITIONS

Created By		Condition Date
scwells	None	8/31/2023