<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	nAPP2331720576
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party							
Responsible Party Hilcorp Energy Company					OGRID 372171		
Contact Nam	Contact Name Mitch Killough				Contact Telephone 713-757-5247		
Contact emai	Contact email mkillough@hilcorp.com				Incident #	nAPP2331720576	
Contact mail 77002	ing address	1111 Travis Stre	eet, Houston, Texa	as			
			Location	ı of Re	elease So	ource	
Latitude 36.8	46612		(NAD 83 in de	L ecimal degr	Longitude - ees to 5 decim	108.087647	
Site Name L	C Kelly 17				Site Type	Well	
Date Release	Discovered:	11/8/2023 @ 09	2:15 am (MT)		API# 30-04	15-31625	
Unit Letter	Section	Township	Range		Coun	tv	
C	3	30N	12W	San Ju	County San Juan		
						justification for the volumes provided below)	
Crude Oil		Volume Release				Volume Recovered (bbls)	
Produced	Water		ed (bbls) 19.5 bbls			Volume Recovered (bbls) 19 bbls	
	Is the concentration of dissolved chlorid produced water >10,000 mg/l?			chloride i	in the	⊠ Yes □ No	
Condensa	Condensate Volume Released (bbls)					Volume Recovered (bbls)	
☐ Natural G	☐ Natural Gas Volume Released (Mcf)					Volume Recovered (Mcf)	
Other (de	scribe)	(be) Volume/Weight Released (provide units)				Volume/Weight Recovered (provide units)	
Cause of Rele	ease:						
On 11/8/2023 at approx. 9:15 am (MT), a Hilcorp operator discovered produced water fluid standing in the wooden cribbing surrounding the 120-bbl BGT. Upon discovery, the well was shut-in pending repairs. The operator called in a water truck to remove all standing fluid from within the cribbing. Spill volume was determined to be 19.5 bbls produced water. After further investigation, it was determined that a hole had formed at the bottom of the BGT, most likely from corrosion. The wooden cribbing prevented spilled fluids from migrating horizontally off the pad surface.							
The spill amo	ount was det	ermined by opera	tor's production d	data.			

Page .	7	0 f
I uge	~ €	"

Incident ID	nAPP2331720576
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?	If YES, for what reason(s) does the respo	nsible party consid	er this a major release?		
☐ Yes ⊠ No					
If VES was immediate n	tice given to the OCD? By whom? To wl	nom? Whan and h	w what maans (phono amail ata)?		
II 1E5, was infinediate in	Siece given to the OCD: By whom: To wi	ioni: when and o	y what means (phone, eman, etc):		
Initial Response					
The responsible p	party must undertake the following actions immediate	ly unless they could cre	ate a safety hazard that would result in injury		
☐ The source of the rele	ease has been stopped.				
	is been secured to protect human health and	the environment.			
	ave been contained via the use of berms or o		ds, or other containment devices.		
	ecoverable materials have been removed an				
	d above have <u>not</u> been undertaken, explain		<u>`</u>		
has begun, please attach		efforts have been	iately after discovery of a release. If remediation successfully completed or if the release occurred formation needed for closure evaluation.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Printed Name: Mitch	Killough_	Title:	Environmental Specialist		
Signature:	Who John		Date:11/21/2023		
email:mkillough@	@hilcorp.com	Telephone:	713-757-5247		
OCD Only					
Received by: _Shelly We	ells	Date: <u>11/21/202</u>	3		

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 287748

CONDITIONS

Operator:	OGRID:
HILCORP ENERGY COMPANY	372171
1111 Travis Street	Action Number:
Houston, TX 77002	287748
	Action Type:
	[C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
scwells	None	11/21/2023