Mexico Page 1 of 30
Incident ID NAPP2310779984

Incident ID	NAPP2310779984
District RP	
Facility ID	
Application ID	

## **Site Assessment/Characterization**

This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

_<50 (ft bgs)
Yes X No
Yes X No
Yes No
Yes No
☐ Yes ☑ No
Yes No
☐ Yes k☐ No
Yes No
Yes No
Yes No
Yes No
Yes No
tical extents of soil
ls.

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

Received by OCD: 9/18/2023 8:36:01 AM State of New Mexico
Page 4 Oil Conservation Division

	Page 2 of 3	30
Incident ID	NAPP2310779984	
District RP		
Facility ID		
Application ID		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.								
Printed Name: Dale Woodall	Title: Environmental Professional							
Signature: Dals Woodall	Date: 9/18/2023							
email:dale.woodall@dvn.com	Telephone: 575-748-1839							
OCD Only								
Received by:	Date:							

te of New Mexico

Incident ID NAPP2310779984

Incident ID	NAPP2310779984
District RP	
Facility ID	
Application ID	

## Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following is	items must be included in the closure report.
X A scaled site and sampling diagram as described in 19.15.29.1	11 NMAC
X Photographs of the remediated site prior to backfill or photos must be notified 2 days prior to liner inspection)	of the liner integrity if applicable (Note: appropriate OCD District office
X Laboratory analyses of final sampling (Note: appropriate ODC	C District office must be notified 2 days prior to final sampling)
Description of remediation activities	
and regulations all operators are required to report and/or file certain may endanger public health or the environment. The acceptance of should their operations have failed to adequately investigate and replaced to the environment. In addition, OCD acceptance of compliance with any other federal, state, or local laws and/or regular restore, reclaim, and re-vegetate the impacted surface area to the conformation accordance with 19.15.29.13 NMAC including notification to the Control of Name:  Dale Woodall	ations. The responsible party acknowledges they must substantially onditions that existed prior to the release or their final land use in DCD when reclamation and re-vegetation are complete.  Title:Environmental Professional
Signature: Dale Woodall	Date: 9/18/2023
email:dale.woodall@dvn.com	Telephone:575-748-1839
OCD Only	
Received by:	Date:
	of liability should their operations have failed to adequately investigate and water, human health, or the environment nor does not relieve the responsible for regulations.
Closure Approved by:	Date:
Printed Name:	Title:



Pima Environmental Services 5614 N. Lovington Highway Hobbs, NM 88240 575-964-7740

May 3, 2023

Bureau of Land Management 620 East Green Street Carlsbad, NM 88220

NMOCD District 2 811 S. First St Artesia, NM, 88210

**RE:** Liner Inspection and Closure Report

**Cotton Draw Unit 25 CTB** 

API No. N/A

GPS: Latitude 32.186984 Longitude -103.732374 UL O, Section 25, Township 24S, Range 31E,

**Eddy County, NM** 

NMOCD Reference No. NAPP2310779984

Devon Energy Production Company (Devon) has contracted Pima Environmental Services, LLC (Pima) to perform a liner inspection and prepare this closure report for a produced water release that happened at the Cotton Draw Unit 25 CTB (Cotton). An initial C-141 was submitted on April 26, 2023, and can be found in Appendix B. This incident was assigned Incident ID NAPP2310779984, by the New Mexico Oil Conservation Division (NMOCD).

#### Site Information and Site Characterization

The Cotton is located approximately twenty (20) miles East of Malaga, NM. This spill site is in Unit O, Section 25, Township 24S, Range 31E, Latitude 32.186984 Longitude -103.732374, Eddy County, NM. A Location Map can be found in Figure 1.

Based upon New Mexico Office of the State Engineer well water data, depth to the nearest groundwater in this area is 135 feet below grade surface (BGS). According to the United States Geological Survey well water data, depth to the nearest groundwater in this area is 406 feet BGS. See Appendix A for referenced water surveys. The Cotton is in a low karst area (Figure 3). A Topographic Map can be found in Figure 2.

#### **Release Information**

**NAPP2310779984:** On April 15, 2023, Lease Operator found water blowing out from gun barrel. Water dump hung open causing fluid to be released onto lined containment. Approximately 5 barrels (bbls) of produced water were released from the pump. A vacuum truck was dispatched and recovered all 5 bbls of fluid from the lined SPCC containment ring. Once fluids were removed, the liner was visually inspected by Devon field staff for any pinholes or punctures, and none were found. Based on this inspection there is no evidence that the spilled fluids left containment.

A Site Map can be found in Figure 4.

#### Site Assessment and Liner Inspection

On April 29, 2023, after sending the 48-hour notification email, Pima Environmental conducted a liner inspection at this location. We concluded that this liner and containment maintained its integrity and was able to retain the fluids. The Liner Inspection Form and Photographic Documentation can be found in Appendix C.

#### **Closure Request**

After careful review, Pima requests that this incident, NAPP2310779984, be closed. Devon has complied with the applicable closure requirements.

Should you have any questions or need additional information, please feel free to contact Gio Gomez at 806-782-1151 or gio@pimaoil.com.

Respectfully,

Gic Gomez Gio Gomez

Project Manager

Pima Environmental Services, LLC

#### **Attachments**

#### Figures:

- 1- Location Map
- 2- Topographic Map
- 3- Karst Map
- 4- Site Map

#### Appendices:

Appendix A- Referenced Water Surveys

Appendix B- C-141 Form & 48 Hour Notification

Appendix C- Liner Inspection Form & Photographic Documentation




## Figures:


1-Location Map


2-Topographic Map


3-Karst Map

4-Site Map











## Appendix A

Water Surveys:

OSE

**USGS** 

Surface Water Map

Wetlands Map



## New Mexico Office of the State Engineer

## Water Column/Average Depth to Water

(A CLW##### in the POD suffix indicates the POD has been replaced & no longer serves a water right file.)

(R=POD has been replaced, O=orphaned, C=the file is

closed)

(quarters are 1=NW 2=NE 3=SW 4=SE)

(quarters are smallest to largest) (NAD83 UTM in meters) (In feet)

	,	POD Sub-		Q	Q	Q									Water
POD Number	Code	basin	County	_	_	_	Sec	Tws	Rng	X	Y	DistanceD	epthWellD	epthWater (	
C 04636 POD1		CUB	ED	3	4	3	25	24S	31E	619200	3561279	656	-	-	
C 04643 POD1		C	ED	4	2	2	05	23S	27E	619200	3561279	656	305	135	170
C 04654 POD1		CUB	ED	3	3	4	25	24S	31E	619764	3561226	692	55		
<u>C 04665</u>		CUB	LE	1	1	2	30	24S	32E	621350	3562798	2075	120		
C 04633 POD1		CUB	ED	2	1	1	35	24S	31E	617394	3561170	2213			
<u>C 02572</u>		CUB	ED	4	2	2	02	25S	31E	618695	3559294*	2693	852		
<u>C 02574</u>		CUB	ED	1	1	2	02	25S	31E	618092	3559494*	2755			
<u>C 02571</u>		CUB	ED	4	1	2	02	25S	31E	618292	3559294*	2839	860		
C 04388 POD1		C	ED	3	2	1	23	24S	31E	617546	3564006	2895	910	868	42
<u>C 02573</u>		CUB	ED	1	4	2	02	25S	31E	618499	3559091*	2947			
<u>C 02568</u>		CUB	ED	4	3	1	01	25S	31E	619103	3558892*	2999	1025		
C 04576 POD1		CUB	ED	1	2	1	23	24S	31E	617700	3564324	3045	910	850	60
<u>C 02569</u>		CUB	ED	4	4	2	02	25S	31E	618699	3558891*	3079	1016		
C 04593 POD1		CUB	ED	3	4	4	34	24S	31E	616903	3559674	3394	55		
<u>C 02570</u>		CUB	ED	4	2	4	02	25S	31E	618704	3558489*	3467	895		
C 03830 POD1		CUB	ED	4	2	4	02	25S	31E	618632	3558432	3539	450		
C 04635 POD1		CUB	ED	4	3	4	01	25S	31E	619958	3558078	3815	55		
C 04508 POD1		CUB	ED	4	4	3	15	24S	31E	616298	3564493	4138	110		
C 04620 POD1		CUB	LE	4	3	4	06	25S	32E	621445	3558018	4312	55		
C 03530 POD1		C	LE	3	4	3	07	24S	32E	620886	3566156	4511	550		
C 04687 POD1		CUB	ED	4	2	3	12	24S	31E	619481	3566450	4584	110		
C 04632 POD1		CUB	ED	1	2	2	10	25S	31E	616802	3557964	4740	55		

Average Depth to Water:

617 feet 135 feet

Minimum Depth:

868 feet

Maximum Depth:

Record Count: 22

<u>UTMNAD83 Radius Search (in meters):</u>

Easting (X): 619495.54 **Northing (Y):** 3561865.39 Radius: 5000

\*UTM location was derived from PLSS - see Help

The data is furnished by the NMOSE/ISC and is accepted by the recipient with the expressed understanding that the OSE/ISC make no warranties, expressed or implied, concerning the accuracy, completeness, reliability, usability, or suitability for any particular purpose of the data.

4/24/23 9:49 AM

WATER COLUMN/ AVERAGE DEPTH TO WATER



USGS Home Contact USGS Search USGS

### **National Water Information System: Web Interface**

**USGS** Water Resources

Data Category:	Geographic Area:		
Groundwater ~	United States	•	GO

#### Click to hideNews Bulletins

- Explore the NEW <u>USGS National Water Dashboard</u> interactive map to access realtime water <u>data</u> from over 13,500 stations nationwide.
- Full News

Groundwater levels for the Nation

Important: <u>Next Generation Monitoring Location Page</u>

#### Search Results -- 1 sites found

site\_no list =

• 320952103444401

#### Minimum number of levels = 1

Save file of selected sites to local disk for future upload

#### USGS 320952103444401 25S.31E.02.214411

Available data for this site	Groundwater:	Field measurements	<b>∨</b>   GO	
Eddy County, New Mexico				
Hydrologic Unit Code 1307	0001			
Latitude 32°09'50.0", Lon	gitude 103°	'44'41.2" NAD83		
Land-surface elevation 3,4	68.0 feet al	oove NGVD29		
This well is completed in the	ne Other aq	uifers (N9999OTh	HER) national aquife	er.

This well is completed in the Azotea Tongue of Seven Rivers Formation (313AZOT) local aquifer.


Table of data

Tab-separated data

Graph of data

Reselect period

#### USGS 320952103444401 255,31E,02,214411



Breaks in the plot represent a gap of at least one year between field measurements. <u>Download a presentation-quality graph</u>

Questions about sites/data?
Feedback on this web site
Automated retrievals
Help
Data Tips
Explanation of terms
Subscribe for system changes
News

Accessibility

FOIA

Privacy

Policies and Notices

U.S. Department of the Interior | U.S. Geological Survey

Title: Groundwater for USA: Water Levels


URL: https://nwis.waterdata.usgs.gov/nwis/gwlevels?

Page Contact Information: <u>USGS Water Data Support Team</u>

Page Last Modified: 2023-04-24 11:47:57 EDT


0.55 0.47 nadww01







## Wetlands Map



April 24, 2023

#### Wetlands

Estuarine and Marine Deepwater

Estuarine and Marine Wetland

Freshwater Emergent Wetland

Freshwater Forested/Shrub Wetland

Freshwater Pond

Lake

Other

Riverine

This map is for general reference only. The US Fish and Wildlife Service is not responsible for the accuracy or currentness of the base data shown on this map. All wetlands related data should be used in accordance with the layer metadata found on the Wetlands Mapper web site.



## Appendix B

C-141 Form

48 Hr Notification

District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	NAPP2310779984
District RP	
Facility ID	
Application ID	

## **Release Notification**

			Resp	onsil	ole Party	y		
Responsible	Party Devoi	n Energy Produc	tion Company		OGRID 61	137		
Contact Name Dale Woodall					Contact Te	elephone 575-7	<sup>7</sup> 48-1838	
		odall@dvn.com	1		Incident #	(assigned by OCD)	NAPP2310779984	
Contact mail	ing address	205 E. Bender	Road. #150; H	lobbs,	NM 8824	.0		
			Location	of D	olooso Sa	nurgo.		
Latitude 32	.186984	4	(NAD 83 in dec		Longitude _	-103.7323	374	
Site Name Co	OTTON DI	RAW UNIT 25 (	CTB		Site Type t	ank battery		
Site Name COTTON DRAW UNIT 25 CTB  Date Release Discovered 04/15/2023					API# (if app			
Unit Letter	Section	Township Range			Coun	nty	]	
0	25	24S	31E EDI			Υ		
Surface Owner	r: State	■ Federal □ Tr	ibal ☐ Private ( <i>N</i>	Vame:			)	
	_		Nature and		uma of I	Palansa		
			Mature and	1 4 01	ume of i	Neicase		
Crude Oil		l(s) Released (Select al Volume Release		calculati	ons or specific	justification for the Volume Reco	vered (bbls)	
Produced		Volume Release				Volume Recovered (bbls) 5		
11000000	,, a.e.		ion of total dissolv	ved soli	<u> </u>			
		in the produced	water >10,000 mg/		71d3 (1123)			
Condensa	ite	Volume Release	d (bbls)			Volume Reco	vered (bbls)	
☐ Natural Gas Volume Released (Mcf)				Volume Recovered (Mcf)				
Other (de	Other (describe) Volume/Weight Released (provide unit			e units)		Volume/Weig	tht Recovered (provide units)	
Cause of Rele	Lease	•	•				on gun barrel and found water en sending everything to the	

gun barrel. The dump was closed and rebuilt to stop the leak. Fluids did not breach lined

containment.

Received by OCD: 9/18/2023 8:36:012AM1 State of New Mexico Page 2 Oil Conservation Division

- 73	777		40	A	~ .	w av
·	ağ	1000	ene.	1	<b>7</b> 11 14	C 81
	$u \sim$	EC 21		40	112	,,,,
	··· 💍		-			

Incident ID	NAPP2310779984
District RP	
Facility ID	
Application ID	

Was this a major release as defined by 19.15.29.7(A) NMAC?  ☐ Yes ■ No	s defined by 7(A) NMAC?					
If YES, was immediate no	otice given to the OCD? By whom? To wh	om? When and by what means (phone, email, etc)?				
	Initial Re	sponse				
The responsible	party must undertake the following actions immediately	unless they could create a safety hazard that would result in injury				
■ The source of the rele	ease has been stopped.					
■ The impacted area ha	s been secured to protect human health and	the environment.				
Released materials ha	ave been contained via the use of berms or d	ikes, absorbent pads, or other containment devices.				
■ All free liquids and re	ecoverable materials have been removed and	managed appropriately.				
has begun, please attach	a narrative of actions to date. If remedial	mediation immediately after discovery of a release. If remediation fforts have been successfully completed or if the release occurred ease attach all information needed for closure evaluation.				
regulations all operators are public health or the environr failed to adequately investig	required to report and/or file certain release notifient. The acceptance of a C-141 report by the O ate and remediate contamination that pose a threa	est of my knowledge and understand that pursuant to OCD rules and ications and perform corrective actions for releases which may endanger CD does not relieve the operator of liability should their operations have it to groundwater, surface water, human health or the environment. In esponsibility for compliance with any other federal, state, or local laws				
Printed Name: Dale Woodall Title: Env. Professional						
Signature: <u>Dale U</u>	Joodall	Date: 4/26/2023				
email:dale.woodall@d	lvn.com	Telephone: 575-748-1838				
OCD Only						
Received by:	elyn Harimon	Date: 04/23/2023				

#### **COTTON DRAW 25 CTB**

4/15/2023

## OCD incident nAPP2310779984

Spills In Lined C	ontainment		
Measurements Of	Standing Fluid		
Length(Ft)	22		
Width(Ft)	48		
Depth(in.)	0.5		
Total Capacity without tank displacements (bbls)	7.84		
No. of 500 bbl Tanks In Standing Fluid	2		
No. of Other Tanks In Standing Fluid			
OD Of Other Tanks In Standing Fluid(feet)			
Total Volume of standing fluid accounting for tank displacement.	5.04		

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 210993

#### **CONDITIONS**

Operator:	OGRID:		
DEVON ENERGY PRODUCTION COMPANY, LP	6137		
333 West Sheridan Ave.	Action Number:		
Oklahoma City, OK 73102	210993		
	Action Type:		
	[C-141] Release Corrective Action (C-141)		

#### CONDITIONS

Created By		Condition Date
jharimon	None	4/26/2023

te of New Mexico

Insident ID NAPP2310779984

Incident ID	NAPP2310779984
District RP	
Facility ID	
Application ID	

## **Site Assessment/Characterization**

This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

What is the shallowest depth to groundwater beneath the area affected by the release?	<u>&lt;50</u> (ft bgs)			
Did this release impact groundwater or surface water?				
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?				
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?				
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?	Yes X No			
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	☐ Yes ☑ No			
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	Yes No			
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?				
Are the lateral extents of the release within 300 feet of a wetland?				
Are the lateral extents of the release overlying a subsurface mine?				
Are the lateral extents of the release overlying an unstable area such as karst geology?				
Are the lateral extents of the release within a 100-year floodplain?	Yes No			
Did the release impact areas <b>not</b> on an exploration, development, production, or storage site?				
Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.				
Characterization Report Checklist: Each of the following items must be included in the report.				
<ul> <li>X Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells.</li> <li>X Field data</li> <li>X Data table of soil contaminant concentration data</li> <li>X Depth to water determination</li> <li>X Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release</li> <li>Boring or excavation logs</li> <li>X Photographs including date and GIS information</li> <li>X Topographic/Aerial maps</li> <li>X Laboratory data including chain of custody</li> </ul>				

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

Received by OCD: 9/18/2023 8:36:01 AM Form C-141 State of New Mexico Page 4 Oil Conservation Division Incident ID NAPP2310779984
District RP
Facility ID
Application ID

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.				
Printed Name: Dale Woodall	Title: Environmental Professional			
Signature: Dale Woodall	Date: 9/18/2023			
email:dale.woodall@dvn.com	Telephone: _ 575-748-1839			
OCD Only				
Received by:	Date:			

Page 24 of 30

Incident ID	NAPP2310779984
District RP	
Facility ID	
Application ID	

## Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following is	tems must be included in the closure report.			
X A scaled site and sampling diagram as described in 19.15.29.1	11 NMAC			
X Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)				
X Laboratory analyses of final sampling (Note: appropriate ODC	C District office must be notified 2 days prior to final sampling)			
Description of remediation activities				
and regulations all operators are required to report and/or file certain may endanger public health or the environment. The acceptance of should their operations have failed to adequately investigate and rerhuman health or the environment. In addition, OCD acceptance of	ations. The responsible party acknowledges they must substantially onditions that existed prior to the release or their final land use in DCD when reclamation and re-vegetation are complete.			
OCD Only				
Received by:	Date:			
	of liability should their operations have failed to adequately investigate and water, human health, or the environment nor does not relieve the responsible or regulations.			
Closure Approved by:	Date:			
Printed Name:	Title:			



Gio PimaOil <gio@pimaoil.com>

## Liner Inspection Cotton Draw Unit 23 CTB -NAPP2310779984

1 message

Gio PimaOil <gio@pimaoil.com>

Wed, Apr 26, 2023 at 10:09 AM

To: ocdonline@state.nm.us, Tom Pima Oil <tom@pimaoil.com>

#### Good Morning,

Pima Environmental would like to notify you that we will be conducting a liner Inspection at the Cotton Draw Unit 25 CTB for the incident NAPP2310779984. Pima personnel are scheduled to be on site for this Inspection event at approximately 7:00 a.m. On Saturday, April 29, 2023. If you have any questions or concerns, please let me know. Thank you

Gio Gomez Project Manager cell-806-782-1151 Office- 575-964-7740 Pima Environmental Services, LLC.

Relition of the second of the



## Appendix C

Liner Inspection Form

Photographic Documentation



## **Liner Inspection Form**

Company Name:	Devon I	Energy				
Site:	Cotton Draw Unit 25 CTB					
Lat/Long:	<u>32.186984 -103.732374</u>					
NMOCD Incident ID & Incident Date:	NA	PP2310	0779984	4/15/2023		
2-Day Notification Sent:	via E	mail by	y Gio Gomez	4/26/2023		
Inspection Date:	4/29	/2023_				
Liner Type:	Earthen	w/line	·	Earthen no liner		Polystar
	Steel w/	poly lii	ner	Steel w/spray epox	ку	No Liner
Other:						
Visualization	Yes	No		Commo	ents	
Is there a tear in the liner?		X				
Are there holes in the liner?	:	X				
Is the liner retaining any fluids?		X				
Does the liner have integrity to contain a leak?	X					
Comments:						
Inspector Name: <u>Au</u>	dry Ben	<u>avidez</u>	Inspe	ector Signature: _ <u>£</u>	Judry Benavia	le <u>z</u>



# SITE PHOTOGRAPHS DEVON ENERGY – LINER INSPECTION COTTON DRAW UNIT 25 CTB





District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

## **State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 266175

#### **CONDITIONS**

Operator:	OGRID:	
DEVON ENERGY PRODUCTION COMPANY, LP	6137	
333 West Sheridan Ave.	Action Number:	
Oklahoma City, OK 73102	266175	
	Action Type:	
	[C-141] Release Corrective Action (C-141)	

#### CONDITIONS

Created By	Condition	Condition Date
rhamlet	We have received your Remediation Closure Report for Incident #NAPP2310779984 COTTON DRAW UNIT 25 CTB, thank you. This Remediation Closure Report is approved. Areas reasonably needed for production or subsequent drilling operations will need to be reclaimed and revegetated as soon as they are no longer reasonably needed. A report for reclamation and revegetation including pictures of the contoured backfilled excavation surface and a thorough discussion on reseeding mixture, vegetation ratio, timelines, etc, will need to be submitted and approved prior to this incident receiving the final status of "Restoration Complete".	2/9/2024