PM State of New Mexico Incident ID NA Proceedings 1

Incident ID	NAPP2319780461
District RP	
Facility ID	
Application ID	

Site Assessment/Characterization

This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

What is the shallowest depth to groundwater beneath the area affected by the release?	_<50 (ft bgs)							
Did this release impact groundwater or surface water?								
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?								
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?								
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?								
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	Yes No							
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	Yes No							
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?								
Are the lateral extents of the release within 300 feet of a wetland?	Yes No							
Are the lateral extents of the release overlying a subsurface mine?	Yes No							
Are the lateral extents of the release overlying an unstable area such as karst geology?								
Are the lateral extents of the release within a 100-year floodplain?								
Did the release impact areas not on an exploration, development, production, or storage site?								
Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and ver- contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.	tical extents of soil							
Characterization Report Checklist: Each of the following items must be included in the report.								
Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring well Field data Data table of soil contaminant concentration data Depth to water determination Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs Photographs including date and GIS information Topographic/Aerial maps Laboratory data including chain of custody	s.							

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

Received by OCD: 10/2/2023 3:03:36 PM Form C-141 State of New Mexico Page 4 Oil Conservation Division

	Page 2 of 31
Incident ID	NAPP2319780461
District RP	
Facility ID	
Application ID	

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.									
Printed Name: Dale Woodall	Title: Environmental Professional								
Signature: Dale Woodall	Date:10/2/2023								
email:dale.woodall@dvn.com	Telephone: _ 575-748-1838								
OCD Only									
Received by:	Date:								

Page 3 of 31

Incident ID	NAPP2319780461
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items mu	ist be included in the closure report.
X A scaled site and sampling diagram as described in 19.15.29.11 NMA	C
x Photographs of the remediated site prior to backfill or photos of the l must be notified 2 days prior to liner inspection)	iner integrity if applicable (Note: appropriate OCD District office
X Laboratory analyses of final sampling (Note: appropriate ODC Distric	et office must be notified 2 days prior to final sampling)
Description of remediation activities	
I hereby certify that the information given above is true and complete to the and regulations all operators are required to report and/or file certain release may endanger public health or the environment. The acceptance of a C-141 should their operations have failed to adequately investigate and remediate human health or the environment. In addition, OCD acceptance of a C-141 compliance with any other federal, state, or local laws and/or regulations. Trestore, reclaim, and re-vegetate the impacted surface area to the conditions accordance with 19.15.29.13 NMAC including notification to the OCD who Printed Name: Dale Woodall Signature: Dale Woodall Date: email: dale.woodall@dvn.com Telephone	e notifications and perform corrective actions for releases which report by the OCD does not relieve the operator of liability contamination that pose a threat to groundwater, surface water, report does not relieve the operator of responsibility for the responsible party acknowledges they must substantially that existed prior to the release or their final land use in en reclamation and re-vegetation are complete. Environmental Professional
OCD Only	
Received by:	Date:
Closure approval by the OCD does not relieve the responsible party of liabil remediate contamination that poses a threat to groundwater, surface water, h party of compliance with any other federal, state, or local laws and/or regul	uman health, or the environment nor does not relieve the responsible
Closure Approved by:	Date:
Printed Name:	Title:



Pima Environmental Services 5614 N. Lovington Highway Hobbs, NM 88240 575-964-7740

October 2, 2023

NMOCD District 2 811 S. First St Artesia, NM, 88210

RE: Liner Inspection and Closure Report

Longview Federal 31-3H

API No. N/A

GPS: Latitude 32.342934 Longitude -104.025269 UL N, Section 31, Township 22S, Range 29E NMOCD Reference No. NAPP2319780461

Devon Energy Production Company (Devon) has contracted Pima Environmental Services, LLC (Pima) to perform a liner inspection and prepare this closure report for a crude oil and produced water release that happened at the Longview Federal 31-3H (Longview). An initial C-141 was submitted on July 26, 2023, and can be found in Appendix B. This incident was assigned Incident ID NAPP2319780461, by the New Mexico Oil Conservation Division (NMOCD).

Site Information and Site Characterization

The Longview is located approximately five (5) miles northeast of Loving, NM. This spill site is in Unit N, Section 31, Township 22S, Range 29E, Latitude 32.342934 Longitude -104.025269, Eddy County, NM. A Location Map can be found in Figure 1.

Based upon New Mexico Office of the State Engineer well water data, depth to the nearest groundwater in this area is 64 feet below grade surface (BGS). According to the United States Geological Survey well water data, depth to the nearest groundwater in this area is 50 feet BGS. See Appendix A for referenced water surveys. The Longview is in a medium karst area (Figure 3). A Topographic Map can be found in Figure 2.

Release Information

NAPP2319780461: On July 13, 2017, a leak developed on a water transfer pump, causing oil, and produced water to be released in lined containment. Approximately 2 barrels (bbls) of crude oil and 3.74 bbls of produced water were released from the pump into the lined, secondary containment. A vacuum truck was dispatched and recovered approximately 5.74 bbls of fluid from the lined SPCC containment ring. Once standing fluids were removed, the liner was visually inspected by Devon field staff for any pinholes or punctures; none were found. Based on this inspection there is no evidence that the spilled fluids left containment.

A Site Map can be found in Figure 4.

Site Assessment and Liner Inspection

On September 30, 2023, after sending the 48-hour notification email, Pima Environmental conducted a liner inspection at this location. We concluded that this liner and containment maintained its integrity and was able to retain the fluids. The liner inspection form and photographic documentation can be found in Appendix C.

Closure Request

After careful review, Pima requests that this incident, NAPP2319780461, be closed. Devon has complied with the applicable closure requirements.

Should you have any questions or need additional information, please feel free to contact Tom Bynum at 575-964-7740 or gio@pimaoil.com.

Respectfully,

Gic Gomez
Gio Gomez

Project Manager

Pima Environmental Services, LLC

Attachments

Figures:

- 1- Location Map
- 2- Topographic Map
- 3- Karst Map
- 4- Site Map

Appendices:

Appendix A- Referenced Water Surveys

Appendix B- C-141 Form & 48 Hour Notification

Appendix C- Liner Inspection Form & Photographic Documentation




Figures:


1-Location Map


2-Topographic Map


3-Karst Map

4-Site Map











Appendix A

Water Surveys:

OSE

USGS

Surface Water Map

Wetlands Map



New Mexico Office of the State Engineer

Water Column/Average Depth to Water

(A CLW##### in the POD suffix indicates the POD has been replaced & no longer serves a water right file.)

(R=POD has been replaced, O=orphaned, C=the file is

closed)

(quarters are 1=NW 2=NE 3=SW 4=SE)

(quarters are smallest to largest) (NAD83 UTM in meters)

(In feet)

	ŕ	POD Sub-		Q	Q	Q								v	/ater
POD Number (Code	basin	County	64	16	4	Sec	Tws	Rng	X	Y	DistanceD	epthWellDe	epthWater Co	lumn
C 04539 POD1		CUB	ED	2	4	2	01	23S	28E	591034	3578223	944	55		
C 04524 POD1		CUB	ED	1	1	2	01	23S	28E	590452	3578629	1296	55		
C 04609 POD1		CUB	ED	2	1	1	01	23S	28E	589816	3578589	1930	51		
<u>C 04417 POD1</u>		CUB	ED	4	3	3	36	22S	28E	589736	3578874	1991	55		
<u>C 02804</u>		CUB	ED		2	1	08	23S	29E	593262	3576905*	2489	100		
<u>C 02805</u>		CUB	ED		2	1	08	23S	29E	593262	3576905*	2489	100		
C 04418 POD1		CUB	ED	4	2	1	12	23S	28E	590104	3576851	2586	55		
C 04470 POD1		CUB	ED	3	1	3	07	23S	29E	591280	3576086	2814			
C 04584 POD1		CUB	ED	3	1	4	12	23S	28E	590392	3576064	3102	63		
<u>C 02806</u>		CUB	ED		1	1	09	23S	29E	594473	3576927*	3361	100		
<u>C 02807</u>		CUB	ED		1	1	09	23S	29E	594473	3576927*	3361	100		
<u>C 02792</u>		CUB	ED		4	3	04	23S	29E	594868	3577336*	3493	200		
<u>C 02793</u>		CUB	ED		4	3	04	23S	29E	594868	3577336*	3493	100		
C 04584 POD3		CUB	ED	3	2	2	13	23S	28E	590887	3575129	3829	31		
C 04688 POD1		CUB	ED	1	3	1	35	22S	28E	587989	3579827	3860	84	64	20
<u>C 02702</u>		C	ED			2	13	23S	28E	590715	3575108*	3891	38	20	18
C 04216 POD3		CUB	ED	1	4	1	11	23S	28E	588501	3576556	3967	23	13	10
C 04216 POD1		CUB	ED	2	4	1	11	23S	28E	588488	3576534	3990	20	10	10
<u>C 00109</u>		CUB	ED	1	3	3	04	23S	27E	588486	3576531	3994	168	120	48
C 04216 POD4		CUB	ED	2	4	1	11	23S	28E	588499	3576513	3994	20	10	10
C 04216 POD2		CUB	ED	1	4	1	11	23S	28E	588465	3576555	3997	20	10	10

Average Depth to Water: 35 feet

Minimum Depth: 10 feet

Maximum Depth: 120 feet

Record Count: 21

UTMNAD83 Radius Search (in meters):

Easting (X): 591727 **Northing (Y):** 3578865.19 **Radius:** 4000

*UTM location was derived from PLSS - see Help

The data is furnished by the NMOSE/ISC and is accepted by the recipient with the expressed understanding that the OSE/ISC make no warranties, expressed or implied, concerning the accuracy, completeness, reliability, usability, or suitability for any particular purpose of the data.

7/18/23 8:58 AM

WATER COLUMN/ AVERAGE DEPTH TO WATER



USGS Home Contact USGS Search USGS

National Water Information System: Web Interface

USGS Water Resources

Data Category:	Geographic Area:	
Groundwater ~	United States	→ GO

Click to hideNews Bulletins

- Explore the NEW <u>USGS National Water Dashboard</u> interactive map to access realtime water data from over 13,500 stations nationwide.
- Full News

Groundwater levels for the Nation

Important: <u>Next Generation Monitoring Location Page</u>

Search Results -- 1 sites found

site no list =

• 322059103585802

Minimum number of levels = 1

Save file of selected sites to local disk for future upload

USGS 322059103585802 22S.29E.33.24130A

Available data for this site Groundwater: Field measurements GO


Eddy County, New Mexico
Hydrologic Unit Code 13060011
Latitude 32°20'59", Longitude 103°58'58" NAD27
Land-surface elevation 3,022 feet above NAVD88
The depth of the well is 70 feet below land surface.
This well is completed in the Other aguifors (N9999OTHER) national


This well is completed in the Other aquifers (N9999OTHER) national aquifer.

This well is completed in the Rustler Formation (312RSLR) local aquifer.

Output formats

Table of data	
Tab-separated data	
Graph of data	
Reselect period	





Breaks in the plot represent a gap of at least one year between field measurements. <u>Download a presentation-quality graph</u>

Questions or Comments
Automated retrievals
Help
Data Tips
Explanation of terms
Subscribe for system changes
News

Accessibility

FOIA

Privacy

Policies and Notices

U.S. Department of the Interior | U.S. Geological Survey

Title: Groundwater for USA: Water Levels


URL: https://nwis.waterdata.usgs.gov/nwis/gwlevels?

Page Contact Information: <u>USGS Water Data Support Team</u>

Page Last Modified: 2023-07-18 10:55:04 EDT


0.57 0.49 nadww02







Wetlands Map



July 18, 2023

Wetlands

Estuarine and Marine Deepwater

Estuarine and Marine Wetland

Freshwater Emergent Wetland

Freshwater Forested/Shrub Wetland

Freshwater Pond

Lake

Riverine

Other

This map is for general reference only. The US Fish and Wildlife Service is not responsible for the accuracy or currentness of the base data shown on this map. All wetlands related data should be used in accordance with the layer metadata found on the Wetlands Mapper web site.



Appendix B

C-141 Form

48-Hour Notification

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	nAPP2319780461
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party De Contact Name Dale V Contact email Dale.V Contact mailing addre	Voodall			elephone					
	Voodall@dvn.cor				Contact Telephone				
Contact mailing addre		n	Incident #	t (assigned by OCD))				
•	ss 6488 Seven Ri	vers Hwy Artes	ia, NM 88210						
		Location	of Release S						
Latitude 32.3429	34		Longitude	-104.0252	269				
		(NAD 83 in dec	cimal degrees to 5 deci	mal places)					
Site Name Longview	Federal 31-3H		Site Type	Oil					
Date Release Discover	^{ed} 7/13/2023		API# (if ap	plicable)					
Unit Letter Section	n Township	Range	Cou	ntv	7				
N 31	22S	29E			-				
IN 31	223	290	Ed	uy					
Surface Owner: Sta	te 🔳 Federal 🗌 T	ribal Private (A	Name:)				
		Noture and	l Volume of	Dalaasa					
Mat Crude Oil	vial(s) Released (Select a	ll that apply and attach ed (bbls) 2 BBLS	calculations or specifi	Volume Reco	e volumes provided below) overed (bbls) 2 BBLS				
Produced Water		ed (bbls) 3.74 BB	1 9	Volume Recovered (bbls) 3.74 BBLS					
		tion of total dissolv							
	in the produced	water >10,000 mg		\					
Condensate	Volume Release			Volume Recovered (bbls)					
☐ Natural Gas	Volume Release	ed (Mcf)		Volume Recovered (Mcf)					
Other (describe) Volume/Weight Released (provide units			e units)	Volume/Wei	ght Recovered (provide units)				

Received by OCD: 10/2/2023 3:03:36 PM State of New Mexico
Page 2 Oil Conservation Division

- 75	30		-4	•	A	~	-MI	
- 17	ağ	120	ct.		1	gra.	æ.	- 81
	uv	cz.	25	7.	A)	D.	D.	Ð
			7	-	-,,		7	_

Incident ID	nAPP2319780461
District RP	
Facility ID	
Application ID	

Was this a major release as defined by	If YES, for what reason(s) does the respon	nsible party consider this a major release?
19.15.29.7(A) NMAC?		
☐ Yes ■ No		
If YES, was immediate no	otice given to the OCD? By whom? To wh	om? When and by what means (phone, email, etc)?
	Initial Ro	esponse
The responsible p	party must undertake the following actions immediatel	y unless they could create a safety hazard that would result in injury
■ The source of the rele	ease has been stonned	
	is been secured to protect human health and	the environment.
_ *	1	ikes, absorbent pads, or other containment devices.
■ All free liquids and re	ecoverable materials have been removed and	d managed appropriately.
If all the actions described	d above have <u>not</u> been undertaken, explain	why:
		emediation immediately after discovery of a release. If remediation
		efforts have been successfully completed or if the release occurred lease attach all information needed for closure evaluation.
		pest of my knowledge and understand that pursuant to OCD rules and
		fications and perform corrective actions for releases which may endanger ICD does not relieve the operator of liability should their operations have
failed to adequately investig	ate and remediate contamination that pose a thre	at to groundwater, surface water, human health or the environment. In responsibility for compliance with any other federal, state, or local laws
and/or regulations.		responsionity for compliance with any other rederat, state, or local laws
Printed Name: Kendr	a Ruiz	Title: EHS Associate
Printed Name: Kendra Signature: Kendra	a Ruiz ı Ruiz	Date: 7/26/2023
_{email:} Kendra.Rui		Telephone: 575-748-0167
eman.		rerephone.
0.07.0.1		
OCD Only		
Received by: Shelly Well	ls	Date: <u>7/27/2023</u>

Spill Volume(Bbls) Calculator				
Int	Inputs in blue, Outputs in red			
Con	taminated S	oil measurement		
Area (squa	re feet)	Depth(inches)		
Cubic Feet of S	oil Impacted	0.000		
Barrels of Soi	I Impacted	0.00		
Soil T		Clay/Sand		
Barrels of Oil 100% Sat		0.00		
Saturation	Fluid pres	sent with shovel/backhoe		
Estimated Ba Relea	rrels of Oil	0.00		
	Free Standin	ng Fluid Only		
Area (squ	are feet)	Depth(inches)		
<u>1546.232</u>		0.250		
Standin	g fluid	5.742		
Total fluids spilled		5.742		

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 244529

CONDITIONS

Operator:	OGRID:
DEVON ENERGY PRODUCTION COMPANY, LP	6137
	Action Number:
Oklahoma City, OK 73102	244529
	Action Type:
	[C-141] Release Corrective Action (C-141)

CONDITIONS

Created By		Condition Date
scwells	None	7/27/2023

State of New Mexico

Insident ID

Incident ID	NAPP2319780461
District RP	
Facility ID	
Application ID	

Site Assessment/Characterization

This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

What is the shallowest depth to groundwater beneath the area affected by the release?	<50(ft bgs)			
Did this release impact groundwater or surface water?				
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?				
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?				
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?				
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?				
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	Yes No			
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?				
Are the lateral extents of the release within 300 feet of a wetland?				
Are the lateral extents of the release overlying a subsurface mine?				
Are the lateral extents of the release overlying an unstable area such as karst geology?				
Are the lateral extents of the release within a 100-year floodplain?	Yes No			
Did the release impact areas not on an exploration, development, production, or storage site?	Yes No			
Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.				
Characterization Report Checklist: Each of the following items must be included in the report.				
 X Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells. X Field data X Data table of soil contaminant concentration data X Depth to water determination X Determination of water sources and significant watercourses within ½-mile of the lateral extents of the release Boring or excavation logs X Photographs including date and GIS information X Topographic/Aerial maps X Laboratory data including chain of custody 				

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

Received by OCD: 10/2/2023 3:03:36 PM Form C-141 State of New Mexico Page 4 Oil Conservation Division

Incident ID NAPP2319780461
District RP
Facility ID
Application ID

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.				
Printed Name: Dale Woodall	Title: Environmental Professional			
Signature: Dale Woodall	Date:10/2/2023			
email:dale.woodall@dvn.com	Telephone:575-748-1838			
OCD Only				
Received by:	Date:			

Page 24 of 31

Incident ID	NAPP2319780461
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the follow	wing items must be included in the closure report.	
X A scaled site and sampling diagram as described in 19.15.29.11 NMAC		
X Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)		
X Laboratory analyses of final sampling (Note: appropriat	te ODC District office must be notified 2 days prior to final sampling)	
Description of remediation activities		
and regulations all operators are required to report and/or file may endanger public health or the environment. The acceptar should their operations have failed to adequately investigate a human health or the environment. In addition, OCD acceptar compliance with any other federal, state, or local laws and/or restore, reclaim, and re-vegetate the impacted surface area to accordance with 19.15.29.13 NMAC including notification to	Title: Environmental Professional	
OCD Only		
Received by:	Date:	
	e party of liability should their operations have failed to adequately investigate and urface water, human health, or the environment nor does not relieve the responsible and/or regulations.	
Closure Approved by:	Date:	
Printed Name:	Title:	



Gio PimaOil <gio@pimaoil.com>

Liner Inspection for Longview 31-3H -NAPP2319780461

2 messages

Gio PimaOil <gio@pimaoil.com>

Wed, Sep 27, 2023 at 12:41 PM

To: OCD.Enviro@emnrd.nm.gov, Tom Pima Oil <tom@pimaoil.com>

Good Afternoon,

Pima Environmental would like to notify you that we will be conducting a liner Inspection at the Longview Federal 31-3H for the incident NAPP2319780461. Pima personnel are scheduled to be on site for this Inspection event at approximately 8:00 a.m. On Saturday, September 30, 2023. If you have any questions or concerns, please let me know. Thank you

Project Manager cell-806-782-1151

Office- 575-964-7740

Pima Environmental Services, LLC.

Rodgers, Scott, EMNRD <Scott.Rodgers@emnrd.nm.gov>

Wed, Sep 27, 2023 at 2:14 PM

To: Gio PimaOil <gio@pimaoil.com>, Tom Pima Oil <tom@pimaoil.com>, "Hamlet, Robert, EMNRD" <Robert.Hamlet@emnrd.nm.gov>, "Bratcher, Michael, EMNRD" <mike.bratcher@emnrd.nm.gov>

The OCD has received your notification. Include a copy of this and all notifications in the remedial and/or closure reports to ensure the notifications are documented in the project file.

Scott Rodgers • Environmental Specialist

Environmental Bureau

EMNRD - Oil Conservation Division

8801 Horizon Blvd. NE, Suite 260 | Albuquerque, NM 87113

505.469.1830 | scott.rodgers@emnrd.nm.gov

http://www.emnrd.nm.gov/ocd



From: Gio PimaOil <gio@pimaoil.com>

Sent: Wednesday, September 27, 2023 12:42 PM

To: Enviro, OCD, EMNRD < OCD. Enviro@emnrd.nm.gov>; Tom Pima Oil < tom@pimaoil.com> **Subject:** [EXTERNAL] Liner Inspection for Longview 31-3H -NAPP2319780461

CAUTION: This email originated outside of our organization. Exercise caution prior to clicking on links or opening attachments.

[Quoted text hidden]



Appendix C

Liner Inspection Form

Photographic Documentation



Liner Inspection Form


Company Name:	Devon I	Energy		
Site:	Longview Federal 31-3H			
Lat/Long:	32.342934, -104.025269			
NMOCD Incident ID & Incident Date:	NA	.PP231	9780461 7/13/2023	
2-Day Notification Sent:	via E	mail b	y Gio Gomez 9/27/2023	
Inspection Date:	9/30	/2023_		
Liner Type:	Earthen	w/line	Earthen no liner	Polystar
	Steel w/	poly li	ner Steel w/spray epoxy	No Liner
Other:				
Visualization	Yes	No	Comments	
Is there a tear in the liner?		X		
Are there holes in the liner?	;	X		
Is the liner retaining any fluids?		X		
Does the liner have integrity to contain a leak?	X			
Comments:				
Inspector Name: <u>An</u>	drew Fr	anco_	Inspector Signature:	lrew Franco



SITE PHOTOGRAPHS DEVON ENERGY – LINER INSPECTION LONGVIEW FEDERAL 31 #003H







District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 271494

CONDITIONS

Operator:	OGRID:
DEVON ENERGY PRODUCTION COMPANY, LP	6137
333 West Sheridan Ave.	Action Number:
Oklahoma City, OK 73102	271494
	Action Type:
	[C-141] Release Corrective Action (C-141)

CONDITIONS

Created By	Condition	Condition Date
rhamlet	We have received your Remediation Closure Report for Incident #NAPP2319780461 LONGVIEW FEDERAL 31 #003H, thank you. This Remediation Closure Report is approved. Areas reasonably needed for production or subsequent drilling operations will need to be reclaimed and revegetated as soon as they are no longer reasonably needed. A report for reclamation and revegetation including pictures of the contoured backfilled excavation surface and a thorough discussion on reseeding mixture, vegetation ratio, timelines, etc, will need to be submitted and approved prior to this incident receiving the final status of "Restoration Complete".	2/16/2024