

13212 N MacArthur Blvd Oklahoma City, Oklahoma 73142 Tel. 832.374.0004 ntgenvironmental.com

July 23, 2025

Mike Bratcher District Supervisor Oil Conservation District 811 S. First Street Artesia, New Mexico 88210

Re: Incident Closure Report

Devon Energy Production Company, LP

Marwari 28 CTB 2

Unit D, Section 28, Township 25S, Range 32E

Site Coordinates: 32.10798, -103.68688

Lea County, New Mexico

Incident ID: nAPP2417749853

Introduction

NTG Environmental, LLC (NTGE), on behalf of Devon Energy Production Company, LP (Devon), submits this Incident Closure Report to the New Mexico Oil Conservation Division (NMOCD). This report provides documentation of liner inspection activities conducted to date in the affected areas at the Marwari 28 CTB 2 (Site). The Site is in Unit Letter D, Section 28, of Township 25 South and Range 32 East in Lea County, New Mexico. The GPS coordinates for the release site are 32.10798° N Latitude and -103.68688° W Longitude. The Site location with respect to the nearest town is shown on Figure 1 and the topography of the area is shown on Figure 2.

Background

Based on the initial C-141 submitted by Devon and obtained by the New Mexico Oil Conservation District (NMOCD), the release was discovered on June 25, 2024. The release was the result of an equipment failure (pump), resulting in the release of thirty-one (31) barrels (bbls) of produced water into lined containment, of which all thirty-one (31) bbls were recovered. Upon discovery the well was shut-in, and the area was secure. The liner area is shown on Figure 3.

Groundwater and Site Characterization

Based on a review of the New Mexico Office of State Engineers and USGS databases, there is one known water source within a ½-mile radius of the Site. C-04879-POD1 was drilled in 2024 to a depth of fifty-five (55) feet (ft) below ground surface (bgs) and no groundwater was encountered. No other receptors (playas, wetlands, waterways, lakebeds, or ordinance boundaries) are located

Creating a Better Environment For Oil & Gas Operations

within each specific boundary or distance from the Site. According to the Karst Potential Map, the Site is located within a Low Karst area. The Site characterization documentation (Points of Diversion, Karst Potential, Significant Watercourse Map, Wetlands Map, and FEMA Map) is attached to the report.

NTGE characterized the Site according to Table I, Closure Criteria for Soils Impacted by a Release, from the New Mexico Administrative Code (NMCA) Title 19, Chapter 15, Part 29, Section 12 (NMAC 19.15.29.12).

General Site Characterization and Groundwater:

Table 3.1 Closure Criteria for Soils Impacted by a Release (NMAC 19.15.29.12 & 19.15.29.13)

| Regulatory Standard | Chloride | ТРН | TPH | BTEX | Benzene |
|-----------------------------|--------------|--------------|-------------|----------|----------|
| | | (GRO+DRO+MRO | (GRO+MRO) | | |
| | | | | | |
| 10 15 20 12 Pastanation | | | | | |
| 19.15.29.13 Restoration, | 600 mg/kg | 100 mg/kg | | 50 mg/kg | 10 mg/kg |
| Reclamation, and Re- | 000 mg/kg | 100 mg/kg | | Jo mg/kg | 10 mg/kg |
| vegetation (<4 feet) | | | | | |
| 19.15.23.12 Remediation | | | | | |
| and Closure Criteria for | 10,000 mg/kg | 2,500 mg/kg | 1,000 mg/kg | 50 mg/kg | 10 mg/kg |
| Soils Impacted by a Release | 7,111 8 8 | ,,,,,, | | 8 8 | |
| (>4 Feet) | | | | | |
| Notes: | | | | | |
| = not defined | | | | | |

Liner Inspection Activities

On May 23, 2025, NTGE conducted a liner inspection to assess the integrity and state of the tank battery's secondary containment liner. Upon inspection it was noted that the liner was intact with no visible holes or breaches, and free of any standing fluids. A photographic log documenting the condition of the liner at the time of the inspection is attached.

Closure Request

Based on the liner inspection, the Site is compliant with NMOCD's regulatory requirements, and no further actions are required at the Site. Devon formally requests closure for the Site (nAPP2417749853). If you have any questions regarding this report or need additional information, please contact us on (832) 374-0004.

Sincerely,

NTG Environmental

Kellan Smith Project Manager

NTGE Project No: 2510096



Attachments:


Figures Site Characterization Photographic Log




Figures


ANTG

NTGE Project No: 2510096





SHEET NUMBER: 1 of 1



PROJECT #: 2510096

Site Characterization

NTGE Project No: 2510096



Karst Potential Map



6/11/2025, 2:38:13 PM


Override 1

Karst Occurrence Potential



PLSS Second Division

PLSS First Division




BLM, OCD, New Mexico Tech, OCD, Maxar, BLM

OSE POD Location Map







Point of Diversion Summary

quarters are 1=NW 2=NE 3=SW 4=SE quarters are smallest to largest

NAD83 UTM in meters

| Well Tag | POD Nbr | Q64 | Q16 | Q4 | Sec | Tws | Rng | X | Υ | Мар |
|----------|--------------|-----|-----|----|-----|-----|-----|----------|-----------|-----|
| NA | C 04879 POD1 | SW | NW | NW | 28 | 25S | 32E | 623889.6 | 3552875.3 | |

* UTM location was derived from PLSS - see Help

| Driller License: | 1862 | Driller Company: | H&R ENTERPRISES, LLC | | |
|-------------------|-------------|----------------------|----------------------|------------------|------------|
| Driller Name: | HAWLEY, JAN | MES CODYELALL OFF | | | |
| Drill Start Date: | 2024-10-07 | Drill Finish Date: | 2024-10-07 | Plug Date: | 2024-10-11 |
| Log File Date: | 2024-10-15 | PCW Rcv Date: | | Source: | |
| Pump Type: | | Pipe Discharge Size: | | Estimated Yield: | |
| Casing Size: | | Depth Well: | 55 | Depth Water: | |

The data is furnished by the NMOSE/ISC and is accepted by the recipient with the expressed understanding that the OSE/ISC make no warranties, expressed or implied, concerning the accuracy, completeness, reliability, usability, or suitability for any particular purpose of the data.


6/11/25 1:12 PM MST Point of Diversion Summary

©2024 New Mexico Office of the State Engineer, All Rights Reserved. | Disclaimer | Contact Us | Help | Home |

National Flood Hazard Layer FIRMette








This map complies with FEMA's standards for the use of digital flood maps if it is not void as described below. The basemap shown complies with FEMA's basemap accuracy standards

The flood hazard information is derived directly from the authoritative NFHL web services provided by FEMA. This map was exported on 6/11/2025 at 6:58 PM and does not reflect changes or amendments subsequent to this date and time. The NFHL and effective information may change or become superseded by new data over time.

This map image is void if the one or more of the following map elements do not appear: basemap imagery, flood zone labels, legend, scale bar, map creation date, community identifiers, FIRM panel number, and FIRM effective date. Map images for unmapped and unmodernized areas cannot be used for regulatory purposes.



2,000





Wetlands Map



June 11, 2025

Wetlands

Estuarine and Marine Deepwater

Estuarine and Marine Wetland

Freshwater Emergent Wetland

Freshwater Pond

Freshwater Forested/Shrub Wetland

L

Lake

Other

Riverine

This map is for general reference only. The US Fish and Wildlife Service is not responsible for the accuracy or currentness of the base data shown on this map. All wetlands related data should be used in accordance with the layer metadata found on the Wetlands Mapper web site.

Photographic Log

NTGE Project No: 2510096



Devon Energy Production Company Marwari 28 CTB 2

Photograph No. 1

Facility: Marwari 28 CTB 2

County: Lea County, New Mexico

Description: View of Liner



Photograph No. 2

Facility: Marwari 28 CTB 2

County: Lea County, New Mexico

Description: View of Liner



Photograph No. 3

Facility: Marwari 28 CTB 2

County: Lea County, New Mexico



Devon Energy Production Company Marwari 28 CTB 2

Photograph No. 4

Facility: Marwari 28 CTB 2

County: Lea County, New Mexico

Description: View of Liner




Photograph No. 5

Facility: Marwari 28 CTB 2

County: Lea County, New Mexico

Description: View of Liner



Photograph No. 6

Facility: Marwari 28 CTB 2

County: Lea County, New Mexico



Devon Energy Production Company Marwari 23 CTB 2


Photograph No. 7

Facility: Marwari 28 CTB 2

County: Lea County, New Mexico

Description: View

of Liner



Photograph No. 8

Facility: Marwari 28 CTB 2

County: Lea County, New Mexico

Description: View

of Liner



Photograph No. 9

Facility: Marwari 28 CTB 2

County: Lea County, New Mexico



Devon Energy Production Company Marwari 28 CTB 2

Photograph No. 10

Facility: Marwari 28 CTB 2

County: Lea County, New Mexico

Description: View of Liner




Photograph No. 11

Facility: Marwari 28 CTB 2

County: Lea County, New Mexico

Description: View of Liner Wall



Photograph No. 12

Facility: Marwari 28 CTB 2

County: Lea County, New Mexico



Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116
Online Phone Directory
https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS

Action 488469

QUESTIONS

| Operator: | OGRID: |
|-------------------------------------|-------------------------------------------------------------|
| DEVON ENERGY PRODUCTION COMPANY, LP | 6137 |
| 333 West Sheridan Ave. | Action Number: |
| Oklahoma City, OK 73102 | 488469 |
| | Action Type: |
| | [C-141] Remediation Closure Request C-141 (C-141-v-Closure) |

QUESTIONS

| Prerequisites | |
|-------------------|-------------------------------------|
| Incident ID (n#) | nAPP2417749853 |
| Incident Name | NAPP2417749853 MARWARI 28 CTB 2 @ 0 |
| Incident Type | Produced Water Release |
| Incident Status | Remediation Closure Report Received |
| Incident Facility | [fAPP2123136202] MARWARI 28 CTB 2 |

| Location of Release Source | | |
|------------------------------------------------|------------|--|
| Please answer all the questions in this group. | | |
| Site Name MARWARI 28 CTB 2 | | |
| Date Release Discovered | 06/25/2024 | |
| Surface Owner | Federal | |

| ncident Details | | |
|------------------------------------------------------------------------------------------------------|------------------------|--|
| Please answer all the questions in this group. | | |
| Incident Type | Produced Water Release | |
| Did this release result in a fire or is the result of a fire | No | |
| Did this release result in any injuries | No | |
| Has this release reached or does it have a reasonable probability of reaching a watercourse | No | |
| Has this release endangered or does it have a reasonable probability of endangering public health | No | |
| Has this release substantially damaged or will it substantially damage property or the environment | No | |
| Is this release of a volume that is or may with reasonable probability be detrimental to fresh water | No | |

| Nature and Volume of Release Material(s) released, please answer all that apply below. Any calculations or specific justifications | for the valumes provided should be attached to the follow up C 141 submission |
|------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Crude Oil Released (bbls) Details | Not answered. |
| Produced Water Released (bbls) Details | Cause: Equipment Failure Pump Produced Water Released: 31 BBL Recovered: 31 BB Lost: 0 BBL. |
| Is the concentration of chloride in the produced water >10,000 mg/l | No |
| Condensate Released (bbls) Details | Not answered. |
| Natural Gas Vented (Mcf) Details | Not answered. |
| Natural Gas Flared (Mcf) Details | Not answered. |
| Other Released Details | Not answered. |
| Are there additional details for the questions above (i.e. any answer containing Other, Specify, Unknown, and/or Fire, or any negative lost amounts) | LO arrived at location and discovered a pinhole on the basket strainer on a water transfer pump. 31 bbls produced water released into lined containment. 31 bbls recovered. |

Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS, Page 2

Action 488469

| QUESTI | ONS (continued) | |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|
| Operator: DEVON ENERGY PRODUCTION COMPANY, LP 333 West Sheridan Ave. Oklahoma City, OK 73102 | OGRID: 6137 Action Number: 488469 Action Type: [C-141] Remediation Closure Request C-141 (C-141-v-Closure) | |
| QUESTIONS | | |
| Nature and Volume of Release (continued) | | |
| Is this a gas only submission (i.e. only significant Mcf values reported) | No, according to supplied volumes this does not appear to be a "gas only" report. | |
| Was this a major release as defined by Subsection A of 19.15.29.7 NMAC | Yes | |
| Reasons why this would be considered a submission for a notification of a major release | From paragraph A. "Major release" determine using: (1) an unauthorized release of a volume, excluding gases, of 25 barrels or more. | |
| With the implementation of the 19.15.27 NMAC (05/25/2021), venting and/or flaring of natural gas (i.e. | e. gas only) are to be submitted on the C-129 form. | |
| Initial Response The responsible party must undertake the following actions immediately unless they could create a s | safety hazard that would result in injury | |
| The source of the release has been stopped | True | |
| The impacted area has been secured to protect human health and the environment | True | |
| Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices | True | |
| All free liquids and recoverable materials have been removed and managed appropriately | True | |
| If all the actions described above have not been undertaken, explain why | Not answered. | |
| | ation immediately after discovery of a release. If remediation has begun, please prepare and attach a narrative ted or if the release occurred within a lined containment area (see Subparagraph (a) of Paragraph (5) of valuation in the follow-up C-141 submission. | |
| to report and/or file certain release notifications and perform corrective actions for releathe OCD does not relieve the operator of liability should their operations have failed to a | knowledge and understand that pursuant to OCD rules and regulations all operators are required asses which may endanger public health or the environment. The acceptance of a C-141 report by adequately investigate and remediate contamination that pose a threat to groundwater, surface t does not relieve the operator of responsibility for compliance with any other federal, state, or | |
| I hereby agree and sign off to the above statement | Name: James Raley Title: EHS Professional Email: jim.raley@dvn.com Date: 07/24/2025 | |

Sante Fe Main Office Phone: (505) 476-3441 General Information

Phone: (505) 629-6116 Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS, Page 3

Action 488469

QUESTIONS (continued)

| Operator: | OGRID: |
|-------------------------------------|-------------------------------------------------------------|
| DEVON ENERGY PRODUCTION COMPANY, LP | 6137 |
| 333 West Sheridan Ave. | Action Number: |
| Oklahoma City, OK 73102 | 488469 |
| | Action Type: |
| | [C-141] Remediation Closure Request C-141 (C-141-v-Closure) |

QUESTIONS

| Site Characterization | | | | |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------|--|--|--|
| Please answer all the questions in this group (only required when seeking remediation plan approval and beyond). This information must be provided to the appropriate district office no later than 90 days after the release discovery date. | | | | |
| What is the shallowest depth to groundwater beneath the area affected by the release in feet below ground surface (ft bgs) | Between 51 and 75 (ft.) | | | |
| What method was used to determine the depth to ground water | NM OSE iWaters Database Search | | | |
| Did this release impact groundwater or surface water | No | | | |
| What is the minimum distance, between the closest lateral extents of the release and the following surface areas: | | | | |
| A continuously flowing watercourse or any other significant watercourse | Greater than 5 (mi.) | | | |
| Any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark) | Greater than 5 (mi.) | | | |
| An occupied permanent residence, school, hospital, institution, or church | Greater than 5 (mi.) | | | |
| A spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes | Greater than 5 (mi.) | | | |
| Any other fresh water well or spring | Greater than 5 (mi.) | | | |
| Incorporated municipal boundaries or a defined municipal fresh water well field | Greater than 5 (mi.) | | | |
| A wetland | Between 300 and 500 (ft.) | | | |
| A subsurface mine | Greater than 5 (mi.) | | | |
| An (non-karst) unstable area | Greater than 5 (mi.) | | | |
| Categorize the risk of this well / site being in a karst geology | Low | | | |
| A 100-year floodplain | Greater than 5 (mi.) | | | |
| Did the release impact areas not on an exploration, development, production, or storage site | No | | | |

| Remediation Plan | |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------|
| Please answer all the questions that apply or are indicated. This information must be provided t | o the appropriate district office no later than 90 days after the release discovery date. |
| Requesting a remediation plan approval with this submission | Yes |
| Attach a comprehensive report demonstrating the lateral and vertical extents of soil contamination | on associated with the release have been determined, pursuant to 19.15.29.11 NMAC and 19.15.29.13 NMAC. |
| Have the lateral and vertical extents of contamination been fully delineated | Yes |
| Was this release entirely contained within a lined containment area | Yes |
| Per Subsection B of 19.15.29.11 NMAC unless the site characterization report includes complete which includes the anticipated timelines for beginning and completing the remediation. | ed efforts at remediation, the report must include a proposed remediation plan in accordance with 19.15.29.12 NMAC, |
| On what estimated date will the remediation commence | 05/01/2025 |
| On what date will (or did) the final sampling or liner inspection occur | 05/23/2025 |
| On what date will (or was) the remediation complete(d) | 05/01/2025 |
| What is the estimated surface area (in square feet) that will be remediated | 13000 |
| What is the estimated volume (in cubic yards) that will be remediated | 0 |
| These estimated dates and measurements are recognized to be the best guess or calculation at t | the time of submission and may (be) change(d) over time as more remediation efforts are completed. |
| The OCD recognizes that proposed remediation measures may have to be minimally adjusted in | accordance with the physical realities encountered during remediation. If the responsible party has any need to |

significantly deviate from the remediation plan proposed, then it should consult with the division to determine if another remediation plan submission is required.

Released to Imaging: 7/25/2025 3:22:12 PM

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

QUESTIONS, Page 4

Action 488469

QUESTIONS (continued)

| ı | Operator: | OGRID: |
|---|-------------------------------------|-------------------------------------------------------------|
| ı | DEVON ENERGY PRODUCTION COMPANY, LP | 6137 |
| ı | 333 West Sheridan Ave. | Action Number: |
| ı | Oklahoma City, OK 73102 | 488469 |
| ı | | Action Type: |
| ı | | [C-141] Remediation Closure Request C-141 (C-141-v-Closure) |

QUESTIONS

| Remediation Plan (continued) | | | | |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|--|--|--|
| Please answer all the questions that apply or are indicated. This information must be provided to the appropriate district office no later than 90 days after the release discovery date. | | | | |
| This remediation will (or is expected to) utilize the following processes to remediate / reduce contaminants: | | | | |
| (Select all answers below that apply.) | | | | |
| Is (or was) there affected material present needing to be removed | Yes | | | |
| Is (or was) there a power wash of the lined containment area (to be) performed | Yes | | | |
| OTHER (Non-listed remedial process) | Not answered. | | | |
| Per Subsection B of 19.15.29.11 NMAC unless the site characterization report includes completed efforts at remediation, the report must include a proposed remediation plan in accordance with 19.15.29.12 NMAC, | | | | |

Per Subsection B of 19.15.29.11 NMAC unless the site characterization report includes completed efforts at remediation, the report must include a proposed remediation plan in accordance with 19.15.29.12 NMAC which includes the anticipated timelines for beginning and completing the remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

I hereby agree and sign off to the above statement

Name: James Raley Title: EHS Professional Email: jim.raley@dvn.com Date: 07/24/2025

The OCD recognizes that proposed remediation measures may have to be minimally adjusted in accordance with the physical realities encountered during remediation. If the responsible party has any need to significantly deviate from the remediation plan proposed, then it should consult with the division to determine if another remediation plan submission is required.

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

QUESTIONS, Page 6

Action 488469

| Operator: | OGRID: |
|---------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------|
| DEVON ENERGY PRODUCTION COMPANY, LP 333 West Sheridan Ave. | 6137 |
| Oklahoma City, OK 73102 | Action Number: 488469 |
| onanoma ony, orchoroz | Action Type: |
| | [C-141] Remediation Closure Request C-141 (C-141-v-Closure) |
| QUESTIONS | |
| iner Inspection Information | |
| Last liner inspection notification (C-141L) recorded | 466960 |
| Liner inspection date pursuant to Subparagraph (a) of Paragraph (5) of Subsection A of 19.15.29.11 NMAC | 05/27/2025 |
| Was all the impacted materials removed from the liner | Yes |
| What was the liner inspection surface area in square feet | 7285 |
| | |
| Remediation Closure Request | |
| Only answer the questions in this group if seeking remediation closure for this release because all re | mediation steps have been completed. |
| Requesting a remediation closure approval with this submission | Yes |
| Have the lateral and vertical extents of contamination been fully delineated | Yes |
| Was this release entirely contained within a lined containment area | Yes |
| What was the total surface area (in square feet) remediated | 13000 |
| What was the total volume (cubic yards) remediated | 0 |
| Summarize any additional remediation activities not included by answers (above) | The affected material was all removed with a vac truck and powerwashed. No signs of staining or breaches of the liner was encountered. |

hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by

the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

Name: James Raley Title: EHS Professional I hereby agree and sign off to the above statement Email: jim.raley@dvn.com Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 488469

CONDITIONS

| Operator: | OGRID: |
|-------------------------------------|-------------------------------------------------------------|
| DEVON ENERGY PRODUCTION COMPANY, LP | 6137 |
| 333 West Sheridan Ave. | Action Number: |
| Oklahoma City, OK 73102 | 488469 |
| | Action Type: |
| | [C-141] Remediation Closure Request C-141 (C-141-v-Closure) |

CONDITIONS

| Created By | Condition | Condition Date |
|---------------|-----------------------------------------|-------------------|
| scott.rodgers | App ID 488469 Liner Inspection approved | 7/25/2025 |