<u>District I</u>

1625 N. French Dr., Hobbs, NM 88240 Phone:(505) 393-6161 Fax:(505) 393-0720

<u>District II</u>

1301 W. Grand Ave., Artesia, NM 88210 Phone:(505) 748-1283 Fax:(505) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico

Energy, Minerals and Natural Resources

Form C-140 Permit 45784 Revised June 10, 2003

Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505 (505) 476-3440

APPLICATION FOR WELL WORKOVER PROJECT

I. Open	tor and Well:										
Operator name & address									OGRID Number		
OCCIDENTAL PERMIAN LTD									157984		
PO Box 42	•										
Houston 7	'X 77210							4			
Contact Party Karen Ellis									Phone 713-366-5161		
Property Name Well Number NORTH HOBBS G/SA UNIT 341								API Number 30-025-05446			
UL - Lot	Section	Towns	hip Range	Feet From	The Nort	h/South Line	Feet From The	East/West L	ine County	Y	
0	13	13 18S		37E 660		S 1980		E	Lea		
II. Word	over:	300	3/2	0.50				1.5	No.		
Date Workover Commenced: Previous Producing Pool(s) (Prior to Workover):											
9/8/2006 HOBBS;GRAYBURG-SAN ANDRES											
Date Workov 10/2/2006	er Completed:										
IV. Attac	h a production d ving the workov	lecline curv er reflectin	ve or table showii g a positive prod		months o	f production po	ior to the workov	ver and at least	tkree months of prod	buction	
V. Sign											
				aplete to the best							
Signature	Electro	onically S	y Signed TitleRegula			itory Team Leader		Date 1/29/2007			
Type or p	orint name <u>E</u>	lizabeth i	Bush-Ivie	E-mail addr	ess Eliz	abeth_Bush	@oxy.com_Te	lephone N	o. <u>713-366-5303</u>		
VI. CER This show	s a positive prod	F APPRO ereby appr buction inc	VAL: oved and the abo rease. By copy h		n notifies 1				n hereby verifies the sartment of this Appro		
Signature	District Sup	ervisor	: Chris Willia	ms		_District	1	Date 2/1/	2007		

VII. DATE OF NOTIFICATION TO THE SECRETARY OF THE TAXATION AND REVENUE DEPARTMENT: 2/1/2007

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

DATE

Revised 5-27-2004 FILE IN TRIPLICATE OIL CONSERVATION DIVISION WELL API NO. 1220 South St. Francis Dr. 1625 N. French Dr., Hobbs, NM 88240 30-025-05446 Santa Fe, NM 87505 5. Indicate Type of Lease DISTRICT II STATE FEE [$\overline{\mathbf{x}}$ 1301 W. Grand Ave, Artesia, NM 88210 6. State Oil & Gas Lease No. DISTRICT III 1000 Rio Brazos Rd, Aztcc, NM 87410 7. Lease Name or Unit Agreement Name SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A North Hobbs (G/SA) Unit DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.) Section 13 1. Type of Well: 8. Well No. Oil Well X Gas Well Other 9. OGRID No. 2. Name of Operator 157984 Occidental Permian Ltd. 10. Pool name or Wildcat Hobbs (G/SA) 3. Address of Operator HCR 1 Box 90 Denver City, TX 79323 4. Well Location Unit Letter O Feet From The 1980 Feet From The East Line : 660 South **NMPM** County Section 13 Township 18-S Range 37-E Lea 11. Elevation (Show whether DF, RKB, RT GR, etc.) 3678' DF Pit or Below-grade Tank Application or Closure ____ Depth of Ground Water ___ Distance from nearest surface water Distance from nearest fresh water well Below-Grade Tank: Volume bbls; Construction Material Pit Liner Thickness Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 12. SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: REMEDIAL WORK ALTERING CASING PLUG AND ABANDON PERFORM REMEDIAL WORK CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT TEMPORARILY ABANDON CASING TEST AND CEMENT JOB **PULL OR ALTER CASING** Multiple Completion OTHER: OTHER: Wellhead upgrade/Cleanout/Acid Treat 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1. RUPU & RU. Kill well. Pull rods out of hole. 2. Run in hole w/RBP set @3900'. Dump sand on RBP. 3. Scan tubing out of hole. 4. Set RBP @800'. Test casing to 500 PSI for 30 minutes. 5. RDPU & RU for well head change out. 6. RUPU. Circulate sand off of RBP @800'. Release RBP & pull out of the hole. Wash sand off of RBP @3900' and pull out of hole. 7. Tag CIBP @4064'. Drill on CIBP, fell to 4250'. Clean out to 5259'. Circ well clean. 8. Rig up wire line and log well from 4259' to 3200'. 9. Run in hole w/treating packer set @4170'. Pump 500 gal 15% HCL, drop 500 lbs gelled rock salt. Flush w/50 bbl fresh water, pump rest of acid (1500 gal). *** See additional data on attached sheet*** 10. Swab back well. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be or an (attached) alternative OCD-approved closed according to NMOCD guidelines , a general permit plan TITLE DATE 08/30/2006 Administrative Associate SIGNATURE E-mail address: TELEPHONE NO. 806-592-6280 TYPE OR PRINT NAME mendy johnson@oxy.com Mendy A. Johnson For State Use Only

TITLE

CONDITIONS OF APPROVAL IF ANY:

APPROVED BY