

District II

1301 W. Grand Ave., Artesia, NM 88210
Phone:(505) 748-1283 Fax:(505) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462State of New Mexico
Energy, Minerals and Natural ResourcesOil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505WELL API NUMBER
30-021-201285. Indicate Type of Lease
S

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name
WEST BRAVO DOME UNIT8. Well Number
3219. OGRID Number
49510. Pool name or Wildcat
See Area 13

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: C

2. Name of Operator

HESS CORPORATION

3. Address of Operator

P.O. BOX 840, SEMINOLE, TX 79360

4. Well Location

Unit Letter K : 2310 feet from the S line and 1980 feet from the W line
Section 32 Township 20N Range 29E NMPM Harding County

11. Elevation (Show whether DR, KB, BT, GR, etc.)

4341 GR

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit Type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐TEMPORARILY ABANDON ☐ CHANGE OF PLANS ☐PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

Other:

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTER CASING ☐COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDON ☐CASING/CEMENT JOB ☐Other: Perforations/Tubing ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Day 1 MIRU. Kill well with 4% KCL. Unset packer. NDWH & NU BOP's

Day 2 Swab well to achieve 600 psi (1386' H₂O) (balance). TOH W/2 3/8" tbg/packer. Stand tbg back. PU & TIH W/two (1) 10' & (1) 5' HSD, 3 3/8" Hyperjet, 3406 guns. Shoot 4 JSPF (2689'-2685" & 2680'-2674") TOH W/& lay down spent guns. PU & TIH with One (1) 10' & (2) 5' HSD, 3 3/8" Hyperjet, 3406 guns. Shoot 4 JSPF (2717'-2712', 2706'-2701' & 2698'-2691') TOH W/& lay down spent guns. TIH set Arrow set 1 packer w/plugset @ 2619' and 2 3/8" tbg

Day 3 ND BOP's & NU WH. Pull Packer plug. Return well to SI status Clean site. RDMO

Perforations

Pool: WEST BRAVO DOME CO₂ GAS, 96387 Location: K -32-20N-29E 1980 S 1980 W

TOP BOT Open Hole Shots/ft Shot Size Material Stimulation Amount

Tubing

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Electronically Signed TITLE Engineering Tech DATE 6/7/2010

Type or print name Rita Smith E-mail address rsmith@hess.com Telephone No. 432-758-6726

For State Use Only:

APPROVED BY: Ed Martin TITLE District Supervisor DATE 6/11/2010 8:03:34 AM