Ceceined by Cop Dis 1/29/2421 FistA: 57 AM	State of New Mexico	Received NMOCD 1/26/21 Form CPass ¹ of C
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources	
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	WELL API NO. 30-025-25206
<u>District III</u> – (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease STATE STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		B-936
	AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS DIFFERENT RESERVOIR. USE "APPLICATIO	TO DRILL OR TO DEEPEN OR PLUG BACK TO A DN FOR PERMIT" (FORM C-101) FOR SUCH	NVANU "11"
PROPOSALS.)		8. Well Number 002
	Well Other	
2. Name of Operator		9. OGRID Number 373671
Unitex Oil & Gas, LLC		
3. Address of Operator 508 W. Wall S	t. Ste #1000 Midland, TX 79701	10. Pool name or Wildcat
		North Vacuum Abo North Unit
4. Well Location		
Unit LetterE198	80feet from theN line and	860feet from theWline
Section 1	Township 17S Range 3	4E NMPM Lea County
the second se	. Elevation <i>(Show whether DR, RKB, RT, GR,</i> 39.9 GL	etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF IN	TENTION TO:	SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WORK ALTERING CASING			
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING OPNS. P AND A			
PULL OR ALTER CASING	MULTIPLE COMPL		CASING/CEMENT JOB			
DOWNHOLE COMMINGLE						
CLOSED-LOOP SYSTEM						
OTHER:			OTHER:]		

 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Plug #1 - ~5000' - tag TOF and see if we can get circulation. If we can get circulation pump cmt past fish.

Plug #2 - 3300' - Mix 50 sx cmt & perf & sqz 4-1/2" & 8-5/8' csgs to cover 8-5/8" shoe. WOC, Tag cmt.

Plug #3 - 2940'-2840' - Mix 50 sx cmt (100') & perf & sqz 8-5/8" csg to cover Yates (salt) top. WOC. Tag cmt.

Plug #4 – 1650' – Mix 50 sx cmt & perf & sqz. WOC. Tag cmt.

Plug #5 – 399'-299' – Mix 50 sx (100') & perf & sqz 13-3/8" & 8-5/8" csgs to cover 13-3/8" shoe. WOC. Tag cmt.

Perf and Sqz at 150' (~100 sx) and circulate cmt to surface. Cut off csg below surface flange. Top off csgs w/ cmt. Install P&A marker with cmt to comply with government specs.

Spud Date:	ESt. Jan. 2021	Rig Release Date:	SEE AT OF APP	TACHED CONDITIONS ROVAL
I hereby certi	fy that the information above is true and	complete to the best of	my knowledge and belief.	
SIGNATURI	Maler in Taxlarchou name Laurie Taxiarchi	TITLE OPERO	tions eng.	DATE 12-14-20
Type or print	name LAURIE JOXIANNI	ME-mail address: It C	wiarchou@unitexol	PHONE: 432-685-0014
For State Us	e Only			
APPROVED Conditions of	BY: Kerry Fortner		ice Officer A	DATE 1/28/21

Released to Imaging: 1/29/2021 7:49:33 AM

Received by OCD: 1/29/2021 7:44:57 AM

(TVD)			
Č (
		1	
		K.	
800			
	- ()	1 Y	
		10	
1,600		1/	
		1.	
	()		
	11	A A	
0.400	± 1	14	
2,400		17	
	/	1 N	
		1.	
3,200			
4,000		1	
4,000			
4,800			
		(Fish/Collapsed Csg @ 5,103'
	/	A	
5,600	(
- ,			
6,400			
7,200		<u> </u>	
0.000			
8,000			1
⁻ ish (tbg & sinker bars) @ 8,395			
8,800			

Last Updated: 12/14/2020 10:14 AM

Field	d Name)			me				We	II No.						
NVA	NU					Norh Vacuum Abo North Unit '11"										
Cou	nty				Stat						API N	lo.				
Lea					New	/ Mexi	со				3002	52520	060000			
Version Version Tag																
0																
GL (KB			tion			hip/	Bloc	:k		je/Su	rvey			
	4,039.9		4,056.	9 1		175					34E					
Operator Well Status Latitude Longitude													gitude			
	ex Oil &					ducin	•									
Dist	. N/S (ff	·	I/S Lir	ne D)ist. I	E/W (1			Line	e Fo	ootage	Fron	n			
	-	80 F	NL			8		FWL								
Prop	p Num						Sp	bud	Date	•	Co	mp. l	Date			
Add	itional	Info	rmatic	n			_									
Othe	or 4			ther 2				ther	2			her 4				
Othe				mer 2				mer	3		Ut	ner 4				
Pror	pared B	v		Un	date	d By				Last	Updat	ed				
	xiarchou	-		-	axiar	-				Luot	-		0 10:14 AM			
-	Summ															
	Date	Di	am.	Тој								Memo				
			n) 4.000	(MD	0											
			9.500		0											
		(6.125		0		8,831									
Tub	ular Su	mma	ary													
D	Date		Desc	riptio	n	O.D. Wt Grade			e To	Top Bo						
				-			in) (lb/ft		-		(MD		(MD ft)			
				urface Casing					0.00				349			
			ermedi						4.00			0	,			
0			oducti		sing	4.	500	1	0.50	k-55		0	8,831			
	ing Cen	lient		-		1 -	Ler:	1.	2 c 44			Mer				
С	Date		No. Sx		sg. . (in)		Гор ID ft		Botto (MD							
			450		13.37	•		0 349								
		1	1,100		8.62	25	3	50	3,	062						
			750		4.50	00	3,9	00	8,	831						
Tool	ls/Prob	lems	s Sum	mary												
Date Tool Type						O.D (in)			D. n)	(Top MD ft)		Bottom (MD ft)			
			Fis				500		3.000		5,1		5,106			
			Csg Da	-		4.5	500		0.000		5,10		5,140			
		C	Csg Co	•	;		500		0.000		5,103		0			
			Fis			2.3	375	(0.000)	8,3	95	8,665			
	oration				1							_				
C Date Perf. Status				Status						A Top /ID ft)	OA Bottom (MD ft)					
	Open						bo					8,685 8,735				

Received by OCD: 1/29/2021 7:44:57 AM Last Updated: 12/14/2020 10:14 AM

East Op								Well No.	Count			Ctat	_		API No			
NVANU	ield Name Leas				um Abo	North L		2	/	State New Mexico				300252		000		
	Verei			n vacu				2	Lea	6	aud Dai							4)
Version		on Tag								St	pud Dat	ate Comp. Date		te	GL (ft)		KB (ft	
0	0			Davi							- 4 - 7 - 7 - 4	1 (84)	F 0.4/ 1 in a	15.		,039.9		4,056
Section	Townshi	ір/Віоск			ge/Surv	ey		Dist. N/S (ft)) DI	St. E/W		E/W Line	FO	otage F	rom		
1	175			34E				1,98	0 FNL			860	FWL	\bot				
Operator						Well S			L	atitud	le		Longitude	1		Prop N	lum	
Unitex Oil 8	Gas				_	Produ	cing											
Other 1				Other	2			Other	3				Other	4				
Last Updat		-			pared By	/					Jpdated							
12/14/2020				LTa	xiarchou						Taxiarc	chou						
Additional	Informati	on																
Hole Sumn	-	1																
Date	Diam.	Top (MD ft)	Botto							Mer	no							
	(in) 14.000		(MD 1	349														
	9.500			062														
	6.125			831														
Tubular Su			-,															
Date		escription		No.	O.D. (in) Wt	Grade	Coupling	Тор	В	ottom	1			Memo			
Duto		coorpaon		Jts		(lb/ft)		ocupiing	(MD ft)		MD ft)				menne	,		
	Surface (-			13.37	5 40.0	0			0	34	9						
		ate Casing	3		8.62					0	3,06	2						
	Productio	on Casing			4.50	0 10.5	0 k-55			0	8,83	1						
Casing Cer	ment Sum	nmary																
C Date		Yield	Vol.		sg. Top Bottom			Description							Memo			
_	Sx	(ft3/sk)	(ft3)	0.D.	(in) 13.375	(MD ft)	(MD ft)											
_	450		450			050	349											
	1,100		1,100 750		8.625	350					-+							
Toolo/Drok			150		4.500	3,900	0,03	'										
Tools/Prob							T	Detterm		ulus 41					Marrie			
Date		Tool Type	ŧ).D. in)	I.D. (in)	Top (MD ft)	Bottom (MD ft)	Desc	πρτιο	n				Memo			
		Fish		+ `	4.500	3.000			Collapsed	Csg								
	Ca	asing Dama	age	+	4.500	0.000	5,103	3 5,140										
	Co	llapsed Ca	sing	+	4.500	0.000	5,103	3 0										
	1	Fish	-	+	2.375	0.000					-+							
Perforation	n Summar				I		· ·											
C Date	Stag	•	rf. Status	s	F	ormatio	n	Closed Da	te				Mem	0				
	1	Open			bo													
Тор		Bottom	5	SPF	Shot	s Ph	asing (deg)	1			Interv	val Memo					
(MD ft) (MD ft)							3 (<u></u>										
	, 8,685		,735															

.

CONDITIONS OF APPROVAL FOR PLUGGING AND ABANDONMENT OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office I (Hobbs) at (575)-263-6633 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down.

Company representative will be on location during plugging procedures.

1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.

2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.

3. Trucking companies being used to haul oilfield waste fluids to a disposal - commercial or private- shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.

4. Filing a subsequent C-103 will serve as notification that the well has been plugged.

5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can +be released.

6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.

7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.

8. Produced water will not be used during any part of the plugging operation.

9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.

10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.

11. Class 'C' cement will be used above 7500 feet.

12. Class 'H' cement will be used below 7500 feet.

13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged

14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.

16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set

17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.

18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).

19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.

20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops

- A) Fusselman
- B) Devonian
- C) Morrow
- D) Wolfcamp
- E) Bone Springs
- F) Delaware
- G) Any salt sections
- H) Abo
- I) Glorieta
- J) Yates.

K) Potash---(In the R-111-P Area (Potash Mine Area),

A solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, woe 4 hours and tag, this plug will be SO' below the bottom and 50' above the top of the Formation.

21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, woe and tagged. These plugs will be set SO' below formation bottom to 50' above formation top inside the casing.

DRY HOLE MARKER REQ.UIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least¹/₄" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. Operator name
- 2. Lease and Well Number
- 3. API Number
- 4. Unit letter
- 5. Quarter Section (feet from the North, South, East or West)
- 6. Section, Township and Range
- 7. Plugging Date
- 8. County

SPECIAL CASES -----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

District I 1625 N. French Dr., Hobbs, NM 88240

Phone:(575) 393-6161 Fax:(575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

District III 1000 Rio Brazos Rd., Aztec, NM 87410

District IV

CONDITIONS

Action 16141

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS OF APPROVAL

Operator:					OGRID:	Action Number:	Action Type:
	UNITEX OIL & GAS, L.L.C.	508 W Wall Street, Suite 1000	Midland, TX79701		373671	16141	C-103F
OCD Rev	iewer			Condition			
plmartine	Z			None			