Office District I – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	AM State of New Me Energy, Minerals and Natu OIL CONSERVATION 1220 South St. Fran Santa Fe, NM 87	DIVISION acis Dr.	Form C-103 of 11 Revised July 18, 2013 WELL API NO. 30-025-27596 5. Indicate Type of Lease STATE FEE 6. State Oil & Gas Lease No. V-3526
(DO NOT USE THIS FORM FOR PROPO	TICES AND REPORTS ON WELLS DISALS TO DRILL OR TO DEEPEN OR PLU DICATION FOR PERMIT" (FORM C-101) FO Gas Well Other	JG BACK TO A	7. Lease Name or Unit Agreement Name RED TANK 30 STATE 8. Well Number 3 9. OGRID Number
OXY USA INC. 3. Address of Operator	DLAND, TX 79710-025	0	16696 10. Pool name or Wildcat BOOTLEG RIDGE DELAWARE
	1980 feet from the NORTH Township 22-S Ra 11. Elevation (Show whether DR,	nge 33-E	NMPM County
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER:	CHANGE PLANS MULTIPLE COMPL	SUBS REMEDIAL WORK COMMENCE DRII CASING/CEMENT OTHER:	SEQUENT REPORT OF: K
of starting any proposed w proposed completion or re	ork). SEE RULE 19.15.7.14 NMAC	C. For Multiple Con	npletions: Attach wellbore diagram of
LPC Area Below ground ma	rker send pics before backfilling	hole	SEE ATTACHED CONDITIONS OF APPROVAL
Spud Date:	Rig Release Da	te:	
I hereby certify that the information	above is true and complete to the be	est of my knowledge	e and belief.
SIGNATURE ttephen form	tik TITLE REGI	ULATORY EN	GINEER DATE 3/8/21
Type or print name STEPHEN For State Use Only		: STEPHEN_JANAC	PHONE: 713-493-1986
APPROVED BY: Yw Conditions of Approval (if any):	my FortherTITLE Com	pliance Officer A	DATE_ <u>5/1</u> 0/21

Notice of Intent to PA

Red Tank 30 State #003

30-025-27596

PROCEDURE

10# MLF between plugs. Utilize above ground steel tanks.

SET CIBP 4896'. DUMP BAIL 5 SX CL C CMT. TAG.

PERF 1300'. SQZ 125 SX CL C CMT TO 900'. TAG.

PERF 800'. EST CIRC IN 13.375 X 10.75 AND 10.75 X 5.5 ANNULI. CIRC 400 SX CL C CMT TO SURFACE. VERIFY AT SURFACE.

LPC Area Below ground marker send pics before backfilling hole

SEE ATTACHED CONDITIONS OF APPROVAL

Current Wellbore

2/24/2021

RED TANK 30 STATE #003

30-025-27596-0000

Lea


String 1 OD 13.375 in TD 711 ft TOC 0 ft (Circ)

String 2 OD 10.75 in TD 4848 ft TOC 1150' (TS)

String 4
OD 5.5 in
TD 5290 ft
TOC 3200 ft (Calc)

String 3 OD 7.625 in TOC 0 ft (Circ) TD 12150' Cut and pulled from 7693'

4.5" OH TD 15450'



Proposed Wellbore

2/24/2021

RED TANK 30 STATE #003

30-025-27596-0000

Lea

PERF 800'. EST CIRC IN 13.375 X 10.75 AND **10.75 X 5.5 ANNULI. CIRC 400 SX CL C CMT TO SURFACE. VERIFY AT SURFACE.**

String 1 OD 13.375 in TD 711 ft TOC 0 ft (Circ)

Squeeze holes 950'-1000'. Cemented off. PERF 1300'. SQZ 125 SX CL C CMT TO 900'. TAG.

String 2 OD 10.75 in TD 4848 ft TOC 1150' (TS)

String 4 OD 5.5 in TD 5290 ft TOC 3200 ft (Calc)

String 3 OD 7.625 in TOC 0 ft (Circ) TD 12150' Cut and pulled from 7693'

4.5" OH TD 15450'

SET CIBP 4896'. DUMP BAIL 5 SX CL C CMT. TAG. Perfs 4946'-4963' (Delaware) Spot 50 sx cmt at 5236'. Plug went downhole. Respot 125 sx cmt plug. Tag 5301'. 100 sx cmt plug 7768'-7588' CIBP 10500' Perfs 10563'-10620' (Bone Spring) 40 sx cmt plug 12050'-12250' 45 sx cmt plug 13262'-13462'

35 sx cmt plug 14400'-14600'

CONDITIONS OF APPROVAL FOR PLUGGING AND ABANDONMENT OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office I (Hobbs) at (575)-263-6633 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down.

Company representative will be on location during plugging procedures.

- **1.** A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
- **2.** Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- **3.** Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private- shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- **5.** A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can +be released.
- **6.** If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- **8.** Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- **10.** All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- **13.** A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- **14.** All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.
- **16.** When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- **18.** A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).

- **19.** No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
- A) Fusselman
- B) Devonian
- C) Morrow
- D) Wolfcamp
- E) Bone Springs
- F) Delaware
- G) Any salt sections
- H) Abo
- I) Glorieta
- J) Yates.
- K) Potash---(In the R-111-P Area (Potash Mine Area),

A solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, woe 4 hours and tag, this plug will be SO' below the bottom and 50' above the top of the Formation.

21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, woe and tagged. These plugs will be set SO' below formation bottom to 50' above formation top inside the casing.

DRY HOLE MARKER REQ.UIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. Operator name
- 2. Lease and Well Number
- 3. API Number
- 4. Unit letter
- 5. Quarter Section (feet from the North, South, East or West)
- 6. Section, Township and Range
- 7. Plugging Date
- 8. County

SPECIAL CASES ----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

Notice of Intent to PA

Red Tank 30 State #003

30-025-27596

PROCEDURE

10# MLF between plugs. Utilize above ground steel tanks.

SET CIBP 4896'. DUMP BAIL 5 SX CL C CMT. TAG.

PERF 1300'. SQZ 125 SX CL C CMT TO 900'. TAG.

PERF 800'. EST CIRC IN 13.375 X 10.75 AND 10.75 X 5.5 ANNULI. CIRC 400 SX CL C CMT TO SURFACE. VERIFY AT SURFACE.

Current Wellbore

2/24/2021

RED TANK 30 STATE #003

30-025-27596-0000

Lea


String 1 OD 13.375 in TD 711 ft TOC 0 ft (Circ)

String 2 OD 10.75 in TD 4848 ft TOC 1150' (TS)

String 4
OD 5.5 in
TD 5290 ft
TOC 3200 ft (Calc)

String 3 OD 7.625 in TOC 0 ft (Circ) TD 12150' Cut and pulled from 7693'

4.5" OH TD 15450'



Proposed Wellbore

2/24/2021

RED TANK 30 STATE #003

30-025-27596-0000

Lea

PERF 800'. EST CIRC IN 13.375 X 10.75 AND **10.75 X 5.5 ANNULI. CIRC 400 SX CL C CMT TO SURFACE. VERIFY AT SURFACE.**

String 1 OD 13.375 in TD 711 ft TOC 0 ft (Circ)


Squeeze holes 950'-1000'. Cemented off. PERF 1300'. SQZ 125 SX CL C CMT TO 900'. TAG.

String 2 OD 10.75 in TD 4848 ft TOC 1150' (TS)

String 4 OD 5.5 in TD 5290 ft TOC 3200 ft (Calc)

String 3 OD 7.625 in TOC 0 ft (Circ) TD 12150' Cut and pulled from 7693'

4.5" OH TD 15450'



35 sx cmt plug 14400'-14600'

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

COMMENTS

Action 19948

COMMENTS

Operator:		OGRID:	Action Number:	Action Type:
OXY USA INC P.O. Box 429	4 Houston, TX772104294	16696	19948	C-103F

Created By	Comment	Comment Date
plmartinez	DATA ENTRY PM	05/11/2021

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410

Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 19948

CONDITIONS OF APPROVAL

OVVIICA INC	Action Type:	ction Number: Action	OGRID:			erator:
OAT OSA INC P.O. BOX 4294 Houstoll, 1A772 104294 10090 19946	C-103F	19948	16696	Houston, TX772104294	P.O. Box 4294	OXY USA INC

OCD Reviewer	Condition
kfortner	See attached conditions of approval