Received by OCD: 5/5/2021 6:39:14	AM State of New Me	exico		Form C-103 of 7	
Office <u>District I</u> – (575) 393-6161	Energy, Minerals and Natu	ral Resources	WELL API NO.	Revised August 1, 2011	
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283 811 S. First St. Asterio, NM 88210 OIL CONSERVATION DIVISION		30-015-22686			
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178	1220 South St. Francis Dr.		5. Indicate Type of Lease STATE		
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505		6. State Oil & Gas I		
1220 S. St. Francis Dr., Santa Fe, NM 87505					
SUNDRY NOT (DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR. USE "APPLI	Williams Gas Com	nit Agreement Name			
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well	A Socii	8. Well Number: 1		
Name of Operator Chevron USA INC	Gus Weii 🔼		9. OGRID Number 4323		
3. Address of Operator			10. Pool name or Wildcat		
6301 DEAUVILLE BLVD., M	IIDLAND, TX 79706		SWD; Delaware		
4. Well Location					
	feet from the <u>North</u> line an		eet from the <u>West</u>	line	
Section 23		Range 35E	NMPM	County Eddy	
	11. Elevation <i>(Show whether DR,</i> 2,989' GL, 3,009' KB	RKB, RT, GR, etc.)		
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or comp	PLUG AND ABANDON CHANGE PLANS CHANGE PLANS CHANGE PLANS COMPL COMPLETE 19.15.7.14 NMACCOMPLETE 1	REMEDIAL WOR COMMENCE DRI CASING/CEMEN OTHER: Description of the control of the	ILLING OPNS. P T JOB Notify OCD 24 hrs. prior done d give pertinent dates,	AND A	
	SEE CHANGES	S TO PROCE	DURE		
I hereby certify that the information SIGNATURE				E04/29/2021	
Type or print name Howie Lucas For State Use Only	PHONE: <u>832-588-4044</u>	_			
APPROVED BY:Conditions of Approval (if any):	TITLE	Staff Man	agerDATE	5/13/2021	
****SEE ATTACHED (COA's****	MUST	BE PLUGGE	D BY 5/13/2022	

Williams Gas Com 1 Short Procedure

CTU Work - All cement plugs calculated with 1.32 yield Class C and 1.18 yield Class H. If a different weight/yield is used, recalculate sacks based on depth.

- 1. Contact NMOCD at least 24 hours prior to performing any work.
- 2. MIRU CTU.
- 3. Verify pressures and kill well as per SOP/Guidance Document.
 - a. Bubble test intermediate and surface casings for 30 minutes each and share results in WellView under daily pressure.
- 4. N/U quad BOP and pressure test 250 psi low for 5 minutes and 1,000 psi, MASP, or max anticipated pressure (whichever is larger) high for 15 minutes (suffice as casing test).
 - a. On a chart with no bleed off aloud.
 - b. Ensure pressure does not exceed 80% burst of tubing/casing. Contact engineer to discuss.
- 5. TIH w/ CT to 6,324'.
- 6. Spot 30 sx CL "C" Cement f/ 6,324' t/ 6,166' (Bone Springs). 6374'
 - a. Plug must be at or above 6, 24'. 6274'
- 7. Spot 30 sx CL "C" Cement f/ 4,759' t/ 4,602' (Brushy Canyon).
 - a. Plug must be at or above 4,656'
- 8. Spot 30 sx CL "C" Cement f/ 3,698' t/ 3,541' (Cherry Canyon).
 - a. Plug must be at or above 3,598'.
- 9. Perforate at 2,500' and squeeze 202 sx CL "C" Cement f/ 2,500' t/ 1,950', WOC & tag (Bell Canyon).
 - a. Plug must be at or above 2,000'.
- 10. Pressure test casing to 1,000 psi for 15 minutes (barrier plug).
- 11. Perforate at 445' and squeeze 165 sx CL "C" Cement f/ 1,055' t/ 0' (Salt, Shoe, FW).
 - a. Base of fresh water in this area is ~80'.
- 12. Verify cement to surface.
- 13. RDMO.
 - a. Perform final bubble test and record in WellView.

CONDITIONS FOR PLUGGING AND ABANDONMENT

OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office II at (575)-748-1283 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down. Company representative will be on location during plugging procedures.

- A notice of intent to plug and abandon a wellbore is required to be approved before plugging
 operations are conducted. A cement evaluation tool is required in order to ensure isolation of
 producing formations, protection of water and correlative rights. A cement bond log or other
 accepted cement evaluation tool is to be provided to the division for evaluation if one has not
 been previously run or if the well did not have cement circulated to surface during the original
 casing cementing job or subsequent cementing jobs. Insure all bradenheads have been
 exposed, identified and valves are operational prior to rig up.
- 2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- 3. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- 5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
- 6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- 8. Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- 10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- 13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- 14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.

- 16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- 18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).
- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
 - A) Fusselman
 - B) Devonian
 - C) Morrow
 - D) Wolfcamp
 - E)Bone Springs
 - F) Delaware
 - G) Any salt sections
 - H) Abo
 - I) Glorieta
 - J) Yates.
 - K) Potash--- (In the R-111-P Area (Potash Mine Area), a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.
- 21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing

DRY HOLE MARKER REQUIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

1. Operator name 2. Lease and Well Number 3.API Number 4. Unit Letter 5. Quarter Section (feet from the North, South, East or West) 6. Section, Township and Range 7. Plugging Date 8. County (SPECIAL CASES)------AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

KB:

DF:

GL:

3,009

2.989'

Well No.: Lease: Williams Gas Com Field: Culebra Bluff (South) С 25 TSHP/Range: 23S/28E **Surface Location:** 560' FNL & 1980' FWL **Unit Ltr:** Sec:

Bottomhole Location: Same **Unit Ltr:** Sec: TSHP/Range:

County: Eddy St: NM **FEE** API: 30-015-22686 Cost Center: St Lease: **Current Status:** Inactive Gas Well 2989' GL CHEVNO: EQ4264 Elevation:

Surface Csg. 16" Size: 65 & 84#, H-40 Wt.: Set @: 395 Sxs cmt: 500 Circ: yes TOC: surface, 5 sx Hole Size: 20"

Intermediate Csg.

10-3/4" Size: 40.5#, K-55 Wt.: Set @: 2626' Sxs Cmt: 3600 Circ: yes, 145 sx TOC: surface Hole Size: 14 3/4"

Production Csg.

7-5/8" Size:

Wt.: 33.7 & 39#, S-95 Set @: 11,448' Sxs Cmt: 2,450 2535' - CBL TOC: Hole Size: 9-1/2"

Production Liner

Size:

Wt.: 17.93#, N-80 TOL 9,825 13,026 **BOL** Cement 450 sx

Note: When well was drilled the drill pipe became stuck after running 5" liner. Drill pipe was backed off to 10,346', a window was cut in 7-5/8" casing and well was sidetracked to TD and an additional 5"liner was ran. This WBD does not not show the abandoned 5" liner.

Spud Date: 9/10/1978 Compl. Date: 1/24/1979 MLF Mud laden fluid from 9,193'-6,324' 30 sx Class H Cement: 9,350'-9,193' MLF CIBP set at 11,146' with 170 sx Class H Cement: 11,480'-9,668'. Strawn/Atoka Perfs: 11,528'-11,990' CIBP @ 12,450' w/ 35' cmt Morrow Perfs: 12,492'-12,763'

PBTD: 12,450' TD: 13,028'

3,009'

2,989

9/10/1978

1/24/1979

Lease: Williams Gas Com 560' FNL & 1980' FWL Surface Location:

Bottomhole Location:

Same

County: **Current Status:**

Eddy St: NM Inactive Gas Well

Well No.: Unit Ltr:

Unit Ltr:

FEE St Lease: 2989' GL Elevation:

Field:

Culebra Bluff (South)

25 **TSHP/Range**: 23S/28E Sec: Sec:

TSHP/Range:

API: 30-015-22686 Cost Center:

CHEVNO: EQ4264

Surface Csg.

16" Size: Wt.: 65 & 84#, H-40 395 Set @: 500 Sxs cmt: Circ: yes TOC: surface, 5 sx Hole Size: 20"

Intermediate Csg.

10-3/4" Size: 40.5#, K-55 Wt.: 2626' Set @: Sxs Cmt: 3600 Circ: yes, 145 sx TOC: surface Hole Size: 14 3/4"

Production Csg.

7-5/8" Size:


Wt.: 33.7 (5544') & 39# (5904'), S-95

Set @: 11,448' 2,450 Sxs Cmt: 2535' - CBL TOC: Hole Size: 9-1/2"

Production Liner

Size: Wt.: 17.93#, N-80 TOL 9,825' BOL 13,026 Cement 450 sx

	TD, ft		
Formation Name	Тор		
BELL CANYON	2,660		
CHERRY CANYON	3,698		
BRUSHY CANYON	4,759		
BONE SPRINGS	6,324		
3RD BONE SPRINGS	9,300		
WOLFCAMP	9,945		
PENN	11,120		
STRAWN	11,310		
ATOKA	11,526		
MORROW LINE	12,208		
MORROW CLASTICS	12,380		



<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III
1000 Rio Brazos Rd., Aztec, NM 87410

Phone:(505) 334-6178 Fax:(505) 334-6170 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 26991

CONDITIONS OF APPROVAL

Operator:			OGRID:	Action Number:	Action Type:
CHEVRON USAINC	6301 Deauville Blvd	Midland, TX79706	4323	26991	C-103F

OCD Reviewer	Condition
gcordero	None