

Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.
30-015-22329
5. Indicate Type of Lease
STATE [] FEE [X]
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)
1. Type of Well: Oil Well [] Gas Well [X] Other
2. Name of Operator
EOG Resources, Inc.
3. Address of Operator
104 South Fourth Street, Artesia, NM 88210
4. Well Location
Unit Letter I : 1980 feet from the South line and 660 feet from the East line
Section 21 Township 17S Range 26E NMPM Eddy County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3362'GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK [] PLUG AND ABANDON [X]
TEMPORARILY ABANDON [] CHANGE PLANS []
PULL OR ALTER CASING [] MULTIPLE COMPL []
DOWNHOLE COMMINGLE []
CLOSED-LOOP SYSTEM []
OTHER: []
SUBSEQUENT REPORT OF:
REMEDIAL WORK [] ALTERING CASING []
COMMENCE DRILLING OPNS. [] P AND A []
CASING/CEMENT JOB []
Notify OCD 24 hrs. prior to any work done
OTHER: []

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

EOG Resources, Inc. plans to plug and abandon this well as follows:

- 1. MIRU all safety equipment as needed. NU BOP. POOH with production equipment.
2. Set a CIBP at 8354' with 12 sx Class "H" cement on top to 8249'. WOC and tag. This will cover Morrow perfs, Morrow, Chester and Morrow tops.
3. Set a CIBP at 8144' with 40 sx Class "H" cement on top to 7791'. WOC and tag. This will cover Atoka perfs, Atoka and Strawn tops.
4. Perforate at 7444'. Spot a 60 sx Class "C" cement plug from 7444'-6963'. WOC and tag. This will cover Canyon top and TOC.
5. Perforate at 4448'. Spot a 25 sx Class "C" cement plug from 4448'-4258'. WOC and tag. This will cover Abo top.
6. Perforate at 2400'. Spot a 25 sx Class "C" cement plug from 2400'-2210'. WOC and tag. This will cover Glorieta top.
7. Perforate at 1470'. Spot a 32 sx Class "C" cement plug from 1470'-1347'. WOC and tag. This will cover casing shoe.
8. Perforate at 1020'. Spot a 35 sx Class "C" cement plug from 1020'-918'. WOC and tag. This will cover San Andres top.
9. Perforate at 510'. Spot a 35 sx Class "C" cement plug from 510'-408'. WOC and tag. This will cover the casing shoe.
10. Perforate at 50'. Spot a 18 sx Class "C" cement plug from 50' up to surface. WOC and tag. Back fill as needed.
11. Cut off wellhead and install dry hole marker. Clean location as per regulated.

Wellbore schematics attached.

Spud Date: []

Rig Release Date: []

****SEE ATTACHED COA's****

Must be plugged by 6/3/2022

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tina Huerta TITLE Regulatory Specialist DATE May 27, 2021

Type or print name Tina Huerta E-mail address: tina.huerta@eogresources.com PHONE: 575-748-4168

For State Use Only

APPROVED BY: [Signature] TITLE Staff Manager DATE 6/3/2021

CONDITIONS FOR PLUGGING AND ABANDONMENT

OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, **Notify NMOCD District Office II at (575)-748-1283 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down. Company representative will be on location during plugging procedures.**

1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
3. Trucking companies being used to haul oilfield waste fluids to a disposal – commercial or private – shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
8. Produced water **will not** be used during any part of the plugging operation.
9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
11. Class 'C' cement will be used above 7500 feet.
12. Class 'H' cement will be used below 7500 feet.
13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.

16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).
19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
 - A) Fusselman
 - B) Devonian
 - C) Morrow
 - D) Wolfcamp
 - E) Bone Springs
 - F) Delaware
 - G) Any salt sections
 - H) Abo
 - I) Glorieta
 - J) Yates.
 - K) **Potash---** (In the R-111-P Area (Potash Mine Area), a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.
21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing

DRY HOLE MARKER REQUIREMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:


1. Operator name 2. Lease and Well Number 3. API Number 4. Unit Letter 5. Quarter Section (feet from the North, South, East or West) 6. Section, Township and Range 7. Plugging Date 8. County (SPECIAL CASES)-----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

Siegenthaler IS 1 Current

Sec-TWN-RNG: Sec. 21-17S-26E API: 30-15-22329
 FOOTAGES: 1980' FSL & 660' FEL GL: 3362
 KB:



CASING DETAIL										
#	HOLE SIZE	SIZE	WGHT	GRADE	Top	Bottom	Sx Cmt	Circ/TOC	TOC Method	
A	17 1/2	13 3/8	61	K-55	0	460	340	Circ		
B	12 1/4	9 5/8	32.3	J-55	0	1,420	1025	Circ		
C	7 7/8	5 1/2	15.5/17	K-55/N-80	0	8,647	335	TOC @ 7014	TS	
Prod Casing:		1968' 17# 5687' 15.5# 276' 17# Total 8647'								

FORMATION TOPS					
	Formation	Top		Formation	Top
	San Andres	970			
	Glorieta	2350			
	Abo	4398			
	Canyon	7394			
	Strawn	7844			
	Atoka	8182			
	Morrow	8401			
	Chester	8625			

TUBING DETAIL									
#	Joints	Description	Length	OD	ID	Grade	Wt (lb/ft):	Top (ftKB):	Btm (ftKB):
		2-3/8" Tubing							8,140

Packer @ 8140

Perforation Detail					
	Formation	Top	Bottom	Treatment	
A	Morrow	8,404	8,430	Natural	
B	Atoka	8,194	8,298	Natural	
C					
D					
E					

PBTD: 8,607 MD
 TD: 8,670 MD

Prepared by: Naomi F 5/27/21

Siegenthaler IS 1 Proposed		Sec-TWN-RNG: Sec. 21-17S-26E	API: 30-15-22329									
		FOOTAGES: 1980' FSL & 660' FEL	GL: 3362									
			KB:									
Plug 9: Surface plug		CASING DETAIL										
Plug 8: Casing shoe		#	HOLE SIZE	SIZE	WGHT	GRADE	Top	Bottom	Sx Cmt	Circ/TOC	TOC Method	
Plug 7: San Andres top		A	17 1/2	13 3/8	61	K-55	0	460	340	Circ		
Plug 6: Casing Shoe		B	12 1/4	9 5/8	32.3	J-55	0	1,420	1025	Circ		
Plug 5: Glorieta top		C	7 7/8	5 1/2	15.5/17	K-55/N-80	0	8,647	335	TOC @ 7014	TS	
Plug 4: Abo top		Prod Casing:		1968' 17# 5687' 15.5# 276' 17# Total 8647'								
Plug 3: Canyon top + TOC plug		FORMATION TOPS		Formation	Top	Formation	Top					
Plug 2: CIBP + Atoka perms + Atoka top + Strawn top				San Andres	970							
Plug 1: CIBP + Morrow perms + Chester top + Morrow top				Glorieta	2350							
			Abo	4398								
			Canyon	7394								
			Strawn	7844								
			Atoka	8182								
			Morrow	8401								
			Chester	8625								
			TUBING DETAIL									
			#	Joints	Description	Length	OD	ID	Grade	Wt (lb/ft):	Top (ftKB):	Btm (ftKB):
					2-3/8" Tubing	.						8,140
			NOTES									
			Packer @ 8140									
			PLUGS									
			#	SX	Class	Top	Bottom	Δ	Notes	Tag		
			1	12	H	8249	8354	105	CIBP + Morrow perms + Chester top + Morrow top	Y		
			2	40	H	7791	8144	353	CIBP + Atoka perms + Atoka top + Strawn top	Y		
			3	60	C	6963	7444	481	Canyon top + TOC plug	Y		
			4	25	C	4258	4448	190	Abo top	Y		
			5	25	C	2210	2400	190	Glorieta top	Y		
			6	32	C	1347	1470	123	Casing shoe	Y		
			7	35	C	918	1020	102	San Andres top	Y		
			8	35	C	408	510	102	Casing shoe	Y		
			8	18	C	0	50	50	Surface plug	Y		
			Perforation Detail									
			Formation	Top	Bottom	Treatment						
			A	Morrow	8,404	8,430	Natural					
			B	Atoka	8,194	8,298	Natural					
			C									
			Prepared by: Naomi F 5/27/21									
			PBTD: 8,607 MD									
			TD: 8,670 MD									

District I
 1625 N. French Dr., Hobbs, NM 88240
 Phone:(575) 393-6161 Fax:(575) 393-0720

District II
 811 S. First St., Artesia, NM 88210
 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
 1220 S. St Francis Dr., Santa Fe, NM 87505
 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS
 Action 29841

CONDITIONS

Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702	OGRID: 7377
	Action Number: 29841
	Action Type: [C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By	Condition	Condition Date
gcordero	None	6/3/2021