Office			State of New Mex			Form C-103
District I - (575) 393	3-6161	Energy, N	linerals and Natur	al Resources		Revised July 18, 2013
1625 N. French Dr.,	Hobbs, NM 88240				WELL API NO	
<u>District II</u> – (575) 744 811 S. First St., Artes		OIL CO	NSERVATION	DIVISION	5 To 4 ¹ or 1	<u>30-025-12270</u>
<u>District III</u> – (505) 33	i St., Aitesia, Nivi 88210		cis Dr.	5. Indicate Type of Lease STATE FEE X		
	io Brazos Rd., Aztec, NM 87410 Sonto Eo. NM 87505			505	6. State Oil & Gas Lease No.	
District IV - (505) 476-3460 Salita Fe, 1NIVI 67505 220 S. St. Francis Dr., Santa Fe, NM Salita Fe, 1NIVI 67505						
87505					313857	
(DO NOT USE THE			ORTS ON WELLS r to deepen or plue	G ΒΑCΚ ΤΟ Α	7. Lease Name	e or Unit Agreement Name
			AIT" (FORM C-101) FOR		WEST DOLLAR	HIDE QUEEN SANDS UNIT
PROPOSALS.)			Other INJECTIO	N	8. Well Numb	
 Type of Well: Name of Oper 			Juner HUJLCHO	11	9. OGRID Nu	21
2. Traine of Oper	RAM EN	NERGY LLC				309777
3. Address of Op	perator				10. Pool name	or Wildcat
	-	JITE #175, TU	JLSA, OK 74114		18	3810
4. Well Location					-	
Unit Let		<u>990</u> feet f	from the <u>W</u>	line and	330 feet :	from the <u>S</u> line
Section			nship 24S Rar		NMPM	County LEA
			(Show whether DR, 1			
		l i	3141 KB		<i>`</i>	
of starting	any proposed wo completion or rec MIRU P&A OVER EXI 35 FT CM CIBP @ 13	ork). SEE RULE ompletion. A UNIT. POO STING PERF I PLUG. SET 20 W/ 35 FT (2 19.15.7.14 NMAC. 9H W/ EXISTINC S @ 3666 - 3827. 2ND CIBP @ 276 CMT PLUG ON	For Multiple Co G STRING. RU PU WORKST 50 & SPOT 35 CIBP. PERF A	EWL & SET C RING & SPOT FT CMT PLUC T 520 & CIRC	, G on Cibp. set 3rd
13. Describe of starting proposed4" diame	any proposed wo completion or rec MIRU P&A OVER EXI 35 FT CM CIBP @ 13	ork). SEE RULE ompletion. A UNIT. POO STING PERF F PLUG. SET 20 W/ 35 FT C ONS TO P&A	2 19.15.7.14 NMAC. 9H W/ EXISTINC S @ 3666 - 3827. 2ND CIBP @ 276 CMT PLUG ON WELL WILL BE	ertinent details, an For Multiple Co G STRING. RU PU WORKST 50 & SPOT 35 CIBP. PERF A GIN IMMED	TEWL & SET (RING & SPOT FT CMT PLUC T 520 & CIRC ATELY FOLL	ch wellbore diagram of CIBP @ 355 3600' G ON CIBP. SET 3RD CMT TO SFC. OWING APPROVAL.
13. Describe of starting proposed	g any proposed wo completion or rec MIRU P&A OVER EXI 35 FT CM CIBP @ 13 OPERATIO	ork). SEE RULE ompletion. A UNIT. POO STING PERF F PLUG. SET 20 W/ 35 FT C ONS TO P&A	2 19.15.7.14 NMAC. 9H W/ EXISTINC S @ 3666 - 3827. 2ND CIBP @ 276 CMT PLUG ON WELL WILL BE	ertinent details, an For Multiple Co G STRING. RU PU WORKST 50 & SPOT 35 CIBP. PERF A GIN IMMED	TEWL & SET (RING & SPOT FT CMT PLUC T 520 & CIRC ATELY FOLL	ch wellbore diagram of CIBP @ 355 3600' G ON CIBP. SET 3RD CMT TO SFC. OWING APPROVAL.
13. Describe of starting proposed4" diame	g any proposed wo completion or rec MIRU P&A OVER EXI 35 FT CM CIBP @ 13 OPERATIO	ork). SEE RULE ompletion. A UNIT. POO STING PERF F PLUG. SET 20 W/ 35 FT C ONS TO P&A	2 19.15.7.14 NMAC. 9H W/ EXISTINC S @ 3666 - 3827. 2ND CIBP @ 276 CMT PLUG ON WELL WILL BE	ertinent details, an For Multiple Co G STRING. RU PU WORKST 50 & SPOT 35 CIBP. PERF A GIN IMMED	TEWL & SET (RING & SPOT FT CMT PLUC T 520 & CIRC ATELY FOLL	ch wellbore diagram of CIBP @ 355 3600' G ON CIBP. SET 3RD CMT TO SFC. OWING APPROVAL.
 13. Describe of starting proposed 4" diame Spud Date: 	eter 4' tall Abov	ork). SEE RULE ompletion. A UNIT. POO STING PERF T PLUG. SET 20 W/ 35 FT C ONS TO P&A	2 19.15.7.14 NMAC. 9H W/ EXISTINC S @ 3666 - 3827. 2ND CIBP @ 276 CMT PLUG ON WELL WILL BE	ertinent details, an For Multiple Co G STRING. RU PU WORKST 50 & SPOT 35 CIBP. PERF A GGIN IMMED	SI	ch wellbore diagram of CIBP @ 355 3600' G ON CIBP. SET 3RD CMT TO SFC. OWING APPROVAL.
 13. Describe of starting proposed 4" diame Spud Date: 	eter 4' tall Abov	ork). SEE RULE ompletion. A UNIT. POO STING PERF T PLUG. SET 20 W/ 35 FT C ONS TO P&A	H W/ EXISTINC S @ 3666 - 3827. 2ND CIBP @ 276 CMT PLUG ON WELL WILL BE WELL WILL BE	ertinent details, an For Multiple Co G STRING. RU PU WORKST 50 & SPOT 35 CIBP. PERF A GGIN IMMED	SI	ch wellbore diagram of CIBP @ 355 3600' G ON CIBP. SET 3RD CMT TO SFC. OWING APPROVAL.
 13. Describe of starting proposed 4" diame Spud Date: hereby certify the 	eter 4' tall Abov	ork). SEE RULE ompletion. A UNIT. POO STING PERF T PLUG. SET 20 W/ 35 FT C ONS TO P&A	PH W/ EXISTING S @ 3666 - 3827. 2ND CIBP @ 276 CMT PLUG ON WELL WILL BE Rig Release Date	ertinent details, an For Multiple Co G STRING. RU PU WORKST 50 & SPOT 35 CIBP. PERF A GIN IMMED CGIN IMMED	TEWL & SET (RING & SPOT FT CMT PLUC T 520 & CIRC ATELY FOLL SI O	ch wellbore diagram of CIBP @ 355 3600' G ON CIBP. SET 3RD CMT TO SFC. OWING APPROVAL. EE ATTACHED CONDITION F APPROVAL
 13. Describe of starting proposed 4" diame Spud Date:	eter 4' tall Abov	ork). SEE RULE ompletion. A UNIT. POO STING PERF T PLUG. SET 20 W/ 35 FT C ONS TO P&A	PH W/ EXISTING S @ 3666 - 3827. 2ND CIBP @ 276 CMT PLUG ON WELL WILL BE Rig Release Date	ertinent details, an For Multiple Co G STRING. RU PU WORKST 50 & SPOT 35 CIBP. PERF A GGIN IMMED	TEWL & SET (RING & SPOT FT CMT PLUC T 520 & CIRC ATELY FOLL SI O	ch wellbore diagram of CIBP @ 355 3600' G ON CIBP. SET 3RD CMT TO SFC. OWING APPROVAL.
 Describe of starting proposed 4" diame Spud Date: hereby certify the SIGNATURE 	any proposed wo completion or rec MIRU P&A OVER EXI 35 FT CM CIBP @ 13 OPERATION eter 4' tall Abov at the information <u>MRP</u> e MATTHEW	ork). SEE RULE ompletion. A UNIT. POO STING PERF 7 PLUG. SET 20 W/ 35 FT C ONS TO P&A ve Ground Ma	PH W/ EXISTING S @ 3666 - 3827. 2ND CIBP @ 276 CMT PLUG ON WELL WILL BE Rig Release Date I complete to the bes 	ertinent details, an For Multiple Co G STRING. RU PU WORKST 50 & SPOT 35 CIBP. PERF A GIN IMMED CIBP. IMMED St of my knowledg	TEWL & SET (RING & SPOT FT CMT PLUC T 520 & CIRC ATELY FOLL SI O	ch wellbore diagram of CIBP @ 3550 3600' G ON CIBP. SET 3RD CMT TO SFC. OWING APPROVAL. EE ATTACHED CONDITION F APPROVAL
 13. Describe of starting proposed 4" diame pud Date:	eter 4' tall Abov	ork). SEE RULE ompletion. A UNIT. POO STING PERF 7 PLUG. SET 20 W/ 35 FT C ONS TO P&A ve Ground Ma	PH W/ EXISTING S @ 3666 - 3827. 2ND CIBP @ 276 CMT PLUG ON WELL WILL BE Rig Release Date I complete to the bes 	ertinent details, an For Multiple Co G STRING. RU PU WORKST 50 & SPOT 35 CIBP. PERF A GIN IMMED CIBP. IMMED St of my knowledg	TEWL & SET (RING & SPOT FT CMT PLUC T 520 & CIRC ATELY FOLL SI O	ch wellbore diagram of CIBP @ 350 3600' G ON CIBP. SET 3RD CMT TO SFC. OWING APPROVAL. EE ATTACHED CONDIT F APPROVAL DATE_8-31-21
 13. Describe of starting proposed 4" diame Spud Date: SIGNATURE Гуре or print name 	any proposed wo completion or rec MIRU P&A OVER EXI 35 FT CM CIBP @ 13 OPERATION eter 4' tall Abov at the information <u>MRP</u> e MATTHEW	ork). SEE RULE ompletion. A UNIT. POO STING PERF 7 PLUG. SET 20 W/ 35 FT C ONS TO P&A ve Ground Ma	PH W/ EXISTING S @ 3666 - 3827. 2ND CIBP @ 276 CMT PLUG ON WELL WILL BE Rig Release Date I complete to the bes 	ertinent details, an For Multiple Co G STRING. RU PU WORKST 50 & SPOT 35 CIBP. PERF A GIN IMMED CIBP. IMMED St of my knowledg	TEWL & SET (RING & SPOT FT CMT PLUC T 520 & CIRC ATELY FOLL SI O	ch wellbore diagram of CIBP @ 350 3600 G ON CIBP. SET 3RD CMT TO SFC. OWING APPROVAL EE ATTACHED COND F APPROVAL DATE_8-31-21

	WELLBORE DIAGRAM WEST DOLLARHIDE QUEEN SAND UNIT #21 CURRENT API: 30-025-12270	
Surface CasingSize:9-5/8"Wt.:36#Depth:312'Sxs Cmt:300Circulate:yesTOC:surfaceHole Size:12-1/4"		
Formation Tops T. Salt <u>1230'</u> B. Salt <u>2522'</u>		
Intermediate Casing Size: <u>7"</u> Wt.: <u>17#</u> Depth: <u>3671'</u> Sxs Cmt: <u>880</u> Circulate: yes TOC: <u>720'</u> Hole Size: <u>8-3/4"</u>		
Production Casing Size: <u>4-1/2"</u> Wt.: <u>10.5#</u> Depth: <u>3950'</u> Sxs Cmt: <u>460</u> Circulate: <u>yes</u>		asing Shoe 3671' 5'-3827'

<u>surface</u> <u>6-1/8"</u>

TOC:

WELLBORE DIAGRAM WEST DOLLARHIDE QUEEN SAND UNIT #21 PROPOSED API: 30-025-12270 Surface Casing 9-5/8" Size: Wt.: <u>36#</u> 312' Depth: Sxs Cmt: 300 Circulate: yes TOC: <u>surface</u> Hole Size: 12-1/4" Cement from 520' to surface 520' PERF MLF **Formation Tops** Cement Plug 35' T. Salt 1230' CMT B. Salt 2522' CIBP 1320' MLF Intermediate Casing Cement Plug 7" 35' Size: CMT Wt.: 17# 2760' Depth: <u>3671'</u> CIBP Sxs Cmt: 880 Circulate: MLF yes TOC: 720' Hole Size: 8-3/4" Cement Plug CMT 35' 3600' 3**%%%**' CIBP **Production Casing** Size: 4-1/2" PERFS 3666'-3827' Wt.: <u>10.5#</u> Depth: 3950' Sxs Cmt: 460 Circulate: yes

<u>surface</u>

6-1/8"

TOC:

CONDITIONS OF APPROVAL FOR PLUGGING AND ABANDONMENT OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office I (Hobbs) at (575)-263-6633 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down.

Company representative will be on location during plugging procedures.

1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.

2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.

3. Trucking companies being used to haul oilfield waste fluids to a disposal - commercial or private- shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.

4. Filing a subsequent C-103 will serve as notification that the well has been plugged.

5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can +be released.

6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.

7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.

8. Produced water will not be used during any part of the plugging operation.

9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.

10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.

11. Class 'C' cement will be used above 7500 feet.

12. Class 'H' cement will be used below 7500 feet.

13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged

14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.

16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set

17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.

18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).

19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.

20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops

- A) Fusselman
- B) Devonian
- C) Morrow
- D) Wolfcamp
- E) Bone Springs
- F) Delaware
- G) Any salt sections
- H) Abo
- I) Glorieta
- J) Yates.

K) Potash---(In the R-111-P Area (Potash Mine Area),

A solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.

21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing.

DRY HOLE MARKER REQ.UIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. Operator name
- 2. Lease and Well Number
- 3. API Number
- 4. Unit letter
- 5. Quarter Section (feet from the North, South, East or West)
- 6. Section, Township and Range
- 7. Plugging Date
- 8. County

SPECIAL CASES -----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

Given by Coche 2/1/2021 12:17:40	State of New Me			F	orm C-103
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natur	ral Resources	WELL API N	10.	l July 18, 2013
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION	DIVISION	5. Indicate T	30-025-12	270
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fran		S. mulcate T		X
District IV - (505) 476-3460	Santa Fe, NM 87	/505	6. State Oil &	& Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505			313857		
	ICES AND REPORTS ON WELLS		7. Lease Nar	ne or Unit Agreer	nent Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				RHIDE QUEEN SA	NDS UNIT
1. Type of Well: Oil Well 🔲 Gas Well 🗌 Other INJECTION			8. Well Number 21		
2. Name of Operator RAM E	NERGY LLC		9. OGRID N	umber 309777	
3. Address of Operator			10. Pool nam		
	UITE #175, TULSA, OK 74114	ł	1	8810	
4. Well Location Unit Letter <u>M</u> :	990 feet from the W	line and3	20 fee	t from the <u>S</u>	line
Section 30		$\underline{\qquad}$ inc and $\underline{}$ inge 38E	NMPM	County	LEA
Section 30	11. Elevation (Show whether DR,			County	LEA
	3141 KB	,,,,,			
12. Check	Appropriate Box to Indicate N	ature of Notice,	Report or Ot	her Data	
PERFORM REMEDIAL WORK	ITENTION TO: PLUG AND ABANDON X CHANGE PLANS	REMEDIAL WOR COMMENCE DRI	K [LLING OPNS.[REPORT OF ALTERING P AND A	
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL	CASING/CEMEN	I JOB [
CLOSED-LOOP SYSTEM		OTHER:			
of starting any proposed w	bleted operations. (Clearly state all pork). SEE RULE 19.15.7.14 NMAC				
proposed completion or rec MIRU P&	Completion. A UNIT. POOH W/ EXISTIN	G STRING, RU	EWL & SET	CIBP @ 3550	
	ISTING PERFS @ 3666 - 3827.			- C	
	T PLUG. SET 2ND CIBP @ 27				SET 3RD
	320 W/ 35 FT CMT PLUG ON				
_	ONS TO P&A WELL WILL B				
01 LIGHT					ROVILL.
Spud Date:	Rig Release Da	te:			
hereby certify that the information	above is true and complete to the be	est of my knowledg	e and belief.		
		ATIONS MAN	AGER	DATE 8-31-2	1
SIGNATURE <u>MRP</u>					1
	PATTERSON E-mail address				
Type or print name MATTHEW					

	WELLBORE DIAGRAM WEST DOLLARHIDE QUEEN SAND UNIT #21 CURRENT API: 30-025-12270
Surface CasingSize:9-5/8"Wt.:36#Depth:312'Sxs Cmt:300Circulate:yesTOC:surfaceHole Size:12-1/4"	
Formation Tops T. Salt <u>1230'</u> B. Salt <u>2522'</u>	
Intermediate Casing Size: 7" Wt.: 17# Depth: 3671' Sxs Cmt: 880 Circulate: yes TOC: 720' Hole Size: 8-3/4"	
Production Casing Size: 4-1/2" Wt.: 10.5# Depth: 3950' Sxs Cmt: 460 Circulate: yes	PERFS 7" Casing Shoe 3671' 3666'-3827'

<u>surface</u> <u>6-1/8"</u>

TOC:

WELLBORE DIAGRAM WEST DOLLARHIDE QUEEN SAND UNIT #21 PROPOSED API: 30-025-12270 Surface Casing 9-5/8" Size: Wt.: <u>36#</u> 312' Depth: Sxs Cmt: 300 Circulate: yes TOC: <u>surface</u> Hole Size: 12-1/4" Cement from 520' to surface 520' PERF MLF **Formation Tops** Cement Plug 35' T. Salt 1230' CMT B. Salt 2522' CIBP 1320' MLF Intermediate Casing Cement Plug 7" 35' Size: CMT Wt.: 17# 2760' Depth: <u>3671'</u> CIBP Sxs Cmt: 880 Circulate: MLF yes TOC: 720' Hole Size: 8-3/4" Cement Plug CMT 35' 3550' CIBP **Production Casing** Size: 4-1/2" PERFS 3666'-3827' Wt.: <u>10.5#</u> Depth: 3950' Sxs Cmt: 460 Circulate: yes

<u>surface</u>

6-1/8"

TOC:

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
RAM ENERGY LLC	309777
5100 East Skelly Drive	Action Number:
Tulsa, OK 74135	45851
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By	Condition	Condition Date
kfortner	See attached conditions of approval Note changes to procedure	9/3/2021

CONDITIONS

Page 9 of 9

Action 45851