	o Appropriate District:40	Dit	ate of New Me			Form C-103
<u>District I</u> – (575) 1625 N. French I	393-6161 Dr., Hobbs, NM 88240	Energy, Min	nerals and Natu	ral Resources	WELL API NO.	Revised July 18, 2013
$\frac{\text{District II}}{811 \text{ S} \text{ First St}} = (575)$	) 748-1283 Artesia, NM 88210	OIL CON	SERVATION	DIVISION	30-025-1227	
District III - (505	- (505) 334-6178 1220 South St. Francis Dr.			5. Indicate Type of STATE	Lease FEE X	
1000 Rio Brazos District IV – (505	Rd., Aztec, NM 87410	Sa	nta Fe, NM 87	7505	6. State Oil & Gas	
	is Dr., Santa Fe, NM		,		313857	
87303	SUNDRY NOT	ICES AND REPOF	RTS ON WELLS	•	7. Lease Name or U	Jnit Agreement Name
· · · · · · · · · · · · · · · · · · ·	THIS FORM FOR PROPO SERVOIR. USE "APPLIC					QUEENS SANDS UNIT
1. Type of Well: Oil Well 🔲 Gas Well 🗌 Other INJECTION			8. Well Number 12			
2. Name of C	Pperator RAM EN	ERGY LLC			9. OGRID Number	309777
3. Address of					10. Pool name or W	Vildcat
	00 S UTICA AVE	., SUITE 175, T	ULSA, OK 74	114		18810
4. Well Locat		990 feet fro	om the <u>W</u>	line and	650 feet from	the S line
Secti				ange 38E		County LEA
				, RKB, RT, GR, etc		
		3122	2 KB			
PULL OR ALT DOWNHOLE CLOSED-LOC OTHER: 13. Descri of star	COMMINGLE DP SYSTEM ibe proposed or comp ting any proposed we sed completion or rec MIRU P&A UN 3550 OVER EXI	ork). SEE RULE 1 completion. ITT. POOH W/ I	Clearly state all p 9.15.7.14 NMAC EXISTING ST @ 3659 - 3839	CASING/CEMEN OTHER: pertinent details, ar C. For Multiple Co RING. RU EWI D. PU WORKST	id give pertinent dates, ompletions: Attach we L & SET CIBP @ RING & SPOT	including estimated date llbore diagram of
		SFC. OPERATI	V/ 35 FT CMT IONS TO P&A	' PLUG ON CIE A WELL WILL I	BP. PERF AT 520 &	
	CIBP. SET 3RD CIRC CMT TO	SFC. OPERATI Y FOLLOWING	V/ 35 FT CMT IONS TO P&A G APPROVAL	' PLUG ON CIE A WELL WILL I	BP. PERF AT 520 & BEGIN	
Spud Date:	CIBP. SET 3RD CIRC CMT TO IMMEDIATELY	SFC. OPERATI Y FOLLOWING	V/ 35 FT CMT IONS TO P&A G APPROVAL	' PLUG ON CIE A WELL WILL I	BP. PERF AT 520 & BEGIN	D CONDITIONS
	CIBP. SET 3RD CIRC CMT TO IMMEDIATELY	SFC. OPERATI Y FOLLOWING	V/ 35 FT CMT ONS TO P&A G APPROVAL Marker Rig Release Da	' PLUG ON CIE A WELL WILL I	P. PERF AT 520 & BEGIN SEE ATTACHE OF APPROVAL	D CONDITIONS
Spud Date:	CIBP. SET 3RD CIRC CMT TO IMMEDIATELY 4" diameter 4' ta	SFC. OPERATI Y FOLLOWING	V/ 35 FT CMT ONS TO P&A G APPROVAL Marker Rig Release Da	PLUG ON CIE WELL WILL I	P. PERF AT 520 & BEGIN SEE ATTACHE OF APPROVAL	
hereby certify	CIBP. SET 3RD CIRC CMT TO IMMEDIATELY 4" diameter 4' ta that the information <u>MRP</u> ame <u>MATTHEW</u>	SFC. OPERATI Y FOLLOWING	V/ 35 FT CMT ONS TO P&A G APPROVAL Marker Rig Release Da complete to the ba	PLUG ON CIE WELL WILL I	BP. PERF AT 520 & BEGIN SEE ATTACHE OF APPROVAL ge and belief. NAGER DAT	

	WELLBORE DIAGRAM WEST DOLLARHIDE QUEEN SAND UNIT #12 CURRENT API: 30-025-12271
Surface CasingSize:9-5/8"Wt.:36#Depth:312'Sxs Cmt:300Circulate:yesTOC:surfaceHole Size:17-1/2"	
Formation Tops T. Salt <u>1230'</u> B. Salt <u>2522'</u>	
Intermediate Casing         Size:       7"         Wt.:       17#         Depth:       3750'         Sxs Cmt:       880         Circulate:       yes         TOC:       490'         Hole Size:       8-3/4"	
Production Casing           Size:         4-1/2"           Wt.:         10.5#           Depth:         3920'           Sxs Cmt:         460           Circulate:         yes	PERFS       7" Casing Shoe 3750'         3659'-3839'

<u>surface</u> <u>6-1/8"</u>

TOC:

WELLBORE DIAGRAM WEST DOLLARHIDE QUEEN SAND UNIT #12 PROPOSED API: 30-025-12271 Surface Casing 9-5/8" Size: Wt.: <u>36#</u> 312' Depth: Sxs Cmt: 300 Circulate: yes TOC: <u>surface</u> Hole Size: 17-1/2" Cement from 520' to surface 520' PERF MLF **Formation Tops** Cement Plug 35' T. Salt 1230' CMT B. Salt 2522' CIBP 1320' MLF Intermediate Casing Cement Plug 7" 35' Size: CMT Wt.: 17# 2760' Depth: CIBP <u>3750'</u> Sxs Cmt: 880 Circulate: MLF yes TOC: 490' Hole Size: 8-3/4" Cement Plug CMT 35' 3560' 3000' CIBP **Production Casing** Size: 4-1/2" PERFS 3659'-3839' Wt.: <u>10.5#</u> Depth: 3920' Sxs Cmt: 460 Circulate: yes

<u>surface</u>

6-1/8"

TOC:

#### CONDITIONS OF APPROVAL FOR PLUGGING AND ABANDONMENT OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office I (Hobbs) at (575)-263-6633 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down.

#### Company representative will be on location during plugging procedures.

**1.** A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.

**2.** Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.

**3.** Trucking companies being used to haul oilfield waste fluids to a disposal - commercial or private- shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.

4. Filing a subsequent C-103 will serve as notification that the well has been plugged.

**5.** A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can +be released.

**6.** If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.

7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.

8. Produced water will not be used during any part of the plugging operation.

9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.

**10.** All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.

11. Class 'C' cement will be used above 7500 feet.

12. Class 'H' cement will be used below 7500 feet.

**13.** A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged

**14.** All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.

**16.** When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set

17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.

**18.** A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).

**19.** No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.

20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops

- A) Fusselman
- B) Devonian
- C) Morrow
- D) Wolfcamp
- E) Bone Springs
- F) Delaware
- G) Any salt sections
- H) Abo
- I) Glorieta
- J) Yates.

### K) Potash---(In the R-111-P Area (Potash Mine Area),

A solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.

**21.** If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing.

# DRY HOLE MARKER REQ.UIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. Operator name
- 2. Lease and Well Number
- 3. API Number
- 4. Unit letter
- 5. Quarter Section (feet from the North, South, East or West)
- 6. Section, Township and Range
- 7. Plugging Date
- 8. County

# SPECIAL CASES -----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

# SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

Ceived by OCP: 2/1 Office	2021 12:35:40	Du	ate of New Me			Form C-1036
<u>District I</u> – (575) 393-61 1625 N. French Dr., Ho		Energy, Mi	nerals and Natu	ral Resources	WELL API NO	
<u>District II</u> – (575) 748-1 811 S. First St., Artesia,	First St., Artesia, NM 88210 OIL CONSERVATION DIVISION			30-025-1 5. Indicate Typ		
<u>District III</u> – (505) 334- 1000 Rio Brazos Rd., A	ztac NM 87/10			STATE	FEE X	
<u>District IV</u> – (505) 476- 1220 S. St. Francis Dr., 87505	3460	Sa	inta Fe, NM 87	/505	6. State Oil & 0 313857	Gas Lease No.
S		CES AND REPOR			7. Lease Name	or Unit Agreement Name
(DO NOT USE THIS F DIFFERENT RESERV PROPOSALS.)	OIR. USE "APPLIC	CATION FOR PERMIT	Г" (FORM C-101) FC	OR SUCH		IDE QUEENS SANDS UNIT
1. Type of Well: C		Gas Well 🗌 Ot	her INJECTIO	N	8. Well Numbe	12
2. Name of Operat	or RAM EN	ERGY LLC			9. OGRID Nun	<sup>nber</sup> 309777
3. Address of Oper 2100 S		., SUITE 175, T	ULSA, OK 74	114	10. Pool name	or Wildcat 18810
4. Well Location	-					0
Unit Letter				line and1		rom the $\underline{S}$ line
Section	30			ange <u>38E</u> , <i>RKB</i> , <i>RT</i> , <i>GR</i> , <i>etc</i> .	NMPM	County LEA
		3122		, KKD, KI, GK, elc.	)	
		<u> </u>				
	12. Check A	Appropriate Box	x to Indicate N	ature of Notice,	Report or Othe	er Data
NC PERFORM REMEL TEMPORARILY AE PULL OR ALTER C DOWNHOLE COM CLOSED-LOOP SY	DIAL WORK  DIAL WORK	TENTION TO PLUG AND ABA CHANGE PLAN MULTIPLE COM	NDON 🕅 S 🗌	SUB REMEDIAL WOR COMMENCE DR CASING/CEMEN		EPORT OF: ALTERING CASING P AND A
OTHER:	_			OTHER:		
of starting a		ork). SEE RULE 1				ates, including estimated date a wellbore diagram of
355 35 CII CII	50 OVER EXI FT CMT PLU BP. SET 3RD RC CMT TO	STING PERFS JG. SET 2ND C CIBP @ 1320 V	@ 3659 - 3839 CIBP @ 2760 & V/ 35 FT CMT IONS TO P&A	RING. RU EWI 9. PU WORKSTI 9 SPOT 35 FT CM 9 PLUG ON CIB 4 WELL WILL F	RING & SPOT MT PLUG ON P. PERF AT 52	
Spud Date:			Rig Release Da			
I hereby certify that	he information	above is true and c	complete to the b	est of my knowledg	ge and belief.	
SIGNATURE	MRP					DATE8-26-21
Type or print name		DATTEDSON	E mail addrag	.MPATTERSON@R	AMENERGY.NET <mark>H</mark>	PHONE: <u>918-947-6301</u>
For State Use Only	MATTHEW			5		
						DATE

	WELLBORE DIAGRAM WEST DOLLARHIDE QUEEN SAND UNIT #12 CURRENT API: 30-025-12271	
Surface CasingSize:9-5/8"Wt.:36#Depth:312'Sxs Cmt:300Circulate:yesTOC:surfaceHole Size:17-1/2"		
Formation Tops T. Salt <u>1230'</u> B. Salt <u>2522'</u>		
Intermediate Casing         Size:       7"         Wt.:       17#         Depth:       3750'         Sxs Cmt:       880         Circulate:       yes         TOC:       490'         Hole Size:       8-3/4"		
Production Casing           Size:         4-1/2"           Wt.:         10.5#           Depth:         3920'           Sxs Cmt:         460           Circulate:         yes	PERFS 3659'-3	ng Shoe 3750' 3839'

<u>surface</u> <u>6-1/8"</u>

TOC:

WELLBORE DIAGRAM WEST DOLLARHIDE QUEEN SAND UNIT #12 PROPOSED API: 30-025-12271 Surface Casing 9-5/8" Size: Wt.: <u>36#</u> 312' Depth: Sxs Cmt: 300 Circulate: yes TOC: <u>surface</u> Hole Size: 17-1/2" Cement from 520' to surface 520' PERF MLF **Formation Tops** Cement Plug 35' T. Salt 1230' CMT B. Salt 2522' CIBP 1320' MLF Intermediate Casing Cement Plug 7" 35' Size: CMT Wt.: 17# 2760' Depth: CIBP <u>3750'</u> Sxs Cmt: 880 Circulate: MLF yes TOC: 490' Hole Size: 8-3/4" Cement Plug CMT 35' 3550' CIBP **Production Casing** Size: 4-1/2" PERFS 3659'-3839' Wt.: <u>10.5#</u> Depth: 3920' Sxs Cmt: 460 Circulate: yes

<u>surface</u>

6-1/8"

TOC:

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
RAM ENERGY LLC	309777
5100 East Skelly Drive	Action Number:
Tulsa, OK 74135	45850
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

#### CONDITIONS

Created By	Condition	Condition Date
kfortner	See attached conditions of approval Note changes to procedure	9/3/2021

CONDITIONS

Page 9 of 9

Action 45850