
Office	State of New Mexico			Form C-103 <sup>1</sup>		
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources		WELL API NO.	Revised July 18, 2013		
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	0 0		30-02	25-30011		
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		5. Indicate Type of Lea			
1000 Rio Brazos Rd., Aztec, NM 87410			STATE	FEE X		
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505		6. State Oil & Gas Lea 313857	se No.		
87505	a the bebobes on the	TEX Y C				
SUNDRY NOTICE (DO NOT USE THIS FORM FOR PROPOSA	ES AND REPORTS ON W LS TO DRILL OR TO DEEPEN		7. Lease Name or Unit	Agreement Name		
DIFFERENT RESERVOIR. USE "APPLICA"	TION FOR PERMIT" (FORM C-	101) FOR SUCH	WEST DOLLARHIDE QU	JEEN SANDS UNIT		
PROPOSALS.)  1. Type of Well: Oil Well X G	as Well  Other		8. Well Number 81			
2. Name of Operator RAM ENERG	GY LLC		9. OGRID Number	9. OGRID Number 309777		
3. Address of Operator			10. Pool name or Wild			
2100 S UTICA AVE., STE	175, TULSA, OK 7411	14	18810			
4. Well Location	_		-			
Unit Letter H :		line and1				
Section 30	Township 24S	Range 38E		unty LEA		
	11. Elevation (Show wheth 3194 KB	er DR, KKB, K1, GR, etc	:.)			
			<u> </u>			
12. Check Ap	propriate Box to Indicate	ate Nature of Notice	, Report or Other Data	ì		
NOTICE OF INT	ENTION TO:	SUE	BSEQUENT REPOR	RT OF:		
	PLUG AND ABANDON X			ERING CASING		
<del></del> -	CHANGE PLANS		RILLING OPNS. P AN	ND A		
<del></del>	MULTIPLE COMPL	] CASING/CEMEN	NT JOB			
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM						
OTHER:		OTHER:				
13. Describe proposed or complet						
of starting any proposed work proposed completion or recon		NMAC. For Multiple Co	ompletions: Attach welloo	ore diagram of		
	•					
	T. POOH W/ EXISTIN		_	0		
	G PERFS @ 3704 - 3911					
	G. SET 2ND CIBP @ 2					
_	35 FT CMT PLUG ON					
OPERATIONS TO P&A WELL WILL BEGIN IMMEDIATELY FOLLOWING APPROVAL.						
4" diameter 4' tall A	bove Ground Marker					
			SEE ATTACHED CO	NDITIONS		
			OF APPROVAL			
	n: n :	-				
Spud Date:	Rig Relea	ase Date:				
I hereby certify that the information ab	ove is true and complete to	the best of my knowled	ge and belief.			
SIGNATURE MRP	TITLE	OPERATIONS MAI	NAGERDATE_	8-31-21		
Type or print name <u>MATTHEW PA</u> <b>For State Use Only</b>	ATTERSON E-mail a	ddress: "	ANIENERGI, NEI PHONE	:918-947-6301		
ADDROVED DV KAAAA	1					
APPROVED BY: Conditions of Approval (if any):	rother TITLE	Compliance Officer A	ADATE	9/7/21		

# WELLBORE DIAGRAM WEST DOLLARHIDE QUEEN SAND UNIT #081 CURRENT

API: 30-025-30011

Surface Size: Wt.: Depth: Sxs Cmt: Circulate: TOC: Hole Size:	Casing  8 5/8"  24#  431'  250  yes  surface  12-1/4"			
Formation T. Salt B. Salt	on Tops <u>1230'</u> <u>2522'</u>			
Production Size: Wt.: Depth: Sxs Cmt: Circulate: TOC: Hole Size:	on Casing 5-1/2" 15.5# 4030' 1150 yes surface 7-7/8"			
			PERFS	3704'-3911'
			I	I

### WELLBORE DIAGRAM WEST DOLLARHIDE QUEEN SAND UNIT #081 PROPOSED



### CONDITIONS OF APPROVAL FOR PLUGGING AND ABANDONMENT OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office I (Hobbs) at (575)-263-6633 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down.

#### Company representative will be on location during plugging procedures.

- **1.** A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
- **2.** Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- **3.** Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private- shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- **5.** A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can +be released.
- **6.** If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- **8.** Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- **10.** All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- **13.** A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- **14.** All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.
- **16.** When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- **18.** A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).

- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
- A) Fusselman
- B) Devonian
- C) Morrow
- D) Wolfcamp
- E) Bone Springs
- F) Delaware
- G) Any salt sections
- H) Abo
- I) Glorieta
- J) Yates.
- K) Potash---(In the R-111-P Area (Potash Mine Area),

A solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.

**21.** If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing.

### DRY HOLE MARKER REQ.UIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. Operator name
- 2. Lease and Well Number
- 3. API Number
- 4. Unit letter
- 5. Quarter Section (feet from the North, South, East or West)
- 6. Section, Township and Range
- 7. Plugging Date
- 8. County

#### SPECIAL CASES ----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

#### SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

eceined by Och Appropriate bistice 26 I	State of field file		Form C-1036 of		
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		Revised July 18, 2013 WELL API NO.		
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-025-30011		
<u>District III</u> – (505) 334-6178	1220 South St. Fran	ncis Dr.	5. Indicate Type of Lease STATE FEE X		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 87	7505	6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM 87505			313857		
SUNDRY NOTI	CES AND REPORTS ON WELLS SALS TO DRILL OR TO DEEPEN OR PLU		7. Lease Name or Unit Agreement Name		
`	CATION FOR PERMIT" (FORM C-101) FO		WEST DOLLARHIDE QUEEN SANDS UNIT		
1. Type of Well: Oil Well X	Gas Well  Other		8. Well Number 81		
2. Name of Operator RAM ENE	RGY LLC		9. OGRID Number 309777		
3. Address of Operator			10. Pool name or Wildcat		
	TE 175, TULSA, OK 74114		18810		
4. Well Location	330 feet from the E	line and 1'	700 feet from the N line		
Unit Letter H :_ Section 30		line and1'	700feet from theNline NMPM County LEA		
Section 30	11. Elevation (Show whether DR,		<b>3</b> =		
	3194 KB		,		
12 Charle	Ammonnioto Dov to Indicate N	Saturna of Notice	Dancett on Other Data		
12. Check F	Appropriate Box to Indicate N	ature of Notice,	Report or Other Data		
NOTICE OF IN			SSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON	PLUG AND ABANDON  ☐  CHANGE PLANS	REMEDIAL WOR	RK		
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	<del>_</del>		
DOWNHOLE COMMINGLE					
CLOSED-LOOP SYSTEM		OTHER:			
OTHER:  13. Describe proposed or comp	leted operations. (Clearly state all r		d give pertinent dates, including estimated date		
of starting any proposed wo	ork). SEE RULE 19.15.7.14 NMAC		mpletions: Attach wellbore diagram of		
proposed completion or rec	ompletion.				
MIRU P&A UN	NIT. POOH W/ EXISTING ST	ΓRING. RU EW	L & SET CIBP @ 3600		
	NG PERFS @ 3704 - 3911. PU		_		
	<del>-</del>		CMT PLUG ON CIBP. SET 3RD		
CIBP @ 1320 V	V/ 35 FT CMT PLUG ON CIE	BP. PERF AT 52	0 & CIRC CMT TO SFC.		
OPERATIONS	TO P&A WELL WILL BEGI	N IMMEDIATE	ELY FOLLOWING APPROVAL.		
3 15	5. 5.				
Spud Date:	Rig Release Da	ite:			
I hereby certify that the information	above is true and complete to the be	est of my knowledg	ge and belief.		
SIGNATURE MRP	TITLE OPE	RATIONS MAN	IAGER DATE 8-31-21		
Type or print name MATTHEW  For State Use Only	PATTERSON E-mail address	S. TI AT TERSONER	AMENERGY.NE <sup>T</sup> PHONE:918-947-6301		
APPROVED BY:Conditions of Approval (if any):	TITLE		DATE		
Conditions of Approval (if any):					

# WELLBORE DIAGRAM WEST DOLLARHIDE QUEEN SAND UNIT #081 CURRENT

API: 30-025-30011

		, ,, ,,	JU U_	.5 50011	
Surface Size: Wt.: Depth: Sxs Cmt: Circulate: TOC: Hole Size:	Casing  8 5/8"  24#  431'  250  yes  surface  12-1/4"				
Formation T. Salt B. Salt	on Tops <u>1230'</u> <u>2522'</u>				
Productio Size: Wt.: Depth: Sxs Cmt: Circulate: TOC: Hole Size:	n Casing 5-1/2" 15.5# 4030' 1150 yes surface 7-7/8"				
				PERFS	3704'-3911'

### WELLBORE DIAGRAM WEST DOLLARHIDE QUEEN SAND UNIT #081 PROPOSED

API: 30-025-30011 **Surface Casing** Size: 8 5/8" Wt.: <u>24#</u> 431' Depth: Sxs Cmt: <u>250</u> Circulate: yes TOC: <u>surface</u> Hole Size: Cement from 520' to surface 12-1/4" 520' PERF MLF **Formation Tops** 35' Cement Plug T. Salt 1230' CMT B. Salt <u>2522'</u> CIBP 1320' MLF **Production Casing** Cement Plug 35' Size: 5-1/2" CMT Wt.: 15.5# 2760' Depth: <u>4030'</u> CIBP Sxs Cmt: <u>1150</u> Circulate: MLF yes TOC: <u>surface</u> Hole Size: <u>7-7/8"</u> 35' Cement Plug CMT 3600' CIBP

**PERFS** 

3704'-3911'

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 45873

#### **CONDITIONS**

Operator:	OGRID:		
RAM ENERGY LLC	309777		
5100 East Skelly Drive	Action Number:		
Tulsa, OK 74135	45873		
	Action Type:		
	[C-103] NOI Plug & Abandon (C-103F)		

#### CONDITIONS

Created By	Condition	Condition Date
kfortner	See attached conditions of approval Note changes to procedure	9/7/2021