

Submit 1 Copy To Appropriate District
Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised July 18, 2013

WELL API NO. 30-025-02709	
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name State B	
8. Well Number 4	
9. OGRID Number 328992	
10. Pool name or Wildcat Townsend-Wolfcamp	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3973.7	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
Sabinal Energy Operating, LLC

3. Address of Operator
1780 Hughes Landing Blvd Ste 1200, The Woodlands, TX 77380

4. Well Location
Unit Letter J : 4610 feet from the South line and 2301 feet from the East line
Section 1 Township 16S Range 35E NMPM County Lea

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
CLOSED-LOOP SYSTEM <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 1) MIRU. Pull downhole equipment.
- 2) Set CIBP @ 10,500. Dump 20 sx cmt. Circ hole w/MLF. Pressure test casing. **25 sx Class H if pumping cement**
- 3) Spot 25 sx cmt @ 9000'. **+ Spot 25 sx 7500 Tubbs WOC & tag + 25 sx 6300 Glorietta**
- 4) Spot 25 sx cmt @ 5900'. **+ P&S 50 sx Class C 4750 WOC & tag**
- 5) Spot 25 sx cmt @ 3930 - 3830'. WOC & tag.
- 6) Spot 25 sx cmt @ 3230 - 3130'. WOC & tag.
- 7) Spot 25 sx cmt @ 1600 top of salt. WOC & tag.
- 8) Spot 25 sx cmt @ 1000 - 900'. WOC & tag.
- 9) Spot 55 sc cmt @ 513 - surface. **Casing shoe 400**
- 10) RDMO. Install P&A marker.

P&S XX

4" diameter 4' tall Above Ground Marker

Spud Date:

Rig Release Date:

SEE ATTACHED

Note changes to procedure

CONDITIONS OF APPROVAL

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Erin Mazur TITLE Sr. Reg Analyst DATE 3/3/21
Type or print name Erin Mazur E-mail address: erinm@sabinalenergy.com PHONE: 346-224-9270

APPROVED BY: Kerry Fortner TITLE Compliance Officer A DATE 3/10/22
Conditions of Approval (if any): 575-263-6633

STATE B 4 Wellbore Diagram

Created: 11/03/21 By: N. Sirgo
 Updated: By:
 Lease:
 Surf. Loc.: 4610' FSL & 2301' FEL
 Surf. Loc.: SEC 1, T-16-S, R-35-E
 Bot. Loc.:
 County: Lea St.: New Mexico
 Status: Shut In

Well #: B4 Fd./St. #:
 API 30-025-02709
 Surface Survey:
 Labor: League:
 Bottom hole Survey:
 Labor: League:
 Cost Code:

Surface Casing

Size: 13-3/8
 Wt., Grd.: 48# H-40
 Depth: 357
 Sxs Cmt: 275
 Circulate: Yes
 TOC: Surf
 Hole Size: 17-1/2

KB: 11
 DF:
 GL:
 Ini. Spud: 04/03/57
 Ini. Comp.: 06/04/57

Production Casing

Size: 8-5/8
 Wt., Grd.: 36# J-55
 Depth: 4,703
 Sxs Cmt: 2,050
 Circulate: Yes
 TOC: Surf
 Hole Size: 11
 DV Tool: N/A

History


11/1970 Csg leak: sqz'd csg leak at 5509-69
 1972 TA'd
 9/1979 Csg leak: sqz'd csg leaks at TOL @ 4728 then 5160, 5214, 5247, 6077, 6119, 6264 with total of 635 sxs cmt, bent csg at 9656, ran swedge thru bad spot

Liner

Size: 5-1/2
 Wt., Grd.: 17# N-80
 Top Liner: 4,528
 Bot Liner: 10,703
 Sxs Cmt: 200
 Circulate:
 TOC:
 Hole Size: 7-3/4
 DV Tool: N/A

Perforations

4 spf @ 10,560-80, 10,591-10,601, 14-28 (176 holes)



9/1979 Sqz'd csg leaks at 4728, 5160, 5214, 5247,

11/1970 Sqz'd csg leak at 5509-69

PBTD: 10,665
 TD: 10,703

STATE B 4 Wellbore Diagram

Created: 03/03/22 By: N. Sirgo
 Updated: By:
 Lease:
 Surf. Loc.: 4610' FSL & 2301' FEL
 Surf. Loc.: SEC 1, T-16-S, R-35-E
 Bot. Loc.:
 County: Lea St.: New Mexico
 Status: Shut In

Well #: B4 Fd./St. #:
 API 30-025-02709
 Surface Survey:
 Labor: League:
 Bottom hole Survey:
 Labor: League:
 Cost Code:

Surface Casing

Size: 13-3/8
 Wt., Grd.: 48# H-40
 Depth: 357
 Sxs Cmt: 275
 Circulate: Yes
 TOC: Surf
 Hole Size: 17-1/2

KB: 11
 DF:
 GL:
 Ini. Spud: 04/03/57
 Ini. Comp.: 06/04/57

Production Casing

Size: 8-5/8
 Wt., Grd.: 36# J-55
 Depth: 4,703
 Sxs Cmt: 2,050
 Circulate: Yes
 TOC: Surf
 Hole Size: 11
 DV Tool: N/A

Plug #6 @ 513 to surface

Plug #5 @ 900' with 25 sx cmt

Plug #4 @ 1600' with 25 sx cmt

Plug #3 @ 3230' with 25 sx cmt

Liner

Size: 5-1/2
 Wt., Grd.: 17# N-80
 Top Liner: 4,528
 Bot Liner: 10,703
 Sxs Cmt: 200
 Circulate:
 TOC:
 Hole Size: 7-3/4
 DV Tool: N/A

9/1979 Sqz'd csg leaks at 4728, 5160, 5214, 5247,

11/1970 Sqz'd csg leak at 5509-69

Plug #2 @ 5900' with 25 sx cmt


Plug #1 @ 9000' with 25 sxs cmt

Perforations

4 spf @ 10,560-80, 10,591-10,601,
 14-28 (176 holes)

History

11/1970 Csg leak: sqz'd csg leak at 5509-69
 1972 TA'd
 9/1979 Csg leak: sqz'd csg leaks at TOL @ 4728 then 5160, 5214, 5247, 6077, 6119, 6264 with total of 635 sxs cmt, bent csg at 9656, ran swedge thru bad



PBTB: 10,665
 TD: 10,703

**CONDITIONS OF APPROVAL
FOR PLUGGING AND ABANDONMENT
OCD - Southern District**

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office I (Hobbs) at (575)-263-6633 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down.

Company representative will be on location during plugging procedures.

1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
3. Trucking companies being used to haul oilfield waste fluids to a disposal - commercial or private- shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
8. Produced water will not be used during any part of the plugging operation.
9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
11. Class 'C' cement will be used above 7500 feet.
12. Class 'H' cement will be used below 7500 feet.
13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.
16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).

19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
- A) Fusselman
 - B) Devonian
 - C) Morrow
 - D) Wolfcamp
 - E) Bone Springs
 - F) Delaware
 - G) Any salt sections
 - H) Abo
 - I) Glorieta
 - J) Yates.
 - K) Potash---(In the R-111-P Area (Potash Mine Area),
A solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.
21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing.

DRY HOLE MARKER REQUIREMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

1. Operator name
2. Lease and Well Number
3. API Number
4. Unit letter
5. Quarter Section (feet from the North, South, East or West)
6. Section, Township and Range
7. Plugging Date
8. County

SPECIAL CASES -----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

Submit 1 Copy To Appropriate District Office

State of New Mexico

Form C-103

Energy, Minerals and Natural Resources

Revised July 18, 2013

District I – (575) 393-6161
 1625 N. French Dr., Hobbs, NM 88240
 District II – (575) 748-1283
 811 S. First St., Artesia, NM 88210
 District III – (505) 334-6178
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV – (505) 476-3460
 1220 S. St. Francis Dr., Santa Fe, NM 87505

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

WELL API NO.
 30-025-02709

5. Indicate Type of Lease
 STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
 Sabinal Energy Operating, LLC

3. Address of Operator
 1780 Hughes Landing Blvd Ste 1200, The Woodlands, TX 77380

7. Lease Name or Unit Agreement Name
 State B

8. Well Number 4

9. OGRID Number 328992

10. Pool name or Wildcat
 Townsend-Wolfcamp

4. Well Location

Unit Letter J : 4610 feet from the South line and 2301 feet from the East line
 Section 1 Township 16S Range 35E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
 3973.7

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
 TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
 PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
 DOWNHOLE COMMINGLE ☐
 CLOSED-LOOP SYSTEM ☐
 OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
 COMMENCE DRILLING OPNS. ☐ P AND A ☐
 CASING/CEMENT JOB ☐
 OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 1) MURU. Pull downhole equipment.
- 2) Set CIBP @ 10,500. Dump 20 sx cnt. Circ hole w/MLF. Pressure test casing.
- 3) Spot 25 sx cnt @ 9000'.
- 4) Spot 25 sx cnt @ 5900'.
- 5) Spot 25 sx cnt @ 3930 - 3830'. WOC & tag.
- 6) Spot 25 sx cnt @ 3230 - 3130'. WOC & tag.
- 7) Spot 25 sx cnt @ 1600 top of salt. WOC & tag.
- 8) Spot 25 sx cnt @ 1000 - 900'. WOC & tag.
- 9) Spot 55 sc cnt @ 513 - surface.
- 10) RDMO. Install P&A marker.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Erin Mazur

TITLE

Sr. Reg Analyst

DATE

3/3/21

Type or print name
Erin Mazur

E-mail address: erl@nm.sabinal

PHONE: 346.244.9270

For State Use Only

energy.com

APPROVED BY:

TITLE

DATE

Conditions of Approval (if any):

STATE B 4 Wellbore Diagram

Created: 11/03/21 By: N. Sirgo
 Updated: By:
 Lease:
 Surf. Loc.: 4610' FSL & 2301' FEL
 Surf. Loc.: SEC 1, T-16-S, R-35-E
 Bot. Loc.:
 County: Lea St.: New Mexico
 Status: Shut In

Well #: B4 Fd./St. #:
 API 30-025-02709
 Surface Survey:
 Labor: League:
 Bottom hole Survey:
 Labor: League:
 Cost Code:

Surface Casing

Size: 13-3/8
 Wt., Grd.: 48# H-40
 Depth: 357
 Sxs Cmt: 275
 Circulate: Yes
 TOC: Surf
 Hole Size: 17-1/2

KB: 11
 DF:
 GL:
 Ini. Spud: 04/03/57
 Ini. Comp.: 06/04/57

Production Casing

Size: 8-5/8
 Wt., Grd.: 36# J-55
 Depth: 4,703
 Sxs Cmt: 2,050
 Circulate: Yes
 TOC: Surf
 Hole Size: 11
 DV Tool: N/A

History


11/1970 Csg leak: sqz'd csg leak at 5509-69
 1972 TA'd
 9/1979 Csg leak: sqz'd csg leaks at TOL @ 4728 then 5160, 5214, 5247, 6077, 6119, 6264 with total of 635 sxs cmt, bent csg at 9656, ran swedge thru bad spot

Liner

Size: 5-1/2
 Wt., Grd.: 17# N-80
 Top Liner: 4,528
 Bot Liner: 10,703
 Sxs Cmt: 200
 Circulate:
 TOC:
 Hole Size: 7-3/4
 DV Tool: N/A

Perforations

4 spf @ 10,560-80, 10,591-10,601, 14-28 (176 holes)



9/1979 Sqz'd csg leaks at 4728, 5160, 5214, 5247,
 11/1970 Sqz'd csg leak at 5509-69

PBTD: 10,665
 TD: 10,703

STATE B 4 Wellbore Diagram

Created: 03/03/22 By: N. Sirgo
 Updated: By:
 Lease:
 Surf. Loc.: 4610' FSL & 2301' FEL
 Surf. Loc.: SEC 1, T-16-S, R-35-E
 Bot. Loc.:
 County: Lea St.: New Mexico
 Status: Shut In

Well #: B4 Fd./St. #:
 API 30-025-02709
 Surface Survey:
 Labor: League:
 Bottom hole Survey:
 Labor: League:
 Cost Code:

Surface Casing

Size: 13-3/8
 Wt., Grd.: 48# H-40
 Depth: 357
 Sxs Cmt: 275
 Circulate: Yes
 TOC: Surf
 Hole Size: 17-1/2

KB: 11
 DF:
 GL:
 Ini. Spud: 04/03/57
 Ini. Comp.: 06/04/57

Production Casing

Size: 8-5/8
 Wt., Grd.: 36# J-55
 Depth: 4,703
 Sxs Cmt: 2,050
 Circulate: Yes
 TOC: Surf
 Hole Size: 11
 DV Tool: N/A

Plug #6 @ 513 to surface

Plug #5 @ 900' with 25 sx cmt

Plug #4 @ 1600' with 25 sx cmt

Plug #3 @ 3230' with 25 sx cmt

Liner

Size: 5-1/2
 Wt., Grd.: 17# N-80
 Top Liner: 4,528
 Bot Liner: 10,703
 Sxs Cmt: 200
 Circulate:
 TOC:
 Hole Size: 7-3/4
 DV Tool: N/A

9/1979 Sqz'd csg leaks at 4728, 5160, 5214, 5247,

11/1970 Sqz'd csg leak at 5509-69

Plug #2 @ 5900' with 25 sx cmt


Plug #1 @ 9000' with 25 sxs cmt

Perforations

4 spf @ 10,560-80, 10,591-10,601,
 14-28 (176 holes)

History

11/1970 Csg leak: sqz'd csg leak at 5509-69
 1972 TA'd
 9/1979 Csg leak: sqz'd csg leaks at TOL @ 4728 then 5160, 5214, 5247, 6077, 6119, 6264 with total of 635 sxs cmt, bent csg at 9656, ran swedge thru bad



PBTD: 10,665
 TD: 10,703

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 85855

CONDITIONS

Operator: Sabinal Energy Operating, LLC 1780 HUGHES LANDING BLVD, STE THE WOODLANDS, TX 77380	OGRID: 328992
	Action Number: 85855
	Action Type: [C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By	Condition	Condition Date
kfortner	See attached conditions of approval Note changes to procedure	3/10/2022