
eiBadhhyi OGDio 402462422 (Sisit & 50) Office	State of New Me		Page 1 Form C-103
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natu	iral Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240			WELLAPI NO.
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION ;	DIVISION	30-025-11214
$\frac{\text{District III}}{\text{District III}} - (505) 334-6178$			5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE 🗖 FEE 🛛
District IV-(505) 476-3460	Santa Fe, NM 87	7505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM			
87505			
	DTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS	TO DRILL OR TO DEEPEN OR PLUG BACK TO A	A DIFFERENT	Langlie Mattix Unit
RESERVOIR USE "APPLICATION FOR PERM	IIT" (FORM C-101) FOR SUCH PROPOSALS.)		8. Well Number #13
	Gas Well 🛛 Other Injection		o. weii huilidei #13
2. Name of Operator			9. OGRID Number
Walsh & Watts Inc			24558
3. Address of Operator			10. Pool name or Wildcat
155 Walsh Drive, Aledo, TX 76008	1		Langlie Mattix; 7 RVS- QN-GB
4. Well Location			
Unit Letter I:	1650 feet from the S	line and	990 feet from the <u>E</u> line
Section 23	Township 24S Range 3'	7E NMI	PM County Lea
	11. Elevation (Show whether DR,		
	(
		REMEDIAL WOR	
	CHANGE PLANS	COMMENCE DR	ILLING OPNS. P AND A
PULL OR ALTER CASING			ILLING OPNS. P AND A
PULL OR ALTER CASING	CHANGE PLANS	COMMENCE DR	ILLING OPNS. P AND A
PULL OR ALTER CASING DOWNHOLE COMMINGLE COMMINGLE COMMINGLE CLOSED-LOOP SYSTEM OTHER:	CHANGE PLANS	COMMENCE DR CASING/CEMEN OTHER:	ILLING OPNS. P AND A
PULL OR ALTER CASING DOWNHOLE COMMINGLE COMMINGLE COMMINGLE CLOSED-LOOP SYSTEM OTHER:	CHANGE PLANS	COMMENCE DR CASING/CEMEN OTHER:	ILLING OPNS. P AND A
PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM DTHER: 13. Describe proposed or comp	CHANGE PLANS	COMMENCE DR CASING/CEMEN OTHER: pertinent details, a	ILLING OPNS. P AND A
PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM DTHER: 13. Describe proposed or comp	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all pleted work). SEE RULE 19.15.7.14 NM	COMMENCE DR CASING/CEMEN OTHER: pertinent details, a	ILLING OPNS. P AND A
PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or comp date of starting any propos	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all pleted work). SEE RULE 19.15.7.14 NM	COMMENCE DR CASING/CEMEN OTHER: pertinent details, a	ILLING OPNS. P AND A
PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or comp date of starting any propos	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all pleted work). SEE RULE 19.15.7.14 NM	COMMENCE DR CASING/CEMEN OTHER: pertinent details, a	ILLING OPNS. P AND A
PULL OR ALTER CASING DOWNHOLE COMMINGLE COMMINGLE COMMINGLE COMMINGLE CLOSED-LOOP SYSTEM DTHER: 13. Describe proposed or completion or reproposed completion of the reproposed completion or reprop	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all pleted work). SEE RULE 19.15.7.14 NM. completion.	COMMENCE DR CASING/CEMEN OTHER: pertinent details, a AC. For Multiple C	ILLING OPNS. P AND A
PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM DI OTHER: 13. Describe proposed or comp date of starting any propos proposed completion or re 1. Set 5 ½" CIBP @ 3206'	CHANGE PLANS MULTIPLE COMPL Deted operations. (Clearly state all pleted work). SEE RULE 19.15.7.14 NM. completion.	COMMENCE DR CASING/CEMEN OTHER: pertinent details, a AC. For Multiple C g. Spot 25 sx cmt (ILLING OPNS. P AND A
 PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or comp date of starting any propos proposed completion or re 1. Set 5 ½" CIBP @ 3206" 2. Perf & Sqz 50 sx cmt (a) 	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all pleted work). SEE RULE 19.15.7.14 NM. completion.	COMMENCE DR CASING/CEMEN OTHER: pertinent details, a AC. For Multiple C g. Spot 25 sx cmt (B/ Salt)	ILLING OPNS. P AND A
 PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completion or redate of starting any propose proposed completion or re 1. Set 5 ½" CIBP @ 3206" 2. Perf & Sqz 50 sx cmt @ 3. Perf & Sqz 60 sx cmt & 3.	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all) ed work). SEE RULE 19.15.7.14 NM. completion. Circ hole w/ MLF. Pressure test cs 2516-2330'. WOC & Tag (Yates & 1400-1145'. WOC & Tag (7" Shoe	COMMENCE DR CASING/CEMEN OTHER: pertinent details, a AC. For Multiple C g. Spot 25 sx cmt (B/ Salt)	ILLING OPNS. P AND A
 PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or comp date of starting any propos proposed completion or re 1. Set 5 ½" CIBP @ 3206" 2. Perf & Sqz 50 sx cmt (a) 	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all) ed work). SEE RULE 19.15.7.14 NM. completion. Circ hole w/ MLF. Pressure test cs 2516-2330'. WOC & Tag (Yates & 1400-1145'. WOC & Tag (7" Shoe	COMMENCE DR CASING/CEMEN OTHER: pertinent details, a AC. For Multiple C g. Spot 25 sx cmt (B/ Salt)	ILLING OPNS. P AND A
 PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or comp date of starting any propos proposed completion or re 1. Set 5 ½" CIBP @ 3206" 2. Perf & Sqz 50 sx cmt @ 3. Perf & Sqz 60 sx cmt @ 4. Perf & Sqz 50 sx cmt @ 	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all pleted work). SEE RULE 19.15.7.14 NM. completion. Circ hole w/ MIF. Pressure test cs 2516-2330'. WOC & Tag (Yates & 10) 1400-1145'. WOC & Tag (7" Shoe plete) 200' to surface.	COMMENCE DR CASING/CEMEN OTHER: pertinent details, a AC. For Multiple C g. Spot 25 sx cmt (B/ Salt) & T/ Salt)	ILLING OPNS. P AND A T JOB C C C C C C C C C C C C C C C C C C C
 PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or comp date of starting any propos proposed completion or re 1. Set 5 ½" CIBP @ 3206" 2. Perf & Sqz 50 sx cmt @ 3. Perf & Sqz 60 sx cmt @ 4. Perf & Sqz 50 sx cmt @ 	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all) ed work). SEE RULE 19.15.7.14 NM. completion. Circ hole w/ MLF. Pressure test cs 2516-2330'. WOC & Tag (Yates & 1400-1145'. WOC & Tag (7" Shoe	COMMENCE DR CASING/CEMEN OTHER: pertinent details, a AC. For Multiple C g. Spot 25 sx cmt (B/ Salt) & T/ Salt) SEE	ILLING OPNS. P AND A T JOB P AND A P AND A P JOB P AND A P AND A P JOB P AND A
 PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or comp date of starting any propos proposed completion or re 1. Set 5 ½" CIBP @ 3206" 2. Perf & Sqz 50 sx cmt @ 3. Perf & Sqz 60 sx cmt @ 4. Perf & Sqz 50 sx cmt @ 	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all pleted work). SEE RULE 19.15.7.14 NM. completion. Circ hole w/ MIF. Pressure test cs 2516-2330'. WOC & Tag (Yates & 10) 1400-1145'. WOC & Tag (7" Shoe plete) 200' to surface.	COMMENCE DR CASING/CEMEN OTHER: pertinent details, a AC. For Multiple C g. Spot 25 sx cmt (B/ Salt) & T/ Salt) SEE	ILLING OPNS. P AND A
 PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or comp date of starting any propos proposed completion or re 1. Set 5 ½" CIBP @ 3206" 2. Perf & Sqz 50 sx cmt @ 3. Perf & Sqz 60 sx cmt @ 4. Perf & Sqz 50 sx cmt @ 	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all pleted work). SEE RULE 19.15.7.14 NM. completion. Circ hole w/ MIF. Pressure test cs 2516-2330'. WOC & Tag (Yates & 10) 1400-1145'. WOC & Tag (7" Shoe plete) 200' to surface.	COMMENCE DR CASING/CEMEN OTHER: pertinent details, a AC. For Multiple C g. Spot 25 sx cmt (B/ Salt) & T/ Salt) SEE	ILLING OPNS. P AND A T JOB P AND A P AND A P JOB P AND A P AND A P JOB P AND A
 PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or comp date of starting any propos proposed completion or re 1. Set 5 ½" CIBP @ 3206" 2. Perf & Sqz 50 sx cmt @ 3. Perf & Sqz 50 sx cmt @ 4. Perf & Sqz 50 sx cmt @ 	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all pleted work). SEE RULE 19.15.7.14 NM. completion. Circ hole w/ MIF. Pressure test cs 2516-2330'. WOC & Tag (Yates & 10) 1400-1145'. WOC & Tag (7" Shoe plete) 200' to surface.	COMMENCE DR CASING/CEMEN OTHER: pertinent details, a AC. For Multiple C g. Spot 25 sx cmt (B/ Salt) & T/ Salt) SEE	ILLING OPNS. P AND A T JOB P AND A T JOB P AND A P A
 PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or comp date of starting any propos proposed completion or re 1. Set 5 ½" CIBP @ 3206" 2. Perf & Sqz 50 sx cmt @ 3. Perf & Sqz 50 sx cmt @ 4. Perf & Sqz 50 sx cmt @ 	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all pleted work). SEE RULE 19.15.7.14 NM. completion. Circ hole w/ MIF. Pressure test cs 2516-2330'. WOC & Tag (Yates & 10) 1400-1145'. WOC & Tag (7" Shoe plete) 200' to surface.	COMMENCE DR CASING/CEMEN OTHER: pertinent details, a AC. For Multiple C g. Spot 25 sx cmt (B/ Salt) & T/ Salt) SEE	ILLING OPNS. P AND A T JOB P AND A T JOB P AND A P A
 PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or comp date of starting any propos proposed completion or re 1. Set 5 ½" CIBP @ 3206" 2. Perf & Sqz 50 sx cmt @ 3. Perf & Sqz 50 sx cmt @ 4. Perf & Sqz 50 sx cmt @ 4" diameter 4' tall A 	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all ped work). SEE RULE 19.15.7.14 NM. completion. Circ hole w/ MIF. Pressure test cs 2516-2330'. WOC & Tag (Yates & 10) 1400-1145'. WOC & Tag (7" Shoe 200' to surface.	COMMENCE DR CASING/CEMEN OTHER: pertinent details, a AC. For Multiple C g. Spot 25 sx cmt (B/ Salt) & T/ Salt) SEE	ILLING OPNS. P AND A T JOB P AND A P AND A P JOB P AND A P AND A P JOB P AND A
 PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or comp date of starting any propos proposed completion or re 1. Set 5 ½" CIBP @ 3206" 2. Perf & Sqz 50 sx cmt @ 3. Perf & Sqz 50 sx cmt @ 4. Perf & Sqz 50 sx cmt @ 4" diameter 4' tall A 	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all pleted work). SEE RULE 19.15.7.14 NM. completion. Circ hole w/ MIF. Pressure test cs 2516-2330'. WOC & Tag (Yates & 10) 1400-1145'. WOC & Tag (7" Shoe plete) 200' to surface.	COMMENCE DR CASING/CEMEN OTHER: pertinent details, a AC. For Multiple C g. Spot 25 sx cmt (B/ Salt) & T/ Salt) SEE	ILLING OPNS. P AND A T JOB P AND A P AND A P JOB P AND A P AND A P JOB P AND A
 PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or comp date of starting any propos proposed completion or re 1. Set 5 ½" CIBP @ 3206" 2. Perf & Sqz 50 sx cmt @ 3. Perf & Sqz 50 sx cmt @ 4. Perf & Sqz 50 sx cmt @ 4" diameter 4' tall A 	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all ped work). SEE RULE 19.15.7.14 NM. completion. Circ hole w/ MIF. Pressure test cs 2516-2330'. WOC & Tag (Yates & 10) 1400-1145'. WOC & Tag (7" Shoe 200' to surface.	COMMENCE DR CASING/CEMEN OTHER: pertinent details, a AC. For Multiple C g. Spot 25 sx cmt (B/ Salt) & T/ Salt) SEE	ILLING OPNS. P AND A T JOB P AND A P AND A P JOB P AND A P AND A P JOB P AND A
PULL OR ALTER CASING DOWNHOLE COMMINGLE COMMINGLE COMMINGLE COMMINGLE CLOSED-LOOP SYSTEM DI CHER: 13. Describe proposed or complete of starting any proposed or proposed completion or resonance of starting any proposed completing and starting any proposed completion or resonance of	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all pleted work). SEE RULE 19.15.7.14 NM completion. Circ hole w/ MIF. Pressure test cs 2516-2330'. WOC & Tag (Yates & 1400-1145'. WOC & Tag (7" Shoe 200' to surface. bove Ground Marker Rig Release Date:	COMMENCE DR CASING/CEMEN OTHER: pertinent details, a AC. For Multiple C g. Spot 25 sx cmt (B/ Salt) & T/ Salt) SEE OF A	ILLING OPNS. PANDA
PULL OR ALTER CASING DOWNHOLE COMMINGLE COMMINGLE COMMINGLE COMMINGLE CLOSED-LOOP SYSTEM DI CHER: 13. Describe proposed or complete of starting any proposed or proposed completion or resonance of starting any proposed completing and starting any proposed completion or resonance of	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all ped work). SEE RULE 19.15.7.14 NM. completion. Circ hole w/ MIF. Pressure test cs 2516-2330'. WOC & Tag (Yates & 10) 1400-1145'. WOC & Tag (7" Shoe 200' to surface.	COMMENCE DR CASING/CEMEN OTHER: pertinent details, a AC. For Multiple C g. Spot 25 sx cmt (B/ Salt) & T/ Salt) SEE OF A	ILLING OPNS. PANDA
PULL OR ALTER CASING DOWNHOLE COMMINGLE COMMINGLE COMMINGLE COMMINGLE CLOSED-LOOP SYSTEM DI CHER: 13. Describe proposed or complete of starting any proposed or proposed completion or resonance of starting any proposed completing and starting any proposed completion or resonance of	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all pleted work). SEE RULE 19.15.7.14 NM completion. Circ hole w/ MIF. Pressure test cs 2516-2330'. WOC & Tag (Yates & 1400-1145'. WOC & Tag (7" Shoe 200' to surface. bove Ground Marker Rig Release Date:	COMMENCE DR CASING/CEMEN OTHER: pertinent details, a AC. For Multiple C g. Spot 25 sx cmt (B/ Salt) & T/ Salt) SEE OF A	ILLING OPNS. PANDA
PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM DI OTHER: 13. Describe proposed or comp date of starting any propose proposed completion or re 1. Set 5 ½" CIBP @ 3206" 2. Perf & Sqz 50 sx cmt @ 3. Perf & Sqz 50 sx cmt @ 4. Perf & Sqz 50 sx cmt @ 4. Perf & Sqz 50 sx cmt @ 4" diameter 4' tall A bpud Date: hereby certify that the information	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all plant operations. (Clearly state all plant operation). Completion. Circ hole w/ MIF. Pressure test cs 2516-2330'. WOC & Tag (Yates & 2) 1400-1145'. WOC & Tag (7" Shoe operation). 200' to surface. bove Ground Marker Rig Release Date: above is true and complete to the R	COMMENCE DR CASING/CEMEN OTHER: pertinent details, a AC. For Multiple C g. Spot 25 sx cmt (B/ Salt) & T/ Salt) SEE OF A	ILLING OPNS. P AND A T JOB
PULL OR ALTER CASING DOWNHOLE COMMINGLE COMMINGLE CLOSED-LOOP SYSTEM DI OTHER: 13. Describe proposed or complete of starting any propose proposed completion or re 1. Set 5 ½" CIBP @ 3206' 2. Perf & Sqz 50 sx cmt @ 3. Perf & Sqz 50 sx cmt @ 4. Perf & Sqz 50 sx cmt @ 4. Perf & Sqz 50 sx cmt @ 5. Spud Date:	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all plant operations. (Clearly state all plant operation). Completion. Circ hole w/ MIF. Pressure test cs 2516-2330'. WOC & Tag (Yates & 2) 1400-1145'. WOC & Tag (7" Shoe operation). 200' to surface. bove Ground Marker Rig Release Date: above is true and complete to the R	COMMENCE DR CASING/CEMEN OTHER: pertinent details, a AC. For Multiple C g. Spot 25 sx cmt (B/ Salt) & T/ Salt) SEE OF A	ILLING OPNS. P AND A T JOB
PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM DI OTHER: 13. Describe proposed or complete of starting any proposed completion or re 1. Set 5 ½" CIBP @ 3206 ⁷ 2. Perf & Sqz 50 sx cmt @ 3. Perf & Sqz 60 sx cmt @ 4. Perf & Sqz 50 sx cmt @ 5. Perf	CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state all plant operations. (Clearly state all plant operation). Completion. Circ hole w/ MIF. Pressure test cs 2516-2330'. WOC & Tag (Yates & 2) 1400-1145'. WOC & Tag (7" Shoe operation). 200' to surface. bove Ground Marker Rig Release Date: above is true and complete to the R	COMMENCE DR CASING/CEMEN OTHER: pertinent details, a AC. For Multiple C g. Spot 25 sx cmt (B/ Salt) & T/ Salt) SEE OF A	ILLING OPNS. P AND A T JOB

N 1 +	Compliance Officer A	4/00/00
APPROVED BY: Kerry Fortmer	TITLE Compliance Officer A	DATE 4/26/22
Conditions of Approval (if an 9):	575-263-6633	

•

,



Received by OCD: 4/20/2022 6:38:50 AM

Walsh & W			CURRE	NT		Descriptio	O.D.	Grade Wei	ght De	epth	Hole	Cmt Sx	TOC
Author:	Abby @ BCM					Surface Cs	g 7	23	# 1.	,350	8 1/4	75	
Vell Name	Langlie Mattix	Well No.		#13									
	LM; 7 RVS-QN-GB	API #:		25-11214	75	Prod Csg	5 1/2	17	# 3,	,256	7	100	
County	Lea	Location:		T24S, R3						and the local data in the local data	1		
State Spud Date	NM	GL:	1650 FS	L & 990 F	EL								
Spuu Dale		GL.		in the second								Formation	Тор
												T/Salt	1195
!	11 1	11										B/Salt	2380
1												Rust	1047
												Salado	1113 2466
		1 N										Yates Glorieta	4870
												Blinebry	5312
												Tubb	5815
												Drinkard	5971
			7 23#	CSG @	1,350							Abo	6334
			Hole Size:	8 1/4								Devonian	7169
												Fusselmen	8583 8868
1												Montoya Simpson	9290
4		N										McKee	9668
												Joins	10145
$\sum_{i=1}^{n}$												Ellenburger	10234
			5 1/2 17# Hole Size:	CSG @ 7	3,256								
	TD @ 3540											32.200 -103.128	

.

CONDITIONS OF APPROVAL FOR PLUGGING AND ABANDONMENT OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office I (Hobbs) at (575)-263-6633 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down.

Company representative will be on location during plugging procedures.

1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.

2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.

3. Trucking companies being used to haul oilfield waste fluids to a disposal - commercial or private- shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.

4. Filing a subsequent C-103 will serve as notification that the well has been plugged.

5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can +be released.

6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.

7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.

8. Produced water will not be used during any part of the plugging operation.

9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.

10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.

11. Class 'C' cement will be used above 7500 feet.

12. Class 'H' cement will be used below 7500 feet.

13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged

14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.

16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set

17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.

18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).

19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.

20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops

- A) Fusselman
- B) Devonian
- C) Morrow
- D) Wolfcamp
- E) Bone Springs
- F) Delaware
- G) Any salt sections
- H) Abo
- I) Glorieta
- J) Yates.

K) Potash---(In the R-111-P Area (Potash Mine Area),

A solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.

21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing.

DRY HOLE MARKER REQ.UIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. Operator name
- 2. Lease and Well Number
- 3. API Number
- 4. Unit letter
- 5. Quarter Section (feet from the North, South, East or West)
- 6. Section, Township and Range
- 7. Plugging Date
- 8. County

SPECIAL CASES -----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS


In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)


SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

Received by OCD: 4/20/2022 6:38:50 AM

TOC

Тор





District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

COMMENTS

Operator:	OGRID:
WALSH & WATTS INC	24558
155 Walsh Drive	Action Number:
Aledo, TX 76008	100063
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)
COMMENTS	

Created By		Comment Date
plmartinez	DATA ENTRY PM	4/29/2022

Page 8 of 9

Action 100063

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:			
WALSH & WATTS INC	24558			
155 Walsh Drive	Action Number:			
Aledo, TX 76008	100063			
	Action Type:			
	[C-103] NOI Plug & Abandon (C-103F)			
	-			

CONDITIONS

Created By	Condition	Condition Date
kfortner	See attached conditions of approval	4/26/2022

Page 9 of 9

Action 100063