
ecestle in the Copy Po Appropriate District 2 AM	State of New Mexico	Form 6-103 of 16
Office <u>District I</u> – (575) 393-6161 Energy	y, Minerals and Natural Resource	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL (	CONSERVATION DIVISION	30-025-37161
off S. Hist St., Artesia, NW 60210	220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE FEE S
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Salita Fe, INIVI 8/303	6. State Oil & Gas Lease No.
87505		
SUNDRY NOTICES AND R	EPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL		W H TURNER
DIFFERENT RESERVOIR. USE "APPLICATION FOR PIPEOPOSALS.)	ERMIT" (FORM C-101) FOR SUCH	
1. Type of Well: Oil Well Gas Well	Other	8. Well Number 3
2. Name of Operator	_ Other	9. OGRID Number
CONTANGO RESOURC	ES. INC	7. COMB Number
3. Address of Operator		10. Pool name or Wildcat
	E 2900, HOUSTON, TX 77002	TUBB; BLINEBRY; PADDOCK
4. Well Location		
	t from the <u>SOUTH</u> line and	2,270 feet from the <u>WEST</u> line
	wnship 21S Range 37E on (Show whether DR, RKB, RT, GR	7
	on (Snow wneiner DK, KKB, K1, GK 3,483' GR	a, etc.)
	5,465 GK	
10 01 1 4	D ( I I' ( N) ( CN)	
12. Check Appropriate	Box to Indicate Nature of No	tice, Report or Other Data
NOTICE OF INTENTION	TO:	SUBSEQUENT REPORT OF:
	ABANDON   REMEDIAL	
TEMPORARILY ABANDON CHANGE F		E DRILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE		
DOWNHOLE COMMINGLE	COMIL D CASING/CL	WIENT JOB
CLOSED-LOOP SYSTEM  OTHER:	□ OTHER:	П
		ls, and give pertinent dates, including estimated date
		e Completions: Attach wellbore diagram of
proposed completion or recompletion.	Note changes to pr	•
	5 .	
Description of Procedure:		
1. Notify OCD 24 hours prior to MIRU to P&A.D	rill out existing plug ,Set CIBP w/35' ceme	nt 6126 Şet CIBP w/35' cement
5516 Set CIBP w/35' cement 5050 Run CBL 5050 to s	urface	
2. Tag TOC @ +/-4,965'. Pressure test csg to 500	psi for 30 mins. Run CBL from +/-4	9,965' to surface.
3. Circulate well w/ water-based mud.		
4. Spot 25 sxs Class C cmt @ 3,775' - 3,905' (Sa		
5. Spot 25 sxs Class C cmt @ 3,227' - 3,357' (Qu		
6. Spot 35 sxs Class C cmt @ 2,595' – 2,898' (Ya	tes & Seven Rivers). WOC. Tag TO	C.
7. Perf @ +/-1,267', Circ/sqz 50 sxs Class C cmt (	<b>&gt;</b> • • • • • • • • • • • • • • • • • • •	Csg Shoe). WOC. Tag TOC.
8. Perf @ +/-200', Circ/sqz 50 sxs Class C cmt @ 9. Cut off wellhead, verify cmt to surface, weld or		
•	•	
LPC Area Below ground marker send p	ics before backfilling hole	SEE ATTACHED CONDITIONS
	7	OF APPROVAL
Spud Date:		
Spud Date.	Rig Release Date:	
Spud Date.	Rig Release Date:	
Spud Date.	Rig Release Date:	
		wledge and belief.
I hereby certify that the information above is true		wledge and belief.
	and complete to the best of my know	
		wledge and belief.  DATE  2/28/23
I hereby certify that the information above is true  SIGNATURE	and complete to the best of my know	DATE 2/28/23
I hereby certify that the information above is true  SIGNATURE  Type or print name Kristy Polk	and complete to the best of my know	2/28/23
I hereby certify that the information above is true  SIGNATURE	and complete to the best of my know	DATE 2/28/23
I hereby certify that the information above is true  SIGNATURE  Type or print name Kristy Polk  For State Use Only	and complete to the best of my know  TITLE Reg Analyst  E-mail address: kristy.pol	DATE 2/28/23 k@contango.com PHONE: 918-748-3349
I hereby certify that the information above is true  SIGNATURE  Type or print name Kristy Polk	and complete to the best of my know	DATE 2/28/23 k@contango.com PHONE: 918-748-3349



## CONDITIONS FOR PLUGGING AND ABANDONMENT

### OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office II at (575)-263-6633 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down. Company representative will be on location during plugging procedures.

- 1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
- 2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- 3. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- 5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
- 6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- 8. Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- 10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- 13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- 14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.

- 16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- 18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).
- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
  - A) Fusselman
  - B) Devonian
  - C) Morrow
  - D) Wolfcamp
  - E) Bone Springs
  - F) Delaware
  - G) Any salt sections
  - H) Abo
  - 1) Glorieta
  - J) Yates.
  - K) Cherry Canyon Eddy County
  - L) Potash---(In the R-111-P Area (Page 3 & 4), a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.
- 21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing

## **DRY HOLE MARKER REQUIRMENTS**

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

1. Operator name 2. Lease and Well Number 3.API Number 4. Unit Letter 5. Quarter Section (feet from the North, South, East or West) 6. Section, Township and Range 7. Plugging Date 8. County (SPECIAL CASES)------AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

## R-111-P Area

#### T 18S - R 30E

Sec 10 Unit P. Sec 11 Unit M,N. Sec 13 Unit L,M,N. Sec 14 Unit C -P. Sec 15 Unit A G,H,I,J,K,N,O,P. Sec 22 Unit All except for M. Sec 23, Sec 24 Unit C,D,E,L, Sec 26 Unit A-G, Sec 27 Unit A,B,C

### T 19S - R 29E

Sec 11 Unit P. Sec 12 Unit H-P. Sec 13. Sec 14 Unit A,B,F-P. Sec 15 Unit P. Sec 22 Unit A,B,C,F,G,H,I,J K,N,O,P. Sec 23. Sec 24. Sec 25 Unit D. Sec 26 Unit A-F. Sec 27 Unit A,B,C,F,G,H.

#### T 19S - R 30E

Sec 2 Unit K,L,M,N. Sec 3 Unit I,L,M,N,O,P. Sec 4 Unit C,D,E,F,G,I-P. Sec 5 Unit A,B,C,E-P. Sec 6 Unit I,O,P. Sec 7 – Sec 10. Sec 11 Unit D, G—P. Sec 12 Unit A,B,E-P. Sec 13 Unit A-O. Sec 14-Sec 18. Sec 19 Unit A-L, P. Sec 20 – Sec 23. Sec 24 Unit C,D,E,F,L,M,N. Sec 25 Unit D. Sec 26 Unit A-G, I-P. Sec 27, Sec 28, Sec 29 Unit A,B,C,D,F,G,H,I,J,O,P. Sec 32 Unit A,B,G,H,I,J,N,O,P. Sec 33. Sec 34. Sec 35. Sec 36 Unit D,E,F,I-P.

## T 19S - R 31E

Sec 7 Unit C,D,E,F,L. Sec 18 Unit C,D,E,F,G,K,L. Sec 31 Unit M. Sec 34 Unit P. Sec 35 Unit M,N,O. Sec 36 Unit O,P.

#### T 20S - R 29E

Sec 1 Unit H,I,P. Sec 13 Unit E,L,M,N. Sec 14 Unit B-P. Sec 15 Unit A,H,I,J,N,O,P. Sec 22 Unit A,B,C,F,G,H,I,J,O,P. Sec 23. Sec 24 Unit C,D,E,F,G,J-P. Sec 25 Unit A-O. Sec 26. Sec 27 Unit A,B,G,H,I,J,O,P. Sec 34 Unit A,B,G,H. Sec 35 Unit A-H. Sec 36 Unit B-G.

## T 20S - R 30E

Sec 1 – Sec 4. Sec 5 Unit A,B,C,E-P. Sec 6 Unit E,G-P. Sec 7 Unit A-H,I,J,O,P. Sec 8 – 17. Sec 18 Unit A,B,G,H,I,J,O,P. Sec 19 Unit A,B,G,H,I,J,O,P. Sec 30 Unit A-L,N,O,P. Sec 31 Unit A,B,G,H,I,P. Sec 32 – Sec 36.

## T 20S - R 31E

Sec 1 Unit A,B,C,E-P. Sec 2. Sec 3 Unit A,B,G,H,I,J,O,P. Sec 6 Unit D,E,F,J-P. Sec 7. Sec 8 Unit E-P. Sec 9 Unit E,F,J-P. Sec 10 Unit A,B,G-P. Sec 11 – Sec 36.

## T 21S - R 29E

Sec 1 – Sec 3. Sec 4 Unit L1 – L16,I,J,K,O,P. Sec 5 Unit L1. Sec 10 Unit A,B,H,P. Sec 11 – Sec 14. Sec 15 Unit A,H,I. Sec 23 Unit A,B. Sec 24 Unit A,B,C,D,F,G,H,I,J,O,P. Sec 25 Unit A,O,P. Sec 35 Unit G,H,I,J,K,N,O,P. Sec 36 A,B,C,F – P.

### T 21S - R 30E

Sec 1 – Sec 36

## T 21S - R 31E

Sec 1 – Sec 36

## T 22S - R 28E

Sec 36 Unit A,H,I,P.

#### T 22S - R 29E

Sec 1. Sec2. Sec 3 Unit I,J,N,O,P. Sec 9 Unit G – P. Sec 10 – Sec 16. Sec 19 Unit H,I,J. Sec 20 – Sec 28. Sec 29 Unit A,B,C,D,G,H,I,J,O,P. Sec 30 Unit A. Section 31 Unit C – P. Sec 32 – Sec 36

### T 22S - R 30E

Sec 1 – Sec 36

### T 22S - R 31E

Sec 1 – Sec 11. Sec 12 Unit B,C,D,E,F,L. Sec 13 Unit E,F,K,L,M,N. Sec 14 – Sec 23. Sec 24 Unit C,D,E,F,K,L,M,N. Sec 25 Unit A,B,C,D. Sec 26 Unit A,BC,D,G,H. Sec 27 – Sec 34.

### T 23S - R 28E

Sec 1 Unit A

## T 23S - R 29E

Sec 1 – Sec 5. Sec 6 Unit A – I, N,O,P. Sec 7 Unit A,B,C,G,H,I,P. Sec 8 Unit A – L, N,O,P. Sec 9 – Sec 16. Sec 17 Unit A,B,G,H,I,P. Sec 21 – Sec 23. Sec 24 Unit A – N. Sec 25 Unit D,E,L. Sec 26. Sec 27. Sec 28 Unit A – J, N,O,P. Sec 33 Unit A,B,C. Sec 34 Unit A,B,C,D,F,G,H. Sec 35. Sec 36 Unit B,C,D,E,F,G,K,L.

## T 23S - R 30E

Sec 1 – Sec 18. Sec 19 Unit A – I,N,O,P. Sec 20, Sec 21. Sec 22 Unit A – N, P. Sec 23, Sec 24, Sec 25. Sec 26 Unit A,B,F-P. Sec 27 Unit C,D,E,I,N,O,P. Sec 28 Unit A – H, K,L,M,N. Sec 29 Unit A – J, O,P. Sec 30 Unit A,B. Sec 32 A,B. Sec 33 Unit C,D,H,I,O,P. Sec 34, Sec 35, Sec 36.

## T 23S - R 31E

Sec 2 Unit D,E,J,O. Sec 3 – Sec 7. Sec 8 Unit A – G, K – N. Sec 9 Unit A,B,C,D. Sec 10 Unit D,P. Sec 11 Unit G,H,I,J,M,N,O,P. Sec 12 Unit E,L,K,M,N. Sec 13 Unit C,D,E,F,G,J,K,L,M,N,O. Sec 14. Sec 15 Unit A,B,E – P. Sec 16 Unit I, K – P. Sec 17 Unit B,C,D,E, I – P. Sec 18 – Sec 23. Sec 24 Unit B – G, K,L,M,N. Sec 25 Unit B – G, J,K,L. Sec 26 – Sec 34. Sec 35 Unit C,D,E.

### T 24S – R 29E

Sec 2 Unit A, B, C, D. Sec 3 Unit A

#### T 24S - R 30E

Sec 1 Unit A – H, J – N. Sec 2, Sec 3. Sec 4 Unit A,B,F – K, M,N,O,P. Sec 9 Unit A – L. Sec 10 Unit A – L, O,P. Sec 11. Sec 12 Unit D,E,L. Sec 14 Unit B – G. Sec 15 Unit A,B,G,H.

#### T 24S - R 31E

Sec 3 Unit B – G, J – O. Sec 4. Sec 5 Unit A – L, P. Sec 6 Unit A – L. Sec 9 Unit A – J, O,P. Sec 10 Unit B – G, K – N. Sec 35 Unit E – P. Sec 36 Unit E,K,L,M,N.

## T 25S - R 31E


Sec 1 Unit C,D,E,F. Sec 2 Unit A – H.

Plugging Plan WH Turner 3, 30-025-37161 Contango Resources, Inc. OGRID #330447


Notify OCD 24 hours prior to MIRU & PA.

## Description of Procedure:

- 1. Notify OCD 24 hours prior to MIRU to P&A.
- 2. Tag TOC @  $\pm$ 4,965'. Pressure test csg to 500 psi for 30 mins. Run CBL from  $\pm$ 4,965' to surface.
- 3. Circulate well w/ water-based mud.
- 4. Spot 25 sxs Class C cmt @ 3,775' 3,905' (San Andres). WOC. Tag TOC.
- 5. Spot 25 sxs Class C cmt @ 3,227' 3,357' (Queen). WOC. Tag TOC.
- 6. Spot 35 sxs Class C cmt @ 2,595' 2,898' (Yates & Seven Rivers). WOC. Tag TOC.
- 7. Perf @ +/-1,267', Circ/sqz 50 sxs Class C cmt @ 1,060' 1,267' (Anhydrite & Surf Csg Shoe). WOC. Tag TOC.
- 8. Perf @+/-200', Circ/sqz 50 sxs Class C cmt @ surface -200'.
- 9. Cut off wellhead, verify cmt to surface, weld on dry hole marker.



eceived by OCP: 3/2/2023 7:15:42 Office	AM State of New Mexico	Form C-103 of 16
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283		WELL API NO. 30-025-37161
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE S
District IV – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
SUNDRY NOT (DO NOT USE THIS FORM FOR PROPO	CICES AND REPORTS ON WELLS DISALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DISALS TO PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name W H TURNER
PROPOSALS.)  1. Type of Well: Oil Well	Gas Well Other	8. Well Number 3
2. Name of Operator		9. OGRID Number
3. Address of Operator	GO RESOURCES, INC	10. Pool name or Wildcat
	S AVE, SUITE 2900, HOUSTON, TX 77002	TUBB; BLINEBRY; PADDOCK
4. Well Location		
Unit Letter K:	2,310 feet from the SOUTH line and	2,270 feet from the WEST line
Section 29	Township 21S Range 37E	
Section 29	11. Elevation (Show whether DR, RKB, RT, GR,	5
	3,483' GR	eic.)
12. Check	Appropriate Box to Indicate Nature of Notice	ce. Report or Other Data
		•
		JBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK		<del>_</del>
TEMPORARILY ABANDON		DRILLING OPNS. P AND A
PULL OR ALTER CASING		ENT JOB
DOWNHOLE COMMINGLE		
CLOSED-LOOP SYSTEM  OTHER:	I	
	pleted operations. (Clearly state all pertinent details,	and give pertinent dates, including estimated date
of starting any proposed w	vork). SEE RULE 19.15.7.14 NMAC. For Multiple	Completions: Attach wellbore diagram of
proposed completion or re-		
Description of Procedure:	IDII 4- De A D III 4 de la CACADO 1051	CIAC C. CURR. 1951
5516 Set CIBP w/35' cement 5050 Ru	IRU to P&A.Drill out existing plug, Set CIBP w/35' cement up CBL 5050 to surface	6126 Şet CIBP w/35' cement
	test csg to 500 psi for 30 mins. Run CBL from +/-4,9	
		065' to surface
3. Circulate well w/ water-based mu		965' to surface.
3. Circulate well w/ water-based mu 4. Spot 25 sxs Class C cmt @ 3,775	ud.	965' to surface.
4. Spot 25 sxs Class C cmt @ 3,775 5. Spot 25 sxs Class C cmt @ 3,227	ud. 5' – 3,905' (San Andres). WOC. Tag TOC. 7' – 3,357' (Queen). WOC. Tag TOC.	
4. Spot 25 sxs Class C cmt @ 3,775 5. Spot 25 sxs Class C cmt @ 3,227 6. Spot 35 sxs Class C cmt @ 2,595	ud. 5' – 3,905' (San Andres). WOC. Tag TOC. 7' – 3,357' (Queen). WOC. Tag TOC. 5' – 2,898' (Yates & Seven Rivers). WOC. Tag TOC	
4. Spot 25 sxs Class C cmt @ 3,775 5. Spot 25 sxs Class C cmt @ 3,227 6. Spot 35 sxs Class C cmt @ 2,595 7. Perf @ +/-1,267', Circ/sqz 50 sxs	ud. 5' – 3,905' (San Andres). WOC. Tag TOC. 7' – 3,357' (Queen). WOC. Tag TOC. 5' – 2,898' (Yates & Seven Rivers). WOC. Tag TOC. 5 Class C cmt @ 1,060' - 1,267' (Anhydrite & Surf Cs	
4. Spot 25 sxs Class C cmt @ 3,775 5. Spot 25 sxs Class C cmt @ 3,227 6. Spot 35 sxs Class C cmt @ 2,595 7. Perf @ +/-1,267', Circ/sqz 50 sxs 8. Perf @ +/-200', Circ/sqz 50 sxs C	ud. 5' – 3,905' (San Andres). WOC. Tag TOC. 7' – 3,357' (Queen). WOC. Tag TOC. 5' – 2,898' (Yates & Seven Rivers). WOC. Tag TOC. 6 Class C cmt @ 1,060' - 1,267' (Anhydrite & Surf Collass C cmt @ surface – 200'.	
4. Spot 25 sxs Class C cmt @ 3,775 5. Spot 25 sxs Class C cmt @ 3,227 6. Spot 35 sxs Class C cmt @ 2,595 7. Perf @ +/-1,267', Circ/sqz 50 sxs	ud. 5' – 3,905' (San Andres). WOC. Tag TOC. 7' – 3,357' (Queen). WOC. Tag TOC. 5' – 2,898' (Yates & Seven Rivers). WOC. Tag TOC. 6 Class C cmt @ 1,060' - 1,267' (Anhydrite & Surf Collass C cmt @ surface – 200'.	
4. Spot 25 sxs Class C cmt @ 3,775 5. Spot 25 sxs Class C cmt @ 3,227 6. Spot 35 sxs Class C cmt @ 2,595 7. Perf @ +/-1,267', Circ/sqz 50 sxs 8. Perf @ +/-200', Circ/sqz 50 sxs O 9. Cut off wellhead, verify cmt to st	ud. 5' – 3,905' (San Andres). WOC. Tag TOC. 7' – 3,357' (Queen). WOC. Tag TOC. 5' – 2,898' (Yates & Seven Rivers). WOC. Tag TOC. 6 Class C cmt @ 1,060' - 1,267' (Anhydrite & Surf Collass C cmt @ surface – 200'.	sg Shoe). WOC. Tag TOC.  SEE ATTACHED CONDITIONS
4. Spot 25 sxs Class C cmt @ 3,775 5. Spot 25 sxs Class C cmt @ 3,227 6. Spot 35 sxs Class C cmt @ 2,595 7. Perf @ +/-1,267', Circ/sqz 50 sxs 8. Perf @ +/-200', Circ/sqz 50 sxs O 9. Cut off wellhead, verify cmt to st	ud.  5' – 3,905' (San Andres). WOC. Tag TOC.  7' – 3,357' (Queen). WOC. Tag TOC.  5' – 2,898' (Yates & Seven Rivers). WOC. Tag TOC.  5 Class C cmt @ 1,060' - 1,267' (Anhydrite & Surf Court Cou	sg Shoe). WOC. Tag TOC.
4. Spot 25 sxs Class C cmt @ 3,775 5. Spot 25 sxs Class C cmt @ 3,227 6. Spot 35 sxs Class C cmt @ 2,595 7. Perf @ +/-1,267', Circ/sqz 50 sxs 8. Perf @ +/-200', Circ/sqz 50 sxs O 9. Cut off wellhead, verify cmt to st	ud.  5' – 3,905' (San Andres). WOC. Tag TOC.  7' – 3,357' (Queen). WOC. Tag TOC.  5' – 2,898' (Yates & Seven Rivers). WOC. Tag TOC.  5 Class C cmt @ 1,060' - 1,267' (Anhydrite & Surf Court Cou	sg Shoe). WOC. Tag TOC.  SEE ATTACHED CONDITIONS
4. Spot 25 sxs Class C cmt @ 3,775 5. Spot 25 sxs Class C cmt @ 3,227 6. Spot 35 sxs Class C cmt @ 2,595 7. Perf @ +/-1,267', Circ/sqz 50 sxs 8. Perf @ +/-200', Circ/sqz 50 sxs O 9. Cut off wellhead, verify cmt to st  LPC Area Below ground ma	ud.  3' – 3,905' (San Andres). WOC. Tag TOC.  3' – 3,357' (Queen). WOC. Tag TOC.  5' – 2,898' (Yates & Seven Rivers). WOC. Tag TOC.  5 Class C cmt @ 1,060' - 1,267' (Anhydrite & Surf Cs.  Class C cmt @ surface – 200'.  1 urface, weld on dry hole marker.  1 urker send pics before backfilling hole	sg Shoe). WOC. Tag TOC.  SEE ATTACHED CONDITIONS
4. Spot 25 sxs Class C cmt @ 3,775 5. Spot 25 sxs Class C cmt @ 3,227 6. Spot 35 sxs Class C cmt @ 2,595 7. Perf @ +/-1,267', Circ/sqz 50 sxs 8. Perf @ +/-200', Circ/sqz 50 sxs O 9. Cut off wellhead, verify cmt to st  LPC Area Below ground ma	ud.  3' – 3,905' (San Andres). WOC. Tag TOC.  3' – 3,357' (Queen). WOC. Tag TOC.  5' – 2,898' (Yates & Seven Rivers). WOC. Tag TOC.  5 Class C cmt @ 1,060' - 1,267' (Anhydrite & Surf Cs.  Class C cmt @ surface – 200'.  1 urface, weld on dry hole marker.  1 urker send pics before backfilling hole	sg Shoe). WOC. Tag TOC.  SEE ATTACHED CONDITIONS
4. Spot 25 sxs Class C cmt @ 3,775 5. Spot 25 sxs Class C cmt @ 3,227 6. Spot 35 sxs Class C cmt @ 2,595 7. Perf @ +/-1,267', Circ/sqz 50 sxs 8. Perf @ +/-200', Circ/sqz 50 sxs C 9. Cut off wellhead, verify cmt to st  LPC Area Below ground ma  Spud Date:	ud.  3' – 3,905' (San Andres). WOC. Tag TOC.  3' – 3,357' (Queen). WOC. Tag TOC.  5' – 2,898' (Yates & Seven Rivers). WOC. Tag TOC.  5 Class C cmt @ 1,060' - 1,267' (Anhydrite & Surf Cs.  Class C cmt @ surface – 200'.  1 urface, weld on dry hole marker.  1 urker send pics before backfilling hole	sg Shoe). WOC. Tag TOC.  SEE ATTACHED CONDITIONS  OF APPROVAL
4. Spot 25 sxs Class C cmt @ 3,775 5. Spot 25 sxs Class C cmt @ 3,227 6. Spot 35 sxs Class C cmt @ 2,595 7. Perf @ +/-1,267', Circ/sqz 50 sxs 8. Perf @ +/-200', Circ/sqz 50 sxs C 9. Cut off wellhead, verify cmt to st  LPC Area Below ground ma  Spud Date:	ud. 5' – 3,905' (San Andres). WOC. Tag TOC. 7' – 3,357' (Queen). WOC. Tag TOC. 5' – 2,898' (Yates & Seven Rivers). WOC. Tag TOC. 5 Class C cmt @ 1,060' - 1,267' (Anhydrite & Surf Cs Class C cmt @ surface – 200'. urface, weld on dry hole marker.  Irker send pics before backfilling hole  Rig Release Date:	sg Shoe). WOC. Tag TOC.  SEE ATTACHED CONDITIONS  OF APPROVAL
4. Spot 25 sxs Class C cmt @ 3,775 5. Spot 25 sxs Class C cmt @ 3,227 6. Spot 35 sxs Class C cmt @ 2,595 7. Perf @ +/-1,267', Circ/sqz 50 sxs 8. Perf @ +/-200', Circ/sqz 50 sxs O 9. Cut off wellhead, verify cmt to so  LPC Area Below ground ma  Spud Date:	ud. 5' – 3,905' (San Andres). WOC. Tag TOC. 7' – 3,357' (Queen). WOC. Tag TOC. 5' – 2,898' (Yates & Seven Rivers). WOC. Tag TOC. 5 Class C cmt @ 1,060' - 1,267' (Anhydrite & Surf Cs Class C cmt @ surface – 200'. urface, weld on dry hole marker.  arker send pics before backfilling hole  Rig Release Date:	SEE ATTACHED CONDITIONS OF APPROVAL edge and belief.
4. Spot 25 sxs Class C cmt @ 3,775 5. Spot 25 sxs Class C cmt @ 3,227 6. Spot 35 sxs Class C cmt @ 2,595 7. Perf @ +/-1,267', Circ/sqz 50 sxs 8. Perf @ +/-200', Circ/sqz 50 sxs C 9. Cut off wellhead, verify cmt to st  LPC Area Below ground ma  Spud Date:	ud. 5' – 3,905' (San Andres). WOC. Tag TOC. 7' – 3,357' (Queen). WOC. Tag TOC. 5' – 2,898' (Yates & Seven Rivers). WOC. Tag TOC. 5 Class C cmt @ 1,060' - 1,267' (Anhydrite & Surf Cs Class C cmt @ surface – 200'. urface, weld on dry hole marker.  Irker send pics before backfilling hole  Rig Release Date:	sg Shoe). WOC. Tag TOC.  SEE ATTACHED CONDITIONS  OF APPROVAL
4. Spot 25 sxs Class C cmt @ 3,775 5. Spot 25 sxs Class C cmt @ 3,227 6. Spot 35 sxs Class C cmt @ 2,595 7. Perf @ +/-1,267', Circ/sqz 50 sxs 8. Perf @ +/-200', Circ/sqz 50 sxs C 9. Cut off wellhead, verify cmt to su  LPC Area Below ground ma  Spud Date:  I hereby certify that the information  SIGNATURE	ud. 5' - 3,905' (San Andres). WOC. Tag TOC. 7' - 3,357' (Queen). WOC. Tag TOC. 5' - 2,898' (Yates & Seven Rivers). WOC. Tag TOC. 6 Class C cmt @ 1,060' - 1,267' (Anhydrite & Surf Collass C cmt @ surface - 200'. 1 urface, weld on dry hole marker.  1 arker send pics before backfilling hole  Rig Release Date:  1 above is true and complete to the best of my knowledge.  TITLE Reg Analyst	SEE ATTACHED CONDITIONS OF APPROVAL edge and belief.  DATE 2/28/23
4. Spot 25 sxs Class C cmt @ 3,775 5. Spot 25 sxs Class C cmt @ 3,227 6. Spot 35 sxs Class C cmt @ 2,595 7. Perf @ +/-1,267', Circ/sqz 50 sxs 8. Perf @ +/-200', Circ/sqz 50 sxs C 9. Cut off wellhead, verify cmt to su  LPC Area Below ground ma  Spud Date:  I hereby certify that the information  SIGNATURE  Type or print name Kristy Polk	ud. 5' - 3,905' (San Andres). WOC. Tag TOC. 7' - 3,357' (Queen). WOC. Tag TOC. 5' - 2,898' (Yates & Seven Rivers). WOC. Tag TOC. 6 Class C cmt @ 1,060' - 1,267' (Anhydrite & Surf Collass C cmt @ surface - 200'. 1 urface, weld on dry hole marker.  1 arker send pics before backfilling hole  Rig Release Date:  1 above is true and complete to the best of my knowledge.  TITLE Reg Analyst	SEE ATTACHED CONDITIONS OF APPROVAL edge and belief.
4. Spot 25 sxs Class C cmt @ 3,775 5. Spot 25 sxs Class C cmt @ 3,227 6. Spot 35 sxs Class C cmt @ 2,595 7. Perf @ +/-1,267', Circ/sqz 50 sxs 8. Perf @ +/-200', Circ/sqz 50 sxs C 9. Cut off wellhead, verify cmt to st  LPC Area Below ground ma  Spud Date:  I hereby certify that the information  SIGNATURE  Type or print name Kristy Polk  For State Use Only	aud. 5' - 3,905' (San Andres). WOC. Tag TOC. 7' - 3,357' (Queen). WOC. Tag TOC. 6' - 2,898' (Yates & Seven Rivers). WOC. Tag TOC. 6 Class C cmt @ 1,060' - 1,267' (Anhydrite & Surf Cs. Class C cmt @ surface - 200'. aurface, weld on dry hole marker.  arker send pics before backfilling hole  Rig Release Date:  TITLE Reg Analyst  E-mail address: kristy.polk()	SEE ATTACHED CONDITIONS OF APPROVAL  edge and belief.  DATE  2/28/23  @contango.com PHONE: 918-748-3349
4. Spot 25 sxs Class C cmt @ 3,775 5. Spot 25 sxs Class C cmt @ 3,227 6. Spot 35 sxs Class C cmt @ 2,595 7. Perf @ +/-1,267', Circ/sqz 50 sxs 8. Perf @ +/-200', Circ/sqz 50 sxs C 9. Cut off wellhead, verify cmt to st  LPC Area Below ground ma  Spud Date:  I hereby certify that the information  SIGNATURE  Type or print name Kristy Polk  For State Use Only	ud. 5' - 3,905' (San Andres). WOC. Tag TOC. 7' - 3,357' (Queen). WOC. Tag TOC. 5' - 2,898' (Yates & Seven Rivers). WOC. Tag TOC. 6 Class C cmt @ 1,060' - 1,267' (Anhydrite & Surf Collass C cmt @ surface - 200'. 1 urface, weld on dry hole marker.  1 arker send pics before backfilling hole  Rig Release Date:  1 above is true and complete to the best of my knowledge.  TITLE Reg Analyst	SEE ATTACHED CONDITIONS OF APPROVAL  edge and belief.  DATE 2/28/23  @contango.com PHONE: 918-748-3349



## CONDITIONS FOR PLUGGING AND ABANDONMENT

#### OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office II at (575)-263-6633 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down. Company representative will be on location during plugging procedures.

- 1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
- 2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- 3. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- 5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
- 6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- 8. Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- 10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- 13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- 14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.

- 16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- 18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).
- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
  - A) Fusselman
  - B) Devonian
  - C) Morrow
  - D) Wolfcamp
  - E) Bone Springs
  - F) Delaware
  - G) Any salt sections
  - H) Abo
  - 1) Glorieta
  - J) Yates.
  - K) Cherry Canyon Eddy County
  - L) Potash---(In the R-111-P Area (Page 3 & 4), a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.
- 21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing

## **DRY HOLE MARKER REQUIRMENTS**

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

1. Operator name 2. Lease and Well Number 3.API Number 4. Unit Letter 5. Quarter Section (feet from the North, South, East or West) 6. Section, Township and Range 7. Plugging Date 8. County (SPECIAL CASES)------AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

## R-111-P Area

#### T 18S - R 30E

Sec 10 Unit P. Sec 11 Unit M,N. Sec 13 Unit L,M,N. Sec 14 Unit C -P. Sec 15 Unit A G,H,I,J,K,N,O,P. Sec 22 Unit All except for M. Sec 23, Sec 24 Unit C,D,E,L, Sec 26 Unit A-G, Sec 27 Unit A,B,C

### T 19S - R 29E

Sec 11 Unit P. Sec 12 Unit H-P. Sec 13. Sec 14 Unit A,B,F-P. Sec 15 Unit P. Sec 22 Unit A,B,C,F,G,H,I,J K,N,O,P. Sec 23. Sec 24. Sec 25 Unit D. Sec 26 Unit A-F. Sec 27 Unit A,B,C,F,G,H.

#### T 19S - R 30E

Sec 2 Unit K,L,M,N. Sec 3 Unit I,L,M,N,O,P. Sec 4 Unit C,D,E,F,G,I-P. Sec 5 Unit A,B,C,E-P. Sec 6 Unit I,O,P. Sec 7 – Sec 10. Sec 11 Unit D, G—P. Sec 12 Unit A,B,E-P. Sec 13 Unit A-O. Sec 14-Sec 18. Sec 19 Unit A-L, P. Sec 20 – Sec 23. Sec 24 Unit C,D,E,F,L,M,N. Sec 25 Unit D. Sec 26 Unit A-G, I-P. Sec 27, Sec 28, Sec 29 Unit A,B,C,D,F,G,H,I,J,O,P. Sec 32 Unit A,B,G,H,I,J,N,O,P. Sec 33. Sec 34. Sec 35. Sec 36 Unit D,E,F,I-P.

## T 19S - R 31E

Sec 7 Unit C,D,E,F,L. Sec 18 Unit C,D,E,F,G,K,L. Sec 31 Unit M. Sec 34 Unit P. Sec 35 Unit M,N,O. Sec 36 Unit O,P.

#### T 20S - R 29E

Sec 1 Unit H,I,P. Sec 13 Unit E,L,M,N. Sec 14 Unit B-P. Sec 15 Unit A,H,I,J,N,O,P. Sec 22 Unit A,B,C,F,G,H,I,J,O,P. Sec 23. Sec 24 Unit C,D,E,F,G,J-P. Sec 25 Unit A-O. Sec 26. Sec 27 Unit A,B,G,H,I,J,O,P. Sec 34 Unit A,B,G,H. Sec 35 Unit A-H. Sec 36 Unit B-G.

## T 20S - R 30E

Sec 1 – Sec 4. Sec 5 Unit A,B,C,E-P. Sec 6 Unit E,G-P. Sec 7 Unit A-H,I,J,O,P. Sec 8 – 17. Sec 18 Unit A,B,G,H,I,J,O,P. Sec 19 Unit A,B,G,H,I,J,O,P. Sec 30 Unit A-L,N,O,P. Sec 31 Unit A,B,G,H,I,P. Sec 32 – Sec 36.

## T 20S - R 31E

Sec 1 Unit A,B,C,E-P. Sec 2. Sec 3 Unit A,B,G,H,I,J,O,P. Sec 6 Unit D,E,F,J-P. Sec 7. Sec 8 Unit E-P. Sec 9 Unit E,F,J-P. Sec 10 Unit A,B,G-P. Sec 11 – Sec 36.

## T 21S - R 29E

Sec 1 – Sec 3. Sec 4 Unit L1 – L16,I,J,K,O,P. Sec 5 Unit L1. Sec 10 Unit A,B,H,P. Sec 11 – Sec 14. Sec 15 Unit A,H,I. Sec 23 Unit A,B. Sec 24 Unit A,B,C,D,F,G,H,I,J,O,P. Sec 25 Unit A,O,P. Sec 35 Unit G,H,I,J,K,N,O,P. Sec 36 A,B,C,F – P.

### T 21S - R 30E

Sec 1 – Sec 36

## T 21S - R 31E

Sec 1 – Sec 36

## T 22S - R 28E

Sec 36 Unit A,H,I,P.

#### T 22S - R 29E

Sec 1. Sec2. Sec 3 Unit I,J,N,O,P. Sec 9 Unit G – P. Sec 10 – Sec 16. Sec 19 Unit H,I,J. Sec 20 – Sec 28. Sec 29 Unit A,B,C,D,G,H,I,J,O,P. Sec 30 Unit A. Section 31 Unit C – P. Sec 32 – Sec 36

### T 22S - R 30E

Sec 1 – Sec 36

### T 22S - R 31E

Sec 1 – Sec 11. Sec 12 Unit B,C,D,E,F,L. Sec 13 Unit E,F,K,L,M,N. Sec 14 – Sec 23. Sec 24 Unit C,D,E,F,K,L,M,N. Sec 25 Unit A,B,C,D. Sec 26 Unit A,B,C,D,G,H. Sec 27 – Sec 34.

### T 23S - R 28E

Sec 1 Unit A

## T 23S - R 29E

Sec 1 – Sec 5. Sec 6 Unit A – I, N,O,P. Sec 7 Unit A,B,C,G,H,I,P. Sec 8 Unit A – L, N,O,P. Sec 9 – Sec 16. Sec 17 Unit A,B,G,H,I,P. Sec 21 – Sec 23. Sec 24 Unit A – N. Sec 25 Unit D,E,L. Sec 26. Sec 27. Sec 28 Unit A – J, N,O,P. Sec 33 Unit A,B,C. Sec 34 Unit A,B,C,D,F,G,H. Sec 35. Sec 36 Unit B,C,D,E,F,G,K,L.

#### T 23S - R 30E

Sec 1 – Sec 18. Sec 19 Unit A – I,N,O,P. Sec 20, Sec 21. Sec 22 Unit A – N, P. Sec 23, Sec 24, Sec 25. Sec 26 Unit A,B,F-P. Sec 27 Unit C,D,E,I,N,O,P. Sec 28 Unit A – H, K,L,M,N. Sec 29 Unit A – J, O,P. Sec 30 Unit A,B. Sec 32 A,B. Sec 33 Unit C,D,H,I,O,P. Sec 34, Sec 35, Sec 36.

## T 23S - R 31E

Sec 2 Unit D,E,J,O. Sec 3 – Sec 7. Sec 8 Unit A – G, K – N. Sec 9 Unit A,B,C,D. Sec 10 Unit D,P. Sec 11 Unit G,H,I,J,M,N,O,P. Sec 12 Unit E,L,K,M,N. Sec 13 Unit C,D,E,F,G,J,K,L,M,N,O. Sec 14. Sec 15 Unit A,B,E – P. Sec 16 Unit I, K – P. Sec 17 Unit B,C,D,E, I – P. Sec 18 – Sec 23. Sec 24 Unit B – G, K,L,M,N. Sec 25 Unit B – G, J,K,L. Sec 26 – Sec 34. Sec 35 Unit C,D,E.

### T 24S – R 29E

Sec 2 Unit A, B, C, D. Sec 3 Unit A

#### T 24S - R 30E

Sec 1 Unit A – H, J – N. Sec 2, Sec 3. Sec 4 Unit A,B,F – K, M,N,O,P. Sec 9 Unit A – L. Sec 10 Unit A – L, O,P. Sec 11. Sec 12 Unit D,E,L. Sec 14 Unit B – G. Sec 15 Unit A,B,G,H.

#### T 24S - R 31E

Sec 3 Unit B – G, J – O. Sec 4. Sec 5 Unit A – L, P. Sec 6 Unit A – L. Sec 9 Unit A – J, O,P. Sec 10 Unit B – G, K – N. Sec 35 Unit E – P. Sec 36 Unit E,K,L,M,N.

## T 25S - R 31E

Sec 1 Unit C,D,E,F. Sec 2 Unit A – H.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

COMMENTS

Action 192256

## **COMMENTS**

Operator:	OGRID:
Contango Resources, LLC	330447
111 E. 5TH STREET	Action Number:
FORT WORTH, TX 76102	192256
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

## COMMENTS

Created By		Comment Date
plmartinez	DATA ENTRY PM	3/16/2023

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

# **State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 192256

## **CONDITIONS**

Operator:	OGRID:
Contango Resources, LLC	330447
111 E. 5TH STREET	Action Number:
FORT WORTH, TX 76102	192256
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

#### CONDITIONS

Created By	Condition	Condition Date
kfortner	See attached COA Note Changes to procedure	3/15/2023