Office	2023 5:46:55 PM	State of New Mex	tico	For	rm C-103	
District I – (575) 393-6	ce Energy Minamla and Natural Decourses				uly 18, 2013	
<u>District I</u> – (575) 595- 1625 N. French Dr., He District II – (575) 748-	obbs, NM 88240			WELL API NO. 30-015-05037		
811 S. First St., Artesia	a, NM 88210	OIL CONSERVATION	5. Indicate Type of Lease STATE ☑ FEE □ 6. State Oil & Gas Lease No.			
<u>District III</u> – (505) 334 1000 Rio Brazos Rd., A		1220 South St. Francis Dr. Santa Fe, NM 87505				
District IV - (505) 476	-3460					
1220 S. St. Francis Dr. 87505	, Santa Fe, NM			B-10920		
		CES AND REPORTS ON WELLS		7. Lease Name or Unit Agreeme	ent Name	
		ALS TO DRILL OR TO DEEPEN OR PLU ATION FOR PERMIT" (FORM C-101) FOI		Featherstone CBS		
PROPOSALS.)		_		8. Well Number #2		
1. Type of Well:		Gas Well Other				
2. Name of Opera		r Operating, LLC		9. OGRID Number 371484		
3. Address of Ope		operating, EEC		10. Pool name or Wildcat		
		St., Ste 700 Plano, TX 75075		(28509) Grayburg Jackson; SR-0	QN-GB-SA	
4. Well Location						
Unit Lette	er <u> </u>	<u>2310</u> feet from the <u>North</u>	line and <u>1650</u>	feet from the <u>West</u>	line	
Section	2	Township 17S Rang	e 31E	NMPM County Edd	y y	
		11. Elevation (Show whether DR,			<u></u>	
		3990'	GL			
TEMPORARILY A PULL OR ALTER DOWNHOLE COM CLOSED-LOOP S OTHER:	CASING	CHANGE PLANS	COMMENCE DRI CASING/CEMENT OTHER: tinent details, and	□ JOB □ Notify OCD 24 hrs. prior to any work done		
of starting a proposed co L. Prep loc. MIR 2. RU Wireline, I 3. Set 5-1/2" CIE 4. 40 sx 1963' – 5. 200 sx 866' –	ny proposed work ompletion or recon RIH w/ gauge ri BP @ 3470' w/3 2063', P.S. & TA Surf, P.S. Atten). SEE RULE 19.15.7.14 NMAC. ipletion. ds and pump, laying down, Ni ng. Test csg 500psi / 30 n 35' cmt, circ w/ P&A mud, test	For Multiple Com D WH. NU BOP. hin - Run CBL to 500 psi. WC alt, T Yates ify ND BOP. <mark>Pe</mark>	pletions: Attach wellbore diagram POOH tubing, laying down. DC & TAG. rf @ 790'		
of starting a proposed co L. Prep loc. MIR 2. RU Wireline, I 3. Set 5-1/2" CIE 4. 40 sx 1963' – 5. 200 sx 866' – 5. Cut off WH 3'	ny proposed work ompletion or recon RIH w/ gauge ri 3P @ 3470' w/3 2063', P.S. & T Surf, P.S. Atten below GL. Inst). SEE RULE 19.15.7.14 NMAC. appletion. ds and pump, laying down, Ni ng. Test csg 500psi / 30 n 35' cmt, circ w/ P&A mud, test AG. Must tag at 1870' - B sa npt to circ cmt to surface. Ver	For Multiple Com D WH. NU BOP. in - Run CBL t to 500 psi. WC alt, T Yates ify ND BOP. <mark>Pe</mark> s 3' below GL. R	POOH tubing, laying down. POOH tubing, laying down. DC & TAG. rf @ 790' &D MO.		
of starting a proposed co Prep loc. MIR RU Wireline, I Set 5-1/2" CIE 4. 40 sx 1963' – 5. 200 sx 866' – 5. Cut off WH 3' spot	ny proposed work ompletion or recon RIH w/ gauge ri 3P @ 3470' w/3 2063', P.S. & T Surf, P.S. Atten below GL. Inst 25 sx @ 50' be). SEE RULE 19.15.7.14 NMAC. apletion. ds and pump, laying down, Ni ng. Test csg 500psi / 30 m 35' cmt, circ w/ P&A mud, test AG. Must tag at 1870' - B sa npt to circ cmt to surface. Ver all DHM. Cut off mast anchorse elow to 50' above TOC minimus	For Multiple Com D WH. NU BOP. to 500 psi. WC alt, T Yates ify ND BOP. Pe s 3' below GL. R n - see CBL WC	POOH tubing, laying down. POOH tubing, laying down. DC & TAG. rf @ 790' RD MO. DC & tag 9/13/11 found holes in surf	of ace casin	
of starting a proposed co Prep loc. MIR RU Wireline, I Set 5-1/2" CIE 4. 40 sx 1963' – 5. 200 sx 866' – 5. Cut off WH 3' spot	ny proposed work ompletion or recon RIH w/ gauge ri 3P @ 3470' w/3 2063', P.S. & T/ Surf, P.S. Atten below GL. Inst 25 sx @ 50' be s 2329' - 2331' (). SEE RULE 19.15.7.14 NMAC. apletion. Mg. Test csg 500psi / 30 m 35' cmt, circ w/ P&A mud, test AG. Must tag at 1870' - B sa apt to circ cmt to surface. Ver all DHM. Cut off mast anchor	For Multiple Com D WH. NU BOP. to 500 psi. WC alt, T Yates ify ND BOP. Pe s 3' below GL. R n - see CBL WC	POOH tubing, laying down. POOH tubing, laying down. DC & TAG. rf @ 790' D MO. DC & tag	of ace casin	
of starting a proposed co Prep loc. MIR RU Wireline, I Set 5-1/2" CIE 4. 40 sx 1963' – 5. 200 sx 866' – 5. Cut off WH 3' spot	ny proposed work ompletion or recon RIH w/ gauge ri 3P @ 3470' w/3 2063', P.S. & T Surf, P.S. Atten below GL. Inst 25 sx @ 50' be). SEE RULE 19.15.7.14 NMAC. apletion. ds and pump, laying down, Ni ng. Test csg 500psi / 30 m 35' cmt, circ w/ P&A mud, test AG. Must tag at 1870' - B sa npt to circ cmt to surface. Ver all DHM. Cut off mast anchorse elow to 50' above TOC minimus	For Multiple Com D WH. NU BOP. in - Run CBL to 500 psi. WC alt, T Yates ify ND BOP. Pe s 3' below GL. R n - see CBL WC 2279'	POOH tubing, laying down. POOH tubing, laying down. DC & TAG. rf @ 790' RD MO. DC & tag 9/13/11 found holes in surf	of ace casing	
of starting a proposed co Prep loc. MIR RU Wireline, I Set 5-1/2" CIE 4. 40 sx 1963' – 5. 200 sx 866' – 5. Cut off WH 3' spot	ny proposed work ompletion or recon RIH w/ gauge ri 3P @ 3470' w/3 2063', P.S. & T/ Surf, P.S. Atten below GL. Inst 25 sx @ 50' be s 2329' - 2331' (). SEE RULE 19.15.7.14 NMAC. apletion. ds and pump, laying down, Ni ng. Test csg 500psi / 30 m 35' cmt, circ w/ P&A mud, test AG. Must tag at 1870' - B st npt to circ cmt to surface. Ver all DHM. Cut off mast anchors alow to 50' above TOC minimum 10/27/59) must sqz & tag cmt of	For Multiple Com D WH. NU BOP. in - Run CBL to 500 psi. WC alt, T Yates ify ND BOP. Pe s 3' below GL. R n - see CBL WC 2279'	POOH tubing, laying down. POOH tubing, laying down. DC & TAG. rf @ 790' RD MO. DC & tag 9/13/11 found holes in surf	of ace casing	
of starting a proposed co 2. Prep loc. MIR 2. RU Wireline, I 3. Set 5-1/2" CIE 4. 40 sx 1963' – 5. 200 sx 866' – 5. Cut off WH 3' spot 5. Cut off WH 3'	ny proposed work ompletion or recon RIH w/ gauge ri 3P @ 3470' w/3 2063', P.S. & T/ Surf, P.S. Atten below GL. Inst 25 sx @ 50' be s 2329' - 2331' (). SEE RULE 19.15.7.14 NMAC. appletion. ds and pump, laying down, NI ng. Test csg 500psi / 30 m 35' cmt, circ w/ P&A mud, test AG. Must tag at 1870' - B sc npt to circ cmt to surface. Ver all DHM. Cut off mast anchors alow to 50' above TOC minimum 10/27/59) must sqz & tag cmt of Rig Release Dates	For Multiple Com D WH. NU BOP. in - Run CBL t to 500 psi. WC alt, T Yates ify ND BOP. Pe s 3' below GL. R m - see CBL WC @ 2279'	POOH tubing, laying down. POOH tubing, laying down. DC & TAG. rf @ 790' RD MO. DC & tag 9/13/11 found holes in surf	of ace casing	
of starting a proposed co L. Prep loc. MIR 2. RU Wireline, I 3. Set 5-1/2" CIE 4. 40 sx 1963' – 5. 200 sx 866' – 5. Cut off WH 3' Spot Perfs 5. Spud Date:	ny proposed work ompletion or recon RIH w/ gauge ri 3P @ 3470' w/3 2063', P.S. & T/ Surf, P.S. Atten below GL. Inst 25 sx @ 50' be s 2329' - 2331' (10/2/1959). SEE RULE 19.15.7.14 NMAC. appletion. ds and pump, laying down, NI ng. Test csg 500psi / 30 m 35' cmt, circ w/ P&A mud, test AG. Must tag at 1870' - B sc npt to circ cmt to surface. Ver all DHM. Cut off mast anchors alow to 50' above TOC minimum 10/27/59) must sqz & tag cmt of Rig Release Dates	For Multiple Com D WH. NU BOP. in - Run CBL t to 500 psi. WC alt, T Yates ify ND BOP. Pe s 3' below GL. R m - see CBL WC @ 2279' 	POOH tubing, laying down. POOH tubing, laying down. DC & TAG. rf @ 790' RD MO. DC & tag 9/13/11 found holes in surf VERIFY cmt to surface on	of ace casin	
of starting a proposed co Prep loc. MIR RU Wireline, I Set 5-1/2" CIE 4. 40 sx 1963' – 5. 200 sx 866' – 5. Cut off WH 3' Spot Perfs Spud Date: ****SEE AT hereby certify that t	ny proposed work ompletion or recon U, POOH w/ ro RIH w/ gauge ri 3P @ 3470' w/3 2063', P.S. & T, Surf, P.S. Atten below GL. Inst 25 sx @ 50' be s 2329' - 2331' (10/2/1959 TACHED COA' he information ab). SEE RULE 19.15.7.14 NMAC. npletion. ds and pump, laying down, Ni ng. Test csg 500psi / 30 m 35' cmt, circ w/ P&A mud, test AG. Must tag at 1870' - B st npt to circ cmt to surface. Ver all DHM. Cut off mast anchors elow to 50' above TOC minimum 10/27/59) must sqz & tag cmt (Rig Release Dates s**** ove is true and complete to the best	For Multiple Com D WH. NU BOP. in - Run CBL to 500 psi. WC alt, T Yates ify ND BOP. Pe s 3' below GL. R n - see CBL WC 2279' MUST BE PLL of my knowledge	POOH tubing, laying down. POOH tubing, laying down. DC & TAG. rf @ 790' D MO. DC & tag 9/13/11 found holes in surf VERIFY cmt to surface on JGGED BY 4/28/2024 and belief.	ace casing all strings	
of starting a proposed co Prep loc. MIR RU Wireline, I Set 5-1/2" CIE 4. 40 sx 1963' – 5. 200 sx 866' – 5. Cut off WH 3' Spot Perfs Spud Date: ****SEE AT hereby certify that t	ny proposed work ompletion or recon RIH w/ gauge ri 3P @ 3470' w/3 2063', P.S. & T/ Surf, P.S. Atten below GL. Inst 25 sx @ 50' be s 2329' - 2331' (10/2/1959). SEE RULE 19.15.7.14 NMAC. npletion. ds and pump, laying down, Ni ng. Test csg 500psi / 30 m 35' cmt, circ w/ P&A mud, test AG. Must tag at 1870' - B st npt to circ cmt to surface. Ver all DHM. Cut off mast anchors elow to 50' above TOC minimum 10/27/59) must sqz & tag cmt (Rig Release Dates s**** ove is true and complete to the best	For Multiple Com D WH. NU BOP. in - Run CBL t to 500 psi. WC alt, T Yates ify ND BOP. Pe s 3' below GL. R m - see CBL WC @ 2279' 	POOH tubing, laying down. POOH tubing, laying down. DC & TAG. rf @ 790' D MO. DC & tag 9/13/11 found holes in surf VERIFY cmt to surface on JGGED BY 4/28/2024 and belief.	ace casing all strings	
of starting a proposed co Prep loc. MIR RU Wireline, I Set 5-1/2" CIE 4. 40 sx 1963' – 5. 200 sx 866' – 5. Cut off WH 3' Spot Perfs Spud Date: ****SEE AT hereby certify that t	ny proposed work mpletion or recon U, POOH w/ ro RIH w/ gauge ri 3P @ 3470' w/3 2063', P.S. & T/ Surf, P.S. Atten below GL. Inst 25 sx @ 50' be s 2329' - 2331' (10/2/1959 TACHED COA' the information ab). SEE RULE 19.15.7.14 NMAC. npletion. ds and pump, laying down, Ni ng. Test csg 500psi / 30 m 35' cmt, circ w/ P&A mud, test AG. Must tag at 1870' - B sa npt to circ cmt to surface. Ver all DHM. Cut off mast anchor slow to 50' above TOC minimum 10/27/59) must sqz & tag cmt of Rig Release Dates s**** ove is true and complete to the best	For Multiple Comp D WH. NU BOP. nin - Run CBL to 500 psi. WC alt, T Yates ify ND BOP. Pe s 3' below GL. R n - see CBL WC 2279' MUST BE PLL of my knowledge _Petroleum Engin	POOH tubing, laying down. POOH tubing, laying down. DC & TAG. rf @ 790' D MO. DC & tag 9/13/11 found holes in surf VERIFY cmt to surface on JGGED BY 4/28/2024 and belief.	ace casing all strings	
of starting a proposed co Prep loc. MIR RU Wireline, I Set 5-1/2" CIE 40 sx 1963' – 200 sx 866' – 200 sx 866' – Cut off WH 3' Spot Perfs Spud Date: ****SEE AT hereby certify that the SIGNATURE	ny proposed work ompletion or recon U, POOH w/ ro RIH w/ gauge ri 3P @ 3470' w/3 2063', P.S. & T Surf, P.S. Atten below GL. Inst 25 sx @ 50' be s 2329' - 2331' (10/2/1959 TACHED COA' the information ab). SEE RULE 19.15.7.14 NMAC. npletion. ds and pump, laying down, Ni ng. Test csg 500psi / 30 m 35' cmt, circ w/ P&A mud, test AG. Must tag at 1870' - B sa npt to circ cmt to surface. Ver all DHM. Cut off mast anchor slow to 50' above TOC minimum 10/27/59) must sqz & tag cmt of Rig Release Dates s**** ove is true and complete to the best	For Multiple Com D WH. NU BOP. in - Run CBL t to 500 psi. WC alt, T Yates ify ND BOP. Pe s 3' below GL. R m - see CBL WC @ 2279' 	POOH tubing, laying down. POOH tubing, laying down. DC & TAG. rf @ 790' D MO. DC & tag 9/13/11 found holes in surf VERIFY cmt to surface on JGGED BY 4/28/2024 and belief. eerDATE4/7/202	ace casin all strings	

•

Released to Imaging: 4/28/2023 3:53:03 PM

ROVER OPERATING, LLC WELLBORE DIAGRAM Lease/Well No.: **FEATHERSTONE CBS 2** ELEVATION, GL: 3,990 ft Location: 2,310' FNL & 1,650' FWL UL: F, SEC: 2, T: 17-S, R:31-E FIELD: GRAYBURG JACKSON; SR-QN-GB-SA EDDY County, NM LEASE No.: State B-10920 Spudded: 10/2/1959 API No. : 30-015-05037 Drlg Stopped: 10/19/1959 Completed: 10/26/1959 LAT: LONG: TOPS DEPTH, ft ANHY 676' 9/13/11 found holes in surface casing 11" HOLE TOP SALT 816' VERIFY cmt to surface on all strings BASE SALT 1,920' Surface Csg: YATES 2,013' 9-5/8" 36# J-55 SEVEN RIVERS 2,230' Csg Set @ 740' 2,920' QUEEN Cmt'd w/ 300 sx 200 sx (866' - Surf) 3,196' GRAYBURG P.S. Circ to Surf SAN ANDRES 3,648' 40 sx (1963' - 2063') P.S. & TAG Must tag at 1870' - B salt, T Yates spot 25 sx @ 50' below to 50' above TOC minimum - see CBL WOC & tag Perfs 2329' - 2331' (10/27/59) must sqz & tag cmt @ 2279' Set 5-1/2" CIBP @ 3470' Test csg 500psi / 30 min - Run CBL 7-7/8" HOLE Spot 35' cmt, WOC & TAG (3470' - 3435') PERFS: 3,520-3,526' METEX 4 spf - 24 holes Ξ 3,535-3,541' METEX 4 spf - 24 holes Ξ 3,573-3,577' METEX 4 spf - 16 holes = 4 spf - 20 holes 3,608-3,613' METEX Ξ METEX 4 spf - 4 holes 3,620-3,621' = METEX 4 spf - 8 holes 3,629-3,631' Ξ 3,637-3,640' PREMIER 4 spf - 12 holes Ξ 3,642-3,646' PREMIER 4 spf - 16 holes Production Csg: 5 1/2" 15.5# J-55 3.657' PBTD Csg Set @ 3,620' 3,660' TD Cmt'd w/ 150 sx

CONDITIONS FOR PLUGGING AND ABANDONMENT

OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office II at (575)-748-1283 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down. Company representative will be on location during plugging procedures.

- 1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
- 2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- 3. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- 5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
- 6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- 8. Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- 10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- 13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- 14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.

- 16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- 18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).
- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
 - A) Fusselman
 - B) Devonian
 - C) Morrow
 - D) Wolfcamp
 - E) Bone Springs
 - F) Delaware
 - G) Any salt sections
 - H) Abo
 - I) Glorieta
 - J) Yates.
 - K) Cherry Canyon Eddy County
 - L) Potash----(In the R-111-P Area (Page 3 & 4), a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.
- 21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing

DRY HOLE MARKER REQUIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

1. Operator name2. Lease and Well Number3. API Number4. Unit Letter5. QuarterSection (feet from the North, South, East or West)6. Section, Township and Range7. Plugging Date8. County(SPECIAL CASES)------AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

R-111-P Area

T 18S – R 30E

Sec 10 Unit P. Sec 11 Unit M,N. Sec 13 Unit L,M,N. Sec 14 Unit C -P. Sec 15 Unit A G,H,I,J,K,N,O,P. Sec 22 Unit All except for M. Sec 23, Sec 24 Unit C,D,E,L, Sec 26 Unit A-G, Sec 27 Unit A,B,C

T 19S – R 29E

Sec 11 Unit P. Sec 12 Unit H-P. Sec 13. Sec 14 Unit A,B,F-P. Sec 15 Unit P. Sec 22 Unit A,B,C,F,G,H,I,J K,N,O,P. Sec 23. Sec 24. Sec 25 Unit D. Sec 26 Unit A- F. Sec 27 Unit A,B,C,F,G,H.

T 19S – R 30E

Sec 2 Unit K,L,M,N. Sec 3 Unit I,L,M,N,O,P. Sec 4 Unit C,D,E,F,G,I-P. Sec 5 Unit A,B,C,E-P. Sec 6 Unit I,O,P. Sec 7 – Sec 10. Sec 11 Unit D, G—P. Sec 12 Unit A,B,E-P. Sec 13 Unit A-O. Sec 14-Sec 18. Sec 19 Unit A-L, P. Sec 20 – Sec 23. Sec 24 Unit C,D,E,F,L,M,N. Sec 25 Unit D. Sec 26 Unit A-G, I-P. Sec 27, Sec 28, Sec 29 Unit A,B,C,D,F,G,H,I,J,O,P. Sec 32 Unit A,B,G,H,I,J,N,O,P. Sec 33. Sec 34. Sec 35. Sec 36 Unit D,E,F,I-P.

T 19S – R 31E

Sec 7 Unit C,D,E,F,L. Sec 18 Unit C,D,E,F,G,K,L. Sec 31 Unit M. Sec 34 Unit P. Sec 35 Unit M,N,O. Sec 36 Unit O,P.

T 20S – R 29E

Sec 1 Unit H,I,P. Sec 13 Unit E,L,M,N. Sec 14 Unit B-P. Sec 15 Unit A,H,I,J,N,O,P. Sec 22 Unit A,B,C,F,G,H,I,J,O,P. Sec 23. Sec 24 Unit C,D,E,F,G,J-P. Sec 25 Unit A-O. Sec 26. Sec 27 Unit A,B,G,H,I,J,O,P. Sec 34 Unit A,B,G,H. Sec 35 Unit A-H. Sec 36 Unit B-G.

T 20S – R 30E

Sec 1 – Sec 4. Sec 5 Unit A,B,C,E-P. Sec 6 Unit E,G-P. Sec 7 Unit A-H,I,J,O,P. Sec 8 – 17. Sec 18 Unit A,B,G,H,I,J,O,P. Sec 19 Unit A,B,G,H,I,J,O,P. Sec 20 – 29. Sec 30 Unit A-L,N,O,P. Sec 31 Unit A,B,G,H,I,P. Sec 32 – Sec 36.

T 20S – R 31E

Sec 1 Unit A,B,C,E-P. Sec 2. Sec 3 Unit A,B,G,H,I,J,O,P. Sec 6 Unit D,E,F,J-P. Sec 7. Sec 8 Unit E-P. Sec 9 Unit E,F,J-P. Sec 10 Unit A,B,G-P. Sec 11 – Sec 36.

T 21S – R 29E

Sec 1 – Sec 3. Sec 4 Unit L1 – L16,I,J,K,O,P. Sec 5 Unit L1. Sec 10 Unit A,B,H,P. Sec 11 – Sec 14. Sec 15 Unit A,H,I. Sec 23 Unit A,B. Sec 24 Unit A,B,C,D,F,G,H,I,J,O,P. Sec 25 Unit A,O,P. Sec 35 Unit G,H,I,J,K,N,O,P. Sec 36 A,B,C,F – P.

T 21S – R 30E

Sec 1 – Sec 36

T 21S – R 31E

Sec 1 – Sec 36

T 22S – R 28E

Sec 36 Unit A,H,I,P.

T 22S – R 29E

Sec 1. Sec2. Sec 3 Unit I,J,N,O,P. Sec 9 Unit G – P. Sec 10 – Sec 16. Sec 19 Unit H,I,J. Sec 20 – Sec 28. Sec 29 Unit A,B,C,D,G,H,I,J,O,P. Sec 30 Unit A. Section 31 Unit C – P. Sec 32 – Sec 36

T 22S – R 30E

Sec 1 – Sec 36

T 22S – R 31E

Sec 1 – Sec 11. Sec 12 Unit B,C,D,E,F,L. Sec 13 Unit E,F,K,L,M,N. Sec 14 – Sec 23. Sec 24 Unit C,D,E,F,K,L,M,N. Sec 25 Unit A,B,C,D. Sec 26 Unit A,BC,D,G,H. Sec 27 – Sec 34.

T 23S – R 28E

Sec 1 Unit A

T 23S – R 29E

Sec 1 – Sec 5. Sec 6 Unit A – I, N,O,P. Sec 7 Unit A,B,C,G,H,I,P. Sec 8 Unit A – L, N,O,P. Sec 9 – Sec 16. Sec 17 Unit A,B,G,H,I,P. Sec 21 – Sec 23. Sec 24 Unit A – N. Sec 25 Unit D,E,L. Sec 26. Sec 27. Sec 28 Unit A – J, N,O,P. Sec 33 Unit A,B,C. Sec 34 Unit A,B,C,D,F,G,H. Sec 35. Sec 36 Unit B,C,D,E,F,G,K,L.

T 23S – R 30E

Sec 1 – Sec 18. Sec 19 Unit A – I,N,O,P. Sec 20, Sec 21. Sec 22 Unit A – N, P. Sec 23, Sec 24, Sec 25. Sec 26 Unit A,B,F-P. Sec 27 Unit C,D,E,I,N,O,P. Sec 28 Unit A – H, K,L,M,N. Sec 29 Unit A – J, O,P. Sec 30 Unit A,B. Sec 32 A,B. Sec 33 Unit C,D,H,I,O,P. Sec 34, Sec 35, Sec 36.

T 23S – R 31E

Sec 2 Unit D,E,J,O. Sec 3 – Sec 7. Sec 8 Unit A – G, K – N. Sec 9 Unit A,B,C,D. Sec 10 Unit D,P. Sec 11 Unit G,H,I,J,M,N,O,P. Sec 12 Unit E,L,K,M,N. Sec 13 Unit C,D,E,F,G,J,K,L,M,N,O. Sec 14. Sec 15 Unit A,B,E – P. Sec 16 Unit I, K – P. Sec 17 Unit B,C,D,E, I – P. Sec 18 – Sec 23. Sec 24 Unit B – G, K,L,M,N. Sec 25 Unit B – G, J,K,L. Sec 26 – Sec 34. Sec 35 Unit C,D,E.

T 24S – R 29E

Sec 2 Unit A, B, C, D. Sec 3 Unit A

T 24S – R 30E

Sec 1 Unit A – H, J – N. Sec 2, Sec 3. Sec 4 Unit A,B,F – K, M,N,O,P. Sec 9 Unit A – L. Sec 10 Unit A – L, O,P. Sec 11. Sec 12 Unit D,E,L. Sec 14 Unit B – G. Sec 15 Unit A,B,G,H.

T 24S – R 31E

Sec 3 Unit B – G, J – O. Sec 4. Sec 5 Unit A – L, P. Sec 6 Unit A – L. Sec 9 Unit A – J, O,P. Sec 10 Unit B – G, K – N. Sec 35 Unit E – P. Sec 36 Unit E,K,L,M,N.

T 25S – R 31E

Sec 1 Unit C,D,E,F. Sec 2 Unit A – H.

Rover Operating, LLC WELLBORE DIAGRAM

Lease/Well No.:	FEATHERSTONE CBS 2	ELEVATION, GL	3,990	ft	
Location:	2,310' FNL & 1,650' FWL	_			
	UL: F, SEC: 2, T: 17-S, R:31-E	FIELD:	GRAYBURG JACH	(SON; SR-QN-GB-S	SA
	EDDY County, NM				
LEASE No.:	State B-10920	Spudded:	10/2/1959		
API No. :	30-015-05037	Drlg Stopped:	10/19/1959		
		Completed:	10/26/1959		
		LAT:			
		LONG:		<u>TOPS</u>	<u>DEPTH, ft</u>
				ANHY	676'
11" HOLE				TOP SALT	816'
				BASE SALT	1,920'
Surface Csg:				YATES	2,013'
9-5/8" 36# J-55				SEVEN RIVERS	2,230'
Csg Set @ 740'		Tubing Details		QUEEN	2,920'
Cmt'd w/ 300 sx		114 jts 2-3/8" tbg	Ţ	GRAYBURG	3,196'
		SN @ 3599'		SAN ANDRES	3,648'
		4' Perf sub			
		BPMJ @ 3634'			
		Rod Details			
7-7/8" HOLE		22' PR			
		4' 5/8" Subs			
		1 3/4" Rod			
		141 5/8" Rods			
		2' x 1-1/4" x 12' P	Pump		
		PERFS:			
		3,520-3,526'	METEX	4 spf - 24 holes	
		3,535-3,541'	METEX	4 spf - 24 holes	
		3,573-3,577'	METEX	4 spf - 16 holes	
		3,608-3,613'	METEX	4 spf - 20 holes	
		3,620-3,621'	METEX	4 spf - 4 holes	
	=	3,629-3,631'	METEX	4 spf - 8 holes	
		3,637-3,640'	PREMIER	4 spf - 12 holes	
	=	3,642-3,646'	PREMIER	4 spf - 16 holes	
Production Csg:		-		-	
5 1/2" 15.5# J-55		3,657' PBTD			
Csg Set @ 3,620'		3,660' TD			
Cmt'd w/ 150 sx					

.

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
ROVER OPERATING, LLC	371484
1255 W. 15th St.	Action Number:
Plano, TX 75075	205172
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By		Condition Date
gcordero	None	4/28/2023

Page 8 of 8

.

Action 205172