eived by OCD: 4/12/2023 12:37:26 Submit I Copy To Appropriate District	State of N	New Mexico)		Form C-103
Office District I - (575) 393-616l	Energy, M merals a		Resources		Rev1sed August 1, 2011
1625 N. French Dr., Hobbs, NM 88240				WELLAPINO.	
District II - (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVA	ATION DI	V 1.511 JIV	0-041-10057	0.7
District m - (505) 334-6178	1220 South	St. Francis	Dr. 5	Indicate Type	
1000 Rio Brazos Rd., Aztec, NM 87410		NM 87505		STATE X	
<u>District IV</u> - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Sulla 10,	14141 07303		. State Off & Ga	as Lease No.
	CES AND REPORTS ON			Lease Name of	r Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLIC			Y COV Y	MILNESAND SA	AN ANDRES UNIT
PROPOSALS.) 1. Type of Well: Oil Well X	Gas Well Other			Well Number 87	
2. Name of Operator				. OGRID Numb	per
EOR OPERATING COMPANY				57420	
3. Address of Operator 575 N. DAIRY ASHFORD RD., E	C II, SUITE 210, HOUST	ON, TX 7707		0. Pool name or CHA VEROO SA	
4. Well Location					
Unit Letter B	660 feet from the NOI	RTH line an	nd 1980 feet	from the EAS'	T line
Section 18	Township	08S Ra	ange 35I	E NMPM	ROOSEVELT County
	111. Elevation (Show whe	ether DR, RKE 46' - DF	B, RT, GR, etc.)		
10 01 1 4		C NT	CNI d' D	0.1	D.
12. Check A	Appropriate Box to Ind	licate Natur	e of Notice, Re	eport or Other	Data
	TENTION TO:			QUENT RE	
NOTICE OF IN					
PERFORM REMEDIAL WORK	PLUG AND ABANDON	_	MEDIAL WORK		ALTERING CASING L
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS	□ co	MMENCE DRILL	_	ALTERING CASING L
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	PLUG AND ABANDON	□ co		_	ALTERING CASING
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL	□ co	MMENCE DRILL	ов 🗆	ars. prior to any work
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL	☐ CO CA	MMENCE DRILL	ов 🗆	=1.7
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: Injection V	PLUG AND ABANDON CHANGE PLANS MULTIPLE COM PL Well leted operations. (Clearly	CO CA OT State all pertir	OMMENCE DRILLI SING/CEMENT J THER: nent details, and g	Notify OCD 24 h done	es, including estimated da
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: Injection of starting any proposed wo	PLUG AND ABANDON CHANGE PLANS MULTIPLE COM PL Well leted operations. (Clearly ork). SEE RULE 19.15.7.1	CO CA OT State all pertir	OMMENCE DRILLI SING/CEMENT J THER: nent details, and g	Notify OCD 24 h done	es, including estimated da
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: Injection V	PLUG AND ABANDON CHANGE PLANS MULTIPLE COM PL Well leted operations. (Clearly ork). SEE RULE 19.15.7.1 completion.	CC CA CA OT State all pertir 4 NMAC. For	OMMENCE DRILL SING/CEMENT J HER: nent details, and g or Multiple Comp	Notify OCD 24 h done letions: Attach v	es, including estimated dawellbore diagram of
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: Injection of starting any proposed wo proposed completion or recomposed completion or recomposed.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COM PL Well leted operations. (Clearly ork). SEE RULE 19.15.7.1 ompletion. Failed MI	CC CA OT State all pertire 4 NMAC. For CT and Failed	OMMENCE DRILLING/CEMENT JOHN THER: T	Notify OCD 24 h done live pertinent data letions: Attach v	es, including estimated day
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: Injection of starting any proposed wo proposed completion or recomposed completion or recomposed to the proposed completion or recomposed completion or recompletion or recomposed completion or recompletion or recomposed completion	PLUG AND ABANDON CHANGE PLANS MULTIPLE COM PL Well leted operations. (Clearly ork). SEE RULE 19.15.7.1 ompletion. Failed Mi " CIBP + CMT. @+/-4,44	CC CA OT State all pertir 4 NMAC. For T and Failed 12'; CIRC. W.	OMMENCE DRILL SING/CEMENT J THER: nent details, and g or Multiple Comp d BHT - Find le ELL W/ M.L.F.;	Notify OCD 24 h done ive pertinent date letions: Attach v ak before proceutions. TEST CSG	es, including estimated day. elibore diagram of eding G. TO 750# X HOLD.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: Injection of starting any proposed wo proposed completion or recomposed completion or recomposed to the proposed completion or recomposed completion or recompletion or recomposed completion or recomposed co	PLUG AND ABANDON CHANGE PLANS MULTIPLE COM PL Well leted operations. (Clearly ork). SEE RULE 19.15.7.1 ompletion. Failed MI " CIBP + CMT. @ +/-4,44 SS "C" CMT. @ 4,442'-3,	CCCCA CA OT State all pertir 4 NMAC. For T and Failed 42'; CIRC. W. 073' (TIS.A.,	OMMENCE DRILL SING/CEMENT J THER: nent details, and g or Multiple Comp d BHT - Find le ELL W/ M.L.F.; T/Y ATES, 8/SA	Notify OCD 24 h done ive pertinent date letions: Attach voor ak before proceute PRES. TEST CSG LT); WOE X TE	es, including estimated dawellbore diagram of ceding G. TO 750# X HOLD. AG TOC.
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: Injection of starting any proposed we proposed completion or recompleted to the proposed completion of starting any proposed we proposed completion or recompleted to the proposed completed to	PLUG AND ABANDON CHANGE PLANS MULTIPLE COM PL Well leted operations. (Clearly ork). SEE RULE 19.15.7.1 ompletion. Failed Mi " CIBP + CMT. @+/-4,44	CCCCCA CA CA State all pertir NMAC. For T and Failed 12'; CIRC. W. 1073' (TIS.A., CMT.@ 2,2.	OMMENCE DRILLINGING/CEMENT JOURNAL THER: Then details, and goor Multiple Comport Multiple C	Notify OCD 24 h done Ive pertinent date letions: Attach v ak before proceute press. TEST CSG LT); WOE X TAT/ANHY., 8-5/8	es, including estimated dawellbore diagram of eding G. TO 750# X HOLD. AG TOC. " CSG.SHOE
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: Injection of Starting any proposed or complete of Starting any proposed we proposed completion or recomplete of Starting and Proposed Completion or recomplete of Starting and Proposed Completion or recomplete of Starting and Proposed Completion or recomplete of Starting 2-7/8 1) TAG EXISTING 2-7/8 2) PUMP (35) SXS. CLASAND AMIX X CIRC. TO SUR ADJUG OUT X CUT OFF PLATE TO CSGS. X I	PLUG AND ABANDON CHANGE PLANS MULTIPLE COM PL Well leted operations. (Clearly ork). SEE RULE 19.15.7.1 completion. Failed MI " CIBP + CMT. @+/-4,44 SS "C" CMT. @ 4,442'-3, RF. (60) SXS. CLASS "C" WELLHEAD 3' B.G.L.; NSTALL BELOW GROU	CCCCA CA CA CA State all pertir 4 NMAC. For T and Failed 42'; CIRC. W. 073' (TIS.A., CMT.@ 2,2. VERIFY CM ND DRY HO	OMMENCE DRILLINGING/CEMENT JETHER: Thenent details, and goor Multiple Composite BHT - Find leter BLL W/ M.L.F.; T/Y ATES, 8/SA 50'-3' (T/SALT, 7T. TO SURF. ON DILE MARKER.	Notify OCD 24 h done ive pertinent date letions: Attach v ak before proceute press. TEST CSG LT); WOE X TATANHY., 8-5/8 ALL ANNULI;	es, including estimated dawellbore diagram of seding G. TO 750# X HOLD. AG TOC. " CSG.SHOE WELD ON STEEL
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE 13. Describe proposed or completion of starting any proposed wo proposed completion or recompletion or recompletion of starting and proposed wo proposed completion or recompletion or reco	PLUG AND ABANDON CHANGE PLANS MULTIPLE COM PL WEIL leted operations. (Clearly ork). SEE RULE 19.15.7.1 ompletion. Failed MI " CIBP + CMT. @+/-4,44 SS "C" CMT. @ 4,442'-3, RF. (60) SXS. CLASS "C" " WELLHEAD 3' B.G.L.; NSTALL BELOW GROUM empt to circ cmt - if no	CCCCA CA CA CA State all pertir 4 NMAC. For T and Failed 12'; CIRC. W. 1073' (TIS.A., CMT.@ 2,2.2 VERIFY CM ND DRY HO circ spot 25	OMMENCE DRILL ASING/CEMENT J THER: Thent details, and g TOTAL TOTA	Notify OCD 24 h done ive pertinent date letions: Attach v ak before proceute press. TEST CSC LT); WOE X T. T/ANHY., 8-5/8 ALL ANNULI;	es, including estimated dawellbore diagram of eding G. TO 750# X HOLD. AG TOC. " CSG.SHOE WELD ON STEEL
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: Injection of Starting any proposed or completion or recompletion or recompletion or recompletion of Starting any proposed work proposed completion or recompletion o	PLUG AND ABANDON CHANGE PLANS MULTIPLE COM PL WEIL leted operations. (Clearly ork). SEE RULE 19.15.7.1 ompletion. Failed MI " CIBP + CMT. @+/-4,44 SS "C" CMT. @ 4,442'-3, RF. (60) SXS. CLASS "C" WELLHEAD 3' B.G.L.; NSTALL BELOW GROUM empt to circ cmt - if no empt to circ cmt - if no	OT state all pertir 4 NMAC. For T and Failed 12'; CIRC. W. 073' (TIS.A., CMT.@ 2,2. VERIFY CMT ND DRY HO circ spot 25 circ spot 25	CHER: THER: TH	Notify OCD 24 h done ive pertinent date letions: Attach v ak before proceute press. TEST CSC LT); WOE X T. T/ANHY., 8-5/8 ALL ANNULI; 250' - woc & ta	es, including estimated dawellbore diagram of eding G. TO 750# X HOLD. AG TOC. " CSG.SHOE WELD ON STEEL
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: Injection of Starting any proposed or complete of starting any proposed we proposed completion or recomplete of Starting and Proposed Complete on the complete on the Complete of Starting and Proposed Complete on the Comp	PLUG AND ABANDON CHANGE PLANS MULTIPLE COM PL WEIL leted operations. (Clearly ork). SEE RULE 19.15.7.1 ompletion. Failed MI " CIBP + CMT. @+/-4,44 SS "C" CMT. @ 4,442'-3, RF. (60) SXS. CLASS "C" " WELLHEAD 3' B.G.L.; NSTALL BELOW GROUM empt to circ cmt - if no	CCCCA CA CA CA CA CA CA CA CA	OMMENCE DRILL ASING/CEMENT J THER: Then details, and go The Multiple Comp The Best of Multiple Comp The Best of Marker of Marker To Surf. ON The Marker of Marker The Sex cmt from 12 The Sex cmt from 12 The Marker of Marker of Marker of Marker of Marker The Sex cmt from 12 The Marker of	Notify OCD 24 h done live pertinent data letions: Attach v ak before proceute press. TEST CS0 LT); WOE X T. T/ANHY., 8-5/8 ALL ANNULI; 250' - woc & ta 250' - woc & ta 0' - woc & tag	es, including estimated dawellbore diagram of seding G. TO 750# X HOLD. AG TOC. " CSG.SHOE WELD ON STEEL
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: Injection of Starting any proposed or complete of starting any proposed we proposed completion or recomplete of Starting and Proposed Complete on the complete on the Complete of Starting and Proposed Complete on the Comp	PLUG AND ABANDON CHANGE PLANS MULTIPLE COM PL WEIL leted operations. (Clearly ork). SEE RULE 19.15.7.1 completion. Failed MI " CIBP + CMT. @ +/-4,44 SS "C" CMT. @ 4,442'-3, RF. (60) SXS. CLASS "C" " WELLHEAD 3' B.G.L.; NSTALL BELOW GROUM empt to circ cmt - if no	CCCCA CA CA CA CA CA CA CA CA	OMMENCE DRILL ASING/CEMENT J THER: Thent details, and go To Multiple Comp To BHT - Find le TO BHT - Find le TO SURF. ON TO SURF. OR TO SUR	Notify OCD 24 h done Ive pertinent data letions: Attach v ak before proceute present	es, including estimated dawellbore diagram of eeding G. TO 750# X HOLD. AG TOC. " CSG.SHOE WELD ON STEEL
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: Injection of Starting any proposed or complete of starting any proposed we proposed completion or recomplete of Starting and Proposed Complete on the complete on the Complete of Starting and Proposed Complete on the Comp	PLUG AND ABANDON CHANGE PLANS MULTIPLE COM PL Well leted operations. (Clearly ork). SEE RULE 19.15.7.1 ompletion. Failed Mi " CIBP + CMT. @+/-4,44 SS "C" CMT. @ 4,442'-3, RF. (60) SXS. CLASS "C" WELLHEAD 3' B.G.L.; NSTALL BELOW GROU empt to circ cmt - if no empt to ci	CCCCA CA CA CA CA CA CA CA CA	OMMENCE DRILL ASING/CEMENT J THER: Thent details, and go To Multiple Comp To BHT - Find le TO BHT - Find le TO SURF. ON TO SURF. OR TO SUR	Notify OCD 24 h done Ive pertinent data letions: Attach v ak before proceute present	es, including estimated dawellbore diagram of seding G. TO 750# X HOLD. AG TOC. " CSG.SHOE WELD ON STEEL
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: Injection 13. Describe proposed or composed starting any proposed we proposed completion or recomposed co	PLUG AND ABANDON CHANGE PLANS MULTIPLE COM PL Well leted operations. (Clearly ork). SEE RULE 19.15.7.1 completion. Failed MI " CIBP + CMT. @ +/-4,44 SS "C" CMT. @ 4,442'-3, RF. (60) SXS. CLASS "C" SWELLHEAD 3' B.G.L.; NSTALL BELOW GROU empt to circ cmt - if no	OT state all pertir 4 NMAC. For T and Failed 42'; CIRC. W. 073' (TIS.A., CMT.@ 2,2. VERIFY CMIND DRY HO circ spot 25	OMMENCE DRILL ASING/CEMENT J THER: Then details, and gor Multiple Comp To BHT - Find le ELL W/ M.L.F.; T/Y ATES, 8/SA 50'-3' (T/SALT, T. TO SURF. ON DLE MARKER. TO SX cmt from 12 SX cmt from 65 SX cmt from 45 MUST	Notify OCD 24 h done live pertinent data letions: Attach voor ak before proceute PRES. TEST CSC LT); WOE X TANHY., 8-5/8 ALL ANNULI; 250' - woc & tan 10' - w	es, including estimated dawellbore diagram of eeding G. TO 750# X HOLD. AG TOC. " CSG.SHOE WELD ON STEEL
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE 13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete or recomplete or proposed complete or recomplete or recomplet	PLUG AND ABANDON CHANGE PLANS MULTIPLE COM PL Well leted operations. (Clearly ork). SEE RULE 19.15.7.1 completion. Failed MI " CIBP + CMT. @ +/-4,44 SS "C" CMT. @ 4,442'-3, RF. (60) SXS. CLASS "C" SWELLHEAD 3' B.G.L.; NSTALL BELOW GROU empt to circ cmt - if no	OT state all pertir 4 NMAC. For T and Failed 42'; CIRC. W. 073' (TIS.A., CMT.@ 2,2. VERIFY CMIND DRY HO circ spot 25	OMMENCE DRILL ASING/CEMENT J THER: Then details, and gor Multiple Comp To BHT - Find le ELL W/ M.L.F.; T/Y ATES, 8/SA 50'-3' (T/SALT, T. TO SURF. ON DLE MARKER. TO SX cmt from 12 SX cmt from 65 SX cmt from 45 MUST	Notify OCD 24 h done live pertinent data letions: Attach voor ak before proceute PRES. TEST CSC LT); WOE X TANHY., 8-5/8 ALL ANNULI; 250' - woc & tan 10' - w	es, including estimated dawellbore diagram of eeding G. TO 750# X HOLD. AG TOC. " CSG.SHOE WELD ON STEEL
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: Injection 13. Describe proposed or composed starting any proposed we proposed completion or recomposed co	PLUG AND ABANDON CHANGE PLANS MULTIPLE COM PL Well leted operations. (Clearly ork). SEE RULE 19.15.7.1 completion. Failed MI " CIBP + CMT. @ +/-4,44 SS "C" CMT. @ 4,442'-3, RF. (60) SXS. CLASS "C" SWELLHEAD 3' B.G.L.; NSTALL BELOW GROU empt to circ cmt - if no	CCA CA CA CA CA CA CA CA CA CA	OMMENCE DRILL ASING/CEMENT J THER: Then details, and gor Multiple Comp To BHT - Find le ELL W/ M.L.F.; T/Y ATES, 8/SA 50'-3' (T/SALT, T. TO SURF. ON DLE MARKER. TO SX cmt from 12 SX cmt from 65 SX cmt from 45 MUST	Notify OCD 24 h done live pertinent date letions: Attach v ak before proceute. TEST CSC LT); WOE X TA I/ANHY., 8-5/8 ALL ANNULI; 250' - woc & ta 250' - woc & ta 0' - woc & tag 0' - woc & tag I'BE PLUGGED Ind belief.	es, including estimated dawellbore diagram of eeding G. TO 750# X HOLD. AG TOC. " CSG.SHOE WELD ON STEEL
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: Injection 13. Describe proposed or complete of starting any proposed we proposed completion or recomplete o	PLUG AND ABANDON CHANGE PLANS MULTIPLE COM PL Well leted operations. (Clearly ork). SEE RULE 19.15.7.1 ompletion. Failed Mi " CIBP + CMT. @+/-4,44 SS "C" CMT. @ 4,442'-3, RF. (60) SXS. CLASS "C" WELLHEAD 3' B.G.L.; NSTALL BELOW GROUM empt to circ cmt - if no empt to ci	CCA CA CA CA CA CA CA CA CA CA	OMMENCE DRILL SING/CEMENT J THER: nent details, and g or Multiple Comp d BHT - Find le ELL W/ M.L.F.; I T/Y ATES, 8/SA 50'-3' (T/SALT, ' T. TO SURF. ON OLE MARKER. Sex cmt from 22 Sex cmt from 12 sex cmt from 45 MUST fmy knowledge a	Notify OCD 24 h done live pertinent data letions: Attach v ak before proceute of the control of	es, including estimated dawellbore diagram of seding G. TO 750# X HOLD. AG TOC. " CSG.SHOE WELD ON STEEL BY 10/30/2023 ATE: 4/12/2023
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: Injection 13. Describe proposed or completion of starting any proposed we proposed completion or recompletion or re	PLUG AND ABANDON CHANGE PLANS MULTIPLE COM PL Well leted operations. (Clearly ork). SEE RULE 19.15.7.1 ompletion. "CIBP + CMT. @+/-4,44 SS "C" CMT. @ 4,442'-3, RF. (60) SXS. CLASS "C" WELLHEAD 3' B.G.L.; NSTALL BELOW GROUM empt to circ cmt - if no empt to circ cmt - if	CCA CA CA CA CA CA CA CA CA CA	OMMENCE DRILL SING/CEMENT J THER: nent details, and g or Multiple Comp d BHT - Find le ELL W/ M.L.F.; I T/Y ATES, 8/SA 50'-3' (T/SALT, ' T. TO SURF. ON OLE MARKER. Sex cmt from 22 Sex cmt from 12 sex cmt from 45 MUST fmy knowledge a	Notify OCD 24 h done live pertinent data letions: Attach v ak before proceute of the control of	es, including estimated dawellbore diagram of seding G. TO 750# X HOLD. AG TOC. " CSG.SHOE WELD ON STEEL
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE 13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete or re	PLUG AND ABANDON CHANGE PLANS MULTIPLE COM PL Well leted operations. (Clearly ork). SEE RULE 19.15.7.1 ompletion. Failed Mi " CIBP + CMT. @+/-4,44 SS "C" CMT. @ 4,442'-3, RF. (60) SXS. CLASS "C" WELLHEAD 3' B.G.L.; NSTALL BELOW GROUM empt to circ cmt - if no empt to ci	CCA CA CA CA CA CA CA CA CA CA	COMMENCE DRILL SING/CEMENT J THER: Then details, and gor Multiple Comp G BHT - Find le ELL W/ M.L.F.; T/Y ATES, 8/SA 50'-3' (T/SALT, T. TO SURF. ON OLE MARKER. Sex cmt from 22 Sex cmt from 45 Sex cmt from 45 MUST The symmetry of the symmetr	Notify OCD 24 h done live pertinent data letions: Attach v ak before proceute press. TEST CS0 LT); WOE X T. I/ANHY., 8-5/8 ALL ANNULI; 250' - woc & ta 250' - woc & ta 0' - woc & tag 0' - woc & tag I/BE PLUGGED	es, including estimated dawellbore diagram of seding G. TO 750# X HOLD. AG TOC. " CSG.SHOE WELD ON STEEL BY 10/30/2023 ATE: 4/12/2023 E: 713.574.7912

CONDITIONS FOR PLUGGING AND ABANDONMENT

OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office II at (575)-748-1283 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down. Company representative will be on location during plugging procedures.

- A notice of intent to plug and abandon a wellbore is required to be approved before plugging
 operations are conducted. A cement evaluation tool is required in order to ensure isolation of
 producing formations, protection of water and correlative rights. A cement bond log or other
 accepted cement evaluation tool is to be provided to the division for evaluation if one has not
 been previously run or if the well did not have cement circulated to surface during the original
 casing cementing job or subsequent cementing jobs. Insure all bradenheads have been
 exposed, identified and valves are operational prior to rig up.
- 2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- 3. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- 5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
- 6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- 8. Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- 10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- 13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- 14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.

- 16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- 18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).
- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
 - A) Fusselman
 - B) Devonian
 - C) Morrow
 - D) Wolfcamp
 - E) Bone Springs
 - F) Delaware
 - G) Any salt sections
 - H) Abo
 - 1) Glorieta
 - J) Yates.
 - K) Cherry Canyon Eddy County
 - L) Potash---(In the R-111-P Area (Page 3 & 4), a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.
- 21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing

DRY HOLE MARKER REQUIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

1. Operator name 2. Lease and Well Number 3.API Number 4. Unit Letter 5. Quarter Section (feet from the North, South, East or West) 6. Section, Township and Range 7. Plugging Date 8. County (SPECIAL CASES)------AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

R-111-P Area

T 18S - R 30E

Sec 10 Unit P. Sec 11 Unit M,N. Sec 13 Unit L,M,N. Sec 14 Unit C -P. Sec 15 Unit A G,H,I,J,K,N,O,P. Sec 22 Unit All except for M. Sec 23, Sec 24 Unit C,D,E,L, Sec 26 Unit A-G, Sec 27 Unit A,B,C

T 19S - R 29E

Sec 11 Unit P. Sec 12 Unit H-P. Sec 13. Sec 14 Unit A,B,F-P. Sec 15 Unit P. Sec 22 Unit A,B,C,F,G,H,I,J K,N,O,P. Sec 23. Sec 24. Sec 25 Unit D. Sec 26 Unit A-F. Sec 27 Unit A,B,C,F,G,H.

T 19S - R 30E

Sec 2 Unit K,L,M,N. Sec 3 Unit I,L,M,N,O,P. Sec 4 Unit C,D,E,F,G,I-P. Sec 5 Unit A,B,C,E-P. Sec 6 Unit I,O,P. Sec 7 – Sec 10. Sec 11 Unit D, G—P. Sec 12 Unit A,B,E-P. Sec 13 Unit A-O. Sec 14-Sec 18. Sec 19 Unit A-L, P. Sec 20 – Sec 23. Sec 24 Unit C,D,E,F,L,M,N. Sec 25 Unit D. Sec 26 Unit A-G, I-P. Sec 27, Sec 28, Sec 29 Unit A,B,C,D,F,G,H,I,J,O,P. Sec 32 Unit A,B,G,H,I,J,N,O,P. Sec 33. Sec 34. Sec 35. Sec 36 Unit D,E,F,I-P.

T 19S - R 31E

Sec 7 Unit C,D,E,F,L. Sec 18 Unit C,D,E,F,G,K,L. Sec 31 Unit M. Sec 34 Unit P. Sec 35 Unit M,N,O. Sec 36 Unit O,P.

T 20S - R 29E

Sec 1 Unit H,I,P. Sec 13 Unit E,L,M,N. Sec 14 Unit B-P. Sec 15 Unit A,H,I,J,N,O,P. Sec 22 Unit A,B,C,F,G,H,I,J,O,P. Sec 23. Sec 24 Unit C,D,E,F,G,J-P. Sec 25 Unit A-O. Sec 26. Sec 27 Unit A,B,G,H,I,J,O,P. Sec 34 Unit A,B,G,H. Sec 35 Unit A-H. Sec 36 Unit B-G.

T 20S - R 30E

Sec 1 – Sec 4. Sec 5 Unit A,B,C,E-P. Sec 6 Unit E,G-P. Sec 7 Unit A-H,I,J,O,P. Sec 8 – 17. Sec 18 Unit A,B,G,H,I,J,O,P. Sec 19 Unit A,B,G,H,I,J,O,P. Sec 30 Unit A-L,N,O,P. Sec 31 Unit A,B,G,H,I,P. Sec 32 – Sec 36.

T 20S - R 31E

Sec 1 Unit A,B,C,E-P. Sec 2. Sec 3 Unit A,B,G,H,I,J,O,P. Sec 6 Unit D,E,F,J-P. Sec 7. Sec 8 Unit E-P. Sec 9 Unit E,F,J-P. Sec 10 Unit A,B,G-P. Sec 11 – Sec 36.

T 21S - R 29E

Sec 1 – Sec 3. Sec 4 Unit L1 – L16,I,J,K,O,P. Sec 5 Unit L1. Sec 10 Unit A,B,H,P. Sec 11 – Sec 14. Sec 15 Unit A,H,I. Sec 23 Unit A,B. Sec 24 Unit A,B,C,D,F,G,H,I,J,O,P. Sec 25 Unit A,O,P. Sec 35 Unit G,H,I,J,K,N,O,P. Sec 36 A,B,C,F – P.

T 21S - R 30E

Sec 1 – Sec 36

T 21S - R 31E

Sec 1 – Sec 36

T 22S - R 28E

Sec 36 Unit A,H,I,P.

T 22S - R 29E

Sec 1. Sec2. Sec 3 Unit I,J,N,O,P. Sec 9 Unit G – P. Sec 10 – Sec 16. Sec 19 Unit H,I,J. Sec 20 – Sec 28. Sec 29 Unit A,B,C,D,G,H,I,J,O,P. Sec 30 Unit A. Section 31 Unit C – P. Sec 32 – Sec 36

T 22S - R 30E

Sec 1 – Sec 36

T 22S - R 31E

Sec 1 – Sec 11. Sec 12 Unit B,C,D,E,F,L. Sec 13 Unit E,F,K,L,M,N. Sec 14 – Sec 23. Sec 24 Unit C,D,E,F,K,L,M,N. Sec 25 Unit A,B,C,D. Sec 26 Unit A,BC,D,G,H. Sec 27 – Sec 34.

T 23S - R 28E

Sec 1 Unit A

T 23S - R 29E

Sec 1 – Sec 5. Sec 6 Unit A – I, N,O,P. Sec 7 Unit A,B,C,G,H,I,P. Sec 8 Unit A – L, N,O,P. Sec 9 – Sec 16. Sec 17 Unit A,B,G,H,I,P. Sec 21 – Sec 23. Sec 24 Unit A – N. Sec 25 Unit D,E,L. Sec 26. Sec 27. Sec 28 Unit A – J, N,O,P. Sec 33 Unit A,B,C. Sec 34 Unit A,B,C,D,F,G,H. Sec 35. Sec 36 Unit B,C,D,E,F,G,K,L.

T 23S - R 30E

Sec 1 – Sec 18. Sec 19 Unit A – I,N,O,P. Sec 20, Sec 21. Sec 22 Unit A – N, P. Sec 23, Sec 24, Sec 25. Sec 26 Unit A,B,F-P. Sec 27 Unit C,D,E,I,N,O,P. Sec 28 Unit A – H, K,L,M,N. Sec 29 Unit A – J, O,P. Sec 30 Unit A,B. Sec 32 A,B. Sec 33 Unit C,D,H,I,O,P. Sec 34, Sec 35, Sec 36.

T 23S - R 31E

Sec 2 Unit D,E,J,O. Sec 3 – Sec 7. Sec 8 Unit A – G, K – N. Sec 9 Unit A,B,C,D. Sec 10 Unit D,P. Sec 11 Unit G,H,I,J,M,N,O,P. Sec 12 Unit E,L,K,M,N. Sec 13 Unit C,D,E,F,G,J,K,L,M,N,O. Sec 14. Sec 15 Unit A,B,E – P. Sec 16 Unit I, K – P. Sec 17 Unit B,C,D,E, I – P. Sec 18 – Sec 23. Sec 24 Unit B – G, K,L,M,N. Sec 25 Unit B – G, J,K,L. Sec 26 – Sec 34. Sec 35 Unit C,D,E.

T 24S – R 29E

Sec 2 Unit A, B, C, D. Sec 3 Unit A

T 24S - R 30E

Sec 1 Unit A – H, J – N. Sec 2, Sec 3. Sec 4 Unit A,B,F – K, M,N,O,P. Sec 9 Unit A – L. Sec 10 Unit A – L, O,P. Sec 11. Sec 12 Unit D,E,L. Sec 14 Unit B – G. Sec 15 Unit A,B,G,H.

T 24S - R 31E

Sec 3 Unit B – G, J – O. Sec 4. Sec 5 Unit A – L, P. Sec 6 Unit A – L. Sec 9 Unit A – J, O,P. Sec 10 Unit B – G, K – N. Sec 35 Unit E – P. Sec 36 Unit E,K,L,M,N.

T 25S - R 31E

Sec 1 Unit C,D,E,F. Sec 2 Unit A – H.

CURRENT

Well Name: MSU 187

Well API #: 30-041-10057 County, State: Roosevelt Co NM

Date: 8/20/2008

Installation		Surface Casing	Make	Size	Wellhead Detail	OD	ID
6	OD:	8-5/8"					
P 4 P	Weight:	24					
	Grade:						
	Top:	0	Length	Depth	Tubing Detail (Top Down)	OD	ID
	Bottom:				KB		
		termediate Csg.	1			1	
	OD:	4.5	1		10/2000: 2-7/8" cemented in place for casing & 2-1/16" tbg	1	
	Weight:		1		utilized for injection string	1	
	Grade:		1			- 1	
	Top:	0	1		08/2008: Well Temporarily Abandoned. CIBP set in 2-7/8"	1	
	Bottom:		1		@ 4,477' w/ 35' cmt. Tagged at 4,442'	1	
	Owners with the Party of the Pa	oduction Casing					
	OD:	2-7/8"	1			1	
	Weight:		1			1	
	Grade:	J55/N80	1				
	Top:	0	1				
	Bottom:						
	- Cottonii	TOC	1				
	surface	(250 sx)	1				
	Juliace	(200 3/)	1				
		DV Tool	1				
	-	DV 1001	1				
	-		1				
			1				
					ROD DETAIL (Bottom Up)		
			Count	Length	ROD DETAIL (BOLLOTT OP)		
				,			
		/	-				
	CIBP se	t @ 4,477' w/ 35' cm					
			-	1			
		Top Perf	-				
	4575		4	l			
		Bottom Perf	4				
	4690		-				
Teles.			-				
			-				
		TD	ļ				
		4670			0' Pump Set Depth		
		PBTD					
		4455	100		Pumping Unit Specs		
		TVD	P.U. Make:	N/A	^		
		4455	P.U. Size:				
			P.U. SL:	1			
			SPM:				
					Pump Details		
			PUMP SIZE:	N/A			
610			PLUNGER:				
	1		STDG VALVE:				
	1						

DAE 02/14/2023

T/ANHY. -2,090'
T/SALT. -2,200'
B/SALT. -3,123'
T/S.A. - 3,846'

PRO	POSED	Well API #	MSU 187 : 30-041-10057 : Roosevelt Co NM : 8/20/2008		
Installation	Surface Casing				
が言葉に見	OD: 8-5/8" Weight: 24	-			
- FAIL E	Grade:				
Co.	Top: 0				
C.C.K	Bottom: 362 Intermediate Csg.	-			
Eg	OD: 4.5				
	Weight: 10.5				
1	Grade:				
814	Top: 0 Bottom: 4720				
7.3	Production Casing				
SCAF	OD: 2-7/8"				
out &	Weight: 6.5				
E CE	Grade: J55/N80 Top: 0				
18/1	Bottom: 4477'				
E	TOC			,	
66	surface (250 sx)	TRC	(60) 5x5.@2,250'-3	•	
LEGAT	DV Tool	4 9270.	(200) = 11 = 2		
2	DV 1001				
					*
14.					
131					
161			1		-
Topic of	-	- Pamp	(35) 5×5. @ 4,442 -3,0	975	- 1H
14%	CIBP set @ 4,477' w/ 35' cr				=
GEV.	CIDI SEC @ 4,477 W/ 33 CI				
Const	Top Perf				
1,294	4575				
KE	Bottom Perf 4690	-			
BUE	4030				
	TD				
	4670 PBTD				
	4455				
	TVD				
	4455	_			
• 1000		,			

DAE 02/14/2023

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

COMMENTS

Action 206824

COMMENTS

Operator:	OGRID:
EOR OPERATING COMPANY	257420
575 N Dairy Ashford Suite 210	Action Number:
Houston, TX 77079	206824
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

COMMENTS

Created By	Comment	Comment Date
plmartinez	DATA ENTRY PM	5/1/2023

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 206824

CONDITIONS

Operator:	OGRID:
EOR OPERATING COMPANY	257420
575 N Dairy Ashford Suite 210	Action Number:
Houston, TX 77079	206824
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By		Condition Date
gcordero	None	4/28/2023