

U.S. Department of the Interior BUREAU OF LAND MANAGEMENT Sundry Print Report

Well Name: ARIZONA JICARILLA Well Location: T25N / R4W / SEC 25 /

SESW / 36.365863 / -107.207904

County or Parish/State: RIO

ARRIBA / NM

Well Number: 9 Type of Well: CONVENTIONAL GAS

WELL

Allottee or Tribe Name: JICARILLA APACHE

Lease Number: JIC125 Unit or CA Name:

Unit or CA Number:

US Well Number: 3003921817 Well Status: Producing Gas Well Operator: HILCORP ENERGY

COMPANY

Notice of Intent

Sundry ID: 2729484

Type of Submission: Notice of Intent

Type of Action: Plug and Abandonment

Date Sundry Submitted: 05/08/2023 Time Sundry Submitted: 07:13

Date proposed operation will begin: 05/22/2023

Procedure Description: Hilcorp Energy Company requests permission to P&A the subject well per the attached procedures, current and proposed wellbore schematics. The Pre-Disturbance Site Visit was held on 4/26/2023 with Jicarilla/BIA. The Re-Vegetation Plan is attached. A closed loop system will be used. Jicarilla has requested that a surface plate be used for the P&A marker for this location. Please see attached letter.

Surface Disturbance

Is any additional surface disturbance proposed?: No

NOI Attachments

Procedure Description

Arizona_Jicarilla_9_P_A_NOI_20230508071329.pdf

Accepted for record - NMOCD

JRH 05/23/23

eived by OCD: 5/17/2023 7:01:43 AM Well Name: ARIZONA JICARILLA

Well Location: T25N / R4W / SEC 25 /

SESW / 36.365863 / -107.207904

County or Parish/State: Rige 2 of

ARRIBA / NM

Well Number: 9

Type of Well: CONVENTIONAL GAS

Allottee or Tribe Name: JICARILLA APACHE

Lease Number: JIC125

Unit or CA Name:

Unit or CA Number:

US Well Number: 3003921817

Well Status: Producing Gas Well

Operator: HILCORP ENERGY

COMPANY

Conditions of Approval

Additional

25N04W25NKpc_Arizona_Jicarilla_009_20230515130148.pdf

2729484_NOIA_9_3003921817_KR_05152023_20230515152452.pdf

General_Requirement_PxA_20230515152432.pdf

Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: KANDIS ROLAND Signed on: MAY 08, 2023 07:13 AM

Name: HILCORP ENERGY COMPANY

Title: Operation Regulatory Tech Street Address: 382 Road 3100

City: Farmington State: NM

Phone: (505) 599-3400

Email address: kroland@hilcorp.com

Field

Representative Name:

Street Address:

City:

State:

Zip:

Phone:

Email address:

BLM Point of Contact

BLM POC Name: KENNETH G RENNICK

BLM POC Phone: 5055647742

Disposition: Approved

Signature: Kenneth Rennick

BLM POC Title: Petroleum Engineer

BLM POC Email Address: krennick@blm.gov

Disposition Date: 05/15/2023

Page 2 of 2



HILCORP ENERGY COMPANY


Arizona Jicarilla 9 NOTICE OF INTENT TO PERMANENTLY ABANDON

API #: 3003921817

		JOB PROCEDURES
7 7	NMOCD Jicarilla	Contact OCD and Jicarilla 2 weeks prior to MIRU (Need PTPW from Jicarilla). Comply with all NMOCD, Jicarilla and HEC safety and environmental regulations.
1	. MIRU service r	ig and associated equipment, record all pressures on wellbore.
2	. Load well, ND	tree, NU BOPs and test.
3	. MU 2-7/8" 6.5#	² GR, clear csg to 3,600', POOH. MU 2-7/8" 6.5# CIBP and set @ 3,594' (PC Top Perf @ 3,644').
4		inhibited brine & circulate clean. Pressure test the csg to 560 psi. Monitor for 30 minutes. Run CBL from 3,594' to surface. ving plug designs are subject to change pending CBL results.
5	"Select" cemer	7' - 3,594' (CIBP @ 3,594' PC Top: 3,635', FRD Top: 3,460', KRD Top: 3,346', Ojo Top: 3,137') Pump 13sx (3.2bbl) Class III and spot a 507' inside plug over the CIBP to cover all tops. plit & NMOCD/BLM will be notified if BH pressure is present.
6	. RU ELU, RIH p	perf circ holes in 2-7/8" csg @ 212'. Establish circulation up 8-5/8" annulus.
7	Plug #2 12' - surface shoe.	212' (Surface Shoe @ 162') Pump 50sx (12.2bbl) Class III "Select" cement and circulate in a 202' inside/outside plug over the
8	. LD tubing. ND	BOP and cut off wellhead below surface casing flange as per NMOCD. Top off cement at surface as needed. Weld new P&A maker.




HILCORP ENERGY COMPANY Arizona Jicarilla 9 NOTICE OF INTENT TO PERMANENTLY ABANDON





HILCORP ENERGY COMPANY Arizona Jicarilla 9 NOTICE OF INTENT TO PERMANENTLY ABANDON



Hilcorp Energy

Arizona Jicarilla 9 36.365610, -107.207557 API-30-039-21817 Jicarilla Lease #125


Final Reclamation Plan

Onsite 4/26/2023 with Kurt Sandoval, Alfred Vigil, Jason Sandoval, Orlando Muniz, Donna Montoya.

- 1 Pick up and remove all trash, metal, cable, and any foreign debris within 200' of location.
- 2 Remove anchors.
- 3 Strip equipment off facility. Test under pit.
- 4 Harvest to remove meter run and piping back to dog leg and line drip.
- 5 Reclaim location, pushing fill west back to cut slope, leaving rolling terrain.
- 6 Set surface wellhead marker plate.
- 7 Reclaim road back to the main road build rolling terrain where necessary.
- 8 Install woven field wire fence at main road.
- 9 Rip compacted soil.
- 10 Re-seed all disturbed areas. Drill where applicable at rate per acre defined by seed mix, and broadcast seed and harrow, at double the rate, all other disturbed areas. Mesa Mix seed mix will be used.









United States Department of the Interior

BUREAU OF INDIAN AFFAIRS

Jicarilla Agency P.O. Box 167 Dulce, New Mexico 87528

IN REPLY REFER TO: Branch of Real Estate Services

November 15, 2019

Memorandum

To:

Robert Switzer, Environmental Protection Specialist

Bureau of Land Management, Farmington Field Office

From:

Kurt Sandoval, Realty Officer

Bureau of Indian Affairs, Jicarilla Agency

Subject:

BIA Concurrence concerning Well Pad Monument Makers

Let this serve as concurrence for the agreed upon preferred method to be used when constructing well pad monument markers on Jicarilla Apache Tribal Lands. We will eliminate the 6 ft. dry hole marker and use a permanent metal plate that will be installed at ground level, effective September 2019. The marker will contain the following information:

- Well Pad Lease Number
- Well Pad Location Name and Number
- Well Pad Legal Description, specifically Section, Township and Range
- Well Pad API Number
- Well Pad Plug Date
- Well Pad Operator Name

You may contact our office if you have any questions or concerns at (575) 759-3936. Thank you.

Realty Officer

cc:

Jicarilla Oil and Gas Administration

BLM FLUID MINERALS P&A Geologic Report

Date Completed: 5/15/2023

Well No. Arizona Jicarilla #009 (A	Location	860	FSL	&	1450	FWL	
Lease No. JIC125	Sec. 25	T25N			R04W		
Operator Hilcorp Energy Compa	County	Rio Arriba		State	New Mexico		
Total Depth 3838'	PBTD 3793'	Formation	Pictured	Cliffs			
AFMSS Sundry ID: 2729484	Elevation (KI	3)					

Geologic Formations	Est. Top	Est. Bottom	Log Top	Log Bottom	Remarks
San Jose			Surface		
Nacimiento				3137	Surface/possible freshwater sands
Ojo Alamo Ss			3137	3346	Aquifer (possible freshwater)
Kirtland Shale			3346	3460	Possible gas
Fruitland			3460	3635	Coal/Gas/Water
Pictured Cliffs Ss			3635	PBTD	Probable Gas
Lewis Shale					
Chacra (lower)					
Cliff House Ss					
Menefee					
Point Lookout Ss					
Mancos Shale					
Gallup					
Greenhorn					
Graneros Shale					
Dakota Ss					
Morrison					

Remarks:

P & A

Pictured Cliffs perfs 3644' – 3701'.

Reference Well:
1) Formation Tops

Same

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

AFMSS 2 Sundry ID 2729484

Attachment to notice of Intention to Abandon

Well: Arizona Jicarilla 9

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence at (505) 564-7750.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.

K. Rennick 5/15/2023

GENERAL REQUIREMENTS FOR PERMANENT ABANDONMENT OF WELLS ON FEDERAL AND INDIAN LEASES FARMINGTON FIELD OFFICE

- 1.0 The approved plugging plans may contain variances from the following <u>minimum general</u> requirements.
 - 1.1 Modification of the approved plugging procedure is allowed only with the prior approval of the Authorized Officer, Farmington Field Office.
 - 1.2 Requirements may be added to address specific well conditions.
- 2.0 Materials used must be accurately measured. (densometer/scales)
- 3.0 A tank or lined pit must be used for containment of any fluids from the wellbore during plugging operations and all pits are to be fenced with woven wire. These pits will be fenced on three sides and once the rig leaves location, the fourth side will be fenced.
 - 3.1 Pits are not to be used for disposal of any hydrocarbons. If hydrocarbons are present in the pit, the fluids must be removed prior to filling in.
- 4.0 All cement plugs are to be placed through a work string. Cement may be bull-headed down the casing with prior approval. Cement caps on top of bridge plugs or cement retainers may be placed by dump bailer.
 - 4.1 The cement shall be as specified in the approved plugging plan.
 - 4.2 All cement plugs placed inside casing shall have sufficient volume to fill a minimum of 100' of the casing, or annular void(s) between casings, plus an excess volume sufficient to provide for 50 linear feet of fill above the plug.
 - 4.3 Surface plugs may be no less than 50' in length.
 - 4.4 All cement plugs placed to fill annular void(s) between casing and the formation shall be of sufficient volume to fill a minimum of 100' of the annular space plus 100% excess, calculated using the bit size, or 100' of annular capacity, determined from a caliper log, plus an excess volume sufficient to provide for 50 linear feet of fill above the plug.
 - 4.5 All cement plugs placed to fill an open hole shall be of sufficient volume to fill a minimum of 100' of hole, as calculated from a caliper log, plus an excess volume sufficient to provide for 50 linear feet of fill above the plug. In the absence of a caliper log, an excess of 100% shall be required.
 - 4.6 A cement bond log or other accepted cement evaluation tool is required to be run if one had not been previously ran or cement did not circulate to surface during the original casing cementing job or subsequent cementing jobs.

2

- 5.0 All cement plugs spotted across, or above, any exposed zone(s), when; the wellbore is not full of fluid or the fluid level will not remain static, and in the case of lost circulation or partial returns during cement placement, shall be tested by tagging with the work string.
 - 5.1 The top of any cement plug verified by tagging must be at or above the depth specified in the approved plan, without regard to any excess.
 - 5.2 Testing will not be required for any cement plug that is mechanically contained by use of a bridge plug and/or cement retainer, if casing integrity has been established.
 - 5.3 Any cement plug which is the only isolating medium, for a fresh water interval or a zone containing a prospectively valuable deposit of minerals, shall be tested by tagging.
 - 5.4 If perforations are required below the surface casing shoe, a 30 minute minimum wait time will be required to determine if gas and/or water flows are present. If flow is present, the well will be shut-in for a minimum of one hour and the pressure recorded. Short or long term venting may be necessary to evacuate trapped gas. If only a water flow occurs with no associated gas, shut well in and record the pressures. Contact the Engineer as it may be necessary to change the cement weight and additives.
- 6.0 Before setting any cement plugs the hole needs to be rolled. All wells are to be controlled by means of a fluid that is to be of a weight and consistency necessary to stabilize the wellbore. This fluid shall be left in place as filler between all plugs.
 - 6.1 Drilling mud may be used as the wellbore fluid in open hole plugging operations.
 - 6.2 The wellbore fluid used in cased holes shall be of sufficient weight to balance known pore pressures in all exposed formations.
- 7.0 A blowout preventer and related equipment (BOPE) shall be installed and tested prior to working in a wellbore with any exposed zone(s); (1) that are over pressured, (2) where the pressures are unknown, or (3) known to contain H_2S .
- 8.0 Within 30 days after plugging work is completed, file a Sundry Notice, Subsequent Report of Abandonment (Form 3160-5), through the Automated Fluid Minerals Support System (AFMSS) with the Field Manager, Bureau of Land Management, 6251 College Blvd., Suite A, Farmington, NM 87402. The report should show the manner in which the plugging work was carried out, the extent, by depth(s), of cement plugs placed, and the size and location, by depth(s), of casing left in the well. Show date well was plugged.
- 9.0 All permanently abandoned wells are to be marked with a permanent monument as specified in 43 CFR 3162.6(d). Unless otherwise approved.
- 10.0 If this well is located in a Specially Designated Area (SDA), compliance with the appropriate seasonal closure requirements will be necessary.

All of the above are minimum requirements. Failure to comply with the above conditions of approval may result in an assessment for noncompliance and/or a Shut-in Order being issued pursuant to 43 CFR 3163.1. You are further advised that any instructions, orders or decisions issued by the Bureau of Land Management are subject to administrative review pursuant to 43 CFR 3165.3 and appeal pursuant to 43 CFR 3165.4 and 43 CFR 4.700.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

COMMENTS

Action 217525

COMMENTS

Operator:	OGRID:
HILCORP ENERGY COMPANY	372171
1111 Travis Street	Action Number:
Houston, TX 77002	217525
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

COMMENTS

Created	d By	Comment	Comment Date
john.h	harrison	Accepted for record - NMOCD JRH 5/23/23. BLM approved P&A 5/15/23	5/23/2023

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 217525

CONDITIONS

Operator:	OGRID:		
HILCORP ENERGY COMPANY	372171		
1111 Travis Street	Action Number:		
Houston, TX 77002	217525		
	Action Type:		
	[C-103] NOI Plug & Abandon (C-103F)		

CONDITIONS

Created By		Condition Date
john.harrisc	n None	5/23/2023