
Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
District I - (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283		WELL API NO. 30-025-03459
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE X FEE
District IV - (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		E-444
	ES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSAL	LS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR, USE "APPLICA" PROPOSALS.)	FION FOR PERMIT" (FORM C-101) FOR SUCH	
	as Well X Other	8. Well Number 1
2. Name of Operator		9. OGRID Number
MOMENTUM OPERATING CO., J	NC.	196069 10. Pool name or Wildcat
3. Address of Operator P.O. BOX 2439, ALBANY, TEXAS	76430	EUMONT YATES SEVEN RIVERS
4. Well Location	70430	EUMONT TATES SEVEN RIVERS
	980 feet from the SOUTH line and 99	feet from the WEST line
Unit Letter L : 19 Section 12		NMPM LEA County
	Township 21S Range 35E 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
	KB 3593'	
		The state of the s
12. Check Ap	propriate Box to Indicate Nature of Notice,	Report or Other Data
•		•
NOTICE OF INTI		SEQUENT REPORT OF:
	PLUG AND ABANDON 🗵 REMEDIAL WOR	in the second se
_	CHANGE PLANS COMMENCE DR MULTIPLE COMPL CASING/CEMEN	
DOWNHOLE COMMINGLE	····	
CLOSED-LOOP SYSTEM	do	tify OCD 24 hrs. prior to any work
020025 2001 01012111		
OTHER:	OTHER:	
13. Describe proposed or complete	ed operations. (Clearly state all pertinent details, an	d give pertinent dates, including estimated date
13. Describe proposed or complete of starting any proposed work	ed operations. (Clearly state all pertinent details, an b. SEE RULE 19.15.7.14 NMAC. For Multiple Co	mpletions: Attach wellbore diagram of
13. Describe proposed or complete of starting any proposed work proposed completion or recomplete.	ed operations. (Clearly state all pertinent details, an b). SEE RULE 19.15.7.14 NMAC. For Multiple Co pletion.	mpletions: Attach wellbore diagram of n CBL to surface.
13. Describe proposed or complete of starting any proposed work proposed completion or recomplete. 1. September 2001. Circles 2001. Circles 2001. Circles 2001.	ed operations. (Clearly state all pertinent details, an b. SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. Ru Culate well with mud Set CIBP @ 3600' - test	mpletions: Attach wellbore diagram of n CBL to surface. casing 500psi/30min. Spot 25 sx cmt on plug
13. Describe proposed or complete of starting any proposed work proposed completion or recom 1. Stot a Msks plug 3600'. Cir 2. Perf and attempt to squeeze	ed operations. (Clearly state all pertinent details, and). SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. Ru Coulate well with mud Set CIBP @ 3600' - test @3190' with Makes plug. If unable to establish spot	mpletions: Attach wellbore diagram of n CBL to surface. casing 500psi/30min. Spot 25 sx cmt on pluga 25ks plug @3250.
13. Describe proposed or complete of starting any proposed work proposed completion or recom 1. Stot a Msks plug 3600'. Cir 2. Perf and attempt to squeeze 3. Perf and attempt to squeeze	ed operations. (Clearly state all pertinent details, and). SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. Rule Coulate well with mud Set CIBP @ 3600' - test @ 3190' with Xsks plug. If unable to establish spot at 1750' with a Xsks plug. If unable to establish rate	mpletions: Attach wellbore diagram of n CBL to surface. casing 500psi/30min. Spot 25 sx cmt on plug a \$0sks plug @3250. e, spot a \$0sks plug @ 1850'
13. Describe proposed or complete of starting any proposed work proposed completion or recommendate. 1. Section 2 Section 2. Perf and attempt to squeeze 3. Perf and attempt to squeeze 4. Perf and attempt to squeeze	ed operations. (Clearly state all pertinent details, and). SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. Ru culate well with mud Set CIBP @ 3600' - test @3190' with Maks plug. If unable to establish spot at 1750' with a Maks plug. If unable to establish rate, at 32' with 100sks plug. If unable to establish rate,	mpletions: Attach wellbore diagram of n CBL to surface. casing 500psi/30min. Spot 25 sx cmt on plug a \$0sks plug @3250. e, spot a \$0sks plug @ 1850'
13. Describe proposed or complete of starting any proposed work proposed completion or recommendate. 1. Sect a Masks plug 3600'. Cit 2. Perf and attempt to squeeze 3. Perf and attempt to squeeze 4. Perf and attempt to squeeze Perf	ed operations. (Clearly state all pertinent details, and). SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. Ru culate well with mud Set CIBP @ 3600' - test @3190' with Xsks plug. If unable to establish spot at 1750' with a Xsks plug. If unable to establish rate, at X2' with 100sks plug. If unable to establish rate, @ 362'	mpletions: Attach wellbore diagram of n CBL to surface. casing 500psi/30min. Spot 25 sx cmt on pluga sysks plug @3250. e, spot a ysks plug @ 1850' fill to surface.
13. Describe proposed or complete of starting any proposed work proposed completion or recommendate. 1. Sept. a Mesks plug 3600'. Cit. 2. Perf and attempt to squeeze 3. Perf and attempt to squeeze 4. Perf and attempt to squeeze Perf. spot 25 sx.	ed operations. (Clearly state all pertinent details, and). SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. Ru Culate well with mud Set CIBP @ 3600' - test @ 3190' with Xsks plug. If unable to establish spot at 1750' with a Xsks plug. If unable to establish rate at 32' with 100sks plug. If unable to establish rate, @ 362' @ 50' below to 50' above TOC minimum - see	mpletions: Attach wellbore diagram of n CBL to surface. casing 500psi/30min. Spot 25 sx cmt on pluga sysks plug @3250. e, spot a ysks plug @ 1850' fill to surface.
13. Describe proposed or complete of starting any proposed work proposed completion or recommendate. 1. Sept. a Mesks plug 3600'. Cit. 2. Perf and attempt to squeeze 3. Perf and attempt to squeeze 4. Perf and attempt to squeeze Perf. spot 25 sx.	ed operations. (Clearly state all pertinent details, and). SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. Ru culate well with mud Set CIBP @ 3600' - test @3190' with Xsks plug. If unable to establish spot at 1750' with a Xsks plug. If unable to establish rate, at X2' with 100sks plug. If unable to establish rate, @ 362'	mpletions: Attach wellbore diagram of n CBL to surface. casing 500psi/30min. Spot 25 sx cmt on pluga sysks plug @3250. e, spot a ysks plug @ 1850' fill to surface.
13. Describe proposed or complete of starting any proposed work proposed completion or recommendate. 1. Sept. a Mesks plug 3600'. Cit. 2. Perf and attempt to squeeze 3. Perf and attempt to squeeze 4. Perf and attempt to squeeze Perf. spot 25 sx.	ed operations. (Clearly state all pertinent details, and). SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. Ru Culate well with mud Set CIBP @ 3600' - test @ 3190' with Xsks plug. If unable to establish spot at 1750' with a Xsks plug. If unable to establish rate at 32' with 100sks plug. If unable to establish rate, @ 362' @ 50' below to 50' above TOC minimum - see	mpletions: Attach wellbore diagram of n CBL to surface. casing 500psi/30min. Spot 25 sx cmt on plug a %sks plug @3250. e, spot a Msks plug @ 1850' fill to surface. CBL WOC & tag
13. Describe proposed or complete of starting any proposed work proposed completion or recommendate. 1. Section 2. Section 2. Perf and attempt to squeeze 3. Perf and attempt to squeeze 4. Perf and attempt to squeeze Perf spot 25 sx minimum.	ed operations. (Clearly state all pertinent details, and). SEE RULE 19.15.7.14 NMAC. For Multiple Coppletion. Rusculate well with mud Set CIBP @ 3600' - test @ 3190' with Maks plug. If unable to establish spot at 1750' with a Maks plug. If unable to establish rate at 32' with 100sks plug. If unable to establish rate, @ 362' @ 50' below to 50' above TOC minimum - see at 25 sx cmt or 100' whichever is greater	mpletions: Attach wellbore diagram of n CBL to surface. casing 500psi/30min. Spot 25 sx cmt on pluga sysks plug @3250. e, spot a ysks plug @ 1850' fill to surface.
13. Describe proposed or complete of starting any proposed work proposed completion or recommendate. 1. Sept. a Mesks plug 3600'. Cit. 2. Perf and attempt to squeeze 3. Perf and attempt to squeeze 4. Perf and attempt to squeeze Perf. spot 25 sx.	ed operations. (Clearly state all pertinent details, and). SEE RULE 19.15.7.14 NMAC. For Multiple Coppletion. Rusculate well with mud Set CIBP @ 3600' - test @ 3190' with Maks plug. If unable to establish spot at 1750' with a Maks plug. If unable to establish rate at 32' with 100sks plug. If unable to establish rate, @ 362' @ 50' below to 50' above TOC minimum - see at 25 sx cmt or 100' whichever is greater	mpletions: Attach wellbore diagram of n CBL to surface. casing 500psi/30min. Spot 25 sx cmt on plug a %sks plug @3250. e, spot a Msks plug @ 1850' fill to surface. CBL WOC & tag
13. Describe proposed or complete of starting any proposed work proposed completion or recommendate. 1. Section 2. Section 2. Perf and attempt to squeeze 3. Perf and attempt to squeeze 4. Perf and attempt to squeeze Perf spot 25 sx minimum. Last Reported Production	ed operations. (Clearly state all pertinent details, and SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. Rusculate well with mud Set CIBP @ 3600' - test @3190' with Msks plug. If unable to establish spot at 1750' with a Msks plug. If unable to establish rate at M2' with 100sks plug. If unable to establish rate, @ 362' @ 50' below to 50' above TOC minimum - see an 25 sx cmt or 100' whichever is greater	mpletions: Attach wellbore diagram of n CBL to surface. casing 500psi/30min. Spot 25 sx cmt on plug a %sks plug @3250. e, spot a Msks plug @ 1850' fill to surface. CBL WOC & tag
13. Describe proposed or complete of starting any proposed work proposed completion or recommendate. 1. Section 2. Section 2. Perf and attempt to squeeze 3. Perf and attempt to squeeze 4. Perf and attempt to squeeze Perf spot 25 sx minimum.	ed operations. (Clearly state all pertinent details, and). SEE RULE 19.15.7.14 NMAC. For Multiple Coppletion. Rusculate well with mud Set CIBP @ 3600' - test @ 3190' with Maks plug. If unable to establish spot at 1750' with a Maks plug. If unable to establish rate at 32' with 100sks plug. If unable to establish rate, @ 362' @ 50' below to 50' above TOC minimum - see at 25 sx cmt or 100' whichever is greater	mpletions: Attach wellbore diagram of n CBL to surface. casing 500psi/30min. Spot 25 sx cmt on plug a %sks plug @3250. e, spot a Msks plug @ 1850' fill to surface. CBL WOC & tag
13. Describe proposed or complete of starting any proposed work proposed completion or recomplete of starting any proposed work proposed completion or recomplete of the starting and proposed completion or recomplete of the starting and sta	ed operations. (Clearly state all pertinent details, and). SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. Rusculate well with mud Set CIBP @ 3600' - test @ 3190' with % sks plug. If unable to establish spot at 1750' with a % sks plug. If unable to establish rate at 3×2' with 100sks plug. If unable to establish rate, @ 362' © 50' below to 50' above TOC minimum - see an 25 sx cmt or 100' whichever is greater Ction 10/1/2005 Rig Release Date:	mpletions: Attach wellbore diagram of n CBL to surface. casing 500psi/30min. Spot 25 sx cmt on plug a %sks plug @3250. e, spot a %sks plug @ 1850' fill to surface. CBL WOC & tag Verify cmt to surface on all strings
13. Describe proposed or complete of starting any proposed work proposed completion or recomplete of starting any proposed work proposed completion or recomplete of starting any proposed work proposed completion or recomplete of the starting and starti	ed operations. (Clearly state all pertinent details, and SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. Rusculate well with mud Set CIBP @ 3600' - test @ 3190' with Sks plug. If unable to establish spot at 1750' with a sks plug. If unable to establish rat at 32' with 100sks plug. If unable to establish rate, @ 362' @ 50' below to 50' above TOC minimum - see an 25 sx cmt or 100' whichever is greater Ction 10/1/2005 Rig Release Date: MUST BE PL	mpletions: Attach wellbore diagram of n CBL to surface. casing 500psi/30min. Spot 25 sx cmt on plug a %sks plug @3250. e, spot a Msks plug @ 1850' fill to surface. CBL WOC & tag Verify cmt to surface on all strings UGGED BY 12/6/2023
13. Describe proposed or complete of starting any proposed work proposed completion or recomplete of starting any proposed work proposed completion or recomplete of starting any proposed work proposed completion or recomplete of the starting and starti	ed operations. (Clearly state all pertinent details, and). SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. Rusculate well with mud Set CIBP @ 3600' - test @ 3190' with % sks plug. If unable to establish spot at 1750' with a % sks plug. If unable to establish rate at 3×2' with 100sks plug. If unable to establish rate, @ 362' © 50' below to 50' above TOC minimum - see an 25 sx cmt or 100' whichever is greater Ction 10/1/2005 Rig Release Date:	mpletions: Attach wellbore diagram of n CBL to surface. casing 500psi/30min. Spot 25 sx cmt on plug a %sks plug @3250. e, spot a Msks plug @ 1850' fill to surface. CBL WOC & tag Verify cmt to surface on all strings UGGED BY 12/6/2023
13. Describe proposed or complete of starting any proposed work proposed completion or recomplete of starting any proposed work proposed completion or recomplete of the starting any proposed work proposed completion or recomplete of the starting and st	ed operations. (Clearly state all pertinent details, and SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. Rust of Clark (Set Clark) (Set	mpletions: Attach wellbore diagram of n CBL to surface. casing 500psi/30min. Spot 25 sx cmt on plug a \$2sks plug @3250. e, spot a \$2sks plug @ 1850' fill to surface. CBL WOC & tag Verify cmt to surface on all strings UGGED BY 12/6/2023 te and belief.
13. Describe proposed or complete of starting any proposed work proposed completion or recomplete of starting any proposed work proposed completion or recomplete of starting any proposed work proposed completion or recomplete of the starting and starti	ed operations. (Clearly state all pertinent details, and SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. Rusculate well with mud Set CIBP @ 3600' - test @ 3190' with Sks plug. If unable to establish spot at 1750' with a sks plug. If unable to establish rat at 32' with 100sks plug. If unable to establish rate, @ 362' @ 50' below to 50' above TOC minimum - see an 25 sx cmt or 100' whichever is greater Ction 10/1/2005 Rig Release Date: MUST BE PL	mpletions: Attach wellbore diagram of n CBL to surface. casing 500psi/30min. Spot 25 sx cmt on plug a %sks plug @3250. e, spot a Msks plug @ 1850' fill to surface. CBL WOC & tag Verify cmt to surface on all strings UGGED BY 12/6/2023
13. Describe proposed or complete of starting any proposed work proposed completion or recomplete of starting any proposed work proposed completion or recomplete of starting any proposed work proposed completion or recomplete of starting and starting a	ed operations. (Clearly state all pertinent details, and SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. Rust of Clark (Set Clark) (Set	mpletions: Attach wellbore diagram of n CBL to surface. casing 500psi/30min. Spot 25 sx cmt on plug a \$2sks plug @3250. e, spot a \$2sks plug @ 1850' fill to surface. CBL WOC & tag Verify cmt to surface on all strings UGGED BY 12/6/2023 te and belief. DATE 06/02/2023
13. Describe proposed or complete of starting any proposed work proposed completion or recomplete of starting any proposed work proposed completion or recomplete of starting any proposed work proposed completion or recomplete of the starting and attempt to squeeze and attemp	ed operations. (Clearly state all pertinent details, and). SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. Rusculate well with mud Set CIBP @ 3600' - test @ 3190' with Sks plug. If unable to establish spot at 1750' with a Sks plug. If unable to establish rate at 32' with 100sks plug. If unable to establish rate, @ 362' © 50' below to 50' above TOC minimum - see an 25 sx cmt or 100' whichever is greater Ction 10/1/2005 Rig Release Date: S***** MUST BE PL TITLE President E-mail address: mike@momenter	mpletions: Attach wellbore diagram of n CBL to surface. casing 500psi/30min. Spot 25 sx cmt on plug a %sks plug @3250. e, spot a %sks plug @ 1850' fill to surface. CBL WOC & tag Verify cmt to surface on all strings UGGED BY 12/6/2023 e and belief. DATE 06/02/2023 moperating.com PHONE: 325-762-2366
13. Describe proposed or complete of starting any proposed work proposed completion or recomplete of starting any proposed work proposed completion or recomplete of starting any proposed work proposed completion or recomplete of starting and starting a	ed operations. (Clearly state all pertinent details, and SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. Rusculate well with mud Set CIBP @ 3600' - test @ 3190' with Sks plug. If unable to establish spot at 1750' with a Sks plug. If unable to establish rate, @ 362' @ 50' below to 50' above TOC minimum - see an 25 sx cmt or 100' whichever is greater Ction 10/1/2005 Rig Release Date: S**** MUST BE PL Dive is true and complete to the best of my knowledge and address: mike@momentumegaen@momentume	mpletions: Attach wellbore diagram of n CBL to surface. casing 500psi/30min. Spot 25 sx cmt on plug a %sks plug @3250. e, spot a %sks plug @ 1850' fill to surface. CBL WOC & tag Verify cmt to surface on all strings UGGED BY 12/6/2023 e and belief. DATE 06/02/2023 moperating.com PHONE: 325-762-2366 ntumoperating.com
13. Describe proposed or complete of starting any proposed work proposed completion or recomplete of starting any proposed work proposed completion or recomplete of starting any proposed work proposed completion or recomplete of the starting and attempt to squeeze and attemp	ed operations. (Clearly state all pertinent details, and). SEE RULE 19.15.7.14 NMAC. For Multiple Copletion. Rusculate well with mud Set CIBP @ 3600' - test @ 3190' with Sks plug. If unable to establish spot at 1750' with a Sks plug. If unable to establish rate at 32' with 100sks plug. If unable to establish rate, @ 362' © 50' below to 50' above TOC minimum - see an 25 sx cmt or 100' whichever is greater Ction 10/1/2005 Rig Release Date: S***** MUST BE PL TITLE President E-mail address: mike@momenter	mpletions: Attach wellbore diagram of n CBL to surface. casing 500psi/30min. Spot 25 sx cmt on plug a %sks plug @3250. e, spot a %sks plug @ 1850' fill to surface. CBL WOC & tag Verify cmt to surface on all strings UGGED BY 12/6/2023 e and belief. DATE 06/02/2023 moperating.com PHONE: 325-762-2366 ntumoperating.com



20# 7" set @ 4211' 8 3/4 Hole cemented

w/300 sks (TOC 2895' calculated)

CONDITIONS FOR PLUGGING AND ABANDONMENT

OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office II at (575)-748-1283 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down. Company representative will be on location during plugging procedures.

- A notice of intent to plug and abandon a wellbore is required to be approved before plugging
 operations are conducted. A cement evaluation tool is required in order to ensure isolation of
 producing formations, protection of water and correlative rights. A cement bond log or other
 accepted cement evaluation tool is to be provided to the division for evaluation if one has not
 been previously run or if the well did not have cement circulated to surface during the original
 casing cementing job or subsequent cementing jobs. Insure all bradenheads have been
 exposed, identified and valves are operational prior to rig up.
- 2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- 3. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- 5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
- 6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- 8. Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- 10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- 13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- 14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.

- 16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- 18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).
- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
 - A) Fusselman
 - B) Devonian
 - C) Morrow
 - D) Wolfcamp
 - E) Bone Springs
 - F) Delaware
 - G) Any salt sections
 - H) Abo
 - 1) Glorieta
 - J) Yates.
 - K) Cherry Canyon Eddy County
 - L) Potash---(In the R-111-P Area (Page 3 & 4), a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.
- 21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing

DRY HOLE MARKER REQUIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

1. Operator name 2. Lease and Well Number 3.API Number 4. Unit Letter 5. Quarter Section (feet from the North, South, East or West) 6. Section, Township and Range 7. Plugging Date 8. County (SPECIAL CASES)------AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

R-111-P Area

T 18S - R 30E

Sec 10 Unit P. Sec 11 Unit M,N. Sec 13 Unit L,M,N. Sec 14 Unit C -P. Sec 15 Unit A G,H,I,J,K,N,O,P. Sec 22 Unit All except for M. Sec 23, Sec 24 Unit C,D,E,L, Sec 26 Unit A-G, Sec 27 Unit A,B,C

T 19S - R 29E

Sec 11 Unit P. Sec 12 Unit H-P. Sec 13. Sec 14 Unit A,B,F-P. Sec 15 Unit P. Sec 22 Unit A,B,C,F,G,H,I,J K,N,O,P. Sec 23. Sec 24. Sec 25 Unit D. Sec 26 Unit A-F. Sec 27 Unit A,B,C,F,G,H.

T 19S - R 30E

Sec 2 Unit K,L,M,N. Sec 3 Unit I,L,M,N,O,P. Sec 4 Unit C,D,E,F,G,I-P. Sec 5 Unit A,B,C,E-P. Sec 6 Unit I,O,P. Sec 7 – Sec 10. Sec 11 Unit D, G—P. Sec 12 Unit A,B,E-P. Sec 13 Unit A-O. Sec 14-Sec 18. Sec 19 Unit A-L, P. Sec 20 – Sec 23. Sec 24 Unit C,D,E,F,L,M,N. Sec 25 Unit D. Sec 26 Unit A-G, I-P. Sec 27, Sec 28, Sec 29 Unit A,B,C,D,F,G,H,I,J,O,P. Sec 32 Unit A,B,G,H,I,J,N,O,P. Sec 33. Sec 34. Sec 35. Sec 36 Unit D,E,F,I-P.

T 19S - R 31E

Sec 7 Unit C,D,E,F,L. Sec 18 Unit C,D,E,F,G,K,L. Sec 31 Unit M. Sec 34 Unit P. Sec 35 Unit M,N,O. Sec 36 Unit O,P.

T 20S - R 29E

Sec 1 Unit H,I,P. Sec 13 Unit E,L,M,N. Sec 14 Unit B-P. Sec 15 Unit A,H,I,J,N,O,P. Sec 22 Unit A,B,C,F,G,H,I,J,O,P. Sec 23. Sec 24 Unit C,D,E,F,G,J-P. Sec 25 Unit A-O. Sec 26. Sec 27 Unit A,B,G,H,I,J,O,P. Sec 34 Unit A,B,G,H. Sec 35 Unit A-H. Sec 36 Unit B-G.

T 20S - R 30E

Sec 1 – Sec 4. Sec 5 Unit A,B,C,E-P. Sec 6 Unit E,G-P. Sec 7 Unit A-H,I,J,O,P. Sec 8 – 17. Sec 18 Unit A,B,G,H,I,J,O,P. Sec 19 Unit A,B,G,H,I,J,O,P. Sec 30 Unit A-L,N,O,P. Sec 31 Unit A,B,G,H,I,P. Sec 32 – Sec 36.

T 20S - R 31E

Sec 1 Unit A,B,C,E-P. Sec 2. Sec 3 Unit A,B,G,H,I,J,O,P. Sec 6 Unit D,E,F,J-P. Sec 7. Sec 8 Unit E-P. Sec 9 Unit E,F,J-P. Sec 10 Unit A,B,G-P. Sec 11 – Sec 36.

T 21S - R 29E

Sec 1 – Sec 3. Sec 4 Unit L1 – L16,I,J,K,O,P. Sec 5 Unit L1. Sec 10 Unit A,B,H,P. Sec 11 – Sec 14. Sec 15 Unit A,H,I. Sec 23 Unit A,B. Sec 24 Unit A,B,C,D,F,G,H,I,J,O,P. Sec 25 Unit A,O,P. Sec 35 Unit G,H,I,J,K,N,O,P. Sec 36 A,B,C,F – P.

T 21S - R 30E

Sec 1 – Sec 36

T 21S - R 31E

Sec 1 – Sec 36

T 22S - R 28E

Sec 36 Unit A,H,I,P.

T 22S - R 29E

Sec 1. Sec2. Sec 3 Unit I,J,N,O,P. Sec 9 Unit G – P. Sec 10 – Sec 16. Sec 19 Unit H,I,J. Sec 20 – Sec 28. Sec 29 Unit A,B,C,D,G,H,I,J,O,P. Sec 30 Unit A. Section 31 Unit C – P. Sec 32 – Sec 36

T 22S - R 30E

Sec 1 – Sec 36

T 22S - R 31E

Sec 1 – Sec 11. Sec 12 Unit B,C,D,E,F,L. Sec 13 Unit E,F,K,L,M,N. Sec 14 – Sec 23. Sec 24 Unit C,D,E,F,K,L,M,N. Sec 25 Unit A,B,C,D. Sec 26 Unit A,BC,D,G,H. Sec 27 – Sec 34.

T 23S - R 28E

Sec 1 Unit A

T 23S - R 29E

Sec 1 – Sec 5. Sec 6 Unit A – I, N,O,P. Sec 7 Unit A,B,C,G,H,I,P. Sec 8 Unit A – L, N,O,P. Sec 9 – Sec 16. Sec 17 Unit A,B,G,H,I,P. Sec 21 – Sec 23. Sec 24 Unit A – N. Sec 25 Unit D,E,L. Sec 26. Sec 27. Sec 28 Unit A – J, N,O,P. Sec 33 Unit A,B,C. Sec 34 Unit A,B,C,D,F,G,H. Sec 35. Sec 36 Unit B,C,D,E,F,G,K,L.

T 23S - R 30E

Sec 1 – Sec 18. Sec 19 Unit A – I,N,O,P. Sec 20, Sec 21. Sec 22 Unit A – N, P. Sec 23, Sec 24, Sec 25. Sec 26 Unit A,B,F-P. Sec 27 Unit C,D,E,I,N,O,P. Sec 28 Unit A – H, K,L,M,N. Sec 29 Unit A – J, O,P. Sec 30 Unit A,B. Sec 32 A,B. Sec 33 Unit C,D,H,I,O,P. Sec 34, Sec 35, Sec 36.

T 23S - R 31E

Sec 2 Unit D,E,J,O. Sec 3 – Sec 7. Sec 8 Unit A – G, K – N. Sec 9 Unit A,B,C,D. Sec 10 Unit D,P. Sec 11 Unit G,H,I,J,M,N,O,P. Sec 12 Unit E,L,K,M,N. Sec 13 Unit C,D,E,F,G,J,K,L,M,N,O. Sec 14. Sec 15 Unit A,B,E – P. Sec 16 Unit I, K – P. Sec 17 Unit B,C,D,E, I – P. Sec 18 – Sec 23. Sec 24 Unit B – G, K,L,M,N. Sec 25 Unit B – G, J,K,L. Sec 26 – Sec 34. Sec 35 Unit C,D,E.

T 24S – R 29E

Sec 2 Unit A, B, C, D. Sec 3 Unit A

T 24S - R 30E

Sec 1 Unit A – H, J – N. Sec 2, Sec 3. Sec 4 Unit A,B,F – K, M,N,O,P. Sec 9 Unit A – L. Sec 10 Unit A – L, O,P. Sec 11. Sec 12 Unit D,E,L. Sec 14 Unit B – G. Sec 15 Unit A,B,G,H.

T 24S - R 31E

Sec 3 Unit B – G, J – O. Sec 4. Sec 5 Unit A – L, P. Sec 6 Unit A – L. Sec 9 Unit A – J, O,P. Sec 10 Unit B – G, K – N. Sec 35 Unit E – P. Sec 36 Unit E,K,L,M,N.

T 25S - R 31E

Sec 1 Unit C,D,E,F. Sec 2 Unit A – H.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 224327

CONDITIONS

Operator:	OGRID:
MOMENTUM OPERATING CO INC	196069
P. O. Box 2439	Action Number:
Albany, TX 76430	224327
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By		Condition Date
gcordero	None	6/6/2023