(June 2019) DI	UNITED STATES PARTMENT OF THE INTERIOR			FORM APPROVED OMB No. 1004-0137 Expires: December 31, 2024		
BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.			5. Lease Serial 1	5. Lease Serial No. MM 13232A 6. If Indian, Allottee or Tribe Name		
			NAME AND ADDRESS AND ADDRESS OF ADDRESS OF ADDRESS ADDRESS ADDRESS ADDRESS ADDRESS ADDRESS ADDRESS ADDRESS ADDR			
SUBMIT IN TRIPLICATE - Other Instructions on page 2			the second s	7. If Unit of CA/Agreement, Name and/or No.		
1. Type of Well			8. Well Name an	8. Well Name and No. Winchester Federal # 3		
2. Name of Operator BXP Operating	, LLC		9. API Well No.	9. API Well No. 30-015-28038		
3a. Address 1515 Calle Sur, Suite Hobbs, NM 88240	174	3b. Phone No. (include area cod (575) 492-1236	le) 10. Field and Poo	10. Field and Pool or Exploratory Area		
4. Location of Well (Footage, Sec., T. 1980' FNL & 2130' FWL UL-F, S	R., M., or Survey Description)		11. Country or Pa	STATE AND ADDRESS OF A DECK OF A		
			Eddy County,			
TYPE OF SUBMISSION		X(ES) TO INDICATE NATUR		OTHER DATA		
Notice of Intent	Acidize	Deepen Hydraulic Fracturing	PE OF ACTION Production (Start/Resul	me) Water Shut-Off Well Integrity		
Subsequent Report	Casing Repair	New Construction	Recomplete	Other		
Final Abandonment Notice	Change Plans	Plug and Abandon Plug Back	Temporarily Abandon Water Disposal			
Artach the bond thider which the w following completion of the involved operatic been completed. Final Abandonme site is ready for final inspection.) 1) Set CIBP at 6117; Pressure test 500psi, 30mir 2) Spot 25 ax ent on CIBP 3. Bone Spring Plug: 4592' to 4248'. 40sx. Perf and 4) Delaware: 2916' to 2787'. 40sx. Perf and sgr. 1	vork will be performed or prov ons. If the operation results in <i>i</i> nt Notices must be filed only a ns nd sqz. WOC & Tag WOC & Tag	ide the Bond No. on file with Bl a multiple completion or recom-	M/BIA. Required subsequent	of work and approximate obtaining the form offs of all pertinent markers and zones it reports must be filed within 30 days rm 3160-4 must be filed once testing ha eted and the operator has determined th		
 Attach the bond thider which the w following completion of the involved operatic been completed. Final Abandonme site is ready for final inspection.) 1) Set CIBP at 6117'. Pressure test 500psi, 30mis 2) Spot 25 as ent on CIBP 3. Bone Spring Plug: 4392' to 4248'. 40as. Perf and 4) Delaware: 2916' to 2787'. 40as. Perf and sqr. 1 5) Base of Salt & Shoe: 1017'.791'. 55as. WOC a 6) Top of Salt + High Cave Karst Surface Plug: 5 9) Circulate emt to surface inside/outside 41/2" of 10) Cut off welthead & Verify cmt 	vork will be performed or prov ons. If the operation results in a nt Notices must be filed only a ns work to be the work to be the ad tag 32' to 0	ide the Bond No. on file with Bl a multiple completion or recom-	M/BIA. Required subsequen letion in a new interval, a Foi eclamation, have been compl	t reports must be filed within 30 days		
 Attach the bond thider which the w following completion of the involved operatic been completed. Final Abandonme site is ready for final inspection.) 1) Set CIBP at 6117'. Pressure test 500psi, 30mir 2) Spot 25 ex cmt on CIBP 3. Bone Spring Plug: 4392' to 4248'. 40sx. Perf and 4) Delaware: 2916' to 2787'. 40sx. Perf and sqt. 4 9) Base of Sait & Shoe: 1017'.791'. 55sx. WOC a 6) Top of Sait + High Cave Karst Surface Plug: 5 9) Circulate cmt to surface inside/outside 41/2" of 	vork will be performed or prov ons. If the operation results in a nt Notices must be filed only a ns work to be the work to be the ad tag 32' to 0	ide the Bond No. on file with Bi a multiple completion or recorn for all requirements, including	M/BIA. Required subsequent letion in a new interval, a Fou eclamation, have been comple D KI	t reports must be filed within 30 days rm 3160-4 must be filed once testing he eted and the operator has detennined th igitally signed by		
 Attach the bond thider which the w following completion of the involved operatic been completed. Final Abandonme site is ready for final inspection.) 1) Set CIBP at 6117', Pressure test 500psl, 30mlr 3) Spot 25 as ent on CIBP 3. Bone Spring Plug: 4392' to 4248', 40sr. Perf and sqr. N 5) Base of Sait & Shoe : 1017'.791', 55sr. WOC a 6) Top of Sait + High Cave Karst Surface Plug: 5 9) Circulate cmt to surface inside/outside 41/2' of 10) Cut off wellhead & Verify cmt 11) Install dry hole marker 	vork will be performed or prov ons. If the operation results in <i>i</i> nt Notices must be filed only a na na se woc & Tag woc & Tag at to 0 ag	ide the Bond No. on file with Bi a multiple completion or recomp for all requirements, including KEITI IMM	M/BIA. Required subsequent letion in a new interval, a Fou eclamation, have been comple D KI	t reports must be filed within 30 days rm 3160-4 must be filed once testing ha eted and the operator has detennined th gitally signed by EITH IMMATTY ate: 2022.09.08		
 Attach the bond thider which the w following completion of the involved operatic been completed. Final Abandonme site is ready for final inspection.) 1) Set CIBP at 6117', Pressure test 500psl, 30mlr 3) Spot 25 as ent on CIBP 3. Bone Spring Plug: 4392' to 4248', 40sr. Perf and sqr. N 5) Base of Sait & Shoe : 1017'.791', 55sr. WOC a 6) Top of Sait + High Cave Karst Surface Plug: 5 9) Circulate cmt to surface inside/outside 41/2' of 10) Cut off wellhead & Verify cmt 11) Install dry hole marker 	vork will be performed or prov ons. If the operation results in <i>i</i> nt Notices must be filed only a ns nd sqz. WOC & Tag NOC & Tag NOC & Tag and Tag 32' to 0 48	Ide the Bond No. on file with Bi a multiple completion or recomp ther all requirements, including KERTI IMMM	M/BIA. Required subsequent letion in a new interval, a Fou eclamation, have been comple D KI	t reports must be filed within 30 days rm 3160-4 must be filed once testing ha eted and the operator has detennined th gitally signed by EITH IMMATTY ate: 2022.09.08		
 Anach the bond thider which the w following completion of the involved operatic been completed. Final Abandonme site is ready for final inspection.) 1) Set CIBP at 6117'. Pressure test 500psl, 30mir 3) Spot 25 as ent on CIBP 3. Bone Spring Plug: 492' to 4248'. 40as. Perf and 45. 1 9 Delaware: 2916' to 2787'. 40as. Perf and 45. 1 9 Delaware: 2916' to 2787'. 40as. Perf and 45. 1 9 Delaware: 2916' to 2787'. 40as. Perf and 45. 1 9 Octoulate cmt to surface inside/outside 41/2' of 10) Cut off weilhead & Verify cmt 11) Install dry hole marker 4. I hereby certify that the foregoing is to M. G. M. M. S. M	rue and correct. Name (Printe the Correct State Print Notices must be filed only a Not of the print Not of the print Not of the print the print of the print the print of the print the print of the print of the print the print of the print of t	Ide the Bond No. on file with Bi a multiple completion or recomp ther all requirements, including KEITI IMM (//Typed) Title	M/BIA. Required subsequent letion in a new interval, a For eclamation, have been comple ATTY D KI ATTY 12 /2 /22	t reports must be filed within 30 days rm 3160-4 must be filed once testing ha eted and the operator has detennined th gitally signed by EITH IMMATTY ate: 2022.09.08		
A taken the bond theor which the w following completion of the involved operatic been completed. Final Abandonme site is ready for final inspection.) 1) Set CIBP at 6117, Pressure test 500psl, 30mit 2) Spot 25 as ant on CIBP 3. Bone Spring Plug: 4392' to 4248', 40ax, Perf and 4. Delsware 2016' to 2787', 40ax, Perf and qa. 4 5) Base of Salt & Shoe : 1017'-791', 55ax, WOC a 6) Top of Salt + High Cave Karst Surface Plug: 5 9) Circulate cmt to surface inside/outside 41/2' of 10) Cut off wellhead & Verify cmt 11) Install dry hole marker 4. I hereby certify that the foregoing is the M. G. Mark Signature Market	rue and correct. Name (Printe the Correct State Print Notices must be filed only a Not of the print Not of the print Not of the print the print of the print the print of the print the print of the print of the print the print of the print of t	Ide the Bond No. on file with Bi a multiple completion or recomp inter all requirements, including the KEITI IMMM (//Typed) Title Date 34 OR FEDERAL OR STA	M/BIA. Required subsequent letion in a new interval, a For eclamation, have been comple ATTY D KI ATTY 12 /2 /22	t reports must be filed within 30 days rm 3160-4 must be filed once testing ha eted and the operator has detennined th EITH IMMATTY ate: 2022.09.08 4:25:47 -06'00'		
Anach the bond theor which the w following completion of the involved operatic been completed. Final Abandonme site is ready for final inspection.) 1) Set CIBP at 6117', Pressure test 500psi, 30mir 2) Spot 25 as ent on CIBP 3) Bons Opting Plug 492' to 4248', 40as, Perf and 4) Delaware: 2916' to 2787', 40as, Perf and ser, t 5) Base of Salt & Shoe : 1017'.791', 55as, WOC a 6) Top of Salt + High Cave Karst Surface Plug: 5 9) Circulate ent to surface inside/outside 41/2' of 10) Cut off welthead & Verify cmt 11) Install dry hole marker 4. I hereby certify that the foregoing is th M. G. M. G. Signature Machine record -NMOCD gc 10/24/200	ork will be performed or prov ons. If the operation results in 1 nt Notices must be filed only a nd sqr. WOC & Tag WOC & Tag MOC & Tag NOC & Tag NO	Ide the Bond No. on file with Bi a multiple completion or recomp ther all requirements, including to the all requirements, including to the all requirements including to the all requirements including to the all requirements including to the al	M/BIA. Required subsequent letion in a new interval, a For eclamation, have been comple ATTY D KI ATTY 12 /2 /22	t reports must be filed within 30 days rm 3160-4 must be filed once testing ha eted and the operator has detennined th gitally signed by EITH IMMATTY ate: 2022.09.08		
A table the bond inder which the w following completion of the involved operatic been completed. Final Abandonme site is ready for final inspection.) 1) Set CIBP at 6117', Pressure test 500psl, 30mir 3) Spot 25 as ent on CIBP 3. Bone Spring Plug: 4321 to 4248', 40sr. Perf and 4) Delaware: 2916' to 2787', 40sr. Perf and sqr. V 5) Base of Salt & Shoe: 1017'-791', 55sr. WOC a 6) Top of Salt + High Cave Karst Surface Plug: 5 9) Circulate emt to surface inside/outside 41/2' of 10) Cut off welthead & Verify emt 11) Install dry hole marker 4. I hereby certify that the foregoing is the Market Market Signature Market Surface Plug: 5 Signature Market Surface Plug: 5 precord -NMOCD gc 10/24/20 pproved by conditions of approval, if sny, are attached to the spelicent holds legal or equilable the applicant holds legal or equilable to the spelicent holds leg	Approval of this notice does altable title to those rights in the solutions the results of the the to the	Ide the Bond No. on file with Bi a multiple completion or recomp ifter all requirements, including the KEIT IMMM (I/Typed) (I/Typed) Title Date OR FEDERAL OR STA Senot warrant or ne subject lease Orffice crime for any person knowingly	M/BIA. Required subsequent letion in a new interval, a For- eclamation, have been comple ATTY D KI ATTY D 12 /8 /22 TE OFICE USE	t reports must be filed within 30 days rm 3160-4 must be filed once testing ha eted and the operator has determined th EITH IMMATTY ate: 2022.09.08 4:25:47 -06'00'		

GENERAL INSTRUCTIONS

This form is designed for submitting proposals to perform certain well operations and reports of such operations when completed as indicated on Federal and Indian lands pursuant to applicable Federal law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local area or regional procedures and practices, are either shown below, will be issued by or may be obtained from the local Federal office.

SPECIFIC INSTRUCTIONS

Item 4 - Locations on Federal or Indian land should be described in accordance with Federal requirements. Consult the local Federal office for specific instructions.

Item 13: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by the local Federal office. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to the top of any tubing left in the hole; method of closing top of well and date well site conditioned for final inspection looking for approval of the abandonment. If the proposal will involve hydraulic fracturing operations, you must comply with 43 CFR 3162.3-3, including providing information about the protection of usable water. Operators should provide the best available information about all formations containing water and their depths. This information could include data and interpretation of resistivity logs run on nearby wells. Information may also be obtained from state or tribal regulatory agencies and from local BLM offices.

NOTICES

The privacy Act of 1974 and the regulation in 43 CFR 2.48(d) provide that you be furnished the following information in connection with information required by this application.

AUTHORITY: 30 U.S.C. 181 et seq., 351 et seq., 25 U.S.C. 396; 43 CFR 3160.

PRINCIPAL PURPOSE: The information is used to: (1) Evaluate, when appropriate, approve applications, and report completion of subsequent well operations, on a Federal or Indian lease; and (2) document for administrative use, information for the management, disposal and use of National Resource lands and resources, such as: (a) evaluating the equipment and procedures to be used during a proposed subsequent well operation and reviewing the completed well operations for compliance with the approved plan; (b) requesting and granting approval to perform those actions covered by 43 CFR 3162.3-2, 3162.3-3, and 3162.3-4; (c) reporting the beginning or resumption of production, as required by 43 CFR 3162.4-1(c)and (d) analyzing future applications to drill or modify operations in light of data obtained and methods used.

ROUTINE USES: Information from the record and/or the record will be transferred to appropriate Federal, State, local or foreign agencies, when relevant to civil, criminal or regulatory investigations or prosecutions in connection with congressional inquiries or to consumer reporting agencies to facilitate collection of debts owed the Government.

EFFECT OF NOT PROVIDING THE INFORMATION: Filing of this notice and report and disclosure of the information is mandatory for those subsequent well operations specified in 43 CFR 3162.3-2, 3162.3-3, 3162.3-4.

The Paperwork Reduction Act of 1995 requires us to inform you that:

The BLM collects this information to evaluate proposed and/or completed subsequent well operations on Federal or Indian oil and gas leases.

Response to this request is mandatory.

The BLM would like you to know that you do not have to respond to this or any other Federal agency-sponsored information collection unless it displays a currently valid OMB control number.


BURDEN HOURS STATEMENT: Public reporting burden for this form is estimated to average 8 hours per response, including the time for reviewing instructions, gathering and maintaining data, and completing and reviewing the form. Direct comments regarding the burden estimate or any other aspect of this form to U.S. Department of the Interior, Bureau of Land Management (1004-0137), Bureau Information Collection Clearance Officer (WO-630), 1849 C St., N.W., Mail Stop 401 LS, Washington, D.C. 20240

(Form 3160-5, page 2)


- 1) Set CIBP at 6117'. Pressure test 500psi, 30mins
- 2) Spot 25 sx cmt on CIBP
- 3. Bone Spring Plug: 4392' to 4248'. 40sx. Perf and sqz. WOC & Tag
- 4) Delaware: 2916' to 2787'. 40sx. Perf and sqz. WOC & Tag
- 5) Base of Salt & Shoe : 1017'-791'. 55sx. WOC and Tag
- 6) Top of Salt + High Cave Karst Surface Plug: 532' to 0
- 9) Circulate cmt to surface inside/outside 41/2" csg
- 10) Cut off wellhead & Verify cmt
- 11) Install dry hole marker

.

BXP Operating, LLC Winchester Federal #3



4 1/2 "10.5# @ 6525' w/ 1925 sx (Reported TOC 5000' on sundry)



Sundry ID	2686253				1	
Plug Type	Тор	Bottom	Length	Tag	Sacks	Notes
Surface Plug	0.00	532.00			130.00	Perf and sqz. Shoe + High cave karst surface plug Perf and sqz. Shoe
Top of Salt @ 482	0.00	532.00	532.00	Verify		+ High cave karst surface plug
Shoe Plug	791.00	1017.00	226.00	Tag/Verify	55.00	Covered/combined with BOS plug
Base of Salt @ 967	791.00	1017.00	226.00	Tag/Verify	55.00	Perf and sqz
Delaware @ 2866	2787.34	2916.00		If solid base no need to Tag (CIBP present and/or Mechanic al Integrity Test), If Perf & Sqz then Tag, Leak Test all CIBP if no Open Perforatio ns		Perf and sqz
Bonesprings @ 4342	4248.58	4392.00		If solid base no need to Tag (CIBP present and/or Mechanic al Integrity Test), If Perf & Sqz then Tag, Leak Test all CIBP if no Open Perforatio ns		Perf and sqz

				If solid base no need to Tag (CIBP present and/or Mechanic al Integrity Test), If Perf & Sqz then Tag, Leak Test all CIBP if no Open Perforatio		Test 500psi, 30min
CIBP Plug	6082.00	6117.00	35.00	115	20.00	Tost Doupsi, outfill

No more than 2000' is to be allowed between plugs in open hole, and n	io more than 3000' between plugs
in cased hole.	
Class H >7500'	
Class C<7500'	
Fluid used to mix the cement in R111P shall be saturated with the salts penetrated, and in suitable proportions, but not more than 3% calcium be considered the desired mixture whenever possible.	CARL STAR CONTRACTOR AND ADDRESS AND ADDRESS AND ADDRESS ADDRESS ADDRESS ADDRESS ADDRESS ADDRESS ADDRESS ADDRESS
Critical, High Cave Karst: Cave Karst depth to surface	
R111P: Solid plug in all annuli - 50' from bottom of sait to surface.	

Class H: 1.06 ft^3/sx

Onshore Order 2.III.G Drilling Abandonment Requirements: "All formations bearing usable-quality water, oll, gas, or geothermal resources, and/or a prospectively valuable deposit of minerals shall be protected.

Cave Karst/Potash Cement	High	KARST DEPTH/TOS to a	surface 500.00
Shoe @ Shoe @	850.00 6525.00		
Perforatons Top @	6217.00	Perforations Bottom @	6416.00
		CIBP @	6117.00

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-689-5981.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds). A weep hole shall be left if a metal plate is welded in place.

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**

8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any/all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip (across the slope and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech/Environmental Protection Specialist 575-234-5909 (Office), 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crisha Morgan Environmental Protection Specialist 575-234-5987

Jose Martinez-Colon Environmental Protection Specialist 575-234-5951

Mark Mattozzi Environmental Protection Specialist 575-234-5713

Robert Duenas Environmental Protection Specialist 575-234-2229

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
BXP Operating, LLC	329487
11757 KATY FREEWAY	Action Number:
HOUSTON, TX 77079	277191
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)
CONDITIONS	

Created By Condition Condition Date 10/24/2023 None gcordero

Page 13 of 13

.

Action 277191