

Office	ate of New Mexico	Form C-1031
Strict I – (575) 393-6161 Energy, Minerals and Natural Resources 25 N. French Dr., Hobbs, NM 88240 Strict II – (575) 748 1383		WELL API NO.
811 S. First St., Artesia, NM 88210 OIL CON	SERVATION DIVISI	ON 50-025-25144 5. Indicate Type of Lease
District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505 1220 South St. Francis Dr. Santa Fe, NM 87505		STATE FEE
		6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other		7. Lease Name or Unit Agreement Name New Mexico S State
		8. Well Number 027
2. Name of Operator Empire Petroleum Corporation – New Mexico		9. OGRID Number 330679
3. Address of Operator 2200 S. Utica Place Suite 150, Tulsa, Oklahoma 74114		10. Pool name or WildcatBlinebry Oil and Gas
4. Well Location		
Unit Letter $\underline{\underline{K}} : \underline{1830}$ feet fr	om the <u>South</u> line	and <u>1900</u> feet from the <u>West</u> line
Section 2 Towns		NMPM County Lea
,	how whether DR, RKB, RT,	GR, etc.)
3402' GR		
11 1		Notice, Report or Other Data
		SUBSEQUENT REPORT OF: AL WORK ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOFF TEMPORARILY ABANDON CHANGE PLANS COMMENCE DE		NCE DRILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE CON	 -	/CEMENT JOB
	_	-
CLOSED-LOOP SYSTEM	_	_
OTLIED.		
	Clearly state all pertinent d	_
13. Describe proposed or completed operations. (Clearly state all pertinent d	etails, and give pertinent dates, including estimated date ltiple Completions: Attach wellbore diagram of
13. Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 proposed completion or recompletion.	Clearly state all pertinent d	etails, and give pertinent dates, including estimated date
13. Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 proposed completion or recompletion.1. MIRU WOR.	Clearly state all pertinent d	etails, and give pertinent dates, including estimated date
 13. Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 proposed completion or recompletion. 1. MIRU WOR. 2. Unhang and PU rod string. 3. Unseat pump and POOH with rod str 	Clearly state all pertinent d 19.15.7.14 NMAC. For Mu	etails, and give pertinent dates, including estimated date
 Describe proposed or completed operations. Of starting any proposed work). SEE RULE 1 proposed completion or recompletion. MIRU WOR. Unhang and PU rod string. Unseat pump and POOH with rod str. ND WH. NU BOP. 	Clearly state all pertinent d 19.15.7.14 NMAC. For Mu	etails, and give pertinent dates, including estimated date
 Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 proposed completion or recompletion. MIRU WOR. Unhang and PU rod string. Unseat pump and POOH with rod str. ND WH. NU BOP. Release TAC and scan tubing OOH. 	Clearly state all pertinent d 19.15.7.14 NMAC. For Mu	etails, and give pertinent dates, including estimated date ltiple Completions: Attach wellbore diagram of
 Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 proposed completion or recompletion. MIRU WOR. Unhang and PU rod string. Unseat pump and POOH with rod str. ND WH. NU BOP. Release TAC and scan tubing OOH. RIH with CIBP and set at 5315'. 	Clearly state all pertinent d 19.15.7.14 NMAC. For Mu	etails, and give pertinent dates, including estimated date ltiple Completions: Attach wellbore diagram of
 Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 proposed completion or recompletion. MIRU WOR. Unhang and PU rod string. Unseat pump and POOH with rod str. ND WH. NU BOP. Release TAC and scan tubing OOH. 	Clearly state all pertinent d 19.15.7.14 NMAC. For Mu	etails, and give pertinent dates, including estimated date ltiple Completions: Attach wellbore diagram of Condition of Approval: notify
 Describe proposed or completed operations. Of starting any proposed work). SEE RULE 1 proposed completion or recompletion. MIRU WOR. Unhang and PU rod string. Unseat pump and POOH with rod str. ND WH. NU BOP. Release TAC and scan tubing OOH. RIH with CIBP and set at 5315'. Dump 4 sks of cement on top. Pressure test. Circulate packer fluid. 	Clearly state all pertinent d 19.15.7.14 NMAC. For Mu ring configuration.	etails, and give pertinent dates, including estimated date ltiple Completions: Attach wellbore diagram of Condition of Approval: notify OCD Hobbs office 24 hours
13. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 proposed completion or recompletion. 1. MIRU WOR. 2. Unhang and PU rod string. 3. Unseat pump and POOH with rod str. 4. ND WH. NU BOP. 5. Release TAC and scan tubing OOH. 6. RIH with CIBP and set at 5315'. 7. Dump 4 sks of cement on top. 8. Pressure test. 9. Circulate packer fluid. 10. Notify NMOCD of MIT.	Clearly state all pertinent d 19.15.7.14 NMAC. For Mu ring configuration.	etails, and give pertinent dates, including estimated date ltiple Completions: Attach wellbore diagram of Condition of Approval: notify
 Describe proposed or completed operations. (of starting any proposed work). SEE RULE 1 proposed completion or recompletion. MIRU WOR. Unhang and PU rod string. Unseat pump and POOH with rod str. ND WH. NU BOP. Release TAC and scan tubing OOH. RIH with CIBP and set at 5315'. Dump 4 sks of cement on top. Pressure test. Circulate packer fluid. 	Clearly state all pertinent d 19.15.7.14 NMAC. For Mu ring configuration.	etails, and give pertinent dates, including estimated date ltiple Completions: Attach wellbore diagram of Condition of Approval: notify OCD Hobbs office 24 hours
13. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 proposed completion or recompletion. 1. MIRU WOR. 2. Unhang and PU rod string. 3. Unseat pump and POOH with rod str. 4. ND WH. NU BOP. 5. Release TAC and scan tubing OOH. 6. RIH with CIBP and set at 5315'. 7. Dump 4 sks of cement on top. 8. Pressure test. 9. Circulate packer fluid. 10. Notify NMOCD of MIT. 11. Perform MIT and submit paperwork.	Clearly state all pertinent d 19.15.7.14 NMAC. For Mu ring configuration.	etails, and give pertinent dates, including estimated date ltiple Completions: Attach wellbore diagram of Condition of Approval: notify OCD Hobbs office 24 hours
 Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 proposed completion or recompletion. MIRU WOR. Unhang and PU rod string. Unseat pump and POOH with rod str. ND WH. NU BOP. Release TAC and scan tubing OOH. RIH with CIBP and set at 5315'. Dump 4 sks of cement on top. Pressure test. Circulate packer fluid. Notify NMOCD of MIT. Perform MIT and submit paperwork. RDMO WOR. TA well. 	Clearly state all pertinent d 19.15.7.14 NMAC. For Mu ring configuration.	etails, and give pertinent dates, including estimated date ltiple Completions: Attach wellbore diagram of Condition of Approval: notify OCD Hobbs office 24 hours
 Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 proposed completion or recompletion. MIRU WOR. Unhang and PU rod string. Unseat pump and POOH with rod str. ND WH. NU BOP. Release TAC and scan tubing OOH. RIH with CIBP and set at 5315'. Dump 4 sks of cement on top. Pressure test. Circulate packer fluid. Notify NMOCD of MIT. Perform MIT and submit paperwork. RDMO WOR. TA well. 	Clearly state all pertinent d 19.15.7.14 NMAC. For Mu ring configuration.	etails, and give pertinent dates, including estimated date ltiple Completions: Attach wellbore diagram of Condition of Approval: notify OCD Hobbs office 24 hours
13. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 proposed completion or recompletion. 1. MIRU WOR. 2. Unhang and PU rod string. 3. Unseat pump and POOH with rod str. 4. ND WH. NU BOP. 5. Release TAC and scan tubing OOH. 6. RIH with CIBP and set at 5315'. 7. Dump 4 sks of cement on top. 8. Pressure test. 9. Circulate packer fluid. 10. Notify NMOCD of MIT. 11. Perform MIT and submit paperwork 12. RDMO WOR. 13. TA well.	Clearly state all pertinent d 19.15.7.14 NMAC. For Mu ring configuration. Rig Release Date:	etails, and give pertinent dates, including estimated date ltiple Completions: Attach wellbore diagram of Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart
13. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 proposed completion or recompletion. 1. MIRU WOR. 2. Unhang and PU rod string. 3. Unseat pump and POOH with rod str. 4. ND WH. NU BOP. 5. Release TAC and scan tubing OOH. 6. RIH with CIBP and set at 5315'. 7. Dump 4 sks of cement on top. 8. Pressure test. 9. Circulate packer fluid. 10. Notify NMOCD of MIT. 11. Perform MIT and submit paperwork. 12. RDMO WOR. 13. TA well. pud Date:	Clearly state all pertinent d 19.15.7.14 NMAC. For Mu ring configuration. Rig Release Date:	etails, and give pertinent dates, including estimated date ltiple Completions: Attach wellbore diagram of Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart cnowledge and belief.
of starting any proposed work). SEE RULE 1 proposed completion or recompletion. 1. MIRU WOR. 2. Unhang and PU rod string. 3. Unseat pump and POOH with rod str. 4. ND WH. NU BOP. 5. Release TAC and scan tubing OOH. 6. RIH with CIBP and set at 5315'. 7. Dump 4 sks of cement on top. 8. Pressure test. 9. Circulate packer fluid. 10. Notify NMOCD of MIT. 11. Perform MIT and submit paperwork 12. RDMO WOR.	Clearly state all pertinent d 19.15.7.14 NMAC. For Mu ring configuration. Rig Release Date:	condition of Approval: notify Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart chowledge and belief. DATE 07/25/2024
13. Describe proposed or completed operations. of starting any proposed work). SEE RULE 1 proposed completion or recompletion. 1. MIRU WOR. 2. Unhang and PU rod string. 3. Unseat pump and POOH with rod str. 4. ND WH. NU BOP. 5. Release TAC and scan tubing OOH. 6. RIH with CIBP and set at 5315'. 7. Dump 4 sks of cement on top. 8. Pressure test. 9. Circulate packer fluid. 10. Notify NMOCD of MIT. 11. Perform MIT and submit paperwork. 12. RDMO WOR. 13. TA well. pud Date: hereby certify that the information above is true and of the starting and submit paperwork. IGNATURE Nathan Sandel	Clearly state all pertinent d 19.15.7.14 NMAC. For Mu ring configuration. Rig Release Date: complete to the best of my k TITLE Production E E-mail address:nsandele	condition of Approval: notify Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart chowledge and belief. DATE 07/25/2024


Current WBD



10-3/4" CSG @ 1167'




Perfs: 5415' - 92', 5506' - 42', 5546' - 70', 5684' - 746', 5786' - 818'



Perfs: 6271' - 6498'


CIBP @ 6720' w/ 20' cmt

Perfs: 6765' - 6903'



CIBP @ 7219' w/ 35' cmt 7" 26,23,26# CSG @ 7252'

Proposed WBD



PBTD: 6220' TD: 7388' 10-3/4" CSG @ 1167'

Set CIBP @ 5315' w/ 4 sks of cmt

Perfs: 5415' - 92', 5506' - 42', 5546' - 70', 5684' - 746', 5786' - 818'

CIBP @ 6220' w/ 20' cmt

Perfs: 6271' - 6498'

CIBP @ 6720' w/ 20' cmt

Perfs: 6765' - 6903'

CIBP @ 7219' w/ 35' cmt 7" 26,23,26# CSG @ 7252'

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 371695

CONDITIONS

Operator:	OGRID:
Empire New Mexico LLC	330679
2200 S. Utica Place	Action Number:
Tulsa, OK 74114	371695
	Action Type:
	[C-103] NOI Temporary Abandonment (C-103I)

CONDITIONS

Created By		Condition Date
kfortner	Perform TA test MIT/BHT	8/22/2024