
Submit 3 Copies To Appropriate District State of New Mexico	E
Office	Form C-103 May 27, 2004
District I 1625 N. French Dr., Hobbs, NM 88240 Energy, Minerals and Natural Resources	WELL API NO.
District II OUL CONSERVATION DIVISION	30-019-20138
1501 W. Grand Ave., Autosia, Avi 66210	5. Indicate Type of Lease
1000 Pio Brazos Rd. Aztec, NM 87410	STATE FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No.
87505 i	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name Singleton Properties LLC
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other	8. Well Number Latigo Ranch 3-3
2. Name of Operator	9. OGRID Number
SWEPI LP	250036
3. Address of Operator P.O. Box 576, Houston, TX 77001	10. Pool name or Wildcat Wildcat
4. Well Location N.	
	-/- feet from the West line
Section 3 Township 10N Range 23E NMPM	County Guadalupe
11. Elevation (Show whether DR, RKB, RT, GR, e	
4640' graded	
Pit or Below-grade Tank Application 🗌 or Closure 🗌	· · · · · · · · · · · · · · · · · · ·
Pit typeDepth to GroundwaterDistance from nearest fresh water well Distance	nce from nearest surface water_N/A
Pit Liner Thickness:     mil     Below-Grade Tank: Volume     bbls;     Con	struction Material
12. Check Appropriate Box to Indicate Nature of Notic	e. Report or Other Data
	· · · ·
	UBSEQUENT REPORT OF:
	$DRILLINGOPNS. \square \qquad PANDA \qquad \boxtimes$
PULL OR ALTER CASING 🔲 MULTIPLE COMPL 🗌 🛛 CASING/CEM	
	ENT JOB
OTHER: OTHER:	
OTHER: OTHER:   13. Describe proposed or completed operations. (Clearly state all pertinent details,	and give pertinent dates, including estimated date
OTHER:   OTHER:     13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 1103. For Multiple Completions:	and give pertinent dates, including estimated date
OTHER: OTHER:   13. Describe proposed or completed operations. (Clearly state all pertinent details,	and give pertinent dates, including estimated date
OTHER:   OTHER:     13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion.	and give pertinent dates, including estimated date
OTHER:   OTHER:     13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion.	and give pertinent dates, including estimated date
OTHER:   OTHER:     13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion.     11/9/11   Spot 100 sx cmt @ 6344' & disp. On vac. (No tag No plug)     11/1/11   Spot 50 sx cmt @ 10549' to ctoc 9845'. (No tag No plug)     11/15/11   Spot 50 sx cmt @ 10549' to ctoc 9845' & tagged @ 9803'.	and give pertinent dates, including estimated date
OTHER:   OTHER:     13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion.     11/9/11   Spot 100 sx cmt @ 6344' & disp. On vac. (No tag No plug)     11/11/11   Spot 50 sx cmt @ 10549' to ctoc 9845'. (No tag No plug)     11/15/11   Spot 50 sx cmt @ 10549' to ctoc 9845' & tagged @ 9803'.     11/16/11   Circ well w/130bbls mlf.	and give pertinent dates, including estimated date
OTHER:   OTHER:     13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion.     11/9/11   Spot 100 sx cmt @ 6344' & disp. On vac. (No tag No plug)     11/1/11   Spot 50 sx cmt @ 10549' to ctoc 9845'. (No tag No plug)     11/15/11   Spot 50 sx cmt @ 10549' to ctoc 9845' & tagged @ 9803'.     11/16/11   Circ well w/130bbls mlf.     11/18/11   Perf @ 6025' unable to pump into perf holding 2500psi.	and give pertinent dates, including estimated date
OTHER:   OTHER:     13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion.     11/9/11   Spot 100 sx cmt @ 6344' & disp. On vac. (No tag No plug)     11/1/11   Spot 50 sx cmt @ 10549' to ctoc 9845'. (No tag No plug)     11/15/11   Spot 50 sx cmt @ 10549' to ctoc 9845' & tagged @ 9803'.     11/16/11   Circ well w/130bbls mlf.     11/18/11   Perf @ 6025' unable to pump into perf holding 2500psi.     11/19/11   Spot 20 sx cmt @ 3066' to ctoc 5718' & tagged @ 5669'.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER:   OTHER:     13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion.     11/9/11   Spot 100 sx cmt @ 6344' & disp. On vac. (No tag No plug)     11/1/11   Spot 50 sx cmt @ 10549' to ctoc 9845'. (No tag No plug)     11/15/11   Spot 50 sx cmt @ 10549' to ctoc 9845' & tagged @ 9803'.     11/16/11   Circ well w/130bbls mlf.     11/18/11   Perf @ 6025' unable to pump into perf holding 2500psi.     11/19/11   Spot 20 sx cmt @ 3066' to ctoc 5718' & tagged @ 5669'.     11/20/11   Perf @ 5419' set cmt retainer @ 5302' & sqz 120 sx cmt leaving 2bbls o	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER:Image: OTHER:13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion.11/9/11Spot 100 sx cmt @ 6344' & disp. On vac. (No tag No plug)11/1/11Spot 50 sx cmt @ 10549' to ctoc 9845'. (No tag No plug)11/1/11Spot 50 sx cmt @ 10549' to ctoc 9845' & tagged @ 9803'.11/16/11Circ well w/130bbls mlf.11/18/11Perf @ 6025' unable to pump into perf holding 2500psi.11/20/11Perf @ 5419' set cmt retainer @ 5302' & sqz 120 sx cmt leaving 2bbls o11/21/11Perf @ 11545' set cmt retainer @ 1451' & sqz 105 sx cmt both 7 5/8 & 10Tagged plug @ 1384'.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion
OTHER:Image: OTHER:13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion.11/9/11Spot 100 sx cmt @ 6344' & disp. On vac. (No tag No plug)11/1/11Spot 50 sx cmt @ 10549' to ctoc 9845'. (No tag No plug)11/1/11Spot 50 sx cmt @ 10549' to ctoc 9845' & tagged @ 9803'.11/16/11Circ well w/130bbls mlf.11/18/11Perf @ 6025' unable to pump into perf holding 2500psi.11/20/11Perf @ 5419' set cmt retainer @ 5302' & sqz 120 sx cmt leaving 2bbls o11/21/11Perf @ 11545' set cmt retainer @ 1451' & sqz 105 sx cmt both 7 5/8 & 10Tagged plug @ 1384'.11/22/1111/22/11Pressure test all casing @ 500 psi for 30 min.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion top of retainer. <sup>3</sup> /4 circ leaving 2bbls on top of retainer.
OTHER:Image: OTHER:13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion.11/9/11Spot 100 sx cmt @ 6344' & disp. On vac. (No tag No plug)11/1/11Spot 50 sx cmt @ 10549' to ctoc 9845'. (No tag No plug)11/1/11Spot 50 sx cmt @ 10549' to ctoc 9845' & tagged @ 9803'.11/16/11Circ well w/130bbls mlf.11/18/11Perf @ 6025' unable to pump into perf holding 2500psi.11/20/11Perf @ 5419' set cmt retainer @ 5302' & sqz 120 sx cmt leaving 2bbls o11/21/11Perf @ 11545' set cmt retainer @ 1451' & sqz 105 sx cmt both 7 5/8 & 10Tagged plug @ 1384'.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion top of retainer. <sup>3</sup> /4 circ leaving 2bbls on top of retainer.
OTHER:Image: OTHER:13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion.11/9/11Spot 100 sx cmt @ 6344' & disp. On vac. (No tag No plug)11/1/11Spot 50 sx cmt @ 10549' to ctoc 9845'. (No tag No plug)11/1/11Spot 50 sx cmt @ 10549' to ctoc 9845' & tagged @ 9803'.11/16/11Circ well w/130bbls mlf.11/18/11Perf @ 6025' unable to pump into perf holding 2500psi.11/20/11Perf @ 5419' set cmt retainer @ 5302' & sqz 120 sx cmt leaving 2bbls o11/21/11Perf @ 11545' set cmt retainer @ 1451' & sqz 105 sx cmt both 7 5/8 & 10Tagged plug @ 1384'.11/22/1111/22/11Pressure test all casing @ 500 psi for 30 min.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion top of retainer. <sup>3</sup> /4 circ leaving 2bbls on top of retainer.
OTHER:   OTHER:     13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion.     11/9/11   Spot 100 sx cmt @ 6344' & disp. On vac. (No tag No plug)     11/1/11   Spot 50 sx cmt @ 10549' to ctoc 9845'. (No tag No plug)     11/11/11   Spot 50 sx cmt @ 10549' to ctoc 9845' & tagged @ 9803'.     11/15/11   Spot 50 sx cmt @ 10549' to ctoc 9845' & tagged @ 9803'.     11/16/11   Circ well w/130bbls mlf.     11/18/11   Perf @ 6025' unable to pump into perf holding 2500psi.     11/19/11   Spot 20 sx cmt @ 3066' to ctoc 5718' & tagged @ 5669'.     11/20/11   Perf @ 5419' set cmt retainer @ 5302' & sqz 120 sx cmt leaving 2bbls o     11/21/11   Perf @ 1545' set cmt retainer @ 1451' & sqz 105 sx cmt both 7 5/8 & 10     Tagged plug @ 1384'.   Tagged plug @ 1384'.     11/22/11   Pressure test all casing @ 500 psi for 30 min.     11/29/11   Cut off well head & run line & fill all casing w/cmt from 100' to surface	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion n top of retainer. <sup>3</sup> / <sub>4</sub> circ leaving 2bbls on top of retainer.
OTHER:Image: OTHER:13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion.11/9/11Spot 100 sx cmt @ 6344' & disp. On vac. (No tag No plug)11/1/11Spot 50 sx cmt @ 10549' to ctoc 9845'. (No tag No plug)11/1/11Spot 50 sx cmt @ 10549' to ctoc 9845' & tagged @ 9803'.11/16/11Circ well w/130bbls mlf.11/18/11Perf @ 6025' unable to pump into perf holding 2500psi.11/20/11Perf @ 5419' set cmt retainer @ 5302' & sqz 120 sx cmt leaving 2bbls o11/21/11Perf @ 11545' set cmt retainer @ 1451' & sqz 105 sx cmt both 7 5/8 & 10Tagged plug @ 1384'.11/22/1111/22/11Pressure test all casing @ 500 psi for 30 min.	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion a top of retainer. <sup>3</sup> /4 circ leaving 2bbls on top of retainer.
OTHER:   □   OTHER:     13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion.     11/9/11   Spot 100 sx cmt @ 6344' & disp. On vac. (No tag No plug)     11/1/11   Spot 50 sx cmt @ 10549' to ctoc 9845'. (No tag No plug)     11/15/11   Spot 50 sx cmt @ 10549' to ctoc 9845' & tagged @ 9803'.     11/16/11   Circ well w/130bbls mlf.     11/18/11   Perf @ 6025' unable to pump into perf holding 2500psi.     11/19/11   Spot 20 sx cmt @ 3066' to ctoc 5718' & tagged @ 5669'.     11/20/11   Perf @ 5419' set cmt retainer @ 5302' & sqz 120 sx cmt leaving 2bbls o     11/21/11   Perf @ 1545' set cmt retainer @ 1451' & sqz 105 sx cmt both 7 5/8 & 10     Tagged plug @ 1384'.   T1/22/11     Pressure test all casing @ 500 psi for 30 min.   11/29/11     Cut off well head & run line & fill all casing w/cmt from 100' to surface     I   hereby certify that the information above is true and complete to the best of my knowle     grade tank has been/will be constructed or closed according to NMOCD guidelines \(\beergradelines	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion a top of retainer. <sup>3</sup> /4 circ leaving 2bbls on top of retainer.
OTHER:   □   OTHER:     13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion.     11/9/11   Spot 100 sx cmt @ 6344' & disp. On vac. (No tag No plug)     11/1/11   Spot 50 sx cmt @ 10549' to ctoc 9845'. (No tag No plug)     11/15/11   Spot 50 sx cmt @ 10549' to ctoc 9845' & tagged @ 9803'.     11/16/11   Circ well w/130bbls mlf.     11/18/11   Perf @ 6025' unable to pump into perf holding 2500psi.     11/19/11   Spot 20 sx cmt @ 3066' to ctoc 5718' & tagged @ 5669'.     11/20/11   Perf @ 5419' set cmt retainer @ 5302' & sqz 120 sx cmt leaving 2bbls o     11/21/11   Perf @ 1545' set cmt retainer @ 1451' & sqz 105 sx cmt both 7 5/8 & 10     Tagged plug @ 1384'.   T1/22/11     Pressure test all casing @ 500 psi for 30 min.   11/29/11     Cut off well head & run line & fill all casing w/cmt from 100' to surface     I   hereby certify that the information above is true and complete to the best of my knowle     grade tank has been/will be constructed or closed according to NMOCD guidelines \(\beergradelines	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion a top of retainer. <sup>3</sup> /4 circ leaving 2bbls on top of retainer.
OTHER:   □   OTHER:     13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion.     11/9/11   Spot 100 sx cmt @ 6344' & disp. On vac. (No tag No plug)     11/1/11   Spot 50 sx cmt @ 10549' to ctoc 9845'. (No tag No plug)     11/15/11   Spot 50 sx cmt @ 10549' to ctoc 9845'. (No tag No plug)     11/15/11   Spot 50 sx cmt @ 10549' to ctoc 9845'. (A tagged @ 9803'.     11/16/11   Circ well w/130bbls mlf.     11/18/11   Perf @ 6025' unable to pump into perf holding 2500psi.     11/19/11   Spot 20 sx cmt @ 3066' to ctoc 5718' & tagged @ 5669'.     11/20/11   Perf @ 5419' set cmt retainer @ 5302' & sqz 120 sx cmt leaving 2bbls o     11/21/11   Perf @ 11545' set cmt retainer @ 1451' & sqz 105 sx cmt both 7 5/8 & 10     Tagged plug @ 1384'.   Tit/22/11     Pressure test all casing @ 500 psi for 30 min.   11/29/11     Cut off well head & run line & fill all casing w/cmt from 100' to surface     I hereby certify that the information above is true and complete to the best of my knowle grade tank has been/will be constructed or closed according to NMOCD guidelines ⊠, a general permit     SIGNATURE	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion top of retainer. <sup>3</sup> / <sub>4</sub> circ leaving 2bbls on top of retainer. <sup>dge</sup> and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan []. ic Energy Services) DATE <u>1-4-11</u>
OTHER:   □   OTHER:     13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion.     11/9/11   Spot 100 sx cmt @ 6344' & disp. On vac. (No tag No plug)     11/1/11   Spot 50 sx cmt @ 10549' to ctoc 9845'. (No tag No plug)     11/15/11   Spot 50 sx cmt @ 10549' to ctoc 9845' & tagged @ 9803'.     11/16/11   Circ well w/130bbls mlf.     11/18/11   Perf @ 6025' unable to pump into perf holding 2500psi.     11/19/11   Spot 20 sx cmt @ 3066' to ctoc 5718' & tagged @ 5669'.     11/20/11   Perf @ 5419' set cmt retainer @ 5302' & sqz 120 sx cmt leaving 2bbls o     11/21/11   Perf @ 11545' set cmt retainer @ 1451' & sqz 105 sx cmt both 7 5/8 & 10     Tagged plug @ 1384'.   Tagged plug @ 1384'.     11/29/11   Cut off well head & run line & fill all casing w/cmt from 100' to surface     Thereby certify that the information above is true and complete to the best of my knowle grade tank has been/will be constructed or closed according to NtOCD guidelines 🖾, a general permit     SIGNATURE   TITLE   P & A Supervisor (Bas     Type or print name:   E-mail address:	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion a top of retainer. <sup>3</sup> /4 circ leaving 2bbls on top of retainer.
OTHER:   □   OTHER:     13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion.     11/9/11   Spot 100 sx cmt @ 6344' & disp. On vac. (No tag No plug)     11/11/11   Spot 50 sx cmt @ 10549' to ctoc 9845'. (No tag No plug)     11/15/11   Spot 50 sx cmt @ 10549' to ctoc 9845' & tagged @ 9803'.     11/16/11   Circ well w/130bbls mlf.     11/18/11   Perf @ 6025' unable to pump into perf holding 2500psi.     11/19/11   Spot 20 sx cmt @ 3066' to ctoc 5718' & tagged @ 5669'.     11/20/11   Perf @ 5419' set cmt retainer @ 5302' & sqz 120 sx cmt leaving 2bbls o     11/21/11   Perf @ 1545' set cmt retainer @ 1451' & sqz 105 sx cmt both 7 5/8 & 10     Tagged plug @ 1384'.   Tagged plug @ 1384'.     11/29/11   Cut off well head & run line & fill all casing w/cmt from 100' to surface     I   hereby certify that the information above is true and complete to the best of my knowle grade tank has been/will be constructed or closed according to NMOCD guidelines 🔄, a general permit     SIGNATURE   I   P & A Supervisor (Bas     Type or print name:   E-mail address:     For State Use Only   E-mail address:	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion a top of retainer. <sup>3</sup> / <sub>4</sub> circ leaving 2bbls on top of retainer. <sup>3</sup> / <sub>4</sub> circ leaving 2bbls on top of retainer. <sup>3</sup> / <sub>4</sub> circ leaving 2bbls on top of retainer. <sup>3</sup> / <sub>4</sub> circ leaving 2bbls on top of retainer.
OTHER:   □   OTHER:     13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion.     11/9/11   Spot 100 sx cmt @ 6344' & disp. On vac. (No tag No plug)     11/1/11   Spot 50 sx cmt @ 10549' to ctoc 9845'. (No tag No plug)     11/15/11   Spot 50 sx cmt @ 10549' to ctoc 9845' & tagged @ 9803'.     11/16/11   Circ well w/130bbls mlf.     11/18/11   Perf @ 6025' unable to pump into perf holding 2500psi.     11/19/11   Spot 20 sx cmt @ 3066' to ctoc 5718' & tagged @ 5669'.     11/20/11   Perf @ 5419' set cmt retainer @ 5302' & sqz 120 sx cmt leaving 2bbls o     11/21/11   Perf @ 1545' set cmt retainer @ 1451' & sqz 105 sx cmt both 7 5/8 & 10     Tagged plug @ 1384'.   Ti/22/11     Pressure test all casing @ 500 psi for 30 min.   11/29/11     Cut off well head & run line & fill all casing w/cmt from 100' to surface     I hereby certify that the information above is true and complete to the best of my knowle grade tank has been/will be constructed or closed according to NMOCD guidelines ⊠, a general permit     SIGNATURE	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion a top of retainer. <sup>3</sup> / <sub>4</sub> circ leaving 2bbls on top of retainer. <sup>3</sup> / <sub>4</sub> circ leaving 2bbls on top of retainer. <sup>3</sup> / <sub>4</sub> circ leaving 2bbls on top of retainer. <sup>3</sup> / <sub>4</sub> circ leaving 2bbls on top of retainer.
OTHER:   □   OTHER:     13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion.     11/9/11   Spot 100 sx cmt @ 6344' & disp. On vac. (No tag No plug)     11/11/11   Spot 50 sx cmt @ 10549' to ctoc 9845'. (No tag No plug)     11/15/11   Spot 50 sx cmt @ 10549' to ctoc 9845' & tagged @ 9803'.     11/16/11   Circ well w/130bbls mlf.     11/18/11   Perf @ 6025' unable to pump into perf holding 2500psi.     11/19/11   Spot 20 sx cmt @ 3066' to ctoc 5718' & tagged @ 5669'.     11/20/11   Perf @ 5419' set cmt retainer @ 5302' & sqz 120 sx cmt leaving 2bbls o     11/21/11   Perf @ 1545' set cmt retainer @ 1451' & sqz 105 sx cmt both 7 5/8 & 10     Tagged plug @ 1384'.   Tagged plug @ 1384'.     11/29/11   Cut off well head & run line & fill all casing w/cmt from 100' to surface     I   hereby certify that the information above is true and complete to the best of my knowle grade tank has been/will be constructed or closed according to NMOCD guidelines 🔄, a general permit     SIGNATURE   I   P & A Supervisor (Bas     Type or print name:   E-mail address:     For State Use Only   E-mail address:	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion a top of retainer. <sup>3</sup> / <sub>4</sub> circ leaving 2bbls on top of retainer. <sup>3</sup> / <sub>4</sub> circ leaving 2bbls on top of retainer. <sup>3</sup> / <sub>4</sub> circ leaving 2bbls on top of retainer. <sup>3</sup> / <sub>4</sub> circ leaving 2bbls on top of retainer.
OTHER:   □   OTHER:     13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion.     11/9/11   Spot 100 sx cmt @ 6344' & disp. On vac. (No tag No plug)     11/1/11   Spot 50 sx cmt @ 10549' to ctoc 9845'. (No tag No plug)     11/15/11   Spot 50 sx cmt @ 10549' to ctoc 9845' & tagged @ 9803'.     11/16/11   Circ well w/130bbls mlf.     11/18/11   Perf @ 6025' unable to pump into perf holding 2500psi.     11/19/11   Spot 20 sx cmt @ 3066' to ctoc 5718' & tagged @ 5669'.     11/20/11   Perf @ 5419' set cmt retainer @ 5302' & sqz 120 sx cmt leaving 2bbls o     11/21/11   Perf @ 1545' set cmt retainer @ 1451' & sqz 105 sx cmt both 7 5/8 & 10     Tagged plug @ 1384'.   Ti/22/11     Pressure test all casing @ 500 psi for 30 min.   11/29/11     Cut off well head & run line & fill all casing w/cmt from 100' to surface     I hereby certify that the information above is true and complete to the best of my knowle grade tank has been/will be constructed or closed according to NMOCD guidelines ⊠, a general permit     SIGNATURE	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion a top of retainer. <sup>3</sup> / <sub>4</sub> circ leaving 2bbls on top of retainer. <sup>3</sup> / <sub>4</sub> circ leaving 2bbls on top of retainer. <sup>3</sup> / <sub>4</sub> circ leaving 2bbls on top of retainer. <sup>3</sup> / <sub>4</sub> circ leaving 2bbls on top of retainer.
OTHER:   □   OTHER:     13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion.     11/9/11   Spot 100 sx cmt @ 6344' & disp. On vac. (No tag No plug)     11/1/11   Spot 50 sx cmt @ 10549' to ctoc 9845'. (No tag No plug)     11/15/11   Spot 50 sx cmt @ 10549' to ctoc 9845' & tagged @ 9803'.     11/16/11   Circ well w/130bbls mlf.     11/18/11   Perf @ 6025' unable to pump into perf holding 2500psi.     11/19/11   Spot 20 sx cmt @ 3066' to ctoc 5718' & tagged @ 5669'.     11/20/11   Perf @ 5419' set cmt retainer @ 5302' & sqz 120 sx cmt leaving 2bbls o     11/21/11   Perf @ 1545' set cmt retainer @ 1451' & sqz 105 sx cmt both 7 5/8 & 10     Tagged plug @ 1384'.   Ti/22/11     Pressure test all casing @ 500 psi for 30 min.   11/29/11     Cut off well head & run line & fill all casing w/cmt from 100' to surface     I hereby certify that the information above is true and complete to the best of my knowle grade tank has been/will be constructed or closed according to NMOCD guidelines ⊠, a general permit     SIGNATURE	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion a top of retainer. <sup>3</sup> / <sub>4</sub> circ leaving 2bbls on top of retainer. <sup>3</sup> / <sub>4</sub> circ leaving 2bbls on top of retainer. <sup>3</sup> / <sub>4</sub> circ leaving 2bbls on top of retainer. <sup>3</sup> / <sub>4</sub> circ leaving 2bbls on top of retainer.
OTHER:   □   OTHER:     13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion.     11/9/11   Spot 100 sx cmt @ 6344' & disp. On vac. (No tag No plug)     11/1/11   Spot 50 sx cmt @ 10549' to ctoc 9845'. (No tag No plug)     11/15/11   Spot 50 sx cmt @ 10549' to ctoc 9845' & tagged @ 9803'.     11/16/11   Circ well w/130bbls mlf.     11/18/11   Perf @ 6025' unable to pump into perf holding 2500psi.     11/19/11   Spot 20 sx cmt @ 3066' to ctoc 5718' & tagged @ 5669'.     11/20/11   Perf @ 5419' set cmt retainer @ 5302' & sqz 120 sx cmt leaving 2bbls o     11/21/11   Perf @ 1545' set cmt retainer @ 1451' & sqz 105 sx cmt both 7 5/8 & 10     Tagged plug @ 1384'.   Ti/22/11     Pressure test all casing @ 500 psi for 30 min.   11/29/11     Cut off well head & run line & fill all casing w/cmt from 100' to surface     I hereby certify that the information above is true and complete to the best of my knowle grade tank has been/will be constructed or closed according to NMOCD guidelines ⊠, a general permit     SIGNATURE	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion a top of retainer. <sup>3</sup> / <sub>4</sub> circ leaving 2bbls on top of retainer. <sup>3</sup> / <sub>4</sub> circ leaving 2bbls on top of retainer. <sup>3</sup> / <sub>4</sub> circ leaving 2bbls on top of retainer. <sup>3</sup> / <sub>4</sub> circ leaving 2bbls on top of retainer.
OTHER:   □   OTHER:     13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion.     11/9/11   Spot 100 sx cmt @ 6344' & disp. On vac. (No tag No plug)     11/1/11   Spot 50 sx cmt @ 10549' to ctoc 9845'. (No tag No plug)     11/15/11   Spot 50 sx cmt @ 10549' to ctoc 9845' & tagged @ 9803'.     11/16/11   Circ well w/130bbls mlf.     11/18/11   Perf @ 6025' unable to pump into perf holding 2500psi.     11/19/11   Spot 20 sx cmt @ 3066' to ctoc 5718' & tagged @ 5669'.     11/20/11   Perf @ 5419' set cmt retainer @ 5302' & sqz 120 sx cmt leaving 2bbls o     11/21/11   Perf @ 1545' set cmt retainer @ 1451' & sqz 105 sx cmt both 7 5/8 & 10     Tagged plug @ 1384'.   Ti/22/11     Pressure test all casing @ 500 psi for 30 min.   11/29/11     Cut off well head & run line & fill all casing w/cmt from 100' to surface     I hereby certify that the information above is true and complete to the best of my knowle grade tank has been/will be constructed or closed according to NMOCD guidelines ⊠, a general permit     SIGNATURE	and give pertinent dates, including estimated date Attach wellbore diagram of proposed completion a top of retainer. <sup>3</sup> / <sub>4</sub> circ leaving 2bbls on top of retainer. <sup>3</sup> / <sub>4</sub> circ leaving 2bbls on top of retainer. <sup>3</sup> / <sub>4</sub> circ leaving 2bbls on top of retainer. <sup>3</sup> / <sub>4</sub> circ leaving 2bbls on top of retainer.





## **Shell Exploration & Production**

State of New Mexico Energy, Minerals and Natural Resources Dept. Oil Conservation Division-District 4 1220 South St. Francis Drive Sante Fe, New Mexico 87505 Attn.: Ed Martin, District Supervisor

## Shell Exploration & Production Co.

Regulatory Affairs-EP Americas 4582 S. Ulster Street Parkway Suite 1400 Denver, Colorado 80237

December 27, 2012

Subject: Subsequent Notice of Plugging and Abandonment Shell Exploration & Production Co., Latigo Ranch 3-3 (API No. 30-019-20138) Guadalupe County, New Mexico

Dear Mr. Martin:

Shell Exploration & Production Company (Shell), as service provider to SWEPI LP in New Mexico, is submitting a Subsequent Notice of Plugging and Abandonment (Form C-103) to detail well plugging and abandonment activities conducted for the subject well, to New Mexico Oil Conservation Division-District 4 (OCD) for your review and approval.

If you have any questions or require any additional information regarding these reports, please contact me at (303) 222-6347, or Steve Compton at (303) 305-4017.

Regards,

Mastro

Michael L. Bergstrom (J Senior Regulatory Advisor Shell Exploration & Production Company

Attachments: Form C-103 Mechanical Well Sketch