State of New Mexico	Form C-103
Office District I Energy, Minerals and Natural Resou	irces May 27, 2004
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
and the second s	ON 30-007-20185
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISI	
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Dia Danga D.J. Alata NNA 97410	STATE FEE
District IV 2005 and Fe 6NM 87410	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	
87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK T	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	VPR B
PROPOSALS.)	8. Well Number 5
1. Type of Well: Oil Well Gas Well Other Coalbed Methane	
2. Name of Operator	9. OGRID Number 180514
EL PASO E & P COMPANY, L.P.	
3. Address of Operator	10. Pool name or Wildcat
	· · · · · · · · · · · · · · · · · · ·
PO BOX 190, RATON, NM 87740	Van Bremmer – Vermejo Gas
4. Well Location	
Unit Letter K: 1615 feet from the South line a	nd 1403 feet from the West line
Section 35 Township 30N Range 18E NM	IPM Colfax County
11. Elevation (Show whether DR, RKB, RT	GR. etc.)
8,290' (GL)	
Pit or Below-grade Tank Application □ or Closure □	
Pit typeDepth to GroundwaterDistance from nearest fresh water well	Distance from nearest surface water
Pit Liner Thickness: mil Below-Grade Tank: Volume	bbls; Construction Material
III Ditter Friedrics, min Delow Grade Faint, Volume	bis, Constitution Material
12. Check Appropriate Box to Indicate Nature of	Notice, Report or Other Data
The frame of the first of the f	
NOTICE OF INTENTION TO	SURSECUENT DEDODT OF
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMED	IAL WORK ALTERING CASING
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMED TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMME	
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMED TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMME	IAL WORK ALTERING CASING CONCENTIAL PLANT OF THE PROPERTY OF T
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMED TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMME	IAL WORK ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMED COMME CHANGE PLANS COMME PULL OR ALTER CASING MULTIPLE COMPL CASING	IAL WORK
PERFORM REMEDIAL WORK PLUG AND ABANDON REMED COMMETEMPORARILY ABANDON CHANGE PLANS COMMETEMPORARILY ABANDON CHANGE PLANS COMMETEMPORARILY ABANDON CASING MULTIPLE COMPL CASING COTHER:	IAL WORK
PERFORM REMEDIAL WORK PLUG AND ABANDON REMED COMMETEMPORARILY ABANDON CHANGE PLANS COMMETEMPORARILY ABANDON MULTIPLE COMPL CASING COMMETEMPORARILY ABANDON OTHER: OTHER: Recompletion	ALTERING CASING ANCE DRILLING OPNS. PAND A CIPERING CASING CASING CIPERING CIPERING CASING CIPERING CIPERING CIPERING CIPERING CIPERING CIPERING CASING CIPERING CIPERING CIPERING CIPERING CIPERING CIPERING CASING CIPERING CIP
PERFORM REMEDIAL WORK PLUG AND ABANDON REMED COMMETEMPORARILY ABANDON CHANGE PLANS COMMETEMPORARILY ABANDON CHANGE PLANS COMMETEMPORARILY ABANDON CASING MULTIPLE COMPL CASING COTHER:	ALTERING CASING ANCE DRILLING OPNS. PAND A CIPERING CASING CASING CIPERING CIPERING CASING CIPERING CIPERING CIPERING CIPERING CIPERING CIPERING CASING CIPERING CIPERING CIPERING CIPERING CIPERING CIPERING CASING CIPERING CIP
PERFORM REMEDIAL WORK PLUG AND ABANDON REMED COMMETEMPORARILY ABANDON CHANGE PLANS COMMETEMPORARILY ABANDON MULTIPLE COMPL CASING MULTIPLE COMPL CASING OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give per SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completed completed operations.)	ALTERING CASING ANCE DRILLING OPNS. PAND A CIPERING CASING CASING CIPERING CIPERING CASING CIPERING CIPERING CIPERING CIPERING CIPERING CIPERING CASING CIPERING CIPERING CIPERING CIPERING CIPERING CIPERING CASING CIPERING CIP
PERFORM REMEDIAL WORK PLUG AND ABANDON REMED COMMETEMPORARILY ABANDON CHANGE PLANS COMMETEMPORARILY ABANDON CHANGE PLANS COMMETEMPORARILY ABANDON CHANGE PLANS COMMETEMPORARILY ABANDON CHANGE PLANS COMMETEMPORARILY ABANDON COMMETEMPORARILY AB	ALTERING CASING AND A AN
PERFORM REMEDIAL WORK PLUG AND ABANDON REMED TEMPORARILY ABANDON CHANGE PLANS COMME PULL OR ALTER CASING MULTIPLE COMPL CASING OTHER: Recompletion OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give per SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completions. 1. MIRU Bronco. PU Rods, Tubing, Production Equipment. 2. MIRU Weatherford and Halliburton and Perforate and Stimulate the follows.	ALTERING CASING AND A AN
PERFORM REMEDIAL WORK PLUG AND ABANDON REMED TEMPORARILY ABANDON CHANGE PLANS COMME PULL OR ALTER CASING MULTIPLE COMPL CASING OTHER: Recompletion OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give per SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completions. MIRU Bronco. PU Rods, Tubing, Production Equipment. 2. MIRU Weatherford and Halliburton and Perforate and Stimulate the follow Stage 1 - 2064'-2067', 2092'-2095', 2107'-2110', 2152'-2155' 48 Holes	ALTERING CASING ANCE DRILLING OPNS. PAND A CICEMENT JOB CITIENT dates, including estimated date of starting any proposed work). Pring Raton Coal Intervals:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMED TEMPORARILY ABANDON CHANGE PLANS COMME PULL OR ALTER CASING MULTIPLE COMPL CASING OTHER: Recompletion OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give per SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completions. Attach wellbore diagram of proposed completions. 1. MIRU Bronco. PU Rods, Tubing, Production Equipment. 2. MIRU Weatherford and Halliburton and Perforate and Stimulate the follow Stage 1 - 2064'-2067', 2092'-2095', 2107'-2110', 2152'-2155' 48 Holes Acidize the perforations, pump 49,019 gal 70 Quality Nitrogen foa	ALTERING CASING ANCE DRILLING OPNS. PAND A CICEMENT JOB CITIENT dates, including estimated date of starting any proposed work). Pring Raton Coal Intervals:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMED TEMPORARILY ABANDON CHANGE PLANS COMME PULL OR ALTER CASING MULTIPLE COMPL CASING OTHER: Recompletion OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give per SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completions. Attach wellbore diagram of proposed completions. 1. MIRU Bronco. PU Rods, Tubing, Production Equipment. 2. MIRU Weatherford and Halliburton and Perforate and Stimulate the follow Stage 1 - 2064'-2067', 2092'-2095', 2107'-2110', 2152'-2155' 48 Holes Acidize the perforations, pump 49,019 gal 70 Quality Nitrogen foa Stage 2 - 1374'-1378', 1456'-1459' 28 Holes	ALTERING CASING ANCE DRILLING OPNS. PAND A P
PERFORM REMEDIAL WORK PLUG AND ABANDON REMED TEMPORARILY ABANDON CHANGE PLANS COMMEDULL OR ALTER CASING MULTIPLE COMPL CASING OTHER: Recompletion OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give performed by the performed state of proposed completed to the performed by the p	ALTERING CASING ANCE DRILLING OPNS. PAND A P
PERFORM REMEDIAL WORK PLUG AND ABANDON REMED TEMPORARILY ABANDON CHANGE PLANS COMME PULL OR ALTER CASING MULTIPLE COMPL CASING OTHER: Recompletion OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give per SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completions. Attach wellbore diagram of proposed completions. 1. MIRU Bronco. PU Rods, Tubing, Production Equipment. 2. MIRU Weatherford and Halliburton and Perforate and Stimulate the follow Stage 1 - 2064'-2067', 2092'-2095', 2107'-2110', 2152'-2155' 48 Holes Acidize the perforations, pump 49,019 gal 70 Quality Nitrogen foa Stage 2 - 1374'-1378', 1456'-1459' 28 Holes	ALTERING CASING ANCE DRILLING OPNS. PAND A P
PERFORM REMEDIAL WORK PLUG AND ABANDON REMED TEMPORARILY ABANDON CHANGE PLANS COMMEDULL OR ALTER CASING MULTIPLE COMPL CASING OTHER: Recompletion OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give per SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completions. Attach wellbore diagram of proposed completions. 1. MIRU Bronco. PU Rods, Tubing, Production Equipment. 2. MIRU Weatherford and Halliburton and Perforate and Stimulate the follow Stage 1 - 2064' - 2067', 2092' - 2095', 2107' - 2110', 2152' - 2155' 48 Holes Acidize the perforations, pump 49,019 gal 70 Quality Nitrogen for Stage 2 - 1374' - 1378', 1456' - 1459' 28 Holes Acidize the perforations, pump 28,776 gal 70 Quality Nitrogen for Stage 3 - 914' - 918', 926' - 932', 996' - 1000' 56 Holes	ALTERING CASING ANCE DRILLING OPNS. PAND A P
PERFORM REMEDIAL WORK PLUG AND ABANDON REMED TEMPORARILY ABANDON CHANGE PLANS COMMEDULL OR ALTER CASING MULTIPLE COMPL CASING OTHER: Recompletion OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give performed by the performed state of proposed completed to the performed by the p	ALTERING CASING ANCE DRILLING OPNS. PAND A P
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMEDIAL REMED COMMEDIAL OR ALTER CASING MULTIPLE COMPL CASING OTHER: Recompletion OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give performed by the performed state of proposed completed to the performed by the perform	ALTERING CASING ANCE DRILLING OPNS. PAND A P
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMETEMPORARILY ABANDON CHANGE PLANS COMMETEMPORARILY ABANDON CHANGE PLANS COMMETEMPORARILY ABANDON MULTIPLE COMPL CASING COMMETEMPORARILY ABANDON CHANGE PLANS COMMETEMPORARILY ABANDON COMPLETEMPORARILY ABANDON COMPLETEMPORARILY ABANDON COMPLETEMPORARILY ABANDON COMPLETEMPORARILY ABANDON COMPLETEMPORARILY ABANDON COMPLETEMPORARILY ABANDON CASING COMPLETEMPORARILY ABANDON COMPLETEMPORARILY ABAND	ALTERING CASING ANCE DRILLING OPNS. PAND A P
PERFORM REMEDIAL WORK PLUG AND ABANDON COMMEDIAL REMED COMMEDIAL OR ALTER CASING MULTIPLE COMPL CASING OTHER: Recompletion OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give performed by the performed state of proposed completed to the performed by the perform	ALTERING CASING ANCE DRILLING OPNS. PAND A CINCEMENT JOB CITION TO THE PAND A PAND A PAND A CITION TO THE PAND A CITION TO THE PAND A PAND A CITION TO THE PAND A CITION TO THE PAND A PAND A CITION TO THE PAND A CITION TO THE PAND A P
PERFORM REMEDIAL WORK PLUG AND ABANDON REMED COMME PULL OR ALTER CASING MULTIPLE COMPL CASING OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give per SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completions: Attach wellbore diagram of proposed completions. 1. MIRU Bronco. PU Rods, Tubing, Production Equipment. 2. MIRU Weatherford and Halliburton and Perforate and Stimulate the follows Stage 1 - 2064' - 2067', 2092' - 2095', 2107' - 2110', 2152' - 2155' 48 Holes Acidize the perforations, pump 49,019 gal 70 Quality Nitrogen for Stage 2 - 1374' - 1378', 1456' - 1459' 28 Holes Acidize the perforations, pump 28,776 gal 70 Quality Nitrogen for Stage 3 - 914' - 918', 926' - 932', 996' - 1000' 56 Holes Acidize the perforations, pump 25,512 gal 70 Quality Nitrogen for 3. MIRU Completion Unit. 4. Retrieve WRBP at +/- 1090, 1350' & 2000'. Clean hole out to WRBP at +/- 5. Turn well over to the Production Supervisor and run pump, tubing, and rod	ALTERING CASING ANCE DRILLING OPNS. PAND A CINCEMENT JOB AND A CINCEMENT JOB AND A CINCEMENT JOB AND A CINCEMENT JOB AND A PAND A PAND A CINCEMENT JOB AND A CINCEMENT
PERFORM REMEDIAL WORK PLUG AND ABANDON REMED COMME PULL OR ALTER CASING MULTIPLE COMPL CASING OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give per SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completed operations. Attach wellbore diagram of proposed completed operations. (Clearly state all pertinent details, and give per SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completed operations. Attach wellbore diagram of proposed complete of the performance of the follow of the performance of the follow of the performance	ALTERING CASING ANCE DRILLING OPNS. PAND A CINCEMENT JOB AND A CIN
PERFORM REMEDIAL WORK PLUG AND ABANDON REMED COMME PULL OR ALTER CASING MULTIPLE COMPL CASING OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give per SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completions: Attach wellbore diagram of proposed completions. 1. MIRU Bronco. PU Rods, Tubing, Production Equipment. 2. MIRU Weatherford and Halliburton and Perforate and Stimulate the follows Stage 1 - 2064' - 2067', 2092' - 2095', 2107' - 2110', 2152' - 2155' 48 Holes Acidize the perforations, pump 49,019 gal 70 Quality Nitrogen for Stage 2 - 1374' - 1378', 1456' - 1459' 28 Holes Acidize the perforations, pump 28,776 gal 70 Quality Nitrogen for Stage 3 - 914' - 918', 926' - 932', 996' - 1000' 56 Holes Acidize the perforations, pump 25,512 gal 70 Quality Nitrogen for 3. MIRU Completion Unit. 4. Retrieve WRBP at +/- 1090, 1350' & 2000'. Clean hole out to WRBP at +/- 5. Turn well over to the Production Supervisor and run pump, tubing, and rod	ALTERING CASING ANCE DRILLING OPNS. PAND A CINCEMENT JOB AND A CIN
PERFORM REMEDIAL WORK PLUG AND ABANDON REMED TEMPORARILY ABANDON CHANGE PLANS COMME PULL OR ALTER CASING MULTIPLE COMPL CASING OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give per SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completions. Attach wellbore diagram of proposed completions. Attach wellbore diagram of proposed completions. 1. MIRU Bronco. PU Rods, Tubing, Production Equipment. 2. MIRU Weatherford and Halliburton and Perforate and Stimulate the follow Stage 1 - 2064'-2067', 2092'-2095', 2107'-2110', 2152'-2155' 48 Holes Acidize the perforations, pump 49,019 gal 70 Quality Nitrogen for Stage 2 - 1374'-1378', 1456'-1459' 28 Holes Acidize the perforations, pump 28,776 gal 70 Quality Nitrogen for Stage 3 - 914'-918', 926'-932', 996'-1000' 56 Holes Acidize the perforations, pump 25,512 gal 70 Quality Nitrogen for 3. MIRU Completion Unit. 4. Retrieve WRBP at +/- 1090, 1350' & 2000'. Clean hole out to WRBP at +/- Turn well over to the Production Supervisor and run pump, tubing, and rod I hereby certify that the information above is true and complete to the best of my kgrade tank has been/will be constructed or closed according to NMOCD guidelines , a general	ALTERING CASING CONCE DRILLING OPNS. PAND A COMMENT JOB PAND A PAND A COMMENT JOB PAND A PAND A COMMENT JOB PAND A PA
PERFORM REMEDIAL WORK PLUG AND ABANDON REMED TEMPORARILY ABANDON CHANGE PLANS COMME PULL OR ALTER CASING MULTIPLE COMPL CASING OTHER: Recompletion	ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMED TEMPORARILY ABANDON CHANGE PLANS COMME PULL OR ALTER CASING MULTIPLE COMPL CASING OTHER: Recompletion	ALTERING CASING CONCE DRILLING OPNS. PAND A COMMENT JOB PAND A PAND A COMMENT JOB PAND A PAND A COMMENT JOB PAND A PA
PERFORM REMEDIAL WORK PLUG AND ABANDON REMED TEMPORARILY ABANDON CHANGE PLANS COMME PULL OR ALTER CASING MULTIPLE COMPL CASING OTHER: Recompletion OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give per SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completed operations. Attach wellbore diagram of proposed complete operations. Attach wellbore diagram of p	ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMED TEMPORARILY ABANDON CHANGE PLANS COMME PULL OR ALTER CASING MULTIPLE COMPL CASING OTHER: Recompletion OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give per SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed complete 1. MIRU Bronco. PU Rods, Tubing, Production Equipment. 2. MIRU Weatherford and Halliburton and Perforate and Stimulate the follow Stage 1 - 2064'-2067', 2092'-2095', 2107'-2110', 2152'-2155' 48 Holes Acidize the perforations, pump 49,019 gal 70 Quality Nitrogen for Stage 2 - 1374'-1378', 1456'-1459' 28 Holes Acidize the perforations, pump 28,776 gal 70 Quality Nitrogen for Stage 3 - 914'-918', 926'-932', 996'-1000' 56 Holes Acidize the perforations, pump 25,512 gal 70 Quality Nitrogen for 3. MIRU Completion Unit. 4. Retrieve WRBP at +/- 1090, 1350' & 2000'. Clean hole out to WRBP at +/- 5. Turn well over to the Production Supervisor and run pump, tubing, and rod I hereby certify that the information above is true and complete to the best of my legrade tank has been/will be constructed or closed according to NMOCD guidelines , a general SIGNATURE Shirley A Mitchell E-mail address: shirley.mitchell@For State Use Only	ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMED TEMPORARILY ABANDON CHANGE PLANS COMME PULL OR ALTER CASING MULTIPLE COMPL CASING OTHER: Recompletion OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give per SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed complete 1. MIRU Bronco. PU Rods, Tubing, Production Equipment. 2. MIRU Weatherford and Halliburton and Perforate and Stimulate the follow Stage 1 - 2064'-2067', 2092'-2095', 2107'-2110', 2152'-2155' 48 Holes Acidize the perforations, pump 49,019 gal 70 Quality Nitrogen for Stage 2 - 1374'-1378', 1456'-1459' 28 Holes Acidize the perforations, pump 28,776 gal 70 Quality Nitrogen for Stage 3 - 914'-918', 926'-932', 996'-1000' 56 Holes Acidize the perforations, pump 25,512 gal 70 Quality Nitrogen for 3. MIRU Completion Unit. 4. Retrieve WRBP at +/- 1090, 1350' & 2000'. Clean hole out to WRBP at +/- 5. Turn well over to the Production Supervisor and run pump, tubing, and rod I hereby certify that the information above is true and complete to the best of my legrade tank has been/will be constructed or closed according to NMOCD guidelines , a general SIGNATURE Shirley A Mitchell E-mail address: shirley.mitchell@For State Use Only	ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMED TEMPORARILY ABANDON CHANGE PLANS COMME PULL OR ALTER CASING MULTIPLE COMPL CASING OTHER: Recompletion OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give per SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed complete 1. MIRU Bronco. PU Rods, Tubing, Production Equipment. 2. MIRU Weatherford and Halliburton and Perforate and Stimulate the follow Stage 1 - 2064'-2067', 2092'-2095', 2107'-2110', 2152'-2155' 48 Holes Acidize the perforations, pump 49,019 gal 70 Quality Nitrogen for Stage 2 - 1374'-1378', 1456'-1459' 28 Holes Acidize the perforations, pump 28,776 gal 70 Quality Nitrogen for Stage 3 - 914'-918', 926'-932', 996'-1000' 56 Holes Acidize the perforations, pump 25,512 gal 70 Quality Nitrogen for 3. MIRU Completion Unit. 4. Retrieve WRBP at +/- 1090, 1350' & 2000'. Clean hole out to WRBP at +/- 5. Turn well over to the Production Supervisor and run pump, tubing, and rod I hereby certify that the information above is true and complete to the best of my legrade tank has been/will be constructed or closed according to NMOCD guidelines , a general SIGNATURE Shirley A Mitchell E-mail address: shirley.mitchell@For State Use Only	ALTERING CASING