GTHT -\_\_\_\_1

# DRILLER REPORTS

2012

#### Chavez, Carl J, EMNRD

From: Sent: To:

Subject: Attachments: RigManager Cyrq [rigmgrcyrq@gmail.com] Friday, February 17, 2012 6:04 AM Chavez, Carl J, EMNRD; Phillips, Haddy L., OSE; mikesmit@blm.gov; Dade, Randy, EMNRD; Ben Barker 47 -7 Report for 2/16/12 OpsActivitySummaryRpt\_120216175558.pdf

#### **Lightning Dock Geothermal**

#### **Morning Report**

#### Well LDG 47-7

#### **Operations last 24 hours:**

Wait on Trinity Tool-pusher to arrive to start nipple down. Tool-pusher on location @ 07:00 hrs. Rig on dayrate @07:00 hrs. Nipple down BOPE. Secure well with blank flange. Rig down & prepare to move rig.

**Current Operations Midnight to 6:00AM:** 

Wait on daylight

.

**Todays Planned Operations:** 

Move & stack rig on the 45-7 pad.

,

Thanks,

Richard Lemon

### **Richard Lemon Consulting**

Cell # 707-398-1645

5

#### Chavez, Carl J, EMNRD

From: Sent: To:

Subject: Attachments: RigManager Cyrq [rigmgrcyrq@gmail.com] Thursday, February 16, 2012 5:53 AM Chavez, Carl J, EMNRD; Phillips, Haddy L., OSE; mikesmit@blm.gov; Dade, Randy, EMNRD; Ben Barker 47 -7 Report for 2/15/12 OpsActivitySummaryRpt\_120215192713.pdf

#### **Lightning Dock Geothermal**

#### **Morning Report**

#### Well LDG 47-7

#### **Operations last 24 hours:**

Wait on Trinity Tool-pusher to arrive to start nipple down. Rig off stand-by @ 07:00 hrs

**Current Operations Midnight to 6:00AM:** 

Wait on Trinity Tool-pusher to arrive to start nipple down.

**Todays Planned Operations:** 

Nipple down BOPE. Install blank flange. Clean mud pits & prepare to move & stack Trinity rig on 45-7 pad.

Thanks,

Richard Lemon

## **Richard Lemon Consulting**

Cell # 707-398-1645