1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 1301 W. Grand Avenue, Artesia, NM 88210		of New Mexico rals and Natural Resources APR 04 2013 Revised October 10, 20						
District III 1000 Rio Brazos Road, Aztec, NM 87410		vation Division	NMOCD ART	Submit 2 Copies to appropria				
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505		n St. Francis Dr. I e, NM 87505	BAILING AND A BLE	ith Rule 116 on ba				
	and the second secon	n and Corrective	Action					
n TMW130251448	case rouncation	OPERATOR		al Report 🔲 Final Rep				
Name of Company Chevron Delaware B		Contact Bradley Blevi						
Address PO Box 190, Hobbs, NM 88241 Facility Name Culebra Bluff SWD Wate		Telephone No. (575) 3 Facility Type SWD	391-1462					
Surface Owner	Mineral Owner		Lease N	Jo				
Surface Owner	•			NO				
Unit Letter Section Township Range		N OF RELEASE	e East/West Line	County				
L 36 22S 28E				Eddy County, NM				
	Latitude <u>N 32.34734°</u>	Longitude <u>W 104.04</u>	1830° AM	<u> </u>				
Type of Release Produced Water		OF RELEASE Volume of Release 77	bbls Volume I	Recovered 0 bbls				
Source of Release Hole in 3" ball valve in the	transition	Date and Hour of Occurr 03/25/2013 @ 12:30 pm	ence Date and	Hour of Discovery				
Was Immediate Notice Given?		If YES, To Whom?		· · · · · · · · · · · · · · · · · · ·				
1	No 🗌 Not Required]						
By Whom? Was a Watercourse Reached?		Date and Hour If YES, Volume Impactin	ng the Watercourse.					
🗌 Yes 🛛	No		5					
Describe Cause of Problem and Remedial Actio A hole in the 3" ball valve in the transition caus repaired.		ater to leak onto the ground	. No fluids were recov	vered and the valve was				
A hole in the 3" ball valve in the transition caus	sed 77 bbls of produced w ken.* A hole in the 3" ball valve d. Further remediation wi t is true and complete to the nd/or file certain release n ce of a C-141 report by the v investigate and remediat	e in the transition caused 77 Il be performed in accordan he best of my knowledge an otifications and perform co e NMOCD marked as "Fina e contamination that pose a	bbls of produced wate be with a NMOCD-ap d understand that purs trective actions for rele Report" does not reli threat to ground wate	er to leak onto the ground. No proved remediation plan. suant to NMOCD rules and eases which may endanger ieve the operator of liability r, surface water, human health				
A hole in the 3" ball valve in the transition cause repaired. Describe Area Affected and Cleanup Action Tal The area affected us approximately 40' x 450'. fluids were recovered and the valve was repaired I hereby certify that the information given above regulations all operators are required to report as public health or the environment. The acceptan- should their operations have failed to adequately or the environment. In addition, NMOCD acceptance	sed 77 bbls of produced w ken.* A hole in the 3" ball valve d. Further remediation wi t is true and complete to the nd/or file certain release n ce of a C-141 report by the v investigate and remediat	e in the transition caused 77 Il be performed in accordan he best of my knowledge an otifications and perform co e NMOCD marked as "Fina e contamination that pose a oes not relieve the operator	bbls of produced wate be with a NMOCD-ap d understand that purs trective actions for rele Report" does not reli threat to ground wate	er to leak onto the ground. No proved remediation plan. mant to NMOCD rules and eases which may endanger ieve the operator of liability r, surface water, human health ompliance with any other				
A hole in the 3" ball valve in the transition cause repaired. Describe Area Affected and Cleanup Action Tal The area affected us approximately 40' x 450'. fluids were recovered and the valve was repaired I hereby certify that the information given above regulations all operators are required to report as public health or the environment. The acceptan- should their operations have failed to adequately or the environment. In addition, NMOCD acceptance	sed 77 bbls of produced w ken.* A hole in the 3" ball valve d. Further remediation wi e is true and complete to the nd/or file certain release n ce of a C-141 report by the provestigate and remediate otance of a C-141 report d	e in the transition caused 77 Il be performed in accordan he best of my knowledge an otifications and perform coi e NMOCD marked as "Fina e contamination that pose a oes not relieve the operator <u>OIL CC</u>	bbls of produced wate the with a NMOCD-ap ad understand that purs trective actions for rela- the to ground water of responsibility for con- DNSERVATION	er to leak onto the ground. No proved remediation plan. mant to NMOCD rules and eases which may endanger ieve the operator of liability r, surface water, human health ompliance with any other				
A hole in the 3" ball valve in the transition cause repaired. Describe Area Affected and Cleanup Action Tal The area affected us approximately 40' x 450', fluids were recovered and the valve was repaired I hereby certify that the information given above regulations all operators are required to report as public health or the environment. The acceptance should their operations have failed to adequately or the environment. In addition, NMOCD accept federal, state, or local laws and/or regulations.	sed 77 bbls of produced w ken.* A hole in the 3" ball valve d. Further remediation wi e is true and complete to the nd/or file certain release n ce of a C-141 report by the provestigate and remediate otance of a C-141 report d	e in the transition caused 77 Il be performed in accordan he best of my knowledge an otifications and perform co e NMOCD marked as "Fina e contamination that pose a oes not relieve the operator	bbls of produced wate the with a NMOCD-ap ad understand that purs trective actions for rela- the to ground water of responsibility for con- DNSERVATION	er to leak onto the ground. No proved remediation plan. mant to NMOCD rules and eases which may endanger ieve the operator of liability r, surface water, human health ompliance with any other				
A hole in the 3" ball valve in the transition cause repaired. Describe Area Affected and Cleanup Action Tal The area affected us approximately 40' x 450'. fluids were recovered and the valve was repaired I hereby certify that the information given above regulations all operators are required to report as public health or the environment. The acceptane should their operations have failed to adequately or the environment. In addition, NMOCD accepted and the analysis and/or regulations. Signature: The Standy The Stand S	sed 77 bbls of produced w ken.* A hole in the 3" ball valve d. Further remediation wi e is true and complete to the nd/or file certain release n ce of a C-141 report by the provestigate and remediate bance of a C-141 report d	e in the transition caused 77 Il be performed in accordan he best of my knowledge an otifications and perform coi e NMOCD marked as "Fina e contamination that pose a oes not relieve the operator <u>OIL CC</u>	bbls of produced wate the with a NMOCD-ap ad understand that purs trective actions for rela- the to ground water of responsibility for con- DNSERVATION	er to leak onto the ground. No oproved remediation plan. muant to NMOCD rules and eases which may endanger ieve the operator of liability r, surface water, human health ompliance with any other <u>DIVISION</u>				
A hole in the 3" ball valve in the transition cause repaired. Describe Area Affected and Cleanup Action Tal The area affected us approximately 40' x 450', fluids were recovered and the valve was repaired I hereby certify that the information given above regulations all operators are required to report as public health or the environment. The acceptance should their operations have failed to adequately or the environment. In addition, NMOCD accepted federal, state, or local laws and/or regulations. Signature: Standy Source Printed Name: Bradley Blevins Title: EHS Specialist	sed 77 bbls of produced w ken.* A hole in the 3" ball valve d. Further remediation wi e is true and complete to the nd/or file certain release n ce of a C-141 report by the provestigate and remediate totance of a C-141 report d	e in the transition caused 77 Il be performed in accordan he best of my knowledge an otifications and perform coi e NMOCD marked as "Fina e contamination that pose a oes not relieve the operator <u>OIL CC</u> Approved by District Super Approval Date:	bbls of produced water be with a NMOCD-ap ad understand that purs trective actions for released and Report" does not reliant threat to ground water of responsibility for construction DNSERVATION rvisor:	er to leak onto the ground. No proved remediation plan. suant to NMOCD rules and eases which may endanger ieve the operator of liability r, surface water, human health ompliance with any other DIVISION				
A hole in the 3" ball valve in the transition cause repaired. Describe Area Affected and Cleanup Action Tal The area affected us approximately 40' x 450', fluids were recovered and the valve was repaired I hereby certify that the information given above regulations all operators are required to report as public health or the environment. The acceptance should their operations have failed to adequately or the environment. In addition, NMOCD accepted federal, state, or local laws and/or regulations. Signature: Dady Descriptions Printed Name: Bradley Blevins Title: EHS Specialist E-mail Address: Bradley.blevins@chk.com	sed 77 bbls of produced w ken.* A hole in the 3" ball valve d. Further remediation wi e is true and complete to the nd/or file certain release n ce of a C-141 report by the provide of a C-141 report d 	e in the transition caused 77 Il be performed in accordan he best of my knowledge an otifications and perform cor- e NMOCD marked as "Fina e contamination that pose a oes not relieve the operator <u>OIL CC</u> Approved by District Super Approval Date: Conditions of Approval: Remediation per C	bbls of produced water the with a NMOCD-ap ad understand that purs trective actions for rela- threat to ground water of responsibility for con- DNSERVATION twisor: Expiration	er to leak onto the ground. No oproved remediation plan. muant to NMOCD rules and eases which may endanger ieve the operator of liability r, surface water, human health ompliance with any other <u>DIVISION</u>				
A hole in the 3" ball valve in the transition cause repaired. Describe Area Affected and Cleanup Action Tal The area affected us approximately 40' x 450', fluids were recovered and the valve was repaired I hereby certify that the information given above regulations all operators are required to report as public health or the environment. The acceptance should their operations have failed to adequately or the environment. In addition, NMOCD accepted federal, state, or local laws and/or regulations. Signature: Dady Descriptions Printed Name: Bradley Blevins Title: EHS Specialist E-mail Address: Bradley.blevins@chk.com	sed 77 bbls of produced w ken.* A hole in the 3" ball valve d. Further remediation wi e is true and complete to the nd/or file certain release n ce of a C-141 report by the provide of a C-141 report d 	e in the transition caused 77 Il be performed in accordan he best of my knowledge an otifications and perform coi e NMOCD marked as "Fina e contamination that pose a oes not relieve the operator <u>OIL CC</u> Approved by District Super Approval Date: Conditions of Approval:	bbls of produced water the with a NMOCD-ap ad understand that purs trective actions for rela- d Report" does not reli- threat to ground water of responsibility for co- DNSERVATION rvisor: Expiration	er to leak onto the ground. No proved remediation plan. suant to NMOCD rules and eases which may endanger ieve the operator of liability r, surface water, human health ompliance with any other DIVISION				
A hole in the 3" ball valve in the transition cause repaired. Describe Area Affected and Cleanup Action Tal The area affected us approximately 40' x 450', fluids were recovered and the valve was repaired I hereby certify that the information given above regulations all operators are required to report as public health or the environment. The acceptance should their operations have failed to adequately or the environment. In addition, NMOCD accepted federal, state, or local laws and/or regulations. Signature: Standy State Printed Name: Bradley Blevins Title: EHS Specialist E-mail Address: Bradley.blevins@chk.com Date: 4/3//3 Pho	sed 77 bbls of produced w ken.* A hole in the 3" ball valve d. Further remediation wi e is true and complete to the nd/or file certain release n ce of a C-141 report by the provide of a C-141 report d 	e in the transition caused 77 Il be performed in accordan he best of my knowledge an otifications and perform cor- e NMOCD marked as "Fina e contamination that pose a oes not relieve the operator <u>OIL CC</u> Approved by District Super Approval Date: Conditions of Approval: Remediation per C Guidelines. SUBMIT R	bbls of produced water the with a NMOCD-ap ad understand that purs trective actions for rela- d Report" does not reli- threat to ground water of responsibility for co- DNSERVATION rvisor: Expiration	er to leak onto the ground. No proved remediation plan. suant to NMOCD rules and eases which may endanger ieve the operator of liability r, surface water, human health ompliance with any other DIVISION				

Bratcher, Mike, EMNRD

From:	Kathy Purvis <kathy@bbcinternational.com></kathy@bbcinternational.com>
Sent:	Wednesday, April 03, 2013 4:27 PM
То:	Bratcher, Mike, EMNRD
Cc:	'Bradley Blevins';
Subject:	Initial C-141 for Culebra Bluff SWD Water Transfer Line
Attachments:	Initial C-141, signed and sent 4-3-13.pdf

Attached is the initial C-141 for the Culebra Bluff SWD Water Transfer Line leak on 03/25/2013 in Eddy County, NM. Receipt notification via email is greatly appreciated. If you have any questions, please contact me.

ł

1


Kathy Purvis BBC International, Inc. 1324 W. Marland Hobbs, NM 88240 Phone: (575) 397-6388 Fax: (575) 397-0397 Email: <u>kathy@bbcinternational.com</u>

ł

Ĵ.


ļ,


Googleearth miles== RKZ Pinaele St#1 6-36-225-280 LAT/LONS Siven on Chevron C-141 Culebra Bluff SWB Water Transfer Line DOR 3/25/13



E-2-235-28E

Chevron Culebra Bluff SWD E-2-23s-28e 015-22754






MapNotes

DrawnBy

4/5/2013 3:39:33 PM

Looking for Chevron Culebra Bluff SWD water xfer line release





This STR has only RKI wells. Release reported from xfer line in this STR - Lat/long given is on the RKI Pinnacle St #1 well pad.

DrawnBy

L- 36-225-28E

4/5/2013 3:16:36 PM

Friday, April 05, 2013

Well Selection Criteria Quick Print

Field No = 310595

Page 1

API Well #	Well Name and No.		Operator Name	Тур S	tat	County	Surf	UL	Sec	Twp	Rng	Ft N/S	Ft E/W UICPrmt	Lst Insp Dt
30-015-22754-00-00	CULEBRA BLUFF SWD	001	CHEVRON U S A INC	S,	A E	ddy	S	E	2	23 S	28 E	1980 N	860 W	10/29/2012
	- CULEBRA-BLUFF-SWD			<u>S</u> ,	AE	ddy	- 6		2	-28-5-		-1980 N-		

32. 336540 104. 063190

RE: Culebra Bluff SWD Water Transfer Line

Blevins, Bradley G [Bradley.Blevins@chevron.com] Sent: Monday, April 08, 2013 8:15 AM To: Warren, JeanMarie, EMNRD Cc: Bratcher, Mike, EMNRD

Jean Marie

The release occurred on the water transfer line that goes to the Culebra Bluff SWD, the API for the Culebra Bluff is 3001522754. If you need further info please let me know.



Bradley Blevins Chevron Delaware Basin HE Specialist Hobbs FMT Direct 575-391-1462 86424 Cell- 575-441-0341

From: Warren, JeanMarie, EMNRD [mailto:JeanMarie.Warren@state.nm.us]
Sent: Monday, April 08, 2013 7:58 AM
To: Blevins, Bradley G
Cc: Bratcher, Mike, EMNRD
Subject: Culebra Bluff SWD Water Transfer Line

Good Morning.

Looking into a release you had submitted last week, we cannot find a well with those S/T/R on file and there is no API listed on the documentation.

Every Well with those Section/Township and/Range are not owned by Chevron, nor do they have the name of Culebra Bluff SWD Water Transfer Line.

Please contact me to let me know what the API is for this release, as I cannot enter any information on this release. Thank you very much, I'll be waiting to hear from you. We appreciate your help. Have a great week!

Jean-Marie Warren Business Operations Specialist NM-OCD District II, Artesia (575) 748-1283, ext· 101