

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

*nJMW 1328455825*

OPERATOR  Initial Report  Final Report

Name of Company OXY USA WTP LP <i>16096</i>	Contact CAMPBELL, RODNEY
Address 329 Marathon Rd, Lakewood	Telephone No. (575) 628-4167
Facility Name INDIAN BASIN GAS PLANT	Facility Type GAS PROCESSING PLANT

Surface Owner	Mineral Owner INDIAN BASIN	Lease No.
---------------	----------------------------	-----------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	23	21-S	23-E					Eddy

Latitude 32°27'52.502" Longitude 104°34'28.004"

**NATURE OF RELEASE**

Type of Release Gas	Volume of Release 67.67 MCF	Volume Recovered 0
Source of Release Residue Flare	Date and Hour of Occurrence 7/18/2012 6:22:00 PM	Date and Hour of Discovery 7/18/2012 6:22:00 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

**RECEIVED**  
 AUG 13 2012  
 NMOCD ARTESIA

If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken.\*  
Cause:  
FLARED FOR 7 MINUTES ON HIGH OXYGEN CONTENT. CONTRACT PIPELINE COMPANY DID A TIE-IN ON THE INDIAN BASIN GAS PLANT LOW PRESSURE LOOP LINE THAT DAY. WHILE PURGING THE PIPELINE A SMALL AMOUNT OF OXYGEN REMAINED IN PIPELINE.  
Remedial Action Taken:  
OPERATIONS CONTACTED ON CALL OXY PERSONNEL, CHECKED THE INLET O2 SENSORS TO DETERMINE WHICH LINE IT WAS COMING FROM AND DIDN'T SHOW ANYTHING ON ANY LINE. OPERATIONS CHECKED TO ENSURE PLANT VRU WAS RUNNING.

Describe Area Affected and Cleanup Action Taken.\*  
N/A

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rodney Campbell</i>	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: RODNEY CAMPBELL	Approved by District Supervisor:	<b>Accepted for record NMOCD</b>
Title: <i>HES specialist</i>	Approval Date: <b>OCT 11 2013</b>	Expiration Date:
E-mail Address: RODNEY_CAMPBELL@OXY.COM	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <i>7-19-2012</i> Phone: (575) 628-4167		

\* Attach Additional Sheets If Necessary

*RJMW 1327034125*

*iJMW 1328456207*

*2 RP-1991*