Primer II Energy Minerals and Natural Resources Review August 3: 7 S115 First St., Arcea, MM 8210 Oil Conservation Division Submit 1 Corp to appropriate Direct Office Descript II Direct II Submit 1 Corp to appropriate Direct Office Submit 1 Corp to appropriate Direct Office PL205 S. St. Francis Dr., Samt Fe, NM 87505 Santa Fe, NM 87505 Submit 1 Corp to appropriate Direct Office Name of Company: Linn Operating, Inc. Contact: Brian Wall Initial Report Final Report Address: 2130 W. Bender Hobs, NM 88240 Telephore No. 575-738-1739 Final Report Final Report Mame of Company: Linn Operating, Inc. Contact: Brian Wall API No. 30-015-26665 LoccArticon Of Release: Direct Office Feet from the Bratt Ward Line Councy Eddy Surface Owner: Federal Month Line Feet from the Bratt Ward Line Councy Eddy Latitude 32.8237284410225 Longitude -103.887811333549 NATURE OF RELEASE Volumo Recovered 9 bbls Date and Hour of Discovery 12/10/2016 Source of Release: Row Ine Date and Hour of Cocorreace Date and Hour of Discovery 12/10/2016 Was Immedute Notice Given? Yes In Noi Required But Merry Gregton Date and Hour of Discovery 12/															
1000 Rob Brazes Rouk, Astee, NM 3740 1220 South St. Francis Dr. accordance with 19.15.29 NMA 1220 South St. Francis Dr. Santa Fe, NM 87505 Santa Fe, NM 87505 Release Notification and Corrective Action OPERATOR Initial Report Final Rep Address 2130 W. Bender Hobbs, NM 88240 Feedboor No. 575-738-1730 Facility Name: Turner B #103 Facility Type: Oil Production Surface Owner Federal Mineral Owner Federal ADI No. 30-015-26665 LOCATION OF RELEASE Unit Letter Section Township Range Feet from the East West Line County Eddy B 20 175 31E 1300 North'South Lin Feet from the East West Line County Eddy Latitude 32.8237284410225 Longitude -103.887811333549 NATURE OF RELEASE Type of Release: flow line Volume Release 12 bits Volume Researed 9 bits Source of Release: flow line Yes No Not Required BM Type Of Release: Anter of Problem Researed 9 bits Source of Release: flow line Yes No Not Required BM Type Of Release: Anter of Problem Researed 9 bits Source of Release: flow line <		1625 N. French District II									Form C-141 Revised August 8, 201				
Salud Fig. NM 87303 Release Notification and Corrective Action OPERATOR Initial Report Final Rep Name of Company: Linn Operating, Inc. Contact: Brinn Wall Address: 2130 W. Bender Hobbs, NM 88240 Federal Contact: Brinn Wall April 100 Wer Federal APP No. 30-015-26665 LOCATION OF RELEASE Unit Letter Section Township Range Fed from the Isot North/South Line Fest from the East/West Line County Eddy Latitude 32.8237284410225 Longitude -103.887811333549 Nature OF Release 12 bbls. Volume Recovered 9 bbls Source of Release: Row line Under of Release 12 bbls. Volume Recovered 9 bbls Source of Release: Row line Under of Release 12 bbls. Volume Recovered 9 bbls Source of Release: Row line Under of Release 12 bbls. Volume Recovered 9 bbls Source of Release: Row line Under of Release 12 bbls. Volume Recovered 9 bbls Source of Release: Row line Under of Release 12 bbls. Volume Recovered 9 bbls		<u>District III</u> 1000 Rio Brazo <u>District IV</u>	os Road, Azte	c, NM 87410	1220) South	uth St. Francis Dr.			Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC					
OPERATOR Initial Report Initian Report Initial Report <td< th=""><th></th><th colspan="13">Sailla FC, INIVI 67303</th></td<>		Sailla FC, INIVI 67303													
Address: 11.90 Facility Type: Oil Production Surface Owner Facility Type: Oil Production Surface Owner Facility Type: Oil Production Surface Owner Federal Unit Letter Section Township Range Federation North/South Line Federation County Eddy Latitude 32.8237284410225 Longitude - 103.887811333549 NATURE OF RELEASE Type of Release: Oil and Produced Water Volume of Release 12 bbls. Volume Recovered 9 bbls Source of Release: Row line Date and Hour of Decurrence Date and Hour of Decurrence Date and Hour of Decurrence Was Immediate Notice Griven? Yes Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. Was a Watercourse was Impacted, Describe Fully.* NA NA MAC 0 6 2014 Norde 2014 Norde 2014 No flow incert the Fusion Taken.* If YES, Volume Impacting the Watercourse and the flow tine was repaired. Na are was remediated and re-seeded according to BLM guidelines. Impacted on the Southside of the pumping unit east to be 90' long X 19' wide. The release ran off the location in two narrow flow shute and the environment. In MACCD aperoved facility.	1	OPERATOR Initial Report												Final Repo	
Surface Owner Federal Mineral Owner Federal API No. 30-015-26665 LOCATION OF RELEASE Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County Eddy B 20 175 31E 1300 North 1370 East/West Line County Eddy B 20 175 31E 1300 North/South Line Feet from the East/West Line County Eddy B 20 175 31E 1300 North 1370 East/West Line County Eddy B 20 175 31E Morth/South Line Feet from the 1370 East/West Line County Eddy Latitude 32.8237284410225 Longitude -103.887811333549 NATURE OF RELEASE Volume Reached Hour of Discovery 12/10/2010 10:00 AM. 10:00 AM. 11/12/10/2010 10:00 AM. 10:00 AM. 11/12/10/2010 10:00 AM. 10:00 AM. 10:00 AM. 11/12/10/2010 10:00 AM. 10:00 AM. 11/12/10/2010 10:00 AM. 10:00 AM. 11/12/10/2010 11:00 AM. 10:00 AM. 11/12/10/2010 11:00 AM. 10:00 AM.	2	Address: 21	130 W. Be	nder Hobbs,		40		Telephone 1	No. 575-738-17	39					
LOCATION OF RELEASE Unit Letter Section Township Range feet from the North North Image of the section of the sectin the secon the section of the section of the section o						Mineral (
B 20 17S 31E 1300 North 1370 East Latitude 32.8237284410225 Longitude -103.887811333549 NATURE OF RELEASE Type of Release: Oil and Produced Water Volume of Release 12 bbls. Volume Recovered 9 bbls Source of Release: Oil and Produced Water Date and Hour of Occurrence Date and Hour of Discovery 12/10/2010 Was Immediate Notice Given? If YES, To Whom? BLM Terry Gregson By Whom? Date and Hour 12/10/2010 11:00 A.M. If YES, Volume Impacting the Watercourse. Was a Watercourse Reached? Yes S No If YES, Volume Impacting the Watercourse. If a Watercourse was Impacted, Describe Fully.* NA NAY 0 6 2014 NAY 0 6 2014 NMOCD ARTES'A NMOCD ARTES'A Describe Cause of Problem and Remedial Action Taken.* The affected and Cleanup Action Taken.* NMOCD ARTES'A Describe Area Affected and Cleanup Action Taken.* Nthe asst the source of the Source of the Budged off a flow time ruptured near the pumping unit. The well was shut in and the flow time was repaired. A vacuum truck was uting fluids. Describe Area Affected and Cleanup Action Taken.* The affected area was the location on the Southside of the pumping unit enst to be 90' long X 19' wide. The release ran off the location in two narow flow pathe eas	ŧ										1				
NATURE OF RELEASE Type of Release: Oil and Produced Water Volume of Release 12 bbls. Volume Recovered 9 bbls Source of Release: flow line Date and Hour of Occurrence Date and Hour of Discovery 12/10/2010 Was Immediate Notice Given? If YES, To Whom? Date and Hour of Discovery 12/10/2010 By Whom? Date and Hour 12/10/2010 0.1.00 A.M. 10:00 A.M. Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. If a Watercourse was Impacted, Describe Fully.* NA NA MAY 0 6 2014 MAY 0 6 2014 NMOCD ARTES A The flow line at the Turner B #103 froze and plugged off a flow line ruptured near the pamping unit. The well was shut in and the flow line was repaired. A vacuum truck was utilized to recover the free standing fluids. Describe Area Affected and Cleanup Action Taken.* The affected area was the location on the Southisde of the pumping unit east to be 90' long. X 19' wide. The release ran off the location in two narrow flow paths east. The spill area mapped was 17,335 sq. ft. of impact. All impacted soil was removed to an NMOCD approved facility. The impacted pastur area was remediated and re-seeded according to BLM guidelines. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required of the certain release notiffications and perform correlases which may en			1				1	South Line			Vest Line	County Edd	у		
Type of Release: Oil and Produced Water Volume of Release 12 bbls. Volume Recovered 9 bbls Source of Release: flow line Date and Hour of Occurrence Date and Hour of Occurrence Date and Hour of Discovery 12/10/2010 Was Immediate Notice Given? If YES, To Whom? Date and Hour 12/10/2010 11:00 A.M. If YES, To Whom? By Whom? Date and Hour 12/10/2010 11:00 A.M. If YES, Volume Impacting the Watercourse. If YES, Volume Impacting the Watercourse. If a Watercourse Reached? If YES No If YES, Volume Impacting the Watercourse. NA Describe Cause of Problem and Remedial Action Taken.* MAY 0 6 2014 NA MACOD ARTES A. MAY 0 6 2014 Describe Area Affected and Cleanup Action Taken.* MMOCD ARTES A. The flow line at the Turner B #103 froze and plugged off a flow line ruptured near the pumping unit. The well was shut in and the flow line was repaired. A vacuum truck was utilized to recover the free standing fluids. Describe Area Affected and Vasia of the ortin release notifications and perform corrective actions for release which may endanger public health or report and/or file certain release notifications and perform corrective actions for release which may endanger public health or the environment. The acceltance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of resoluting the rowinch may endanger public health or the environment. The acceltance of a C-141 report by the NMOCD marked a		-													
12/10/2010 A.M. 10:00 A.M. Was Immediate Notice Given? If YES, To Whom? By Whom? Date and Hour: 12/10/2010 11:00 A.M. Was a Watercourse Reached? Yes No If a Watercourse was Impacted, Describe Fully.* If YES, Volume Impacting the Watercourse. MAY 0 6 2014 Describe Cause of Problem and Remedial Action Taken.* Immode Ammedial Action Taken.* The flow line at the Turner B #103 froze and plugged off a flow line ruptured near the pumping unit. The well was shut in and the flow line was repaired. A vacuum truck was utilized to recover the free standing fluids. Describe Area Affected area was the location on the Southside of the pumping unit east to be 90' long X 19' wide. The release ran off the location in two narrow flow paths east. The spill area mapped was 17,335 sq. ft. of impact. All impacted soil was removed to an NMOCD approved facility. The impacted pastura area was remediated and re-seeded according to BLM guidelines. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for release which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and termediate contamination that post and/or fregulations. Signature: Fred B Wall	1	Type of Rele	ase: Oil and			Volume F	Volume Recovered 9 bbls								
Was infiniteduate force Order Yes No In Figs (10 Minute) By Whom? Date and Hour: 12/10/2010 11:00 A.M. If YES, Volume Impacting the Watercourse. If a Watercourse Reached? If YES If YES, Volume Impacting the Watercourse. If a Watercourse was Impacted, Describe Fully.* If YES, Volume Impacting the Watercourse. NA If a Watercourse was Impacted, Describe Fully.* NA If a Watercourse was Impacted, Describe Fully.* NA If PECEIVED MAY 0 6 2014 MAY 0 6 2014 Describe Cause of Problem and Remedial Action Taken.* If the flow line at the Turner B #103 froze and plugged off a flow line ruptured near the pumping unit. The well was shut in and the flow line was repaired. A vacuum truck was utilized to recover the free standing fluids. Describe Area Affected and Cleanup Action Taken.* The affected area was the location on the Southside of the pumping unit east to be 90' long. X 19' wide. The release ran off the location in two narrow flow paths east. The spill area mapped was 17,335 sq. ft. of impact. All impacted soil was removed to an NMOCD approved facility. The impacted pastur area was remediated and re-seeded according to BLM guidelines. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which								12/10/2010	12/10/2010 A.M. 10:00 A.M.					2/10/2010	
If a Watercourse was Impacted, Describe Fully.* NA Describe Cause of Problem and Remedial Action Taken.* The flow line at the Turner B #103 froze and plugged off a flow line ruptured near the pumping unit. The well was shut in and the flow line was repaired. A vacuum truck was utilized to recover the free standing fluids. Describe Area Affected and Cleanup Action Taken.* The affected area was the location on the Southside of the pumping unit east to be 90' long X 19' wide. The release ran off the location in two narrow flow paths east. The spill area mapped was 17,335 sq. ft. of impact. All impacted soil was removed to an NMOCD approved facility. The impacted pasture area was remediated and re-seeded according to BLM guidelines. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report ad/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: Fried B Wall Printed Name: Brian Wall Approved by Environmental Specialist:															
If a Watercourse was Impacted, Describe Fully.* NA Describe Cause of Problem and Remedial Action Taken.* The flow line at the Turner B #103 froze and plugged off a flow line ruptured near the pumping unit. The well was shut in and the flow line was repaired. A vacuum truck was utilized to recover the free standing fluids. Describe Area Affected and Cleanup Action Taken.* The affected area was the location on the Southside of the pumping unit east to be 90' long X 19' wide. The release ran off the location in two narrow flow paths east. The spill area mapped was 17,335 sq. ft. of impact. All impacted soil was removed to an NMOCD approved facility. The impacted pasture area was remediated and re-seeded according to BLM guidelines. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: Fried B Wall Printed Name: Brian Wall Approved by Environmental Specialist: <th></th> <td colspan="6"></td> <td colspan="7"></td>															
NA MAY 06 2014 Describe Cause of Problem and Remedial Action Taken.* Image: Cause of Problem and Remedial Action Taken.* The flow line at the Turner B #103 froze and plugged off a flow line ruptured near the pumping unit. The well was shut in and the flow line was repaired. A vacuum truck was utilized to recover the free standing fluids. Describe Area Affected and Cleanup Action Taken.* The affected area was the location on the Southside of the pumping unit east to be 90' long X 19' wide. The release ran off the location in two narrow flow paths east. The spill area mapped was 17,335 sq. ft. of impact. All impacted soil was removed to an NMOCD approved facility. The impacted pasture area was remediated and re-seeded according to BLM guidelines. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: Fred B Wall Printed Name: Brian Wall Approved by Environmental Specialist:								p			7	_			
A vacuum truck was utilized to recover the free standing fluids. Describe Area Affected and Cleanup Action Taken.* The affected area was the location on the Southside of the pumping unit east to be 90' long X 19' wide. The release ran off the location in two narrow flow paths east. The spill area mapped was 17,335 sq. ft. of impact. All impacted soil was removed to an NMOCD approved facility. The impacted pasture area was remediated and re-seeded according to BLM guidelines. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: Fred B Wall Printed Name: Brian Wall Approved by Environmental Specialist:			irse was Im	pacted, Descri	ibe Fully.*									_	
A vacuum truck was utilized to recover the free standing fluids. Describe Area Affected and Cleanup Action Taken.* The affected area was the location on the Southside of the pumping unit east to be 90' long X 19' wide. The release ran off the location in two narrow flow paths east. The spill area mapped was 17,335 sq. ft. of impact. All impacted soil was removed to an NMOCD approved facility. The impacted pasture area was remediated and re-seeded according to BLM guidelines. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: Fred B Wall Printed Name: Brian Wall Approved by Environmental Specialist:									a second and a second s						
Interaction area was the location of the solutistic of the painping init cast to be 90 long. X 19 wide. The release fail of the location in two harlow flow paths east. The spill area mapped was 17,335 sq. ft. of impact. All impacted soil was removed to an NMOCD approved facility. The impacted pasture area was remediated and re-seeded according to BLM guidelines. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: Fred B Wall Printed Name: Brian Wall Approved by Environmental Specialist:								red near the p	oumping unit. The	e well wa	is shut in a	nd the flow li	ne was i	repaired.	
flow paths east. The spill area mapped was 17,335 sq. ft. of impact. All impacted soil was removed to an NMOCD approved facility. The impacted pasture area was remediated and re-seeded according to BLM guidelines. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: Fred B Wall Printed Name: Brian Wall Approved by Environmental Specialist:							g unit ea	est to be 90' lo	ong X 19' wide.	The rele	ase ran off	the location i	in two n	arrow	
Printed Name: Brian Wall Printed Name: Brian Wall							t. All im	pacted soil w	as removed to an	NMOCI	D approved	l facility. The	impacto	ed pasture	
Signature: Fred B Wall Printed Name: Brian Wall		regulations all public health of should their of or the environ	l operators a or the enviro perations ha ment. In ad	are required to conment. The source failed to action lote failed to action, NMO	e report an acceptance dequately CD accept	d/or file certain re e of a C-141 report investigate and re	elease no rt by the mediate	tifications an NMOCD ma contaminatio	d perform correct rked as "Final Re on that pose a thre	tive actic eport" do eat to gro	ons for rele es not relie und water,	ases which ma eve the operate surface water	ay enda or of lia r, huma	nger bility n health	
Printed Name: Brian Wall Approved by Environmental Specialist:		Signature F	Fred B V	Nall			OIL CONSERVATION DIVISION								
Title: Construction Foreman II Approval Date: 5/2/14 Expiration Date: 1/A								Approved by Environmental Specialist:							
		Title: Construction Foreman II						Approval Date: 5/7/11/ Expiration Date: NA							
E-mail Address: bwall@linnenergy.com Conditions of Approval:		E-mail Addres	ss: bwall@li	nnenergy.con	n		c	onditions of	Approval:		/	Attached []		
Date: 04/25/2014 Phone: 806-367-0645 * Attach Additional Sheets If Necessary 2P-565	*			Pho s If Necessa	one: <u>806-3</u> ry	67-0645			T YY	ral					