

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company: Linn Operating, Inc.	Contact: Brian Wall
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No. 575-738-1739
Facility Name: Turner B #7	Facility Type: Injection

Surface Owner Federal	Mineral Owner Federal	API No. 30-015-05185
-----------------------	-----------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter O	Section 17	Township 17S	Range 31E	Feet from the 660	North/South Line South	Feet from 1980	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-------------------	------------------------	-------------

Latitude 32.8291123655792 Longitude -103.889826027795

**NATURE OF RELEASE**

Type of Release: Produced water	Volume of Release 18 bbls	Volume Recovered 15 bbls
Source of Release: 1" fiberglass line	Date and Hour of Occurrence 01/27/2014	Date and Hour of Discovery 01/27/2014 unknown
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher NMOCD - Mike Burton BLM	
By Whom? Brian Wall	Date and Hour: 01/28/2014 0730	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*  
NA

Describe Cause of Problem and Remedial Action Taken.\*  
DFSI struck a 2" fiberglass injection line. The construction foreman closed the lateral valve to prevent further leakage. The spill was contained within the previously excavated area. A vacuum truck was utilized to remove all residual fluids. There was 15 bbls of fluids removed.

Describe Area Affected and Cleanup Action Taken.\*  
Residual fluids remained in the previously excavated area. DFSI scraped, lined and backfilled the area, contouring to the landscape and seeding restoring the site to its natural and reclaimed state per BLM guidelines. The impacted soils were removed to an NMOCD approved facility.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Fred B Wall</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Brian Wall	Approved by Environmental Specialist:	
Title: Construction Foreman II	Approval Date:	Expiration Date:
E-mail Address: bwall@linenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 05/23/2014 Phone: 806-367-0645		

\* Attach Additional Sheets If Necessary

**NM OIL CONSERVATION**

ARTESIA DISTRICT

JUN 04 2014

RECEIVED