Rice Environmental Consulting & Safety

P.O. Box 2948, Hobbs, NM 88241 Phone 575.393.2967

September 30th, 2013

Mike Bratcher

New Mexico Energy, Minerals, & Natural Resources Oil Conservation Division, Environmental Bureau – District 2 811 S. First St. Artesia, NM 88210 PECEIVED
OCT 0 2 2013
NMOCD ARTESIA

RE: Corrective Action Plan Linn Energy – McClay Federal #7 (2RP-1914) UL/C sec. 33 T18S R30E API No. 3001510370

Mr. Bratcher:

Linn Energy (Linn) has retained Rice Environmental Consulting and Safety (RECS) to address potential environmental concerns at the above-referenced site.

Background and Previous Work

The site is located approximately 7.5 miles south of Loco Hills, New Mexico in Eddy County. NM OSE and BLM records indicate that there is no groundwater located beneath the site.

On September 8th, 2013, a hole at the base of the heater at the McClay #7 Battery released a total of 4 barrels of produced water and oil into the lined, bermed area surrounding the heater. A vacuum truck was called to the site and recovered one barrel of fluid from the bermed area and emptied the heater. A total of 31 sq ft of the lined, bermed area surrounding the heater was affected (Figure 1). An initial C-141 was sent by Linn to NMOCD and BLM on September 10th, 2013 (Appendix A).

RECS personnel arrived on site on September 10th, 2013. The site was photographed and mapped. The liner was found across the base of the heater and none of the release occurred outside the liner (Appendix B).

RECS recommends that the contaminated caliche above the liner be removed and taken to a NMOCD approved facility for disposal. Clean caliche will be imported to the site to replace the contaminated caliche. Once this has been completed, a Termination Request will be sent to BLM and NMOCD that will ask for 'remediation termination' or similar site closure status for the site along with a final C-141.

RECS appreciates the opportunity to work with you on this project. Please call Hack Conder at (575) 393-2967 or me if you have any questions or wish to discuss the site.

Sincerely,

Lara Weinheimer

Project Scientist

RECS

(575) 441-0431

cc. Mike Burton, BLM

Attachments:


Figure 1 – Site Map

Appendix A – Initial C-141

Appendix B – Photo Documentation

Figures

Site Map





LINN MCCLAY
FEDERAL #7
TANK BATTERY
(2RP-1914)

LEGALS: UL/C sec. 33 T-18-S R-30-E EDDY COUNTY, NM

Figure 1



0 10 20 HHH Feet

> GPS date: 9/10/13 JK Drawing date: 9/11/13 Drafted by: L. Weinheimer

Appendix A Initial C-141

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV

State of New Mexico
Energy Minerals and Natural Resources

SEP 1 0 2013

RECEIVED

Form C-141 Revised October 10, 2003

NMOGD APTES In propriate District Office in accordance with 19.15.29 NMAC

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

1220 S. St. Francis Dr., Santa Fe, NM 87505 Santa Fe, NM 87505													
Release Notification and Corrective Action													
NJMW 1326252893							OPERATOR :					Final Report	
Name of Co	mpany: Li	OPERATOR											
							Telephone No.: 575-738-1739						
Facility Name: McClay Federal # 7							Facility Type: Oil Producer						
Surface Owner: Federal . Mineral Owner:							API No.: 3001510370						
	LOCATION OF RELEASE												
Unit Letter C	t Letter Section Township Range Feet from the North			North/				/West Line County West E			y		
Latitude: 32.7103208597655 Longitude: -103.980175130974													
NATURE OF RELEASE													
Type of Release: Produced Water / Oil							Release: 4bbls/ 1	elease: 4bbls/ 1bbl Volume Recovered: 4 bbls / 1 b				l bbl	
Source of Release: Heater							lour of Occurrenc 12:00am	e:	Date and Hour of Discovery: 09/08/2013			:	
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required						If YES, To Whom? Mike Burton- BLM Mike Bratcher-NM OCD							
By Whom? Brian Wall						Date and Hour 09/10/2013							
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.							
If a Watercourse was Impacted, Describe Fully.*:													
į													
\cdot													
Describe Cause of Problem and Remedial Action Taken.*: Hole in bottom of heater in side base ring.													
Describe Area Affected and Cleanup Action Taken.*: All fluid in dike area picked up with vaccum truck emptied heater. Cause degradation.													
							!						
;													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
40							OIL CONSERVATION DIVISION						
Signature:	188 al	!/ ·											
Printed Name	e: Brian Wa	Approved by District Supervisor:											
·						Approval Date 19 2013 Expiration Date:							
E-mail Address: bwall@linnenergy.com						Conditions of Approval:				Attached			

* Attach Additional Sheets If Necessary

Phone: 806-367-0645

Date: 09/10/2013

Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:


2RP-1914

Appendix B Photo Documentation

RICE Environmental Consulting and Safety (RECS)
P.O. Box 2948 Hobbs, NM 88241
Phone 575.393.2967


Linn McClay Federal #7 Tank Battery

Unit Letter C, Section 33, T18S, R30E




Initial site photo, facing southeast

9/10/13




Initial site photo, facing southwest

9/10/13



Initial site photo, facing northwest

9/10/13



Showing berm with liner, facing west

9/10/13