

MDistrict I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 811 S. First St., Artesia, NM 88210
 District III
 1000 Rio Brazos Road, Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy Minerals and Natural Resources
 Oil Conservation Division
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

HOBBS OCD

Form C-141
 Revised August 8, 2011

SEP 02 2014
 Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company	Chevron USA Inc.	Contact	David A. Pagano
Address	15 Smith Rd., Midland, TX, 79705	Telephone No.	wk: 575-396-4414X275 cell: 505-787-9816
Facility Name	Vacuum Glorietta West Unit Battery	Facility Type	Battery
Surface Owner	NA	Mineral Owner	State of New Mexico
		API No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	1	18.0S	34E					Lea

Latitude = 32.796051 Longitude = -103.514502

NATURE OF RELEASE

Type of Release	Spill to Land	Volume of Release	2.88 bbl oil & 14.48 bbl produced water	Volume Recovered	0mcf
Source of Release	West Suction Tank	Date and Hour of Occurrence	11/9/13 6:00AM	Date and Hour of Discovery	11/9/13 6:00AM
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Geoffrey Leking		
By Whom?	James Trujillo	Date and Hour	11/10/13 1:30PM left voicemail		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
N/A					
Describe Cause of Problem and Remedial Action Taken.*					
West Suction produced water tank over filled due water extraction well producing into the tank unexpectedly. Operations immediately shut in production to minimize volume released.					
Describe Area Affected and Cleanup Action Taken.*					
Spill area was approx. 8' by 8' area just north and north west of the West Suction Tank. Vacuum Truck called out to vacuum up standing fluids and hydrovac excavated top layer of soil approx. 8-12". Vacuum Truck Recovered 16.7 bbls of fluid. Next step is to take samples to determine effectiveness of local remediation and possibly turn remediation over to the Chevron Environmental Management Company.					

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>David Pagano</i>	Approved by Environmental Specialist:	
Printed Name: David A. Pagano	Approval Date: 9-2-14	Expiration Date: 11-2-14
Title: Health & Environmental Specialist	Conditions of Approval:	
E-mail Address: dpgn@chevron.com	Attached <input type="checkbox"/>	
Date: 10/23/13 Phone: 505-787-9816	<i>Site specific remediation & remediate necessary NMOCD guidance. Submit final C-141 by 11-2-14.</i>	

* Attach Additional Sheets If Necessary

SEP 05 2014

IRP-3293
 ogrid 4228
 NTO 14 24 5374 73
 P 70 14 24 5376 63
 F 70 14 24 5373 21