

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Chicken Hawk State #1	Facility Type	Tank Battery
Surface Owner	State	Mineral Owner	API No. 30-015-33682

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	15	25S	28E					Eddy

Latitude N 32 08.236

Longitude W 104 04.079

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	85bbbls	Volume Recovered	80bbbls
Source of Release	Produced water tank	Date and Hour of Occurrence	06/26/2012	Date and Hour of Discovery	06/26/2012 @ 8:40 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher- OCD		
By Whom?	Michelle Mullins	Date and Hour	06/26/2012 @ 3:12 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

RECEIVED

AUG 13 2013

NMOCD ARTESIA

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*



The produced water tank at the Chicken Hawk State Tank Battery overflowed due to an electrical problem that did not allow the high level alarm to be sent out. Electricians repaired the problem.

Describe Area Affected and Cleanup Action Taken.*

Initially roughly 85bbbls of produced water was released from the water tank and we were able to recover 80bbbls with a vacuum truck. The entire release was completely contained inside the dike walls of the tank battery. The spill measured approximately 20' x 40'. Remediation was completed in accordance with a remediation plan approved by Mike Bratcher of NMOCD via email on 05/08/2013.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 	
Printed Name: Robert Grubbs Jr.	Approval Date: 8/25/14	Expiration Date: NA
Title: Senior Environmental Coordinator	Conditions of Approval: Final	Attached <input type="checkbox"/>
E-mail Address: rgrubbs@concho.com		
Date: 06-17-2013 Phone: 432-661-6601		

* Attach Additional Sheets If Necessary

ZRP-1213