

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT Form C-141
Revised October 10, 2003

SEP 24 2014
Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC

RECEIVED

Release Notification and Corrective Action

NAB1424854825 OPERATOR Initial Report Final Report

Name of Company: Linn Operating 209384 Contact: Brian Wall
Address: 2130 W. Bender Hobbs, NM 88240 Telephone No.: 575-738-1739
Facility Name: Skelly A Inj Plant (Skelly # 41) Facility Type: Water Flood

Surface Owner: Federal Mineral Owner: API No.: (closest well 3001505343)

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	22	17S	31E	330	North	330	East	Eddy

Latitude: 32.8264443770721 Longitude: -103.85001508143

NATURE OF RELEASE

Type of Release: Produced Water / Oil	Volume of Release: 50 bbls / 1 gal	Volume Recovered: 30 / .5 gal
Source of Release: 3" Steel line	Date and Hour of Occurrence: 07/16/2014	Date and Hour of Discovery: 07/16/2014 8:00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jeff Robertson- BLM Mike Bratcher- NMOCD	
By Whom? Brian Wall	Date and Hour 07/17/2014 0650	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*:		
Describe Cause of Problem and Remedial Action Taken.*: 3" steel transfer line leading from injection header toward Satellite 1 eroded and leaked into its dike between 2 AM and 8 AM this morning.		
Describe Area Affected and Cleanup Action Taken.* : The dike was standing about 4-6" deep over a distance of 12' x 25'. Because it was an injection line, there was very little oil involved. Directions to site: From intersection of Hwy 82 and 529, turn east on 82, go 2.2 miles, turn north for .6 miles, location on left		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Brian Wall	Approved by District Supervisor:	
Title: Construction Foreman II	Approval Date: 7/25/14	Expiration Date: N/A
E-mail Address: bwall@linenergy.com Date: 07/17/2014 Phone: 806-367-0645	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

Remediation per O.C.D. Rules & Guidelines
SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 10/25/14

229-2515

Patterson, Heather, EMNRD

From: Guillermo Garcia <ggarcia@diversifiedfsi.com>
Sent: Wednesday, September 24, 2014 2:36 PM
To: Patterson, Heather, EMNRD
Subject: linn energy, skelly injection plant (skelly #41)
Attachments: MX-2615N_20140924_141928.pdf

MX-2615N_20140924_141928.pdf;

Good afternoon, this is Guillermo Garcia with Diversified Field Service. I need a RP for the C141 I attached in this email. Thanks, have a good day.