

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OGD
State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505
RECEIVED

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company – Devon Energy	Contact – Trae Warcup
Address – 4134 Seven Rivers Highway	Telephone No. – (575) 748-3371
Facility Name – Mean Green 27 Federal 1H	Facility Type – Oil/Gas Well Pad (Drilling)

Surface Owner - Federal	Mineral Owner - Federal	API No. - 3002541433
-------------------------	-------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	22	26S	34E	100	South	480	East	Lea

Latitude 32.0218812141 Longitude -103.450836744

NATURE OF RELEASE

Type of Release – Produced Water	Volume of Release – 5 bbls.	Volume Recovered – 0 bbls.
Source of Release – Steel line coming from well head	Date and Hour of Occurrence – 10/13/14, 10:50 pm	Date and Hour of Discovery – 10/13/14, 10:50 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

A lowboy (trailer) struck a steel linebacker that contained a 2 inch line that is coming from the Mean Green 27 Federal 1H. The movement of the linebacker when hit by the lowboy pulled the pipe threads out of a 2 inch steel fitting; allowing the spillage of produced water from the broken 2 inch line. The pipe fitting was repaired. The linebacker was repositioned and a 10 foot wide approach on each side of the linebacker was constructed from road building material.

Describe Area Affected and Cleanup Action Taken.*

Area was approximately 135 cubic ft. and because of the sand soil, all fluid soaked in.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Trae Warcup	Approved by Environmental Specialist:	
Title: EHS Professional Drilling	Approval Date: 10-27-14	Expiration Date: 12-27-17
E-mail Address: traе.warcup@dvп.com	Conditions of Approval: Site Supply Road Rebate & maintenance area on NMACO grounds. Submit Final C-141 by 12-27-14.	Attached <input type="checkbox"/> 12P 3395 Sign 6137 NTO 14 3003 2229 P70 14 3003 2498
Date: 10/20/2014	Phone: 575-628-2846	

* Attach Additional Sheets If Necessary

OCT 27 2014