

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

DEC 29 2014

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1436354278

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P.	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: JRU-21-Legg Federal SWD Battery	Facility Type: SWD

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-04734
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter B	Section 27	Township 22S	Range 30E	Feet from the 660	North/South Line North	Feet from the 2004	East/West Line East	County: Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	-----------------

Latitude N 32.368838 Longitude W 104.090212

NATURE OF RELEASE



Type of Release: Crude oil and produced water	Volume of Release: 220 bbls crude oil and 279 bbls PW	Volume Recovered: 200 bbls crude oil and 279 bbls PW
Source of Release: 500 bbl skim tank	Date and Hour of Occurrence: 12/21/14 time between 2 a.m. and 4 a.m.	Date and Hour of Discovery: 12/21/14 at 4:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD emergency #104	
By Whom? Tony Savoie	Date and Hour 12/21/14 at 3:10 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* A motor valve failed sending all of the fluid to the skim tank causing it to over-flow. The vessel was by-passed until the motor valve could be replaced.

Describe Area Affected and Cleanup Action Taken.*
The skim tank was located in 0-perm containment capable of holding 382 bbls, the skim tank containment overflowed spilling approximately 27 bbls of crude oil on the ground and approximately 70 bbls into the adjoining containment around the gun barrel tanks. Seven bbls of oil was recovered off the ground and 193 bbls from the containments. Also spilled was 279 bbls of produced water which was all contained in the 0-perm.
The spill impacted approximately 8,950 sq. ft. of caliche tank battery area. All of the free standing fluid was recovered and approximately 14 cubic yards of saturated soil was scraped up and placed on plastic.
The impacted area will be cleaned up in accordance to the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by Environmental Specialist: 	
Title: Waste Management and Remediation Specialist	Approval Date: 12/29/14	Expiration Date: N/A
E-mail Address: tasavoie@basspet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12/29/14	Phone: 432-556-8730	

Remediation per O.C.D. Rules & Guidelines
SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 1/29/15

* Attach Additional Sheets If Necessary

2RP-24915

FIELD SPILL REPORT

Distribution List: CJ Barry, TA Savoie, RL Gawlik, B. Biehl, JR Smitherman, SF Johnson, FD Schoch, G Fletcher, J Fuqua, A Ruth, A Thompson, S Walters, B Blevins, G Goodgame

DATE: December 21, 2014

LOCATION OF SPILL SITE: Legg Federal SWD Battery (API-30-015-04734)

GPS COORDINATES (Lat & Long): N 32.368838 W104.090212(UL-B-27-22S-30E) (660 FNL & 2004 FEL)

ESTIMATED VOLUMES (Oil & Water Separately):

*If BBLs Recovered are not available at time of Initial Report: Send in Follow-up report when numbers are known

Volume spilled:		BBLs Spilled	*BBLs Recovered	Net Spilled		BBLs Spilled	*BBLs Recovered	Net Spilled
On ground /or earth berm -	Oil:	27	7	20	Water:	0	0	0
Contained in impervious liner -	Oil:	193	193	0	Water:	279	279	0
Total:	Oil:	220	200	20	Water:	279	279	0

DESCRIPTION (What happened?):

A motor valve failed causing the skim tank to overflow. The containment around the skim tank overflowed to the ground and to the containment around the gun-barrel tanks. Discovered at 4:00 a.m. 12/21/14. Reported to agencies at 3:10 p.m. 12/21/14

SPILL RESPONSE (How was the spill cleaned up?):

A vacuum truck recovered 7 bbls off of the ground and all of the fluid in the containments. The containments were washed down and approximately 14 cubic yards of soil was scraped up and placed on plastic. All of the spill was contained inside the fenced area.

PICTURE ATTACHMENT:

