

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised October 10, 2003

APR 27 2015

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC

RECEIVED

Release Notification and Corrective Action

NAB1512035046 **269324** **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company: Linn Operating	Contact: Brian Wall	
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739	
Facility Name: Turner B 78	Facility Type: Injection	
Surface Owner: Federal	Mineral Owner:	API No.: 30-015-05303

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	20	17S	31E	2080	South	1980	East	Eddy

Latitude: 32.8185247710611 Longitude: -103.889788634368

NATURE OF RELEASE



Type of Release: Produced Water	Volume of Release: 17 bbls	Volume Recovered: 5 bbls
Source of Release: 2" Fiberglass collar	Date and Hour of Occurrence: 05/07/2014	Date and Hour of Discovery: 05/07/2014 0930
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Burton- BLM M.Bratcher-NM OCD	
By Whom? Brian Wall	Date and Hour 05/08/2014 0645	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*:

Describe Cause of Problem and Remedial Action Taken.*: Replaced 400ft 2 inch fiber glass line from well head number 78 west. Crew pressured up on line and noticed pressure dropped, shut in valve and drove towards well head, found the same line further down west about another 800ft that blew out of the collar.

Describe Area Affected and Cleanup Action Taken.*: Leak ran north west through arroyo, 1236 feet long by 2ft wide. Estimated barrels lost 17. Water truck was used on leak site and picked 5barrels/BSG roustabout gang fixed line, Diversified back hoe was used to dig out line. Scrape and remove contaminated soils. Haul to approved disposal and haul back clean soils to replace.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Brian Wall	Approved by District Supervisor: 	
Title: Construction Foreman II	Approval Date: 4/29/15	Expiration Date: N/A
E-mail Address: bwall@linenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 05/08/2014 Phone: 806-367-0645		

* Attach Additional Sheets If Necessary

Remediation per O.C.D. Rules & Guidelines
SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 5/29/15

2RD-2472