

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT
JUL 06 2015
RECEIVED

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Holly Energy Partners	Contact: Jeff Stubblefield
Address: 1602 W. Main Artesia, NM 88210	Telephone No. 972-322-5782
Facility Name: Mimosa Gathering	Facility Type: Crude Oil Gathering Line

Surface Owner: State Land	Mineral Owner:	API No.
---------------------------	----------------	---------

LOCATION OF RELEASE

2RP-1119

Unit Letter I	Section 30	Township 17S	Range 29E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32.80217° Longitude 104.11297°

NATURE OF RELEASE

Type of Release: Crude Oil	Volume of Release 12.5Bbls	Volume Recovered 10 bbls
Source of Release: Pipeline corrosion	Date and Hour of Occurrence 4/19/2012 15:41	Date and Hour of Discovery 4/19/2012 15:41
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, To Whom? Mike Bratcher	
By Whom?	Date and Hour 04/19/2012 @ 17:22 left message at office	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

Pipeline corrosion is the suspected cause of the release. Pumping sources immediately shut down and the flow path was diked. A vacuum truck was mobilized to the location. Impacted soils at the source were excavated and placed on a plastic liner to allow repairs to the line.

Describe Area Affected and Cleanup Action Taken.*

Flow path was in the Aero road south ditch. Delineation and remediation efforts were conducted by SESI of Hobbs, NM and closure documentation submitted to the NMOCD on 07-03-13.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Allison Stockweather		OIL CONSERVATION DIVISION	
Printed Name: Allison Stockweather		Approved by District Supervisor: 	
Title: EHS Senior Manager		Approval Date: 7/8/15	Expiration Date: N/A
E-mail Address: allison.stockweather@hollyenergycorp.com		Conditions of Approval: 	
Date: 07/02/15	Phone: 575-573-9338	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

2RP-1119